# **Laser Cutter**



Machine:	Laser Cutter	
Make/Model:	FSL P20x12	
Revised:	3 / 16 / 2023	
Author:	Trevor Marks	
Location:	Engr. II, rm 2226	
Department:	Mechanical Engineering	

DO NOT use this machine unless you have been trained in its safe use and operation!

## **Personal Protective Equipment**



Caution Laser Hazard



Inhalation Hazard



Caution Hot Surface



Caution Fire Hazard

### **Select Specifications**

 $45~\mathrm{W}~C0_2~\mathrm{Laser}$ 

Working Area:  $20" \times 12" (508 \text{ mm} \times 304 \text{ mm})$ 

Height: < 6.5" (161 mm)

Max. load: 25 lb (22 kg)


#### Do's and Don'ts


#### Do:

- Read the laser cutter manual: [GitHub LINK]
- o Only use materials on the Approved Material list
- Follow the *Procedure Flow Chart* (see next page)

#### Don'ts:

- o Do not use the laser cutter without approval!
- o Do not use material on the **Prohibited Material list!**
- o Do not leave the laser cutter while it is cutting!
- o Do not operate the machine with any of the panels removed without permission





Menu bar details with most used icons highlighted.



Accessories (water chiller, air assist supply, and exhaust system) are turned on using the power strip.

# **Approved Material List**

Only *approved* materials may be used in the laser cutter. Do not use material if you are unsure what type of material you have.

Material	Cut	Engrave/Etch
Acrylic	•	•
Delrin	•	•
Polyethylene	•	•
Silicone	•	•
Nylon	•	•
Denim	•	•
Wood (most types)	•	•
MDF	•	•
Balsa	•	
Cardstock/Paper	•	•
Glass		•