









E4: 50 g/L, 100 rpm



— PINN params + Heun's method
 — PINN params + ode45 (nonstiff solver)
 PINN params + ode15s (stiff solver)

E4: 50 g/L, 100 rpm



— GA params + Heun's method
 — GA params + ode45 (nonstiff solver)
 GA params + ode15s (stiff solver)