

Invoice Work Order #093 277213

7777 BURLINGTON PIKE ST RTE 18 Page I-75/I-71 EXIT 181

(859) 371-7166

CUM

FLORENCE, KY 41042-Service Dept Manager:

IL

558009

JAMES L BALL 859-371-7166 District Manager: Company Varie RICK KRUPINSKI 859-445-8658 DRIVER CELL# 2173053477 YOUNGS TRUCKING ERENT RACOBS 093 277213 A. Street TRIDA Card # 1323612288 I CRK 7255 E 1450 NORTH RD uthorized by 425858 iri kh FAIRMOUNT II. 61841 02/13/19 05:26 02/13/19 08:36 02/13/19 09:42 02/13/19 10:22 307 15 VOL Engine Make May

P999152

icenne it

MCRE: BAYS. EXPERTISE. SOLUTIONS

Work Requested

Tropier #

BRENT RACOBS REQUESTS:

Make Model

00

REPLACE DEF FILTER HAS TRUCK DERATED

177236

UNIT SVCD: TRACTOR

For Questinents or Concerns:

ERVICE	PLU #	PART NUMBER	DESCRIPTION	UOM	REG. PRICE	PRICE		
2T	503 152	21516229	21516229 VOLVO DEF FILTER	EA	111.99	111.99		EXTENDED AMOUNT
RFSD		1	REPLACE DEF FILTER		111.99	111.99	1.00	111.99
RFSD		REPLACE DEF FILTER		1			1.00	43.99
RFSD	997 050	-	STANDARD SERVICE LABOR B	HR				
RFSD	998 002	777777	STANDARD SERVICE LABOR				.20	
SL	415 999	DEF FLUID	DEF FLUID	HR			.49	
SL	997 002		SHOP SUPPLY/ENVIRONMENTAL F	EA	33.91	33.91	1.00	33.91
SL	998 004	LABOR	MECHANICAL HOURLY LABOR		14.90	14.90	1.00	14.90
			THE PROPERTY HABOR	HR	116.99	116.99	.50	58.50
		İ					1 1	
							1 1	
		1						
								1
					1			
		1						
- 1				37.00				1.0
			1		100	2.2	1	
			1		1	1		1
		I				AMOUNT	TENDERE	279.
Parts	: 145	.90 New Tires : 0.	0 Total : 263.29 No	n-taxable	: 0.00		WST Tax:	
Labor	: 117	.39 Used Tires : 0.	0 00		. 263.29			0. 279.
211	; 0	.00 Trade-In : 0.	00 263.20	xable	: 15.80	1 .0	E RETURNE	

Thereby authorize the above repair work to be done along with the necessary material, and hereby grant you and/or your employees permanant to operate the virtue for the purpose of testing and or inspection. An express mechanics lien is hereby acknowledged, on above vertice to active the amount of repairs thereby.

Not responsible for loss or damage to vehicles or articles left in vehicles in case of fire, theft or any other cause beyond our