

CÓDIGO	REVISÃO	DATA
FRGH.049		

REGISTRO DE INVESTIGAÇÃO DE PRODUTO

Caso algum campo não seja aplicável, preencha com N/A.

1. IDENTIFICAÇÃO DO PRODUTO

Produto:	HealthGo Air
Data:	15/04/2026
Número de Série / Lote:	202603130008
HGID:	26031901
Cliente (caso aplicável):	ERNESTO COMELLI JÚNIOR

2. INFORMAÇÕES DO PROBLEMA

PROBLEMA RELATADO PELO CLIENTE:
O aparelho está piscando o led vermelho intermitentemente e não reconhece o dispositivo no Software.
PROBLEMA CONSTATADO PELO SUPORTE:
Falha de autenticação da placa

3. ANÁLISE TÉCNICA INTERNA

RESULTADO DA INVESTIGAÇÃO:
Foi realizada uma análise detalhada dos logs do Software e identificamos falha de autenticação. foi realizado um reset no firmware para testar e não solucionou. Nos logs do terminal foi identificado a falha de hardware. Solicitei à cliente um reset geral do aparelho de 10-20min e não solucionou o erro de autenticação da placa HTU. Necessário recolhimento.
OBSERVAÇÕES:
Equipamento NOVO, nunca utilizado!

CÓDIGO	REVISÃO	DATA
FRGH.049		

4. EVIDÊNCIA FOTOGRÁFICA

```

C:\Windows\system32\cmd.e. X
2026-04-20T08:51:07.6292665-03:00 WRN FULL ERROR protoErr="payloadType:ERROR_EVENT  errorCode:INITIALIZATION_FAIL  descr
ption:"\\nSM: INITIALIZE Erro no logger. \\n\"
2026-04-20T08:51:07.6321231-03:00 WRN ERROR CODE ErrorCode=INITIALIZATION_FAIL
2026-04-20T08:51:07.6359274-03:00 WRN ERROR DESCRIPTION Description="\\nSM: INITIALIZE Erro no logger. \\n"
2026-04-20T08:51:09.6252591-03:00 WRN Received error from device error=INITIALIZATION_FAIL
2026-04-20T08:51:09.6280565-03:00 WRN FULL ERROR protoErr="payloadType:ERROR_EVENT  errorCode:INITIALIZATION_FAIL  descr
ption:"\\nSM: INITIALIZE Erro no logger. \\n\"
2026-04-20T08:51:09.6308024-03:00 WRN ERROR CODE ErrorCode=INITIALIZATION_FAIL
2026-04-20T08:51:09.6339336-03:00 WRN ERROR DESCRIPTION Description="\\nSM: INITIALIZE Erro no logger. \\n"
2026-04-20T08:51:11.6255175-03:00 WRN Received error from device error=INITIALIZATION_FAIL
2026-04-20T08:51:11.6266645-03:00 WRN FULL ERROR protoErr="payloadType:ERROR_EVENT  errorCode:INITIALIZATION_FAIL  descr
ption:"\\nSM: INITIALIZE Erro no logger. \\n\"
2026-04-20T08:51:11.6272764-03:00 WRN ERROR CODE ErrorCode=INITIALIZATION_FAIL
2026-04-20T08:51:11.6278934-03:00 WRN ERROR DESCRIPTION Description="\\nSM: INITIALIZE Erro no logger. \\n"
2026-04-20T08:51:13.6251304-03:00 WRN Received error from device error=INITIALIZATION_FAIL
2026-04-20T08:51:13.6257689-03:00 WRN FULL ERROR protoErr="payloadType:ERROR_EVENT  errorCode:INITIALIZATION_FAIL  descr
ption:"\\nSM: INITIALIZE Erro no logger. \\n\"
2026-04-20T08:51:13.6263636-03:00 WRN ERROR CODE ErrorCode=INITIALIZATION_FAIL
2026-04-20T08:51:13.6263636-03:00 WRN ERROR DESCRIPTION Description="\\nSM: INITIALIZE Erro no logger. \\n"
2026-04-20T08:51:15.6243613-03:00 WRN Received error from device error=INITIALIZATION_FAIL
2026-04-20T08:51:15.6281671-03:00 WRN FULL ERROR protoErr="payloadType:ERROR_EVENT  errorCode:INITIALIZATION_FAIL  descr
ption:"\\nSM: INITIALIZE Erro no logger. \\n\"
2026-04-20T08:51:15.6321367-03:00 WRN ERROR CODE ErrorCode=INITIALIZATION_FAIL
2026-04-20T08:51:15.6339352-03:00 WRN ERROR DESCRIPTION Description="\\nSM: INITIALIZE Erro no logger. \\n"
2026-04-20T08:51:17.6247042-03:00 WRN Received error from device error=INITIALIZATION_FAIL
2026-04-20T08:51:17.6252081-03:00 WRN FULL ERROR protoErr="payloadType:ERROR_EVENT  errorCode:INITIALIZATION_FAIL  descr
ption:"\\nSM: INITIALIZE Erro no logger. \\n\"
2026-04-20T08:51:17.6258701-03:00 WRN ERROR CODE ErrorCode=INITIALIZATION_FAIL
2026-04-20T08:51:17.6265184-03:00 WRN ERROR DESCRIPTION Description="\\nSM: INITIALIZE Erro no logger. \\n"


```

5. DISPOSIÇÃO FINAL

- X Recolhimento do produto
- Atualização de firmware
- Recalibração Remota

CÓDIGO	REVISÃO	DATA
FRGH.049		

ASSINATURA

A handwritten signature in black ink, appearing to read 'André Luiz de Souza', is written over a horizontal line within a rectangular box.

Analista responsável: André Luiz de Souza