

CÓDIGO	REVISÃO	DATA
FRGH.049		

REGISTRO DE INVESTIGAÇÃO DE PRODUTO

Caso algum campo não seja aplicável, preencha com N/A.

1. IDENTIFICAÇÃO DO PRODUTO

Produto:	HealthGo Air
Data:	06/04/2026
Número de Série / Lote:	202601150002
HGID:	26010804
Cliente (caso aplicável):	DEBORA AFONSO CAMPELLO

2. INFORMAÇÕES DO PROBLEMA

PROBLEMA RELATADO PELO CLIENTE:
Aparelho piscando o led vermelho
PROBLEMA CONSTATADO PELO SUPORTE:
Falha na autenticação do HTU

3. ANÁLISE TÉCNICA INTERNA

RESULTADO DA INVESTIGAÇÃO:
Após a médica relatar que o equipamento estava com o led piscando vermelho, foram feitas algumas ações para tentar corrigir a falha. Identifiquei nos logs do debug que a autenticação do HTU está em falha por motivo desconhecido remotamente. Necessário recolhimento para investigação.
OBSERVAÇÕES:
N/A

CÓDIGO	REVISÃO	DATA
FRGH.049		

4. EVIDÊNCIA FOTOGRÁFICA

```

2026-03-23T10:47:43.3977054-03:00 INF Sending to serial port protoSerialPayloadType=PREDICTION_PARAMETER_CNT
2026-03-23T10:47:43.4173019-03:00 INF Prediction parameter received parameter=102
2026-03-23T10:47:43.4188621-03:00 INF Prediction parameter retrieved successfully predictionParam=102
2026-03-23T10:47:43.4193907-03:00 INF Heartbeat persistence-only mode stopped
2026-03-23T10:47:43.4193907-03:00 INF Sensor monitor started
2026-03-23T10:47:44.9653395-03:00 INF ESP-SPECIFIC DUMB TERMINAL MSG RECEIVED dumbMsg="\x1b[0;31mE (3072) gpio: gpio_install_isr_service(502): GPIO isr service already instal
led\x1b[0m\n"
2026-03-23T10:47:46.5659212-03:00 WRN Received error from device error=INITIALIZATION_FAIL
2026-03-23T10:47:46.5665238-03:00 WRN FULL ERROR protoErr=payloadType:ERROR_EVENT errorCode=INITIALIZATION_FAIL description:"\n\nSM: INITIALIZE Erro no logger. \n\n"
2026-03-23T10:47:46.5672205-03:00 WRN ERROR CODE ErrorCode=INITIALIZATION_FAIL
2026-03-23T10:47:46.5678777-03:00 WRN ERROR DESCRIPTION Description="\nSM: INITIALIZE Erro no logger. \n"
2026-03-23T10:47:48.5647684-03:00 WRN Received error from device error=INITIALIZATION_FAIL
2026-03-23T10:47:48.5652711-03:00 WRN FULL ERROR protoErr=payloadType:ERROR_EVENT errorCode=INITIALIZATION_FAIL description:"\n\nSM: INITIALIZE Erro no logger. \n\n"
2026-03-23T10:47:48.5664431-03:00 WRN ERROR CODE ErrorCode=INITIALIZATION_FAIL
2026-03-23T10:47:48.5669902-03:00 WRN ERROR DESCRIPTION Description="\nSM: INITIALIZE Erro no logger. \n"
2026-03-23T10:47:50.5649842-03:00 WRN Received error from device error=INITIALIZATION_FAIL
2026-03-23T10:47:50.5654897-03:00 WRN FULL ERROR protoErr=payloadType:ERROR_EVENT errorCode=INITIALIZATION_FAIL description:"\n\nSM: INITIALIZE Erro no logger. \n\n"
2026-03-23T10:47:50.566843-03:00 WRN ERROR CODE ErrorCode=INITIALIZATION_FAIL
2026-03-23T10:47:50.5669043-03:00 WRN ERROR DESCRIPTION Description="\nSM: INITIALIZE Erro no logger. \n"
2026-03-23T10:47:52.5658135-03:00 WRN Received error from device error=INITIALIZATION_FAIL
2026-03-23T10:47:52.5663602-03:00 WRN FULL ERROR protoErr=payloadType:ERROR_EVENT errorCode=INITIALIZATION_FAIL description:"\n\nSM: INITIALIZE Erro no logger. \n\n"
2026-03-23T10:47:52.5663602-03:00 WRN ERROR CODE ErrorCode=INITIALIZATION_FAIL
2026-03-23T10:47:52.5669932-03:00 WRN ERROR DESCRIPTION Description="\nSM: INITIALIZE Erro no logger. \n"
2026-03-23T10:47:54.5649941-03:00 WRN Received error from device error=INITIALIZATION_FAIL
2026-03-23T10:47:54.5660774-03:00 WRN FULL ERROR protoErr=payloadType:ERROR_EVENT errorCode=INITIALIZATION_FAIL description:"\n\nSM: INITIALIZE Erro no logger. \n\n"
2026-03-23T10:47:54.5660774-03:00 WRN ERROR CODE ErrorCode=INITIALIZATION_FAIL
2026-03-23T10:47:54.5672855-03:00 WRN ERROR DESCRIPTION Description="\nSM: INITIALIZE Erro no logger. \n"
2026-03-23T10:47:56.5646578-03:00 WRN Received error from device error=INITIALIZATION_FAIL
2026-03-23T10:47:56.5649719-03:00 WRN FULL ERROR protoErr=payloadType:ERROR_EVENT errorCode=INITIALIZATION_FAIL description:"\n\nSM: INITIALIZE Erro no logger. \n\n"
2026-03-23T10:47:56.5670191-03:00 WRN ERROR CODE ErrorCode=INITIALIZATION_FAIL
2026-03-23T10:47:56.5676577-03:00 WRN ERROR DESCRIPTION Description="\nSM: INITIALIZE Erro no logger. \n"

```

5. DISPOSIÇÃO FINAL


X Recolhimento do produto

Atualização de firmware

Recalibração Remota

CÓDIGO	REVISÃO	DATA
FRGH.049		

ASSINATURA

A handwritten signature in black ink, appearing to read 'André Luiz de Souza', is written over a horizontal line within a rectangular box.

Analista responsável: André Luiz de Souza