Item	Source	Notes	Item cost (\$)	Quantity	Total cost
AS01-ML01s	https://bit.ly/30JMeky	RF transceiver for the beeper	5.62	4	22.48
		transmitter and receiver			
3080TR	https://bit.ly/45j8Vl6	Coin cell battery holder	1.03	4	4.12
CMT-8540S-SMT-TR	https://bit.ly/30qGxXn	Receiver buzzer	3.26	3	9.78
STR1550	https://bit.ly/3Yr1gik	Buzzer transistor	0.55	3	1.65
LRC HF1600G	https://bit.ly/3DKrinl	Buzzer flyback diode	0.1586	5	0.793
RC0402FR-07180RL	https://bit.ly/3rZpcNT	Buzzer resistor	0.1	3	0.3
ATTINY84A-MU	https://bit.ly/45iiT6w	Buzzer and receiver microchip	2.78	5	13.9
TS02-66-70-BK-160-L	C https://bit.ly/3Yq9Bmx	Transmitter button	0.1	3	0.3
Solder paste	https://amzn.to/3YsoG75	Solder paste used to attach	11.99	1	11.99
		components onto the PCB			
Solder wick	https://amzn.to/3QpfYEP	Used in case the need to disassemble	7.99	1	7.99
		components on the PCB arises			
Solder flux	https://amzn.to/30nAinl	Used to attach components on the	8.99	1	8.99
		PCB			
Attiny 84 programme	r https://amzn.to/3QmYPLY	Used to program the receiver and	15.99	1	15.99
		transmitter microchips			
CR1225	https://amzn.to/47ilm1o	Receiver and transmitter battery	5.79	1	5.79
PCB		Will be ordered through JLPCB with 2-	24.86	1	24.86
		4 day shipping. 5 receiver and 5			
		transmitter PCBs			
					0
					0
			-	Total:	128.933