

Revision 1.0.0

**ADV Issue Date: 07/02/2020** 

# CUSTOMER ADVISORY ADV2020

# Intel® Arria® 10 Device Datasheet Update

# **Description:**

Intel® is notifying customers of an update to the Intel Arria® 10 Device Datasheet.

The following footnote has been removed from Intel Arria® 10 Device Datasheet as it was a typo error-

(15) This is also applicable to HPS power supply. For HPS power supply, refer to  $t_{RAMP}$  specifications for standard POR when HPS\_PORSEL = 0 and  $t_{RAMP}$  specifications for fast POR when HPS\_PORSEL = 1.

You can find the updated Intel Arria 10 Device Datasheet herehttps://www.intel.com/content/dam/www/programmable/us/en/pdfs/literature/hb/arria -10/a10 datasheet.pdf

## **Recommended Actions:**

Customers are requested to review the change and refer to the revision history for a complete history of updates.

For questions or support, please contact your local Sales representative, or submit a question or request at the My Intel support page, log-in via: https://www.intel.com/content/www/us/en/my-intel/fpga-sign-in.html

## **Products Affected:**

All Intel Arria 10 Devices.

Intel Corporation Page 1 of 2 07/02/2020 ADV2020

# The list of affected part numbers (OPNs) can be downloaded in Excel form:

https://www.intel.com/content/dam/www/programmable/us/en/pdfs/literature/pcn/adv 2020-opn-list.xlsx

# **Change Implementation:**

#### Table 1

| Milestone  | Availability |
|--|--------------|
| Availability of Intel Arria 10 Device Datasheet update | Now          |

#### **Contact:**

For more information, please contact your local Sales representative, or submit a question or request at the My Intel support page, log-in via: <a href="https://www.intel.com/content/www/us/en/my-intel/fpga-sign-in.html">https://www.intel.com/content/www/us/en/my-intel/fpga-sign-in.html</a>

# **Customer Notifications Subscription:**

Customers that subscribe to the Intel FPGA customer notification mailing list will receive the notifications automatically via email.

If you would like to receive Intel FPGA customer notifications by email, you can register to the Intel FPGA program and set up your subscription at:

https://www.intel.com/content/www/us/en/programmable/my-intel/malemailsub/technical-updates.html

# Revision

| Date       | Rev   | Description     |
|------------|-------|-----------------|
| 07/02/2020 | 1.0.0 | Initial Release |

©2020 Intel Corporation. All rights reserved. Intel, the Intel logo, Altera, Arria, Cyclone, Enpirion, Max, Nios, Quartus and Stratix words and logos are trademarks of Intel Corporation or its subsidiaries in the U.S. and/or other countries. Other marks and brands may be claimed as the property of others. Intel reserves the right to make changes to any products and services at any time without notice. Intel assumes no responsibility or liability arising out of the application or use of any information, product, or service described herein except as expressly agreed to in writing by Intel. Intel customers are advised to obtain the latest version of device specifications before relying on any published information and before placing orders for products or services.

Intel Corporation Page 2 of 2 07/02/2020 ADV2020

## **Ordering Part Number (OPN)**

- 10AS016C3U19E2LG
- 10AS016C3U19E2SG
- 10AS016C3U19I2LG
- 10AS016C3U19I2SG
- 10AS016C4U19E3LG
- 10AS016C4U19E3SG
- 10AS016C4U19E3VG
- 10AS016C4U19I3LG
- 10AS016C4U19I3SG
- 10AS016C4U19I3VG
- 10AS016E3F27E1HG
- 10AS016E3F27E2LG
- 10AS016E3F27E2SG
- 10AS016E3F27I1HG
- 10,100102012711110
- 10AS016E3F27I2LG
- 10AS016E3F27I2SG
- 10AS016E3F27I2SGHZ
- 10AS016E3F29E1HG
- 10AS016E3F29E2LG
- 10AS016E3F29E2SG
- 10AS016E3F29E2SGHZ
- 10AS016E3F29I1HG
- 10AS016E3F29I2LG
- 10AS016E3F29I2SG
- 10AS016E4F27E3LG
- 10AS016E4F27E3SG
- 10AS016E4F27I3LG
- 10AS016E4F27I3SG
- 10AS016E4F29E3LG
- 10AS016E4F29E3SG
- 10AS016E4F29I3LG
- 10AS016E4F29I3SG
- 10AS016XXAA
- 10AS022C3U19E2LG
- 10AS022C3U19E2SG
- 10AS022C3U19I2LG
- 10AS022C3U19I2LP
- 10AS022C3U19I2LPAA
- 10AS022C3U19I2SG
- 10AS022C4U19E3LG
- 10AS022C4U19E3SG
- 10AS022C4U19E3VG
- 10AS022C4U19I3LG
- 10AS022C4U19I3SG
- 10AS022C4U19I3VG
- 10AS022E3F27E1HG
- 10AS022E3F27E2LG

- 10AS022E3F27E2SG
- 10AS022E3F27I1HG
- 10AS022E3F27I2LG
- 10AS022E3F27I2SG
- 10AS022E3F29E1HG
- 10AS022E3F29E2LG
- 10AS022E3F29E2SG
- 10/10/22/25/29/200
- 10AS022E3F29I1HG
- 10AS022E3F29I2LG
- 10AS022E3F29I2SG
- 10AS022E4F27E3LG
- 10AS022E4F27E3SG
- 10AS022E4F27I3LG
- 10AS022E4F27I3SG
- 10AS022E4F29E3LG
- 10AS022E4F29E3SG
- 10AS022E4F29I3LG
- 10AS022E4F29I3LGJW
- 10AS022E4F29I3SG
- 10AS027E1F27E1HG
- 10AS027E1F27I1HG
- 10AS027E1F29E1HG
- 10AS027E1F29I1HG
- 10AS027E2F27E1HG
- 10AS027E2F27E2LG
- 10AS027E2F27E2SG
- 10AS027E2F27I1HG
- 10AS027E2F27I2LG
- 10AS027E2F27I2SG
- 10AS027E2F29E1HG
- 10AS027E2F29E2LG
- 10AS027E2F29E2SG
- 10AS027E2F29I1HG
- 10AS027E2F29I2LG
- 10AS027E2F29I2SG
- 10AS027E3F27E2LG
- 10AS027E3F27E2SG
- 10AS027E3F27I2LG
- 10AS027E3F27I2SG 10AS027E3F29E2LG
- 10AS027E3F29E2LGAA
- 10AS027E3F29E2SG
- 10AS027E3F29I2LG
- 10AS027E3F29I2SG
- 10AS027E4F27E3LG
- 10AS027E4F27E3SG
- 10AS027E4F27I3LG
- 10AS027E4F27I3SG

- 10AS027E4F29E3LG
- 10AS027E4F29E3SG
- 10AS027E4F29I3LG
- 10AS027E4F29I3LGJW
- 10AS027E4F29I3SG
- 10AS027H1F34E1HG
- 10AS027H1F34I1HG
- 10AS027H1F35E1HG
- 10AS027H1F35I1HG
- 10AS027H2F34E1HG
- 10AS027H2F34E2LG
- 10AS027H2F34E2SG
- 10AS027H2F34I1HG
- 10AS027H2F34I2LG
- 10AS027H2F34I2SG
- 10AS027H2F35E1HG
- 10AS027H2F35E2LG
- 10AS027H2F35E2SG
- 10AS027H2F35I1HG
- 10AS027H2F35I2LG
- 10AS027H2F35I2SG
- 10AS027H3F34E2LG
- 10AS027H3F34E2SG
- 10AS027H3F34I2LG
- 10AS027H3F34I2SG
- 10AS027H3F35E2LG
- 10AS027H3F35E2SG
- 10AS027H3F35I2LG
- 10AS027H3F35I2SG
- 10AS027H4F34E3LG
- 10/1002/1111 0 12020
- 10AS027H4F34E3SG
- 10AS027H4F34E3VG
- 10AS027H4F34I3LG
- 10AS027H4F34I3LGJW
- 10AS027H4F34I3SG
- 10AS027H4F34I3VG
- 10AS027H4F34I3VGJW
- 10AS027H4F35E3LG
- 10AS027H4F35E3SG
- 10AS027H4F35I3LG
- 10AS027H4F35I3SG
- 10AS032E1F27E1HG
- 10AS032E1F27I1HG
- 10AS032E1F29E1HG
- 10AS032E1F29I1HG
- 10AS032E2F27E1HG 10AS032E2F27E2LG
- 10AS032E2F27E2SG

- 10AS032E2F27I1HG
- 10AS032E2F27I2LG
- 10AS032E2F27I2SG
- 10AS032E2F29E1HG
- 10AS032E2F29E2LG
- 10AS032E2F29E2SG
- 10AS032E2F29I1HG
- 10AS032E2F29I2LG
- 10AS032E2F29I2SG
- 10AS032E3F27E2LG
- 10AS032E3F27E2SG
- 10AS032E3F27I2LG
- 10AS032E3F27I2SG
- 10AS032E3F29E2LG
- 10AS032E3F29E2SG
- 10AS032E3F29I2LG
- 10AS032E3F29I2SG
- 10AS032E4F27E3LG
- 10AS032E4F27E3SG
- 10AS032E4F27I3LG
- 10AS032E4F27I3SG
- 10AS032E4F29E3LG
- 10AS032E4F29E3SG
- 10AS032E4F29I3LG
- 10AS032E4F29I3SG
- 10AS032H1F34E1HG
- 10AS032H1F34I1HG
- 10AS032H1F35E1HG
- 10AS032H1F35I1HG
- 10AS032H2F34E1HG
- 10AS032H2F34E2LG
- 10AS032H2F34E2SG
- 10AS032H2F34I1HG
- 10AS032H2F34I2LG
- 10AS032H2F34I2SG
- 10AS032H2F35E1HG
- 10AS032H2F35E2LG
- 10AS032H2F35E2SG
- 10A3032H2F33E230
- 10AS032H2F35I1HG
- 10AS032H2F35I2LG 10AS032H2F35I2SG
- 10AS032H3F34E2LG
- 10/10002/10/ 042220
- 10AS032H3F34E2SG 10AS032H3F34I2LG
- 10AS032H3F34I2SG
- 10AS032H3F34I2SGJW
- 10AS032H3F35E2LG
- 10AS032H3F35E2SG

- 10AS032H3F35I2LG
- 10AS032H3F35I2SG
- 10AS032H4F34E3LG
- 10AS032H4F34E3SG
- 10AS032H4F34E3VG
- 10AS032H4F34I3LG
- 10AS032H4F34I3SG
- 10430321141341330
- 10AS032H4F34I3VG
- 10AS032H4F35E3LG
- 10AS032H4F35E3SG
- 10AS032H4F35I3LG
- 10AS032H4F35I3SG
- 10AS048E1F29E1HG
- 10AS048E1F29I1HG
- 10AS048E2F29E1HG
- 10AS048E2F29E2LG
- 10AS048E2F29E2SG
- 10AS048E2F29I1HG
- 10AS048E2F29I2LG
- 10AS048E2F29I2SG
- 10AS048E3F29E2LG
- . . . . . . . . . . . . . . . . .
- 10AS048E3F29E2SG
- 10AS048E3F29I2LG
- 10AS048E3F29I2SG
- 10AS048E4F29E3LG
- 10AS048E4F29E3SG
- 10AS048E4F29I3LG
- 10AS048E4F29I3SG
- 10AS048E4F29I3SP
- 10AS048H1F34E1HG
- 10AS048H1F34I1HG
- 10AS048H2F34E1HG
- 10AS048H2F34E2LG
- 10AS048H2F34E2SG
- 10AS048H2F34I1HG
- 10AS048H2F34I2LG
- 10AS048H2F34I2SG
- 10AS048H3F34E2LG
- 10AS048H3F34E2SG
- 10AS048H3F34I2LG
- 10AS048H3F34I2SG
- 10AS048H4F34E3LG
- 10AS048H4F34E3SG
- 10AS048H4F34E3VG
- 10AS048H4F34I3LG
- 10AS048H4F34I3SG
- 10AS048H4F34I3VG
- 10AS048H4F34M3SGAA

- 10AS048K1F35E1HG
- 10AS048K1F35I1HG
- 10AS048K2F35E1HG
- 10AS048K2F35E2LG
- 10AS048K2F35E2SG
- 10AS048K2F35I1HG
- 10AS048K2F35I2LG
- . . . . . . . . . . . . . . . . . .
- 10AS048K2F35I2SG
- 10AS048K3F35E2LG
- 10AS048K3F35E2SG
- 10AS048K3F35I2LG
- 10AS048K3F35I2SG
- 10AS048K4F35E3LG
- 10AS048K4F35E3SG
- 10AS048K4F35I3LG
- 10AS048K4F35I3SG
- 10AS057H1F34E1HG
- 10AS057H1F34I1HG
- 10AS057H2F34E1HG
- 10AS057H2F34E2LG
- 10AS057H2F34E2SG
- 10AS057H2F34I1HG
- 10AS057H2F34I2LG
- 10AS057H2F34I2SG
- 10AS057H3F34E2LG
- 10AS057H3F34E2SG
- 10AS057H3F34I2LG
- 10AS057H3F34I2SG
- 10AS057H4F34E3LG
- 10AS057H4F34E3SG
- 10AS057H4F34E3VG
- 10AS057H4F34I3LG
- 10AS057H4F34I3SG
- 10AS057H4F34I3VG
- 10AS057K1F35E1HG
- 10A00371(11 33E 1110
- 10AS057K1F35I1HG 10AS057K1F40E1HG
- 10AS057K1F40I1HG
- TUASUS/KTF40TTHG
- 10AS057K2F35E1HG
- 10AS057K2F35E2LG 10AS057K2F35E2SG
- 10AS057K2F35I1HG
- 10AS057K2F35I2LG
- 10AS057K2F35I2SG
- 10AS057K2F40E1HG
- 10AS057K2F40E2LG
- 10AS057K2F40E2SG
- 10AS057K2F40I1HG

- 10AS057K2F40I2LG
- 10AS057K2F40I2SG
- 10AS057K3F35E2LG
- 10AS057K3F35E2SG
- 10AS057K3F35I2LG
- 10AS057K3F35I2SG
- 10AS057K3F40E2LG
- 10AS057K3F40E2SG
- 10AS057K3F40I2LG
- 10AS057K3F40I2SG
- 10AS057K4F35E3LG
- 10AS057K4F35E3SG
- 10AS057K4F35l3LG
- 10AS057K4F35I3SG
- 10AS057K4F40E3LG
- 10AS057K4F40E3SG
- 10AS057K4F40I3LG
- 10AS057K4F40I3SG
- 10AS057N1F40E1HG
- 10AS057N1F40I1HG
- 10AS057N2F40E1HG
- 10AS057N2F40E2LG
- 10AS057N2F40E2SG
- 10AS057N2F40I1HG
- 10AS057N2F40I2LG
- 10AS057N2F40I2SG
- 10AS057N3F40E2LG
- 10AS057N3F40E2SG
- 10AS057N3F40I2LG
- 10AS057N3F40I2SG
- 10AS057N4F40E3LG
- 10AS057N4F40E3SG
- 10AS057N4F40E3VG
- 10AS057N4F40I3LG
- 10AS057N4F40I3SG
- 10AS057N4F40I3VG
- 10AS066H1F34E1HG
- 10AS066H1F34I1HG
- 10AS066H2F34E1HG
- 10AS066H2F34E1HGAA
- 10AS066H2F34E2LG
- 10AS066H2F34E2LGES
- 10AS066H2F34E2LGJA
- 10AS066H2F34E2LGJZ
- 10AS066H2F34E2SG
- 10AS066H2F34E2SGHZ
- 10AS066H2F34I1HG
- 10AS066H2F34I2LG

- 10AS066H2F34I2LGAD
- 10AS066H2F34I2SG
- 10AS066H2F34I2SGHZ
- 10AS066H2F34I2SP
- 10AS066H3F34E2LG
- 10AS066H3F34E2SG
- 10AS066H3F34E2SGAA
- 10AS066H3F34I2LG
- 10AS066H3F34I2LGAB
- 10AS066H3F34I2SG
- 10AS066H4F34E3LG
- 10AS066H4F34E3SG
- 10AS066H4F34E3VG
- 10AS066H4F34I3LG
- 10AS066H4F34I3LP
- 10AS066H4F34I3SG
- 10AS066H4F34I3VG
- 10AS066K1F35E1HG
- 10AS066K1F35I1HG
- 10AS066K1F40E1HG
- 10AS066K1F40I1HG
- 10AS066K2F35E1HG
- TOAGOOOKZI GGETTIC
- 10AS066K2F35E2LG
- 10AS066K2F35E2SG
- 10AS066K2F35I1HG
- 10AS066K2F35I2LG
- 10AS066K2F35I2SG
- 10AS066K2F40E1HG
- 10AS066K2F40E2LG
- 10AS066K2F40E2SG
- 10AS066K2F40I1HG
- 10AS066K2F40I2LG
- 10AS066K2F40I2SG
- 10AS066K3F35E2LG
- 10AS066K3F35E2SG
- 10AS066K3F35I2LG
- 10AS066K3F35I2SG
- 10AS066K3F35I2SP
- 10AS066K3F40E2LG
- 10AS066K3F40E2SG
- 10AS066K3F40I2LG
- 10AS066K3F40I2SG
- 10AS066K4F35E3LG
- 10AS066K4F35E3SG
- 10AS066K4F35I3LG
- 10AS066K4F35I3SG
- 10AS066K4F40E3LG
- 10AS066K4F40E3SG

- 10AS066K4F40I3LG
- 10AS066K4F40I3SG
- 10AS066N1F40E1HG
- 10AS066N1F40I1HG
- 10AS066N2F40E1HG
- 10AS066N2F40E2LG
- 10AS066N2F40E2SG
- 10AS066N2F40I1HG
- 10AS066N2F40I2LG
- 10AS066N2F40I2SG
- 10AS066N3F40E2LG
- 10AS066N3F40E2SG
- 10AS066N3F40E2SGE2
- 10AS066N3F40I2LG
- 10AS066N3F40I2SG
- 10AS066N4F40E3LG
- 10AS066N4F40E3SG
- 10AS066N4F40E3SGE2
- 10AS066N4F40E3VG
- 10AS066N4F40I3LG
- 10AS066N4F40I3SG
- 10AS066N4F40I3SGES
- 10AS066N4F40I3VG
- 10AS066N4F40M3SGAA
- 10AT090S1F45E1SG
- 10AT090S2F45E2SG
- 10AT115S1F45E1SG
- 10AT115S1F45E1SGJA
- 10AT115S1F45E1SGJY
- 10AT115S1F45E1SGJZ
- 10AT115S2F45E2SG
- 10AX016C3U19E2LG
- 10AX016C3U19E2SG
- 10AX016C3U19I2LG
- 10AX016C3U19I2SG
- 10AX016C4U19E3LG
- 10AX016C4U19E3SG
- 10/1/10/100/10/10/2000
- 10AX016C4U19E3VG
- 10AX016C4U19I3LG
- 10AX016C4U19I3SG
- 10AX016C4U19I3VG
- 10AX016C4U19M3SG 10AX016E3F27E1HG
- 10AX016E3F27E2LG
- 10AX016E3F27E2LGJW
- 10AX016E3F27E2SG
- 10AX016E3F27I1HG
- 10AX016E3F27I2LG

- 10AX016E3F27I2SG
- 10AX016E3F29E1HG
- 10AX016E3F29E2LG
- 10AX016E3F29E2SG
- 10AX016E3F29I1HG
- 10AX016E3F29I2LG
- 10AX016E3F29I2SG
- 10AX016E4F27E3LG
- 10AX016E4F27E3SG
- 10AX016E4F27I3LG
- 10AX016E4F27I3SG
- 10AX016E4F29E3LG
- 10AX016E4F29E3SG
- 10AX016E4F29I3LG
- 10AX016E4F29I3SG
- 10AX016E4F29M3SG
- 10AX022C3U19E2LG
- 10AX022C3U19E2SG
- 10AX022C3U19I2LG
- 10AX022C3U19I2SG
- 10AX022C4U19E3LG
- 10AX022C4U19E3SG
- 10AX022C4U19E3VG
- 10AX022C4U19I3LG
- 10AX022C4U19I3SG
- 10AX022C4U19I3VG
- 10AX022C4U19M3SG
- 10AX022E3F27E1HG
- 10AX022E3F27E2LG
- 10AX022E3F27E2SG
- 10AX022E3F27I1HG
- 10AX022E3F27I2LG
- 10AX022E3F27I2SG
- 10AX022E3F29E1HG
- 10AX022E3F29E2LG
- TOANOZZESI ZSEZEG
- 10AX022E3F29E2SG
- 10AX022E3F29I1HG
- 10AX022E3F29I2LG
- 10AX022E3F29I2SG
- 10AX022E4F27E3LG
- 10AX022E4F27E3SG 10AX022E4F27I3LG
- 10AX022E4F27I3SG
- 10AX022E4F29E3LG
- 10AX022E4F29E3SG
- 10AX022E4F29I3LG
- 10AX022E4F29I3SG
- 10AX022E4F29M3SG

- 10AX027E1F27E1HG
- 10AX027E1F27I1HG
- 10AX027E1F29E1HG
- 10AX027E1F29I1HG
- 10AX027E2F27E1HG
- 10AX027E2F27E2LG
- 10AX027E2F27E2SG
- 10,000,02,22,2,2,200
- 10AX027E2F27I1HG 10AX027E2F27I2LG
- 10AX027E2F27I2SG
- 10AX027E2F29E1HG
- 10AX027E2F29E2LG
- 10AX027E2F29E2SG
- 10AX027E2F29I1HG
- 10AX027E2F29I2LG
- 10AX027E2F29I2SG
- 10AX027E3F27E2LG
- 10AX027E3F27E2SG
- 10AX027E3F27I2LG
- 10AX027E3F27I2SG
- 10AX027E3F29E2LG
- 10AX027E3F29E2SG
- 10AX027E3F29I2LG
- 10AX027E3F29I2SG
- 10AX027E4F27E3LG
- 10AX027E4F27E3SG
- 10AX027E4F27I3LG
- 10AX027E4F27I3SG
- 10AX027E4F29E3LG
- 10AX027E4F29E3SG
- 10AX027E4F29I3LG
- 10AX027E4F29I3SG
- 10AX027H1F34E1HG
- 10AX027H1F34I1HG
- 10AX027H1F35E1HG
- 10AX027H1F35I1HG
- 10AX027H2F34E1HG
- 10AX027H2F34E2LG
- 10AX027H2F34E2SG
- 10AX027H2F34I1HG
- 10AX027H2F34I2LG
- 10AX027H2F34I2SG
- 10AX027H2F35E1HG 10AX027H2F35E2LG
- 10AX027H2F35E2SG
- 10AX027H2F35I1HG
- 10AX027H2F35I2LG
- 10AX027H2F35I2SG

- 10AX027H3F34E2LG
- 10AX027H3F34E2SG
- 10AX027H3F34I2LG
- 10AX027H3F34I2SG
- 10AX027H3F35E2LG
- 10AX027H3F35E2SG
- 10AX027H3F35I2LG
- 10AX027H3F35I2SG
- 10AX027H4F34E3LG
- 10AX027H4F34E3SG
- 10AX027H4F34E3VG
- 10AX027H4F34I3LG
- 10AX027H4F34I3SG
- 10AX027H4F34I3VG
- 10AX027H4F35E3LG
- 10AX027H4F35E3SG
- 10AX027H4F35I3LG
- 10AX027H4F35I3SG
- 10AX032E1F27E1HG
- 10AX032E1F27I1HG
- 10AX032E1F29E1HG
- 10AX032E1F29I1HG
- 10AX032E2F27E1HG
- 10AX032E2F27E2LG
- 10AX032E2F27E2SG
- 10AX032E2F27I1HG
- 10AX032E2F27l2LG 10AX032E2F27l2SG
- 10/4/1002221 2/1200
- 10AX032E2F29E1HG
- 10AX032E2F29E2LG
- 10AX032E2F29E2SG
- 10AX032E2F29I1HG
- 10AX032E2F29I2LG 10AX032E2F29I2SG
- 10AX032E3F27E2LG
- 10AX032E3F27E2SG
- 10AX032E3F27I2LG
- 10AX032E3F27I2SG
- 10AX032E3F29E2LG
- TUANUSZESFZ9EZLG
- 10AX032E3F29E2SG 10AX032E3F29I2LG
- 10AX032E3F29I2SG
- 10AX032E4F27E3LG
- 10AX032E4F27E3SG
- 10AX032E4F27I3LG
- 10AX032E4F27I3SG
- 10AX032E4F29E3LG
- 10AX032E4F29E3SG

- 10AX032E4F29I3LG
- 10AX032E4F29I3SG
- 10AX032H1F34E1HG
- 10AX032H1F34I1HG
- 10AX032H1F35E1HG
- 10AX032H1F35I1HG
- 10AX032H2F34E1HG
- 10AX032H2F34E2LG
- 10AX032H2F34E2SG
- 10AX032H2F34I1HG
- 10AX032H2F34I2LG
- 10AX032H2F34I2LGAA
- 10,0,00021121 0 11220,1
- 10AX032H2F34I2LP
- 10AX032H2F34I2LPAA
- 10AX032H2F34I2SG
- 10AX032H2F35E1HG
- 10AX032H2F35E2LG
- 10AX032H2F35E2SG
- 10AX032H2F35I1HG
- 10AX032H2F35I2LG
- 10AX032H2F35I2SG
- 10AX032H3F34E2LG
- 10AX032H3F34E2SG
- 10AX032H3F34I2LG
- 10AX032H3F34I2SG
- 10AX032H3F35E2LG
- 10AX032H3F35E2SG
- 10AX032H3F35I2LG
- 10AX032H3F35I2SG
- 10AX032H4F34E3LG
- 10AX032H4F34E3SG
- 10AX032H4F34E3VG
- 10AX032H4F34I3LG
- 10AX032H4F34I3LP
- 10AX032H4F34I3SG
- 10AX032H4F34I3VG
- 10AX032H4F34I3VGJW
- 10AX032H4F35E3LG
- 10AX032H4F35E3SG
- 10AX032H4F35I3LG
- 10AX032H4F35I3SG
- 10AX048E1F29E1HG
- 10AX048E1F29I1HG
- 10AX048E2F29E1HG
- 10AX048E2F29E2LG
- 10AX048E2F29E2SG
- 10AX048E2F29I1HG
- 10AX048E2F29I2LG

- 10AX048E2F29I2SG
- 10AX048E3F29E2LG
- 10AX048E3F29E2SG
- 10AX048E3F29I2LG
- 10AX048E3F29I2SG
- 10AX048E4F29E3LG
- 10AX048E4F29E3SG
- 10AX048E4F29I3LG
- . . . . . . . . . . . . . . . . . . .
- 10AX048E4F29I3SG
- 10AX048E4F29M3SG
- 10AX048H1F34E1HG
- 10AX048H1F34I1HG
- 10AX048H2F34E1HG
- 10AX048H2F34E2LG
- 10AX048H2F34E2SG
- 10AX048H2F34I1HG
- 10AX048H2F34I2LG
- 10AX048H2F34I2SG
- 10AX048H3F34E2LG
- 10AX048H3F34E2SG
- 10AX048H3F34I2LG
- 10AX048H3F34I2LGAA
- 10AX048H3F34I2SG
- 10AX048H4F34E3LG
- 10AX048H4F34E3SG
- 10AX048H4F34E3VG
- 10AX048H4F34I3LG
- 10AX048H4F34I3SG
- 10AX048H4F34I3VG
- 10AX048HF34GAC
- 10AX048K1F35E1HG
- 10AX048K1F35I1HG
- 10AX048K2F35E1HG
- 10AX048K2F35E2LG
- 10AX048K2F35E2SG
- 10AX048K2F35I1HG
- 10AX048K2F35I2LG
- 10AX048K2F35I2SG
- 10AX048K3F35E2LG
- 10AX048K3F35E2SG
- 10AX048K3F35I2LG
- 10AX048K3F35I2SG
- 10AX048K4F35E3LG
- 10AX048K4F35E3SG
- 10AX048K4F35I3LG
- 10AX048K4F35I3SG
- 10AX048K4F35M3SG
- 10AX057H1F34E1HG

- 10AX057H1F34I1HG
- 10AX057H2F34E1HG
- 10AX057H2F34E2LG
- 10AX057H2F34E2SG
- 10AX057H2F34I1HG
- 10AX057H2F34I2LG
- 10AX057H2F34I2SG
- 10AX057H3F34E2LG
- 10AX057H3F34E2SG
- 10AX057H3F34I2LG
- 10AX057H3F34I2SG
- 10AX057H4F34E3LG
- 10AX057H4F34E3SG
- 10AX057H4F34E3VG
- . . . . . . . . . . . . . . . . . .
- 10AX057H4F34I3LG
- 10AX057H4F34I3SG
- 10AX057H4F34I3VG
- 10AX057K1F35E1HG
- 10AX057K1F35I1HG
- 10AX057K1F40E1HG
- 10AX057K1F40I1HG
- 10AX057K2F35E1HG
- 10AX057K2F35E2LG
- 10AX057K2F35E2SG
- 10AX057K2F35I1HG
- 10AX057K2F35I2LG
- 10AX057K2F35I2SG
- 10AX057K2F40E1HG
- 10AX057K2F40E2LG
- 10AX057K2F40E2SG
- 10AX057K2F40I1HG
- 10AX057K2F40I2LG
- 10AX057K2F40I2SG
- 10AX057K3F35E2LG
- 10AX057K3F35E2SG
- 10AX057K3F35I2LG
- 10AX057K3F35I2SG
- 10AX057K3F40E2LG
- 10AX057K3F40E2SG
- 10AX057K3F40l2LG 10AX057K3F40l2SG
- 10AX057K4F35E3LG
- 10AX057K4F35E3SG
- 10AX057K4F35I3LG
- 10AX057K4F35I3SG
- 10AX057K4F35M3SG
- 10AX057K4F40E3LG
- 10AX057K4F40E3SG

- 10AX057K4F40E3SGJW
- 10AX057K4F40I3LG
- 10AX057K4F40I3SG
- 10AX057N1F40E1HG
- 10AX057N1F40I1HG
- 10AX057N2F40E1HG
- 10AX057N2F40E2LG
- 10AX03/11/21 40L2LC
- 10AX057N2F40E2SG
- 10AX057N2F40I1HG
- 10AX057N2F40I2LG
- 10AX057N2F40I2SG
- 10AX057N3F40E2LG
- 10AX057N3F40E2SG
- 10AX057N3F40I2LG
- 10AX057N3F40I2SG
- 10AX057N4F40E3LG
- 10AX057N4F40E3SG
- 10AX057N4F40E3VG
- 10AX057N4F40I3LG
- 10AX057N4F40I3SG
- 10AX057N4F40I3VG
- 10AX057N4F40M3SG
- 10AX066F40GAC
- 10AX066H1F34E1HG
- 10AX066H1F34I1HG
- 10AX066H2F34E1HG
- 10AX066H2F34E2LG
- 10AX066H2F34E2SG
- 10AX066H2F34I1HG
- 10AX066H2F34I2LG
- 10AX066H2F34I2SG
- 10AX066H3F34E2LG
- 10AX066H3F34E2SG
- 10AX0001131 34L230
- 10AX066H3F34I2LG 10AX066H3F34I2SG
- 10AX066H4F34E3LG
- 10,0,00001111 0 12020
- 10AX066H4F34E3SG
- 10AX066H4F34E3VG
- 10AX066H4F34I3LG
- 10AX066H4F34I3LGJW
- 10AX066H4F34I3SG
- 10AX066H4F34I3VG
- 10AX066K1F35E1HG
- 10AX066K1F35I1HG
- 10AX066K1F40E1HG
- 10AX066K1F40I1HG
- 10AX066K2F35E1HG
- 10AX066K2F35E2LG

- 10AX066K2F35E2SG
- 10AX066K2F35I1HG
- 10AX066K2F35I2LG
- 10AX066K2F35I2SG
- 10AX066K2F40E1HG
- 10AX066K2F40E1HP
- 10AX066K2F40E2LG
- 10AX066K2F40E2SG
- 10AX066K2F40I1HG
- 10AX066K2F40I2LG
- 10AX066K2F40I2SG
- 10AX066K3F35E2LG
- 10AX066K3F35E2SG
- 10AX066K3F35E2SGE2
- 10AX066K3F35I2LG
- 10AX066K3F35I2SG
- 10AX066K3F40E2LG
- 10AX066K3F40E2SG
- 10AX066K3F40I2LG
- 10AX066K3F40I2SG
- 10AX066K4F35E3LG
- 10AX066K4F35E3SG
- 10AX066K4F35I3LG
- 10AX066K4F35I3SG
- 10AX066K4F35M3SG
- 10AX066K4F40E3LG
- 10AX066K4F40E3SG
- 10AX066K4F40I3LG
- 10AX066K4F40I3SG
- 10AX066N1F40E1HG
- 10AX066N1F40I1HG
- 10AX066N2F40E1HG
- 10AX066N2F40E2LG
- 10AX066N2F40E2SG
- 10AX066N2F40I1HG
- 10AX066N2F40I2LG
- 10AX066N2F40I2SG
- 10AX066N3F40E2LG
- 10AX066N3F40E2SG
- 10AX066N3F40I2LG
- 10AX066N3F40I2LGAA
- 10AX066N3F40I2SG
- 10AX066N3F40I2SGAA
- 10AX066N4F40E3LG
- 10AX066N4F40E3SG
- 10AX066N4F40E3VG
- 10AX066N4F40I3LG
- 10AX066N4F40I3SG

- 10AX066N4F40I3VG
- 10AX066N4F40M3SG
- 10AX066N4F40M3SGAB
- 10AX090H1F34E1SG
- 10AX090H1F34I1SG
- 10AX090H2F34E1SG
- 10AX090H2F34E2LG
- 10AX090H2F34E2SG
- 10AX090H2F34I1SG
- 10AX090H2F34I2LG
- 10AX090H2F34I2SG
- 10AX090H3F34E2LG
- 10AX090H3F34E2SG
- 10AX090H3F34I2LG
- 10AX090H3F34I2SG
- 10AX090H4F34E3LG
- 10AX090H4F34E3SG
- 10AX090H4F34I3LG
- 10AX090H4F34I3SG
- 10AX090N1F40E1SG
- 10AX0301111 40L 13C
- 10AX090N1F40I1SG
- 10AX090N1F45E1SG
- 10AX090N1F45I1SG
- 10AX090N2F40E1SG
- 10AX090N2F40E2LG
- 10AX090N2F40E2SG
- 10AX090N2F40I1SG
- 10AX090N2F40I2LG
- 10AX090N2F40I2SG
- 10AX090N2F45E1SG
- 10AX090N2F45E2LG
- 10AX090N2F45E2SG
- 10AX090N2F45I1SG
- 10AX090N2F45I2LG
- 10AX090N2F45I2SG
- 10AX090N3F40E2LG
- 10AX090N3F40E2SG
- 10AX090N3F40I2LG
- 10AX090N3F40I2SG
- 10AX090N3F45E2LG
- 10AX090N3F45E2SG
- 10AX090N3F45I2LG
- 10AX090N3F45I2SG
- 10AX090N4F40E3LG
- 10AX090N4F40E3SG
- 10AX090N4F40I3LG
- 10AX090N4F40I3SG
- 10AX090N4F45E3LG

- 10AX090N4F45E3SG
- 10AX090N4F45I3LG
- 10AX090N4F45I3SG
- 10AX090R1F40E1SG
- 10AX090R1F40I1SG
- 10AX090R2F40E1SG
- 10AX090R2F40E2LG
- 10AX090R2F40E2SG
- 10AX090R2F40I1SG
- 10AX090R2F40I2LG
- 10AX090R2F40I2SG
- 10AX090R3F40E2LG
- 10AX090R3F40E2SG
- 10AX090R3F40I2LG
- 10AX090R3F40I2SG
- 10AX090R4F40E3LG
- 10AX090R4F40E3SG
- 10AX090R4F40I3LG
- 10AX090R4F40I3SG
- 10AX090S1F45E1SG
- 10AX090S1F45I1SG
- 10AX090S2F45E1SG
- 10/1/10000021 102100
- 10AX090S2F45E2LG
- 10AX090S2F45E2SG
- 10AX090S2F45I1SG
- 10AX090S2F45I2LG
- 10AX090S2F45I2SG
- 10AX090S3F45E2LG
- 10AX090S3F45E2SG
- 10AX090S3F45I2LG
- 10AX090S3F45I2SG
- 10AX090S4F45E3LG
- 10AX090S4F45E3SG
- 10AX090S4F45E3VG
- 10AX090S4F45I3LG
- 10AX090S4F45I3SG
- 10AX090S4F45I3VG
- 10AX090U1F45E1SG
- 10AX090U1F45I1SG
- 10AX090U2F45E1SG
- 10AX090U2F45E2LG
- 10AX090U2F45E2SG
- 10AX090U2F45I1SG
- 10AX090U2F45I2LG
- 10AX090U2F45I2SG
- 10AX090U3F45E2LG
- 10AX090U3F45E2SG
- 10AX090U3F45I2LG

- 10AX090U3F45I2SG
- 10AX090U4F45E3LG
- 10AX090U4F45E3SG
- 10AX090U4F45E3VG
- 10AX090U4F45I3LG
- 10AX090U4F45I3SG
- 10AX090U4F45I3VG
- 10AX115H1F34E1SG
- 10AX115H1F34I1SG
- 10AX115H2F34E1SG
- 10AX115H2F34E2LG
- 10AX115H2F34E2SG
- 10AX115H2F34I1SG
- . . . . . . . . . . . . . . . . . .
- 10AX115H2F34I2LG
- 10AX115H2F34I2SG
- 10AX115H3F34E2LG
- 10AX115H3F34E2SG
- 10AX115H3F34I2LG
- 10AX115H3F34I2SG
- 10AX115H4F34E3LG
- 10AX115H4F34E3SG
- 10AX115H4F34I3LG
- 10AX115H4F34I3SG
- 10AX115N1F40E1SG
- 10AX115N1F40I1SG
- 10AX115N1F45E1SG
- 10AX115N1F45I1SG
- 10AX115N1F45I1SGAD
- 10AX115N2F40E1SG
- 10AX115N2F40E2LG
- 10AX115N2F40E2LGJZ
- 10AX115N2F40E2SG
- 10AX115N2F40I1SG
- 10AX115N2F40I1SGAA
- 10AX115N2F40I2LG
- 10AX115N2F40I2SG
- 10AX115N2F45E1SG
- 10AX115N2F45E2LG
- 10AX115N2F45E2SG
- 10AX115N2F45I1SG
- 10AX115N2F45I1SGJW
- 10AX115N2F45I2LG
- 10AX115N2F45I2SG
- 10AX115N2F46E2SGAA
- 10AX115N3F40E2LG
- 10AX115N3F40E2SG
- 10AX115N3F40E2SGJW
- 10AX115N3F40I2LG

- 10AX115N3F40I2SG
- 10AX115N3F45E2LG
- 10AX115N3F45E2SG
- 10AX115N3F45I2LG
- 10AX115N3F45I2SG
- 10AX115N3F45I2SGJZ
- 10AX115N4F40E3LG
- 10AX115N4F40E3SG
- 10AX115N4F40E3VGAB
- 10AX115N4F40I3LG
- 10AX115N4F40I3LP
- 10AX115N4F40I3SG
- 10AX115N4F40M3SPAA
- 10AX115N4F45E3LG
- 10AX115N4F45E3SG
- 10AX115N4F45I3LG
- 10AX115N4F45I3SG
- 10AX115R1F40E1SG
- 10AX115R1F40I1SG
- 10AX115R2F40E1SG
- 10AX115R2F40E2LG
- 10AX115R2F40E2SG
- 10AX115R2F40I1SG
- 10AX115R2F40I2LG
- 10AX115R2F40I2SG
- 10AX115R3F40E2LG
- 10AX115R3F40E2SG
- 10AX115R3F40I2LG
- 10AX115R3F40I2LGAA
- 10AX115R3F40I2SG
- 10AX115R4F40E3LG
- 10AX115R4F40E3SG
- 10AX115R4F40I3LG
- 10AX115R4F40I3SG
- 10AX115S1F45E1SG
- 10AX115S1F45I1SG
- 10AX115S2F45E1SG
- 10AX115S2F45E2LG
- 10AX115S2F45E2LGAA
- 10AX115S2F45E2SG
- 10AX115S2F45I1SG
- 10AX115S2F45I2LG
- 10AX115S2F45I2SG
- 10AX115S3F45E2LG
- 10AX115S3F45E2SG
- 10AX115S3F45I2LG
- 10AX115S3F45I2SG
- 10AX115S4F45E3LG

- 10AX115S4F45E3SG
- 10AX115S4F45E3SP
- 10AX115S4F45E3VG
- 10AX115S4F45I3LG
- 10AX115S4F45I3SG
- 10AX115S4F45I3VG
- 10AX115U1F45E1SG
- 10AX115U1F45I1SG
- 10AX115U2F45E1SG
- 10AX115U2F45E2LG
- 10AX115U2F45E2SG
- 10AX115U2F45I1SG
- 10/0/110021 101100
- 10AX115U2F45I2LG
- 10AX115U2F45I2SG
- 10AX115U3F45E2LG
- 10AX115U3F45E2SG
- 10AX115U3F45E2SGE3
- 10AX115U3F45I2LG
- 10AX115U3F45I2SG
- 10AX115U4F45E3LG
- 10AX115U4F45E3SG
- 10AX115U4F45E3VG
- 10AX115U4F45I3LG
- 10AX115U4F45I3SG
- 10AX115U4F45I3VG
- 10AX115WWG
- 10AX115XXAA
- 10AXF29GAA
- 10AXF40GAA
- 10AXF40GAE
- 10AXF40GGA
- 10AXF45GAA
- 10AXN2F40E2LGAB
- 10AXN3F40E2SGAA
- 10AXS3F45E2SGBB