

Report No.	DOUS-TBT-006	Project No.	
Date		Project Name	
Vessel / Spread		Offshore Manager	

Copies of the completed Toolbox Talks shall be sent to HSEQS Department upon request.

The Toolbox Talk is a discussion meeting, hence it shall be delivered verbally by a TBT Leader.

Part 1 Project Operational Overview (Tick and discuss the area of operations as applicable)

1	Mobilisation / demobilisation	☐	9	Plough Operations / Launch & Recovery	☐
2	Vessel Transit Operations	☐	10	Trencher Operations / Launch & Recovery	☐
3	Platform 500m Zone Entry	☐	11	ROV Operations / Launch & Recovery	☐
4	Lifts – Deck	☐	12	Simultaneous Operations	☐
5	Lifts – Subsea	☐	13	Abandonment of Asset(s)	☐
6	Deck Operations	☒	14	Recovery of Asset(s)	☐
7	Cable Working Equipment	☐	15	Equipment Maintenance	☒
8	Equipment / Procedure Trials	☐	16	Other:	☐

Part 2 Specific Task (Identify what the task is that is to be performed)

Working at Heights.

Part 3 HSE Considerations & Requirements (Tick and discuss as applicable)

1	PPE	☒	14	Environmental Requirements	☒
2	Working at Height	☒	15	Over side Working	☐
3	Risk Assessment / JSA / Take 2	☒	16	Life Saving & Fire Fighting Equipment	☒
4	Lifting Operations & Lift Plans	☐	17	Boat Transfers	☐
5	Manual Handling	☐	18	First Aid – Medical Support	☐
6	Slips, Trips & Falls	☒	19	Housekeeping	☒
7	Permit to Work	☒	20	Noise / Vibration	☐
8	Electrical Work & Precautions	☐	21	Confined Spaces	☐
9	Hot Work	☐	22	COSHH	☐
10	Safety & Warning Signs	☐	23	Stored Pressure Systems	☐
11	Rescue Equipment/Plan	☒	24	HV Electrical Work	☐
12	Communication Protocols	☒	25	Spill Prevention / Containment	☐
13	Dropped Objects	☒	26	Other:	☐

Part 4 Supporting Documents – List applicable documents discussed and reviewed during TBT

(Method Statements, Task Plans, Lift Plans, COSHH RA, Drawing, MOC's, RA's / SJA's, Storyboards, etc.)

DOUS-TRA-006 WORKING AT HEIGHTS
DO-HSE-FRM-069 Work at Height Checklist
DO-HSE-FRM-057 Rescue Plan

Part 5 Emergency Arrangements

Discuss / list specific Rescue Plans, Contingency Plans as applicable

All personnel to review the DO Working at Heights Rescue Plan (DO-HSE-FRM-057) before work starts.
Proper inspection of all fall arrest equipment, to include inspection of rescue gear.

Name and contact of the assigned Medic / First Aider

Part 6 Life Saving Rules (Identify and tick applicable rules)

 Bypassing Safety Controls ☐	 Confined Space ☐	 Driving ☐	 Energy Isolation ☐	 Hot Work ☐	 Line of Fire ☐	 Safe Mechanical Lifting ☐	 Work Authorisation ☐	 Working at Height ☒
---	---	--	---	---	---	---	--	--

Part 7 Confirm and discuss the subsequent control measures implemented relevant to the Life Saving Rule

Locate tie-off points above the work area so that if a fall does happen, personnel do not impact the deck.
 No working at heights without a secondary tech on hand and observing the individual.
 Inspect harness and lanyard for proper fit, function and wear. If wear is found take out of service, red tag and notify Supervisor.
 Inspect ladder prior to use and secure it to a secure location. Secure to highest point while ascending.
 Use 3 points of contact with the lanyard system; all tie-off points must be stable and the lanyard above personnel's head.
 Inspect all tooling prior to use and tie off tools if required. Only bring the tools required - use the 2nd tech to retrieve / hand off tools.
 Communications with bridge (rapid vessel movement can cause unstable footing and equipment movement).

Part 8 TBT Discussion Topics / Notes (to include reinforcement of ACT for Safety and Stop Work Authority)

Working at Heights.
 Potential hazards to include but not limited to falling and dropped objects. Personnel injury due to improper harness use, lack of use or lack of attention from monitor.
 Proper PPE. Proper inspection of all fall arrest equipment to include inspection of rescue gear. Having an efficient rescue plan in place.
 Safety Principle: 'STOP THE JOB' if safety is compromised or you see something going wrong.

Part 9 Identify any actions from TBT and assign Responsible Person and timescale

Secure ladder after use.
 Put away all tools and equipment in proper area and dispose of all waste material in segregated bins.
 Clear area and walkway of all trips, slips and falls.
 Close out work permit upon completion if one was required by vessel.

Part 10 TBT Attendees					
Print Name	Sign	Print Name	Sign	Print Name	Sign
TBT Leader Name		TBT Leader Signature		Position	Date
					0000-2400

Part 11 Confirmation from TBT Leader		
Have all relevant persons involved in / affected by the task attended the TBT?	☒ Yes	☐ No
Have specific roles and responsibilities required for the task been adequately communicated and understood?	☒ Yes	☐ No
Are all control measures understood by those involved and suitably implemented?	☒ Yes	☐ No