

[illegible]

No.	Task /Activity	Hazard and Consequence		Initial Risk			Mitigating Controls	Residual Risk		
	Sequential Steps	Hazard	Consequence	Probability	Consequence Severity	Risk Rating	Measures to Reduce Risk to ALARP	Probability	Consequence Severity	Risk Rating
1	Review TRA and TBT	Miscommunication	Personnel Injury / Environmental Pollution	1	2	2	Situational awareness and proper use of PPE. Hard hats, impact gloves, cotton gloves, latex gloves, steel toed boots, safety glasses, side shields and face shield	1	1	1
2	Prior to any task being undertaken ensure that all personnel are aware of the hazards involved.	Electrical shock, possible slips trips and falls. Pinch points poor body position. Hydraulic discharge and spills.	Personnel Injury / Environmental Pollution	2	3	6	All personnel must be aware of their surrounds and weather conditions. Use proper Manual Handling techniques, i.e., Always use proper body positioning, lift with legs, and obtain second personnel when loads are over 40lbs. Read all SDS on chemicals used, use PPE that is specified in SDS and be aware of where all spill kits are located.	2	2	4
3	Grinding on deck with angle grinder, Paint chipping with needle gun.	People, equipment, and fire hazards	Personnel Injury / Equipment Damage / Environmental Pollution	2	3	6	Danger tape off area work is being performed to keep non-essential personnel out of the area. Inspect all equipment before use to ensure tool integrity. Remove any combustible items from work area to be performed in to help prevent fires as well as a fire watch wear appropriate PPE.	2	2	4
4	Preparation for grinding or needle gunning in planned area.	Fire Hazards due to sparks.	Personnel Injury / Equipment Damage / Environmental Pollution	2	3	6	Check with bridge if PTW is needed to perform task.	2	2	4
5	Select proper tool for the job at hand.	Damage to equipment, electrical shock.	Personnel Injury / Equipment Damage / Environmental Pollution	2	3	6	If tool is corded check cord is in good condition with no wear or damaged areas and that all guards or safety devices are in place. Check extension cords are in good condition with no wear or damaged areas. If any are discovered, take out of service and red tag.	2	2	4

Task Risk Assessment Form

DEEPOCEAN

6	Proper PPE for the task at hand	Eye, Hand, Ear, or other injury for lack of proper PPE.	Personnel Injury / Equipment Damage / Environmental Pollution	2	3	6	Double PPE will be worn for Eye Protection (Face Shield and Safety Glasses) Hearing Protection must be always worn. Impact Gloves must be worn for task at hand. If in confined space a dust mask or respirator will be worn.	2	2	4
7	Needle Gun Operations	Hand, eye, and ear injuries due to lack of PPE or proper equipment use. Back injury due to poor body positioning.	Personnel Injury / Equipment Damage / Environmental Pollution	2	3	6	NEVER TIE TRIGGER TO ON POSITION. Take regular breaks during task to prevent long term vibration injuries to hands and dehydration.	2	2	4
8	Air Hose	Burst air hose, hand, and eye and equipment damage.	Personnel Injury / Equipment Damage / Environmental Pollution	2	3	6	Check air hose is in good condition with no wear or damaged area. Check connector of damage or wear. If any are discovered, take out of service and red tag.	2	2	4
9	Grinding Operations	Fire hazard, hand, eye, ear, and back injury due to lack of proper PPE and poor body positioning.	Personnel Injury / Equipment Damage / Environmental Pollution	2	3	6	Barricade work area off and non-personnel are not allowed in the area. Ensure grinding area is clear of flammable materials, check areas occasionally for hot spots.	2	2	4
10	<i>Fire watch during grinding operations if one is needed according to bridge or procedures.</i>	<i>Fire Hazards, damage to equipment</i>	Personnel Injury / Equipment Damage / Environmental Pollution	2	3	6	<i>Only trained personnel are to be on fire watch. If one is not available, then Supervisor will be on fire watch during task.</i>	2	2	4
11	Grinding, Needle Gun Operations	Blowing debris and dust. Eye injuries due to blowing debris.	Personnel Injury / Equipment Damage / Environmental Pollution	2	3	6	Take regular breaks and clean area of debris and dust. Place all debris in proper bin for disposal.	2	2	4
12	Completion of operations.	Debris on deck, slips, trips and falls.	Personnel Injury / Equipment Damage / Environmental Pollution	2	3	6	The area of task must be cleaned thoroughly of all debris and tools. Be aware of hot metal parts left on deck. Fire watch will remain on work site for 20min after task has been completed.	2	2	4

TRA Approval	Name	Position	Signature	Date
By signing, the Approver confirms that the TRA has been reviewed and considers the task acceptable to proceed with residual risk meeting the acceptance criteria of DO Risk Matrix.				

*Reference DO-HSE-FRM-140 for DeepOcean Risk Assessment Matrix (RAM) and Guidewords

Doc ID : DO-HSE-FRM-138
 Doc Name : Task Risk Assessment Form
 Parent Doc ID : DO-HSE-PRO-074 Risk Assessment Procedure

Rev : A
 Date : 29/07/2021
 Page : 3 of 3