

Project (If Applicable)			TRA Ref. No.	DOUS-TRA-022	
Location / Worksite					
Sub Location / Area					
Equipment Spread (Optional)					
Task / Activity					
Approver					
Responsible Person					
Date TRA Created					
Reference Supporting Documents & Task Plan					
S3RA:			Hot Work Checklist:		
Task Plan:			Work at Height Checklist:		
Lift Plan:			Confined Space Work Checklist:		
PTW:			Electrical Equipment Checklist:		
COSHH / SDS:			Electrical Isolation Checklist:		
Rescue Plan:			Machinery Isolation Checklist:		
Work Equipment Assessment:			Pressure Systems Checklist:		
Other:			Other: DOUS-TRA-017		
Reason for TRA (Tick where Applicable)					
Identification of New Task		Annual Review	Review following Incident	Management of Change Record	Other, Please Specify
☐		☐	☐	☐	☐
Other (Details):					
TRA Participants					
Name		Position		Signature	
NOTE: STANDARD PPE OF SAFETY FOOTWEAR, SAFETY HELMET, COVERALLS, GLASSES AND GLOVES MUST BE WORN. ANY ADDITIONAL PPE REQUIRED SHALL BE CAPTURED IN THE MITIGATING CONTROLS SECTION OF THE TRA TEMPLATE BELOW.					

No.	Task /Activity	Hazard and Consequence		Initial Risk			Mitigating Controls	Residual Risk		
	Sequential Steps	Hazard	Consequence	Probability	Consequence Severity	Risk Rating	Measures to Reduce Risk to ALARP	Probability	Consequence Severity	Risk Rating
1	Review TRA and TBT	Miscommunication	Personnel Injury / Environmental Pollution	1	2	2	Situational awareness and proper use of PPE. Hard hats, impact gloves, cotton gloves, latex gloves, steel toed boots, safety glasses, side shields and face shield	1	1	1
2	Prior to any task being undertaken ensure that all personnel are aware of the hazards involved.	Electrical shock, possible slips trips and falls. Pinch points poor body position. Hydraulic discharge and spills.	Personnel Injury / Environmental Pollution	2	3	6	All personnel must be aware of their surrounds and weather conditions. Use proper Manual Handling techniques, i.e., Always use proper body positioning, lift with legs, and obtain second personnel when loads are over 40lbs. Read all SDS on chemicals used, use PPE that is specified in SDS and be aware of where all spill kits are located.	2	2	4
3	<i>If task requires working with power tools a TRA is required and or permit to work from vessel.</i>	Personnel injury, pinch points, improper use of tool, damage to equipment, malfunctioning equipment.	Personnel Injury / Equipment Damage / Environmental Pollution	1	2	2	Review <i>TRA Power Tool Use</i> . Obtain permit to work if required by vessel.	1	1	1
4	Use of hand tools.	Pinch points, cuts, stabs, trips and slip hazards.	Personnel Injury / Equipment Damage / Environmental Pollution	2	2	4	Use proper PPE for the task. Use the proper tool for the task at hand. Keep tools clean and secured when not in use. NEVER leave tools laying around in walkways, staircases or on top of ladders.	1	1	1
5	Integration and Mounting of Survey equipment	Electrical shock, damage to equipment, pinch points, and poor body positioning. Hydraulic discharge and spills.	Personnel Injury / Equipment Damage / Environmental Pollution	2	3	6	Personnel shall work with survey during integration of survey equipment. Nothing is to be put on ROV without surveys instructions. Use correct lifting procedures and correct body positioning. Personnel are be sure that Hydraulics have been turned off before opening any hydraulic ports. Oil absorbent pads and rags are to be used to clean spilled oil.	2	2	4

6	Test and function survey equipment	Hydraulic discharge, leaks from hydraulic circuit and spills. Damage to equipment and injuries to personnel.	Personnel Injury / Equipment Damage / Environmental Pollution	2	3	6	Personnel are to be in constant communication with Pilot as hydraulic circuit is powered on. All personnel are to be in safe zone as test is being performed. Have oil absorbent pads, rags, and spill kit on hand for any accidental discharge.	2	2	4
7	Bleed air from hydraulic circuit and compensate system.	Hydraulic discharge, damage to equipment and injuries to personnel.	Personnel Injury / Equipment Damage / Environmental Pollution	2	3	6	Personnel will check for air in the hydraulic circuit and clean up all oil discharge. Personnel will be in contact with pilot as system is compensated to proper level.	2	2	4
8	All tools used are to be cleaned and stowed away in proper location.	Damage to equipment, slips, trips, and falls. Dropped objects	Personnel Injury / Equipment Damage / Environmental Pollution	1	2	2	Stow all equipment in their proper location or cases and tools in their proper location. Clean area of all slips, trips, and falls. Put all used oil, oil absorbent pads and rags away in proper containers.	1	1	1
TRA Approval		Name	Position		Signature		Date			
By signing, the Approver confirms that the TRA has been reviewed and considers the task acceptable to proceed with residual risk meeting the acceptance criteria of DO Risk Matrix.										

*Reference DO-HSE-FRM-140 for DeepOcean Risk Assessment Matrix (RAM) and Guidewords