

Project (If Applicable)		TRA Ref. No.	DOUS-TRA-024	
Location / Worksite				
Sub Location / Area				
Equipment Spread (Optional)				
Task / Activity				
Approver				
Responsible Person				
Date TRA Created				
Reference Supporting Documents & Task Plan				
S3RA:	Hot Work Checklist:			
Task Plan:	Work at Height Checklist:			
Lift Plan:	Confined Space Work Checklist:			
PTW:	Electrical Equipment Checklist:			
COSHH / SDS:	Electrical Isolation Checklist:			
Rescue Plan:	Machinery Isolation Checklist:			
Work Equipment Assessment:	Pressure Systems Checklist:			
Other:	Other:			
Reason for TRA (Tick where Applicable)				
Identification of New Task	Annual Review	Review following Incident	Management of Change Record	Other, Please Specify
☐	☐	☐	☐	☐
Other (Details):				
TRA Participants				
Name	Position	Signature		
NOTE: STANDARD PPE OF SAFETY FOOTWEAR, SAFETY HELMET, COVERALLS, GLASSES AND GLOVES MUST BE WORN. ANY ADDITIONAL PPE REQUIRED SHALL BE CAPTURED IN THE MITIGATING CONTROLS SECTION OF THE TRA TEMPLATE BELOW.				

No.	Task /Activity	Hazard and Consequence		Initial Risk			Mitigating Controls	Residual Risk		
	Sequential Steps	Hazard	Consequence	Probability	Consequence Severity	Risk Rating	Measures to Reduce Risk to ALARP	Probability	Consequence Severity	Risk Rating
1	Review TRA and TBT	Miscommunication	Personnel Injury / Environmental Pollution	1	2	2	Situational awareness and proper use of PPE. Hard hats, impact gloves, cotton gloves, latex gloves, steel toed boots, safety glasses, side shields and face shield	1	1	1
2	Prior to any task being undertaken ensure that all personnel are aware of the hazards involved.	Electrical shock, possible slips trips and falls. Pinch points poor body position. Hydraulic discharge and spills.	Personnel Injury / Environmental Pollution	2	3	6	All personnel must be aware of their surrounds and weather conditions. Use proper Manual Handling techniques, i.e., Always use proper body positioning, lift with legs, and obtain second personnel when loads are over 40lbs. Read all SDS on chemicals used, use PPE that is specified in SDS and be aware of where all spill kits are located.	2	2	4
3	<i>If task requires working with power tools a TRA is required and or permit to work from vessel.</i>	Personnel injury, pinch points, improper use of tool, damage to equipment, malfunctioning equipment.	Personnel Injury / Environmental Pollution / Equipment Damage	1	2	2	Review TRA Power Tool Use . Obtain permit to work if required by vessel.	1	1	1
4	Use of hand tools.	Pinch points, cuts, stabs, trips, slips and fall hazards.	Personnel Injury / Environmental Pollution / Equipment Damage	2	2	4	Use proper PPE for the task. Use the proper tool for the task at hand. Keep tools clean and secured when not in use. NEVER leave tools laying around in walkways, staircases or on top of ladders.	1	1	1
5	<i>If task requires Pumping out LARS a TRA is required.</i>	Environmental spills	Personnel Injury / Environmental Pollution / Equipment Damage	1	2	2	Review TRA Pumping Out LARS .	1	1	1
PERFORM STEPS 6 THRU 13 IF ROV NEEDS TO BE OVERBOARDED TO PERFORM TASK										
6	Pilot, Winch Operator, Recovery/Launch Observer all on comms	No communication between personnel causing injury to personnel and damage to equipment	Personnel Injury / Environmental Pollution / Equipment Damage	2	3	6	All personnel involved must remain in constant communication	2	2	4

Task Risk Assessment Form

DEEPOCEAN

	Check weather condition prior ROV leaving the deck and get green light from the Bridge personnel	Damage to equipment from weather patterns or vessel movement	Personnel Injury / Environmental Pollution / Equipment Damage	2	3	6	Communication with bridge personnel prior to lifting system from deck.	2	2	4
	Energize Winch HPU.	Damage to equipment.	Personnel Injury / Environmental Pollution / Equipment Damage	2	3	6	Winch operator obtains visual of lights and listens to HPU upon energizing system, before leaving HPU.	2	2	4
	Ensure <i>cooling water pump is on. If one is equipped.</i>	Damage to HPU from overheating	Personnel Injury / Environmental Pollution / Equipment Damage	2	3	6	Launch/Observer confirms cooling water is on and flowing with visual of water going overboard.	2	2	4
	Recovery/Launch Observer will remove grounding strap and cargo strap from ROV.	Possible electrical shock when grounding strap has been removed. Straps under tension	Personnel Injury / Environmental Pollution / Equipment Damage	2	3	6	Do not touch the ROV after grounding strap has been removed. Place cargo straps in secure area out of walkways.	2	2	4
	Winch operator will bring the LARS to hard stops and always keep slack in umbilical.	Damage to equipment due to failure to follow LAR procedures.	Personnel Injury / Environmental Pollution / Equipment Damage	2	3	6	Winch operator will ensure that slack there is slack in umbilical while on the hard stops.	2	2	4
	De energize Winch HPU	Damage to equipment, electrical shock	Personnel Injury / Environmental Pollution / Equipment Damage	2	3	6	Winch operator will either de energize system via control station or at the winch HPU.	2	2	4
	Ensure that <i>cooling water has been shut off. If one is equipped.</i>	Waste of water and possible flooding of LARS pit. Burst hose, slips and falls.	Personnel Injury / Environmental Pollution / Equipment Damage	2	3	6	Ensure that cooling water has been turned off at main source.	2	2	4
PERFORM STEPS 14 THRU 16 TO PERFORM TASK										
	Remove grating on LARS	Slips, trips, falls, strains, pinch points, and improper body positioning	Personnel Injury / Environmental Pollution / Equipment Damage	2	2	4	Ensure proper hand and foot placement. Two man always lifting due to weight of grating. Utilize proper lifting techniques.	1	1	1

Doc ID : DO-HSE-FRM-138
 Doc Name : Task Risk Assessment Form
 Parent Doc ID : DO-HSE-PRO-074 Risk Assessment Procedure

Rev : A
 Date : 29/07/2021
 Page : 3 of 5

Task Risk Assessment Form

DEEPOCEAN

	Clean out debris	Slips, trips, falls, pinch points and improper body positioning.	Personnel Injury / Environmental Pollution / Equipment Damage	2	2	4	Ensure proper hand and foot placement. Dispose of all debris in proper containers for disposal.	1	1	1
	Replace grating on LARS	Slips, trips, falls, pinch points and improper body positioning.	Personnel Injury / Environmental Pollution / Equipment Damage	2	2	4	Ensure proper hand and foot placement. Two man always lifting due to weight of grating. Utilize proper lifting techniques.	1	1	1
PERFORM STEPS 17 THRU 23 IF ROV HAS BEEN OVERBOARDED FOR TASK										
	Pilot, Winch Operator, Recovery/Launch Observer all on comms	No communication between personnel causing injury to personnel and damage to equipment	Personnel Injury / Environmental Pollution / Equipment Damage	2	3	6	All personnel involved must remain in constant communication	2	2	4
	Energize Winch HPU.	Damage to equipment.	Personnel Injury / Environmental Pollution / Equipment Damage	2	3	6	Winch operator obtains visual of lights and listens to HPU upon energizing system, before leaving HPU.	2	2	4
	Ensure <i>cooling water pump is on. If one is equipped.</i>	Damage to HPU from overheating	Personnel Injury / Environmental Pollution / Equipment Damage	2	3	6	Launch/Observer confirms cooling water is on and flowing with visual of water going overboard.	2	2	4
	Land ROV on to stands/deck	Damage to equipment due to crushing ROV on stands or deck.	Personnel Injury / Environmental Pollution / Equipment Damage	2	3	6	Constant communication with observer and winch operator.	2	2	4
	Place ground strap on ROV and strap ROV to deck with approved cargo straps	Electrical shock, damage to equipment, straps under tension	Personnel Injury / Environmental Pollution / Equipment Damage	2	3	6	Personnel are to strap down ROV with approved cargo straps and check all straps for worn or frays. If straps are found to be defective remove from service.	2	2	4
	De energize Winch HPU	Damage to equipment, electrical shock	Personnel Injury / Environmental Pollution / Equipment Damage	2	3	6	Winch operator will either de energize system via control station or at the winch HPU.	2	2	4

Doc ID : DO-HSE-FRM-138
 Doc Name : Task Risk Assessment Form
 Parent Doc ID : DO-HSE-PRO-074 Risk Assessment Procedure

Rev : A
 Date : 29/07/2021
 Page : 4 of 5

Task Risk Assessment Form

DEEPOCEAN

TRA Approval	Name	Position	Signature	Date
By signing, the Approver confirms that the TRA has been reviewed and considers the task acceptable to proceed with residual risk meeting the acceptance criteria of DO Risk Matrix.				

**Reference DO-HSE-FRM-140 for DeepOcean Risk Assessment Matrix (RAM) and Guidewords*

Doc ID : DO-HSE-FRM-138
Doc Name : Task Risk Assessment Form
Parent Doc ID : DO-HSE-PRO-074 Risk Assessment Procedure

Rev : A
Date : 29/07/2021
Page : 5 of 5