

Project (If Applicable)		TRA Ref. No.	DOUS-TRA-034	
Location / Worksite				
Sub Location / Area				
Equipment Spread (Optional)				
Task / Activity	SHALLOW WATER OPERATIONS			
Approver				
Responsible Person				
Date TRA Created				
Reference Supporting Documents & Task Plan				
S3RA:	Hot Work Checklist:			
Task Plan:	Work at Height Checklist:			
Lift Plan:	Confined Space Work Checklist:			
PTW:	Electrical Equipment Checklist:			
COSHH / SDS:	Electrical Isolation Checklist:			
Rescue Plan:	Machinery Isolation Checklist:			
Work Equipment Assessment:	Pressure Systems Checklist:			
Other: DOUS-TRA-001 / DOUS-TRA-002	Other: VESSEL RUMS			
Reason for TRA (Tick where Applicable)				
Identification of New Task	Annual Review	Review following Incident	Management of Change Record	Other, Please Specify
☐	☐	☐	☐	☒
Other (Details): Shallow Water Operations to be performed.				
TRA Participants				
Name	Position	Signature		
NOTE: STANDARD PPE OF SAFETY FOOTWEAR, SAFETY HELMET, COVERALLS, GLASSES AND GLOVES MUST BE WORN. ANY ADDITIONAL PPE REQUIRED SHALL BE CAPTURED IN THE MITIGATING CONTROLS SECTION OF THE TRA TEMPLATE BELOW.				

No.	Task /Activity	Hazard and Consequence		Initial Risk			Mitigating Controls	Residual Risk		
	Sequential Steps	Hazard	Consequence	Probability	Consequence Severity	Risk Rating	Measures to Reduce Risk to ALARP	Probability	Consequence Severity	Risk Rating
1	Review TRA, TBT and Vessel Specific RUMS.	Miscommunication	Personnel Injury / Environmental Pollution	1	2	2	Situational awareness and proper use of PPE. Hard hats, impact gloves, cotton gloves, latex gloves, steel toed boots, safety glasses, side shields and face shield	1	1	1
2	Prior to any task being undertaken ensure that all personnel are aware of the hazards involved.	Electrical shock, possible slips trips and falls. Pinch points poor body position. Hydraulic discharge and spills.	Personnel Injury / Environmental Pollution	2	3	6	All personnel must be aware of their surrounds and weather conditions. Use proper Manual Handling techniques, i.e., Always use proper body positioning, lift with legs, and obtain second personnel when loads are over 40lbs. Read all SDS on chemicals used, use PPE that is specified in SDS and be aware of where all spill kits are located.	2	2	4
3	Predive Checks <i>DOUS-TRA-001</i>	Personal Injury, Electrical Shock, Projecting Material, or fluid.	Personnel Injury / Damage to Equipment / Environmental Pollution	2	2	4	Proper PPE, Good Coms, Grounding Strap, Barricades, and Only authorized personnel allowed in area.	1	2	2
4	Launch of ROV <i>DOUS-TRA-002</i>	No Coms, Injury to personnel and equipment,	Personnel Injury / Damage to Equipment / Environmental Pollution	2	2	4	Good Coms with deck Personnel and bridge. No Unauthorized personnel on deck during launch.	1	2	2
5	ROV Operations Close to Surface	Damage to asset and equipment due to loss of Coms to ROV or change in weather or sea state. Dead ROV or TMS, Winch Failure and Vessel loss of DP.	Personnel Injury / Damage to Equipment / Environmental Pollution	2	3	6	Pilot obtains good tether management, ROV should always maintain Negative ballast while shallow or under structure. Utilize DOUS Dead ROV recovery Plan. Obtain Good Communications with Bridge, ROV and Rig/SPAR.	2	2	4
6	Perform Task per Work Scope	Damage to assets and equipment. Dropped Objects. Dead ROV or TMS, Winch Failure and Vessel loss of DP.	Personnel Injury / Damage to Equipment / Environmental Pollution	2	3	6	Pilot obtains good tether management, ROV should always maintain Negative ballast while shallow or under structure. Utilize DOUS Dead ROV recovery Plan. Obtain Good Communications with Bridge, ROV and Rig/SPAR.	2	2	4

7	Recovery of ROV – <i>DOUS-TRA-002</i>	No Coms, Injury to personnel and equipment,	Personnel Injury / Damage to Equipment / Environmental Pollution	2	2	4	Good Coms with deck Personnel and bridge. No Unauthorized personnel on deck during recovery.	2	2	4
TRA Approval		Name	Position	Signature		Date				
By signing, the Approver confirms that the TRA has been reviewed and considers the task acceptable to proceed with residual risk meeting the acceptance criteria of DO Risk Matrix.										

*Reference DO-HSE-FRM-140 for DeepOcean Risk Assessment Matrix (RAM) and Guidewords