

[illegible]

Description of Activity	Hazards <u>People, Environment, Equipment, and Reputation</u>	Initial Risk = L. M. H.	CONTROL MEASURES	RESIDUAL RISK = L. M. H.
Assisting divers with crossover line	- Injury to personnel - Damage to equipment - Damage to asset	H	- Competent personnel - Sea state limitations - Good communication between diver, dive shack, and ROV	M
Working around or near divers	- Injury to personnel - Damage to equipment - Entanglement of ROV tether and dive lines - Entanglement of ROV tether and dive equipment	M	- Competent personnel - Good communication between diver, dive shack, and ROV - ROV / TMS to stay at least 30' below dive equipment - ROV to stay in TMS if not needed	L
Launch and Recovery of dive equipment	- Damage to equipment - Entanglement of ROV and dive equipment	M	ROV to maintain visual of dive equipment being deployed and recovered	L
Tooling operation for divers	- Injury to personnel - Damage to equipment - Loss of oil to sea	M	- Competent personnel - Good communication between diver, dive shack, and ROV - ROV to keep 4m distance from diver while operating tooling	L

TRA Approval	Name	Position	Signature	Date
By signing, the Approver confirms that the TRA has been reviewed and considers the task acceptable to proceed with residual risk meeting the acceptance criteria of DO Risk Matrix.				

*Reference DO-HSE-FRM-140 for DeepOcean Risk Assessment Matrix (RAM) and Guidewords