

Project (If Applicable)		TRA Ref. No.	DOUS-TRA-006	
Location / Worksite				
Sub Location / Area				
Equipment Spread (Optional)				
Task / Activity	WORKING AT HEIGHTS			
Approver				
Responsible Person				
Date TRA Created				
Reference Supporting Documents & Task Plan				
S3RA:	Hot Work Checklist:			
Task Plan:	Work at Height Checklist: DO-HSE-FRM-069			
Lift Plan:	Confined Space Work Checklist:			
PTW:	Electrical Equipment Checklist:			
COSHH / SDS:	Electrical Isolation Checklist:			
Rescue Plan: DO-HSE-FRM-057	Machinery Isolation Checklist:			
Work Equipment Assessment:	Pressure Systems Checklist:			
Other:	Other:			
Reason for TRA (Tick where Applicable)				
Identification of New Task	Annual Review	Review following Incident	Management of Change Record	Other, Please Specify
☐	☐	☐	☐	☒
Other (Details):				
TRA Participants				
Name	Position		Signature	
NOTE: STANDARD PPE OF SAFETY FOOTWEAR, SAFETY HELMET, COVERALLS, GLASSES AND GLOVES MUST BE WORN. ANY ADDITIONAL PPE REQUIRED SHALL BE CAPTURED IN THE MITIGATING CONTROLS SECTION OF THE TRA TEMPLATE BELOW.				

No.	Task /Activity	Hazard and Consequence		Initial Risk			Mitigating Controls	Residual Risk		
	Sequential Steps	Hazard	Consequence	Probability	Consequence Severity	Risk Rating	Measures to Reduce Risk to ALARP	Probability	Consequence Severity	Risk Rating
1	Review TRA and TBT WORKING AT HEIGHTS TBT, DO-HSE-FRM-057, DO-HSE-FRM-069	Miscommunication	Personnel Injury / Environmental Pollution	1	2	M	Situational awareness and proper use of PPE. Hard hats, impact gloves, cotton gloves, latex gloves, steel toed boots, safety glasses, side shields and face shield	1	1	L
2	Prior to any task being undertaken ensure that all personnel are aware of the hazards involved.	Electrical shock, possible slips trips and falls. Pinch points poor body position. Hydraulic discharge and spills.	Personnel Injury / Environmental Pollution	2	3	M	All personnel must be aware of their surrounds and weather conditions. Use proper Manual Handling techniques, i.e., Always use proper body positioning, lift with legs, and obtain second personnel when loads are over 40lbs. Read all SDS on chemicals used, use PPE that is specified in SDS and be aware of where all spill kits are located.	2	2	L
3	Assess height of work location	Falling from height without proper length lanyard or arrestor	Personnel Injury	2	3	M	Ensure personnel have located tie off points above work area so that if fall does happen, they do not impact deck.	1	1	L
4	All Personnel should review Working at Heights Rescue Plan	<i>Falls from height and personnel suspended from harness</i>	Personnel Injury	2	3	M	Perform tasks as stated in DO Working at Heights Rescue Plan	1	1	L
5	Communications with bridge	Rapid movement of vessel causing unstable footing and equipment movement	Personnel Injury	2	3	M	Rapid movement of vessel causing unstable footing and equipment movement	1	1	L
6	Working at heights	Falling with no personnel aware of personnel aloft	Personnel Injury	2	3	M	<u>No working at heights to be completed without a secondary tech on hand and observing the individual.</u> Ensure harness and lanyard are inspected for proper fit, function and wear. <i>If wear is found take out of service, red tag and notify Supervisor.</i>	1	1	L

7	Proper tool usage and condition	Broken or worn tools causing personnel to slip and fall, dropped objects. Damage to equipment	Personnel Injury	2	3	M	Inspect all tooling prior to use, ensure all tools are tied off if required.	1	1	L
8	Climbing to work location	Slip or fall during climb, dropped objects, damaged ladder.	Personnel Injury	2	3	M	Inspect ladder prior to use, ensure clean and safe climbing area, secure ladder to secure location. Secure to highest point while ascending	1	1	L
9	Working at Heights	Fall during work, dropped objects.	Personnel Injury	2	3	M	Ensure that 3 points of contact are used with use of lanyard system and that all contact points are stable locations for tie off. Ensure that lanyard is above personnel's head.	1	1	L
10	Working at project location at heights	Falling from heights, dropped objects, pinch points	Personnel Injury	2	3	M	Only bring the tools required to complete the job, if more tools are needed utilize 2 nd tech to retrieve tools.	1	1	L
11	Climbing down from work location	Slip or fall during descent, dropped objects, damaged ladder	Personnel Injury	2	3	M	Hand off tools to 2 nd tech, ensure ladder is tied down to secure location. Inspect work area to ensure all tools are retrieved.	1	1	L
12	Completion of task, put away all tools and equipment used for task.	Slips, trips and falls due to tools being left lying around, dropped objects, ladder not secured. Permits not closed out	Personnel Injury	2	3	M	Ensure all tools are inspected and put in proper locations. Make sure all tools used are a counted for. Put away and secure ladders. Work permit must be closed upon completion of project if one was required by Vessel.	1	1	L

TRA Approval	Name	Position	Signature	Date
By signing, the Approver confirms that the TRA has been reviewed and considers the task acceptable to proceed with residual risk meeting the acceptance criteria of DO Risk Matrix.				

*Reference DO-HSE-FRM-140 for DeepOcean Risk Assessment Matrix (RAM) and Guidewords