

Project (If Applicable)		TRA Ref. No.	DOUS-TRA-021	
Location / Worksite				
Sub Location / Area				
Equipment Spread (Optional)				
Task / Activity	SURVEY INTEGRATION ELECTRICAL & TESTING			
Approver				
Responsible Person				
Date TRA Created				
Reference Supporting Documents & Task Plan				
S3RA:	Hot Work Checklist:			
Task Plan:	Work at Height Checklist: DO-HSE-FRM-069			
Lift Plan:	Confined Space Work Checklist:			
PTW:	Electrical Equipment Checklist:			
COSHH / SDS:	Electrical Isolation Checklist: DO-HSE-FRM-062			
Rescue Plan:	Machinery Isolation Checklist:			
Work Equipment Assessment:	Pressure Systems Checklist:			
Other: DO-HSE-FRM-057	Other: DOUS-TRA-017 / DOUS-TRA-006 / DOUS-TRA-027			
Reason for TRA (Tick where Applicable)				
Identification of New Task	Annual Review	Review following Incident	Management of Change Record	Other, Please Specify
☐	☐	☐	☐	☐
Other (Details):				
TRA Participants				
Name	Position	Signature		
NOTE: STANDARD PPE OF SAFETY FOOTWEAR, SAFETY HELMET, COVERALLS, GLASSES AND GLOVES MUST BE WORN. ANY ADDITIONAL PPE REQUIRED SHALL BE CAPTURED IN THE MITIGATING CONTROLS SECTION OF THE TRA TEMPLATE BELOW.				

No.	Task /Activity	Hazard and Consequence		Initial Risk			Mitigating Controls	Residual Risk		
	Sequential Steps	Hazard	Consequence	Probability	Consequence Severity	Risk Rating	Measures to Reduce Risk to ALARP	Probability	Consequence Severity	Risk Rating
1	Review TRA and TBT	Miscommunication	Personnel Injury / Environmental Pollution	1	2	2	Situational awareness and proper use of PPE. Hard hats, impact gloves, cotton gloves, latex gloves, steel toed boots, safety glasses, side shields and face shield	1	1	1
2	Prior to any task being undertaken ensure that all personnel are aware of the hazards involved.	Electrical shock, possible slips trips and falls. Pinch points poor body position. Hydraulic discharge and spills.	Personnel Injury / Environmental Pollution	2	3	6	All personnel must be aware of their surrounds and weather conditions. Use proper Manual Handling techniques, i.e., Always use proper body positioning, lift with legs, and obtain second personnel when loads are over 40lbs. Read all SDS on chemicals used, use PPE that is specified in SDS and be aware of where all spill kits are located.	2	2	4
3	<i>If task requires working with power tools a JSA is required and or permit to work from vessel.</i>	Personnel injury, pinch points, improper use of tool, damage to equipment, malfunctioning equipment.	Personnel Injury / Equipment Damage	1	2	2	Review TRA Power Tool Use . Obtain permit to work if required by vessel.	1	1	1
4	<i>If task requires working at heights a JSA is required and or permit to work from vessel.</i>	Personal injury due to falls, dropped objects or improper use of PPE.	Personnel Injury / Equipment Damage	1	2	2	Review TRA Working At Heights . Obtain permit to work if required by vessel.	1	1	1
5	Use of hand tools.	Pinch points, cuts, stabs, trips and slip hazards.	Personnel Injury / Equipment Damage	2	2	4	Use proper PPE for the task. Use the proper tool for the task at hand. Keep tools clean and secured when not in use. NEVER leave tools laying around in walkways, staircases or on to of ladders.	1	1	1
6	Intergradation and Mounting of Survey equipment	Electrical shock, damage to equipment, pinch points and poor body positioning	Personnel Injury / Equipment Damage	2	2	4	Personnel shall work with survey during integration of survey equipment. Nothing is to be put on ROV without surveys instructions. Use correct lifting procedures and correct body positioning.	1	1	1

7	If Required a Lock out Tag out electrical source preparing for integration and testing. Review TRA LOTO. Obtain a Permit to work if required by vessel.	Electrical shock, damage to equipment	Personnel Injury / Equipment Damage	1	2	2	Review LOTO JSA. All personnel conducting work will always have a key for locks on them.	1	1	1
8	Use of chemicals, potting material, and oil.	Inhalation, ingestion, and skin irritation with personnel. Slip hazards and chemical reactions.	Personnel Injury / Equipment Damage	2	2	4	Use proper PPE when handling chemicals. Review MSDS for each chemical.	1	1	1
9	Remove lock out tag out, ready for voltage to be re applied.	Electrical shock, damage to equipment.	Personnel Injury / Equipment Damage	2	2	4	Personnel will remove their locks from the lock out tag out. Before turning on circuit they must be sure that all personnel are clear, and circuit is hooked back up. Good communication between personnel. Close out PTW from vessel if one was obtained.	1	1	1
10	Test and function survey equipment	Electrical shock, damage to equipment	Personnel Injury / Equipment Damage	2	2	4	Personnel shall be in contact with pilot as equipment is being turned on and tested.	1	1	1
11	Put all tools and testing equipment away in its proper location after task is completed.	Damage to equipment, slips, trips and falls. Dropped objects.	Personnel Injury / Equipment Damage	2	2	4	Stow all equipment in their proper location or cases and tools in their proper location. Clean area of all slips, trips and falls. Put away and secure all ladders if used.	1	1	1

TRA Approval	Name	Position	Signature	Date
By signing, the Approver confirms that the TRA has been reviewed and considers the task acceptable to proceed with residual risk meeting the acceptance criteria of DO Risk Matrix.				

*Reference DO-HSE-FRM-140 for DeepOcean Risk Assessment Matrix (RAM) and Guidewords