

[illegible]

No.	Task /Activity	Hazard and Consequence		Initial Risk			Mitigating Controls	Residual Risk		
	Sequential Steps	Hazard	Consequence	Probability	Consequence Severity	Risk Rating	Measures to Reduce Risk to ALARP	Probability	Consequence Severity	Risk Rating
1	Review TRA and TBT	Miscommunication	Personnel Injury / Environmental Pollution	1	2	2	Situational awareness and proper use of PPE. Hard hats, impact gloves, cotton gloves, latex gloves, steel toed boots, safety glasses, side shields and face shield	1	1	1
2	Prior to any task being undertaken ensure that all personnel are aware of the hazards involved.	Electrical shock, possible slips trips and falls. Pinch points poor body position. Hydraulic discharge and spills.	Personnel Injury / Environmental Pollution	2	3	6	All personnel must be aware of their surrounds and weather conditions. Use proper Manual Handling techniques, i.e., Always use proper body positioning, lift with legs, and obtain second personnel when loads are over 40lbs. Read all SDS on chemicals used, use PPE that is specified in SDS and be aware of where all spill kits are located.	2	2	4
3	Obtain all painting equipment to perform task and check equipment.	Hazardous vapor, skin, and eye irritants. Damaged equipment	Personnel Injury / Environmental Pollution	2	2	4	Use of proper PPE to perform task. Keep area well ventilated. MSDS on hand for chemicals being used.	1	1	1
4	Barricade off area to be painted (if needed).	Slips, trips, and falls caused by wet paint.	Personnel Injury / Environmental Pollution	2	2	4	Ensure area to be painted is barricaded off and that all spills are cleaned up immediately.	1	1	1
5	Paint work area	Slips, trips, falls, spills, and environmental discharge.	Personnel Injury / Environmental Pollution	2	2	4	Ensure that all paint items are secured from spills and tipping over during task. Clean up spills immediately and dispose in proper container for disposal.	1	1	1
6	Clean work area	Slips, trips and falls caused by wet paint.	Personnel Injury / Environmental Pollution	2	2	4	Ensure that work area remains barricaded until work area is dry and remove barricade. Dispose of all waste into proper container for disposal.	1	1	1
7	Clean equipment, put away equipment in proper location and store paint in fire locker.	Chemical reaction, spills, and possible fire.	Personnel Injury / Environmental Pollution	2	2	4	Store all paint products in fire locker and secure. Ensure that all PPE is worn while cleaning equipment with chemicals and MSDS is on hand. Dispose of cleaning agent in proper container for disposal.	1	1	1

Task Risk Assessment Form

DEEPOCEAN

TRA Approval	Name	Position	Signature	Date
By signing, the Approver confirms that the TRA has been reviewed and considers the task acceptable to proceed with residual risk meeting the acceptance criteria of DO Risk Matrix.				

**Reference DO-HSE-FRM-140 for DeepOcean Risk Assessment Matrix (RAM) and Guidewords*

Doc ID : DO-HSE-FRM-138
Doc Name : Task Risk Assessment Form
Parent Doc ID : DO-HSE-PRO-074 Risk Assessment Procedure

Rev : A
Date : 29/07/2021
Page : 3 of 3