

[illegible]

No.	Task /Activity	Hazard and Consequence		Initial Risk			Mitigating Controls	Residual Risk		
	Sequential Steps	Hazard	Consequence	Probability	Consequence Severity	Risk Rating	Measures to Reduce Risk to ALARP	Probability	Consequence Severity	Risk Rating
1	Review TRA and TBT	Miscommunication	Personnel Injury / Environmental Pollution	1	2	2	Situational awareness and proper use of PPE. Hard hats, impact gloves, cotton gloves, latex gloves, steel toed boots, safety glasses, side shields and face shield	1	1	1
2	Prior to any task being undertaken ensure that all personnel are aware of the hazards involved.	Electrical shock, possible slips trips and falls. Pinch points poor body position. Hydraulic discharge and spills.	Personnel Injury / Environmental Pollution	2	3	6	All personnel must be aware of their surrounds and weather conditions. Use proper Manual Handling techniques, i.e., Always use proper body positioning, lift with legs, and obtain second personnel when loads are over 40lbs. Read all SDS on chemicals used, use PPE that is specified in SDS and be aware of where all spill kits are located.	2	2	4
3	A TRA for Launch and Recovery is needed.	Damage to equipment, miscommunication.	Personnel Injury / Environmental Pollution / Equipment Damage	1	2	2	Review Launch and Recovery TRA to preform task.	1	1	1
4	Use of hand tools.	Pinch points, cuts, stabs, trip and slip hazard	Personnel Injury / Environmental Pollution / Equipment Damage	2	2	4	Use proper PPE for the task. Use hand tools properly for their use. Keep tools clean and secured when not in use. Do not leave tools laying around in walkways or staircases	1	1	1
5	Install and secure gland clam shell around umbilical. If working at heights higher than 6 ft. a WAH checklist will be needed.	Damage to equipment, slips, trips and falls.	Personnel Injury / Environmental Pollution / Equipment Damage	1	2	2	Ensure that clam shell is properly secured to tie down areas and installed per manufactures instructions. Use proper tool for installing shells. If working above 6 ft. a Working at Heights Checklist will be reviewed.	1	1	1
6	Prepare luber	Damage to equipment, injury to personnel	Personnel Injury / Environmental Pollution / Equipment Damage	2	2	4	Load lube according to manufactures instructions. Be aware of hand placement and use proper lifting techniques.	1	1	1

7	Connect airline to luber.	Damage to equipment, injury to personnel.	Personnel Injury / Environmental Pollution / Equipment Damage	2	2	4	Ensure that airline is in good condition if damage is seen take out of service immediately and contact supervisor. Ensure that the luber has a proper pressure setting according to manufacturer.	1	1	1
8	Begin to lube umbilical while paying out.	Damage to equipment, injury to personnel	Personnel Injury / Environmental Pollution / Equipment Damage	2	2	4	Two personnel will be on hand as lube operations are commencing. Personnel will monitor lube level while paying out. If lube bucket is empty, an all stop will occur, and a new bucket will be installed into the luber.	1	1	1
9	Remove clam shell once desired length is payed out on umbilical.	Damage to equipment, injury to personnel. Equipment under tension	Personnel Injury / Environmental Pollution / Equipment Damage	2	2	4	Ensure that tension on clam shells has been relieved and tie offs have been removed. Use proper tools to remove clam shells. Personnel are to never be under umbilical while removing clam shells.	1	1	1
10	Clean work area	Slips, trips and falls.	Personnel Injury / Equipment Damage	2	2	4	Store luber in proper location and clean deck of any extra lube to prevent slips and falls. Store left over lube in proper location. Dispose of rage in proper container for disposal. Clean and put away all tools and equipment that was used for task. Secure ladder if one was used for task.	1	1	1

TRA Approval	Name	Position	Signature	Date
By signing, the Approver confirms that the TRA has been reviewed and considers the task acceptable to proceed with residual risk meeting the acceptance criteria of DO Risk Matrix.				

*Reference DO-HSE-FRM-140 for DeepOcean Risk Assessment Matrix (RAM) and Guidewords