ORIGINATING CUST REF NO:

515653

BMS571R1-2

ALL

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE: 1 OF 83 RUN DATE:

9/28/2023

RUN TIME : 11:09

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL STATUS: ALL ORIG-STAGE: ALL PERIOD: ALL ESTIMATED MHR: ALL

> ATA NO: ALL ZONE: ALL DISPOSITION CODE: ALL

DEFECT TYPE: ALL TRADE: ALL CUST ENDORSE: ALL AREA: ALL STAGE: ALL

CTRL CODE: TYPE CODE: ORIGINATOR: ALL

	ZONE	STG						STATUS	UPDATED DATE
JOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH NO DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
XJL0017	500	NRR	AE	2800	TA28000201	PERFORM A/C DE-FUELLING FOR MAINTENANCE	L001	COMP	09/20/2023
	WNG								0.0
								-	0.0
XJL0025	500	NRR	AE	2800	TA28000201	PERFORM A/C FUEL SUMP DRAIN FOR FUEL TANK MAINTENANCE	L002	COMP	09/24/2023
	F/T								0.0
								-	0.0
XJL0033	100	NRP	AE	07	777-BM-CONTROL- CARD-01	TOWING A/C FOR MAINTENANCE/OPERATIONAL NEEDS	L003	WIP	09/20/2023
	FUS				CARD-01				0.0
						1C 1 PERFORM AIRPLANE TOWING FROM OUTSIDE 3 BAY TO BAY9.			5.0
								-	5.0
XJL0041	100	NRP	ΑE	0711	777-900002-01-1-01	JACK THE AIRPLANE FOR MAINTENANCE	L004	WIP	09/20/2023
	FUS					REF TO XMN TASK CARD: TA07000101-BOE			0.0
						1C 1 REMOVE BODY FAIRING 191SL &192SR			0.0
						1C 2 AIR MOD SIMULATION PREPARATION			0.0
						1C 3 LIFT THE AIRCRAFT WITH JACK			0.0
						1C 4 LOWER THE AIRCRAFT OFF OF THE JACK			0.0
						2C 5 REINSTALL THE BODYFAIRING191SL&192SR			0.0
						2C 6 AIR MODE SIMULATION RESTORATION			0.0
						2C 7 PERFORM WOW LOAD SENSOR CALIBRATION		-	0.0
									0.1
XJL0058	200 CAB	NRR	Al	2500	777-53-904-00-01	CABIN G1 GALLERY R112 TOASTER MACHINE TRACK FOUND DAMAGE	L005	OPEN	09/20/2023
	CAD								4.0
								-	4.0
XJL0066	200	NRR	AV	2500	777-53-904-00-01	CABIN VCC V01 COMPARTMENT INNER DOOR CLOSE SWITCH BOX FOUND DAMAGE	L006	OPEN	09/20/2023
	CAB								0.0
								-	0.0
XJL0074	200	NRP	SS	25	777-25-050-08-CX-R- 01	PEY SEAT CONSOLE PTV ARM OPERATION FOUND TIGHTEN AT 30D E F G 31A C 32H K TOTAL:8EA	L007	OPEN	09/20/2023
	CAB				UI				8.0
								-	8.0

ORIGINATING CUST REF NO:

515653

BMS571R1-2

ALL

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE: 2 OF 83

RUN DATE: 9/28/2023

RUN TIME: 11:09

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL STATUS: ALL ORIG-STAGE: ALL PERIOD: ALL ESTIMATED MHR: ALL

ATA NO: ALL ZONE: ALL DISPOSITION CODE: ALL

DEFECT TYPE: ALL TRADE: ALL CUST ENDORSE: ALL AREA: ALL STAGE: ALL

CTRL CODE : TYPE CODE : ORIGINATOR : ALL

TRL CODE :					TYPE CODE:	ORIGINATOR	:: ALL		CTATUC	LIDDATED DATE
JOB NO	ZONE AREA	STG	TD	ATA	ORIG CUST REF NO.	CTRL SH NO	DEFECT DESCRIPTION	JSN	STATUS STATUS	UPDATED DATE EST Mhr
(JL0082	200	NRR	Al	2541	777-53-904-00-01	SPEC NO.B777-25-3-7179 -CABIN Z	ONE B LAV 3F-RC TOILET SEAT COVER BUMPER FUNCTION DISAPPEARED	L008	OPEN	09/20/2023
	CAB									4.0
									-	4.0
JL0090	200	NRR	Al	2541	777-53-904-00-01	CABIN ZONE A LAV A TOILET SEA	T COVER BUMPER FUNCTION DISAPPEARED	L009	OPEN	09/20/2023
	CAB									4.0
									-	4.0
JL0108	200	NRR	Al	2541	777-53-904-00-01	CABIN ZONE A LAV A FAUCET FOL	JND DAMAGE	L010	WIP	09/28/2023
	CAB									4.0
									-	4.0
JL0116	200	NRR	Al	2531	777-53-904-00-01	CABIN ZONE A G1 GALLERY PLAC	ARD FOUND CHIPPED	L011	OPEN	09/20/2023
	CAB									3.0
									-	3.0
JL0124	200	NRR	Al	2500	777-53-908-00-01	CABIN FB2 STOWAGE COMPARTM	IENT S1CA TOP DOOR SNUBBER FOUND WEAK	L012	WIP	09/27/2023
	CAB									1.0
									-	1.0
JL0132	200	NRR	Al	2500	777-53-908-00-01	CABIN FB2 STOWAGE COMPARTM	IENT S2CA TOP DOOR SNUBBER FOUND WEAK	L013	OPEN	09/20/2023
	CAB									1.0
									-	1.0
JL0140	200	NRR	Al	2531	777-53-908-00-01	CABIN ZONE B GALLERY G2 PLAC	ARD FOUND CHIPPED	L014	OPEN	09/20/2023
	CAB									4.0
									-	4.0
JL0157	200	NRR	Al	2531	777-53-908-00-01	CABIN ZONE B GALLERY G3 PLAC	ARD FOUND CHIPPED	L015	OPEN	09/20/2023
	CAB									4.0
									-	4.0
IL0165	200	NRR	SS	2525	777-C252440-04-02- 01	EY PAX SEAT BACKREST TABLE F	ND TIGHT AT :40H J K 41H J K 42H J K 43H J K 44H J K 45H J K 46H J K TTL:21EA	L016	WIP	09/25/2023
	CAB									4.0
									-	4.0

0PPC DISTRIBUTION:

REQUESTED BY:

REFERENCE NO:

DEFECT TYPE: ALL

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

3 OF 83 PAGE:

RUN TIME :

RUN DATE: 9/28/2023 11:09

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL

515653

BMS571R1-2

STATUS: ALL ORIG-STAGE: ALL PERIOD: ALL

ESTIMATED MHR: ALL DISPOSITION CODE: ALL

ORIGINATING CUST REF NO: ALL

TRADE: ALL

ATA NO: ALL ZONE: ALL CUST ENDORSE: ALL AREA: ALL

STAGE: ALL

CTRL CODE:

TYPE CODE: ORIGINATOR: ALL

STATUS	UPD

	ZONE	STG						STATUS	UPDATED DATE
JOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH NO DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
XJL0173	200	NRR	Al	2500	777-53-912-00-01	CABIN DOOR 3 FWD CENTER PARTITION ATTACHED MAGAZINE RACK FOUND WORN 4 EA	L017	WIP	09/26/2023
	CAB								4.0
								-	4.0
XJL0181	200	NRR	Al	2500	777-53-904-00-01	CABIN FIRST CLASS TABLE SNUBBER FOUND WEAK AT 1A 2D 1K	L018	OPEN	09/20/2023
	CAB								12.0
								-	12.0
XJL0199	200	NRR	Al	2500	777-53-904-00-01	CABIN VCC V01 COMPARTMENT DOOR LATCH BUMPER FOUND MISSING	L019	OPEN	09/20/2023
	CAB								1.0
								-	1.0
XJL0207	200	NRR	SS	2525	777-C252440-04-02-	EY PAX SEAT BACKREST TABLE FND TIGHT AT :39D E F G 40D E F G 41D E F G 42D E F G 43D E F G 44D E F G 45D E F	L020	WIP	09/25/2023
	CAB				01	G 46D E F G			6.0
								-	6.0
XJL0215	100	NRR	Al	2580	777-53-822-00-01	FWD CARGO COMPARTMENT BILGE AREA INSULATION BLANKET FOUND DIRTY	L021	OPEN	09/20/2023
	LWR								8.0
								-	8.0
XJL0223	200	NRR	Al	2541	777-53-904-00-01	CABIN ZONE A LAV B WASTE BIN FLAP DOOR MALFUNCTION	L022	OPEN	09/20/2023
	CAB								4.0
								-	4.0
XJL0231	100	NRR	Al	2580	777-53-822-00-01	FWD CARGO COMPARTMENT BILGE AREA INSULATION BLANKET FOUND TORN.	L023	OPEN	09/20/2023
	LWR								8.0
								-	8.0
XJL0249	100	NRR	Al	2580	777-53-818-00-01	FWD CARGO COMPARTMENT S/W AREA INSULATION BLANKET FOUND TORN.	L024	OPEN	09/20/2023
	LWR								16.0
								-	16.0
XJL0256	200	NRR	Al	2541	777-53-904-00-01	CABIN ZONE A LAV B WATER ACCESS PANEL BOX LOWER HOOK LOOSE	L025	OPEN	09/20/2023
	CAB								5.0
								-	5.0

515653

BMS571R1-2

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE: 4 OF 83

RUN DATE: 9/28/2023

RUN TIME: 11:09

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL STATUS: ALL ORIG-STAGE: ALL PERIOD: ALL ESTIMATED MHR: ALL

ORIGINATING CUST REF NO: ALL ATA NO: ALL ZONE: ALL DISPOSITION CODE: ALL

DEFECT TYPE: ALL TRADE: ALL CUST ENDORSE: ALL AREA: ALL STAGE: ALL

CTRL CODE : TYPE CODE: ORIGINATOR : ALL

CIRL CODE:					TYPE CODE:	ORIGINATOR: ALL				
	ZONE	STG							STATUS	UPDATED DATE
JOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH NO	DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
XJL0264	100	NRR	Al	2580	777-53-822-00-01	FWD CARGO COMPARTMENT BILGE AREA INS	JLATION BLANKET CLAMPS FOUND MISSING.	L026	OPEN	09/20/2023
	LWR									1.0
									-	1.0
XJL0272	100	NRR	Al	2580	777-53-862-00-01	AFT CARGO COMPARTMENT BILGE AREA INSU	LATION BLANKET FOUND TORN.	L027	WIP	09/25/2023
	LWR									8.0
									-	8.0
XJL0280	100	NRR	Al	2580	777-53-862-00-01	AFT CARGO COMPARTMENT BILGE AREA INSU	LATION BLANKET FOUND DIRTY.	L028	WIP	09/25/2023
	LWR									16.0
									-	16.0
XJL0298	100	NRR	Al	2580	777-53-862-00-01	AFT CARGO COMPARTMENT BILGE AREA INSL	LATION BLANKET CLAMPS FOUND MISSING.	L029	OPEN	09/20/2023
	LWR									1.0
									-	1.0
XJL0306	100	NRR	Al	2580	777-53-854-00-01	AFT CARGO COMPARTMENT SIDEWALL AREA	NSULATION BLANKET FOUND TORN.	L030	OPEN	09/20/2023
	LWR									16.0
									-	16.0
XJL0314	200	NRR	Al	5600	777-53-904-00-01	CABIN A ZONE L2 WINDOW DUST COVER FOUR	ID SCRATCHED	L031	OPEN	09/20/2023
	CAB									4.0
									-	4.0
XJL0322	100	NRR	Al	5300	777-53-874-00-01	BULK CARGO COMPARTMENT FLOOR PANEL S	CREWS FOUND WORN.	L032	OPEN	09/20/2023
	LWR									1.0
									-	1.0
XJL0330	100	NRR	Al	2580	777-53-874-00-01	BULK CARGO COMPARTMENT BILGE AREA INS	ULATION BLANKET FOUND BROKEN	L033	OPEN	09/20/2023
	LWR							2000	0	5.0
									-	5.0
XJL0348	200	NRR	SS	2525	777-C252440-04-02-	EY PAX SEAT BACKREST TABLE FND TIGHT AT	: 59H J K 60H J K 61H J K 62H J K 63H J K 64H J K 65H J K 66H J K 67H J	L034	WIP	09/25/2023
	CAB				01	EY PAX SEAT BACKREST TABLE FND TIGHT AT : 59H J K 60H J K 61H J K 62H J K 63H J K 64H J K 65H J K 66H J K 67H J K 68H J K 69H J K 70H J K 71H J K TTL:39EA	2004	****	8.0	
									-	8.0
										8.0

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE: 5 OF 83 RUN DATE:

9/28/2023

RUN TIME : 11:09

3.0

1.0 1.0

09/20/2023

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL

515653

BMS571R1-2

STATUS: ALL

ORIG-STAGE: ALL

CUST ENDORSE: ALL

AFT CGO COMP'T CEILING PNL FIREPROOF TAPE FOUND AGED.

PERIOD: ALL

ESTIMATED MHR: ALL

L043

OPEN

ORIGINATING CUST REF NO: ALL

ZONE: ALL

AREA: ALL

DISPOSITION CODE: ALL STAGE: ALL

CTRL CODE:

XJL0439

100

LWR

NRR

ΑI

2552

777-53-854-00-01

DEFECT TYPE : ALL

TRADE: ALL TYPE CODE:

ORIGINATOR: ALL

ATA NO: ALL

	ZONE	STG							STATUS	UPDATED DATE
JOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH NO	DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
XJL0355	200	NRR	SS	2525	777-C252440-04-02-		TIGHT AT : 39A C 40A B C 41A B C 42A B C 43A B C 44A B C 45A B C 46A B C	L035	WIP	09/25/2023
	CAB				01	TTL:20EA				4.0
									-	4.0
XJL0363	100	NRR	Al	2580	777-53-874-00-01	BULK CARGO COMPARTMENT SIDEW	VALL AREA INSULATION BLANKET FOUND BROKEN	L036	OPEN	09/20/2023
	LWR									4.0
									-	4.0
XJL0371	100	NRR	Al	2580	777-53-874-00-01	BULK CARGO COMPARTMENT BILGE	AREA INSULATION BLANKET FOUND DIRTY	L037	WIP	09/25/2023
	LWR									5.0
									-	5.0
XJL0389	200	NRR	Al	2541	777-53-904-00-01	CABIN ZONE B LAV D FAUCET FOUND	MALFUNCTION	L038	WIP	09/28/2023
	CAB									4.0
									-	4.0
XJL0397	200	NRR	Al	5600	777-53-904-00-01	CABIN A ZONE R1 WINDOW DUST CO	VER FOUND SCRATCHED	L039	OPEN	09/20/2023
	CAB									4.0
									-	4.0
XJL0405	100	NRR	Al	2552	777-53-818-00-01	FWD CGO COMP'T CEILING PNL FIRE	PROOF TAPE FOUND AGED.	L040	OPEN	09/20/2023
	LWR									1.0
									-	1.0
XJL0413	100	NRR	Al	2552	777-53-818-00-01	FWD CGO COMP'T S/W PNL FIREPRO	OF TAPE FOUND AGED.	L041	OPEN	09/20/2023
	LWR									1.0
									-	1.0
XJL0421	200	NRR	Al	2531	777-53-908-00-01	CABIN ZONE B GALLERY G2 COMPAR	RTMENT 210 DOOR LATCH DAMAGE	L042	WIP	09/27/2023
	CAB									3.0

ORIGINATING CUST REF NO:

515653

BMS571R1-2

ALL

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE: 6 OF 83 RUN DATE: 9/28/2023

RUN TIME :

11:09

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL STATUS: ALL ORIG-STAGE: ALL PERIOD: ALL ESTIMATED MHR: ALL

> ATA NO: ALL ZONE: ALL DISPOSITION CODE: ALL

DEFECT TYPE: ALL TRADE: ALL CUST ENDORSE: ALL AREA: ALL STAGE: ALL

CTRL CODE: TYPE CODE: ORIGINATOR: ALL

CIRL CODE :					TYPE CODE:	ORIGINATOR: AL	L .			
	ZONE	STG							STATUS	UPDATED DATE
JOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH NO	DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
XJL0447	100	NRR	Al	2552	777-53-854-00-01	AFT CGO COMP'T S/W PNL FIREPROOF TAI	PE FOUND AGED.	L044	OPEN	09/20/2023
	LWR									1.0
									-	1.0
XJL0454	100	NRR	Al	2552	777-53-822-00-01	FWD CGO COMPARTMENT FLOOR PNL SCI	REWS FOUND WORN.	L045	OPEN	09/20/2023
	LWR									1.0
									-	1.0
XJL0462	200	NRR	Al	2531	777-53-908-00-01	CABIN ZONE B GALLERY G3 OVEN 3 4 5 DC	OR EXTERNAL PLACARD FOUND CHIPPED	L046	OPEN	09/20/2023
	CAB									3.0
									-	3.0
XJL0470	200	NRR	Al	2524	777-53-912-00-01	CABIN L/R 3 DOOR O/B FWD CLOSETS TOP	SEAL FOLIND DAMAGE	L047	OPEN	09/20/2023
	CAB					0.5	52. E . 55.15 B. a.m. 62	2047	OI LIV	6.0
									-	
XJL0488	100	LOG	Al	25		AS PER CX B-KPV OPEN TL ENTRIES TL351	7. EOLIID COOLING EAN DICTATUS)	1.040	ODEN	6.0
AJE0400	LWR	LOG	AI	23		AS FER CA B-REV OFEN IL ENTRIES 11331	1. EQUIP COOLING FAN K(STATUS)	L048	OPEN	09/20/2023
						1C 1 PLS MAKE LOG BOOK ENTR	Y.			0.0 0.2
									-	0.2
XJL0496	100	NRR	Al	2552	777-53-818-00-01	FWD CGO COMP'T CEILING PNL SCREWS F	OUND WORN.	L049	OPEN	09/20/2023
	LWR							2010	OI LIV	1.0
									-	1.0
XJL0504	100	NRR	Al	2552	777-53-818-00-01	FWD CGO COMPARTMENT S/W PNL SCREV	VS FOLIND WORN	L050	OPEN	09/20/2023
7.02000.	LWR			2002	55 5.5 55 5.	THE GOOD COMM FIRTHER CONTENT	NOTION DIVINI	2030	OFLIN	1.0
									-	
XJL0512	200	NRR	Al	2524	777-53-912-00-01	CABIN R 3 DOOR O/B FWD CLOSETS FWD S	PEAL DETAINED FOLIND DETACHED	1.054	0051	1.0
AJL0312	CAB	INIXIX	AI	2024	777-55-912-00-01	CABIN R 3 DOOR O/B FWD CLOSE 13 FWD 3	EAL RETAINER FOUND DETACHED	L051	OPEN	09/20/2023
									_	6.0
										6.0
XJL0520	200 CAB	NRR	Al	2524	777-53-912-00-01	CABIN L3 DOOR O/B FWD CLOSETS FWD S	EAL RETAINER FOUND DETACHED	L052	OPEN	09/20/2023
	CAB									6.0
									-	6.0

ORIGINATING CUST REF NO:

515653

BMS571R1-2

ALL

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE: 7 OF 83

RUN TIME :

ESTIMATED MHR: ALL

RUN DATE: 9/28/2023

11:09

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL STATUS: ALL ORIG-STAGE: ALL PERIOD: ALL

ATA NO: ALL ZONE: ALL DISPOSITION CODE: ALL

DEFECT TYPE: ALL TRADE: ALL CUST ENDORSE: ALL AREA: ALL STAGE: ALL

CTRL CODE: TYPE CODE: ORIGINATOR: ALL

	ZONE	STG							STATUS	UPDATED DATE
JOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH NO	DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
JL0538	100	NRR	Al	2552	777-53-854-00-01	AFT CGO COMP'T CEILING PNL SCREWS FOU	ND WORN.	L053	OPEN	09/20/2023
	LWR									1.0
									-	1.0
JL0546	100	NRR	ΑI	2552	777-53-854-00-01	AFT CGO COMPARTMENT S/W PNL SCREWS	FOUND WORN.	L054	OPEN	09/20/2023
	LWR									1.0
									-	1.0
L0553	100	NRR	ΑI	2552	777-53-862-00-01	AFT CGO COMPARTMENT FLOOR PNL SCREV	S FOUND WORN.	L055	OPEN	09/20/2023
	LWR									1.0
									-	1.0
L0561	200	NRR	SS	2525	777-C252440-04-02-		T :59A B C 60A B C 61A B C 62A B C 63A B C 64A B C 65A B C 66A B C 67A	L056	WIP	09/25/2023
	CAB				01	B C 68A B C 69A B C 70A B C 71A B C 72A C TT	:41EA			8.0
									-	8.0
L0579	200	NRR	SS	2525	777-C252440-04-02-		T : 60D E F G 61D E F G 62D E F G 63D E F G 64D E F G 65D E F G 66D E F	L057	WIP	09/25/2023
	CAB				01	G 67D E F G 68D E F G 69D E G 70D E G 71D E	G 72D E G TTL: 48EA			9.0
									-	9.0
L0587	400	NRP	CL	7100	777-900001-01-1-01	#1 ENG BOTH FAN COWLS DIRTY.		L058	WIP	09/27/2023
	ENG									4.0
									-	4.0
L0595	400	NRP	CL	7100	777-900001-01-1-01	#2 ENG BOTH FAN COWLS DIRTY.		L059	WIP	09/27/2023
	ENG									4.0
									-	4.0
JL0603	400	NRP	CL	4900	777-900001-01-1-01	APU CAVITY DIRTY.		L060	WIP	09/28/2023
	ENG									6.0
									-	6.0
L0611	400	NRP	CL	7100	777-900001-01-1-01	#1 ENG GEARBOX AREA DIRTY		L061	OPEN	09/20/2023
	ENG									6.0
									-	6.0

JSN RANGE SELECTED: ALL

ORIGINATING CUST REF NO:

515653

BMS571R1-2

ALL

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

ORIG-STAGE: ALL

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE: RUN TIME :

ESTIMATED MHR: ALL

8 OF 83

RUN DATE: 9/28/2023 11:09

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

ATA NO: ALL ZONE: ALL DISPOSITION CODE: ALL

PERIOD: ALL

DEFECT TYPE: ALL TRADE: ALL CUST ENDORSE: ALL AREA: ALL STAGE: ALL

CTRL CODE: TYPE CODE: ORIGINATOR: ALL

STATUS: ALL

01112 00BE .	ZONE	STG			111 2 0002.	orden with order.	, LE		STATUS	UPDATED DATE
JOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH NO	DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
XJL0629	400	NRP	CL	7100	777-900001-01-1-01	#2 ENG GEARBOX AREA DIRTY		L062	WIP	09/28/2023
	ENG									6.0
									-	6.0
XJL0637	400	NRP	CL	7800	777-900001-01-1-01	#1 ENG BOTH TR COWL DIRTY.		L063	OPEN	09/20/2023
	ENG									6.0
									-	6.0
KJL0645	400	NRP	CL	7800	777-900001-01-1-01	#2 ENG BOTH TR COWL DIRTY.		L064	WIP	09/28/2023
	ENG									6.0
									-	6.0
XJL0652	400	NRP	CL	5400	777-900001-01-1-01	#2 PYLON AFT CAVITY DIRTY		L065	WIP	09/28/2023
	ENG									4.0
									-	4.0
XJL0660	400	NRP	CL	5400	777-900001-01-1-01	#1 PYLON AFT CAVITY DIRTY		L066	OPEN	09/20/2023
	ENG									4.0
									-	4.0
KJL0678	400	NRP	PT	7100	777-900001-01-1-01	#2 ENG NOSE COWL INLET ACOUSTIC S	URFACE PAINT IN POOR CONDITION.	L067	OPEN	09/20/2023
	ENG									8.0
									-	8.0
KJL0686	400	NRP	PT	7100	777-900001-01-1-01	#1 ENG NOSE COWL INLET ACOUSTIC S	URFACE PAINT IN POOR CONDITION.	L068	OPEN	09/20/2023
	ENG									8.0
									-	8.0
XJL0694	400	NRP	PT	7800	777-900001-01-1-01	#2 ENG BOTH TR COWL EXTERNAL DUC	T AFT ACOUSTIC SURFACE PAINT IN POOR CONDITION.	L069	OPEN	09/20/2023
	ENG									8.0
									-	8.0
KJL0702	400	NRP	PT	7800	777-900001-01-1-01	#1 ENG BOTH TR COWL EXTERNAL DUC	T AFT ACOUSTIC SURFACE PAINT IN POOR CONDITION.	L070	OPEN	09/20/2023
	ENG					#1 ENG BOTH TO COME EXTENSIVE BOOT AT I ACCOUNT OUT AND I AND THAT CONTOURDINGS.			8.0	
									-	8.0

515653

BMS571R1-2

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

AREA: ALL

STAGE: ALL

PAGE: 9 OF 83

RUN DATE: 9/28/2023

RUN TIME : 11:09

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL STATUS: ALL ORIG-STAGE: ALL PERIOD: ALL ESTIMATED MHR: ALL

ORIGINATING CUST REF NO: ALL ATA NO: ALL ZONE: ALL DISPOSITION CODE: ALL

DEFECT TYPE : ALL TRADE : ALL CUST ENDORSE : ALL CTRL CODE : TYPE CODE: ORIGINATOR : ALL

020022.	ZONE	STG			2 0052.	5. W.S. W. W. S. K. P. L. L.			STATUS	UPDATED DATE
JOB NO	AREA	313	TD	ATA	ORIG CUST REF NO.	CTRL SH NO	DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
XJL0710	400	NRP	PT	7100	777-900001-01-1-01	#2 ENG RH FAN COWL INNER LOWER SURFACE PAINT IN PO	DOR CONDITION.	L071	OPEN	09/20/2023
	ENG									8.0
									-	8.0
XJL0728	400	NRP	SM	7100	777-900001-01-1-01	#2 ENG NOSE COWL LIP SKIN MULTIPLE FND CORROSION.		L072	WIP	09/24/2023
	ENG									0.0
						1C 1 REMOVE THE LIP SKIN CORROSION				60.0
						1C 2 PTOTECT THE REWORK AREA				4.0
						1C 3 NDT THICKNESS CHK				60.0
						1C 4 NDT CRACK CHK				20.0
									-	144.0
XJL0736	400	NRP	SM	7100	777-900001-01-1-01	#1 ENG NOSE COWL LIP SKIN MULTIPLE FND CORROSION.		L073	WIP	09/23/2023
	ENG									0.0
						1C 1 REMOVE THE LIP SKIN CORROSION				40.0
						1C 2 PTOTECT THE REWORK AREA				4.0
						1C 3 NDT THICKNESS CHK				130.0
						1C 4 NDT CRACK CHK				20.0
									-	194.0
XJL0744	400	NRP	SM	5400	777-900001-01-1-01	#2 PYLON ACC PNL 12EA ANCHOR NUTS FND BROKEN.		L074	WIP	09/28/2023
	ENG									6.0
									-	6.0
XJL0751	400	NRP	SM	5400	777-900001-01-1-01	#1 PYLON ACC PNL 13EA ANCHOR NUTS FND BROKEN.		L075	WIP	09/28/2023
	ENG									6.0
									-	6.0
XJL0769	400	NRP	AE	5400	777-900001-01-1-01	#2 PYLON ACC PNL 12EA SCREWS HEAD FND WORN.		L076	WIP	09/28/2023
	ENG									2.0
									-	2.0
XJL0777	200	NRR	Al	25	777-53-920-00-01	M/D L LAV I/B AFT BABY BASSINET TABLE MIRROR BUMPER	MISSING	L077	COMP	09/26/2023
	CAB									1.0
									-	1.0

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE: 10 OF 83

RUN DATE: 9/28/2023

RUN TIME : 11:09

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL

515653

BMS571R1-2

STATUS: ALL

ORIG-STAGE: ALL

CUST ENDORSE: ALL

PERIOD: ALL

ESTIMATED MHR: ALL

ORIGINATING CUST REF NO:

ALL

ATA NO: ALL

ZONE: ALL

DISPOSITION CODE: ALL

DEFECT TYPE: ALL

CTRL CODE:

TRADE: ALL

TYPE CODE: ORIGINATOR: ALL AREA: ALL STAGE: ALL

STATUS	UPDATED DATE
0171100	01 07 11 00 07 11 0

JSN L078	STATUS	EST Mhr
I 078		
2070	WIP	09/28/2023
		2.0
	-	2.0
L079	OPEN	09/20/2023
		4.0
	-	4.0
L080	OPEN	09/20/2023
OG IPAD R D "CX DEFERRAL		0.0
		0.2
	-	0.2
L081	OPEN	09/20/2023
		4.0
	-	4.0
L082	OPEN	09/20/2023
		8.0
	-	8.0
L083	OPEN	09/20/2023
		9.0
	-	9.0
L084	WIP	09/25/2023
		0.0
		3.0
		0.5
	-	3.5
)(R	L079 L080 G IPAD **CX DEFERRAL L081 L082	L079 OPEN L080 OPEN GIPAD CX DEFERRAL L081 OPEN L082 OPEN L083 OPEN L084 WIP

REQUESTED BY:

REFERENCE NO:

CTRL CODE:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE: 11 OF 83

RUN TIME :

RUN DATE: 9/28/2023

11:09

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL

515653

BMS571R1-2

STATUS: ALL

ORIG-STAGE: ALL

ESTIMATED MHR: ALL

ORIGINATING CUST REF NO:

ALL

ATA NO: ALL

PERIOD: ALL ZONE: ALL AREA: ALL

DISPOSITION CODE: ALL

DEFECT TYPE: ALL

TRADE: ALL TYPE CODE:

CUST ENDORSE: ALL ORIGINATOR: ALL

STAGE: ALL

STATUS	LIPDATED DATE

	ZONE	STG							STATUS	UPDATED DATE
JOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH	IO DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
XJL0850	200	LOG	SS	25			B-KPV DEFERRAL REPORT ITEM ADD A091: 251 6-08 SEAT BELT PROBLEM. REF CMADD CM503. SEATS	L085	OPEN	09/20/2023
	CAB						,17A,18A,19A,20A,21A,22A,23A,24A,25A,25G,26A,26K AIRBAG SEAT BELT INFLATOR REPLACED AND NEW EXPIRY DATE: 0621 / MAF DATE: A0711, LESS THAN 2 YEARS LIFE BUT OVER 100 DAY. (CONTINUE TO SWS			0.0
						1C 1	AS PER CMADD 503 INSTRUCTION NEW INFLATOR EXPIRY DATE LESS THAN 2 YEARS LIFE BUT OVER 100 DAYS, RAISED ADD. ACTIONED IAW CMM 25-02-05 REV SEP 2020. (PLS REF TO ATTACHED "CX DEFERRAL REPORT" FOR THE REQUIRED ACTION ITEMS)			0.0
						1C 2	PLS MAKE LOG BOOK ENTRY			0.2
									-	0.2
XJL0868	200 CAB	NRR	Al	25	777-53-916-00-01	M/D H LA\	FAUCET FOUND WATER LEAKING	L086	OPEN	09/20/2023
	CAB									0.0
						1C 1	REPLACE LAV FAUCET			4.0
						1C 2	C/O LAV FAUCET WATER LEAK CHECK			0.5
										4.5
XJL0876	400	LOG	AV	71			B-KPV DEFERRAL REPORT ITEM ADD A095: OB2 9 ITEM NOT FOUND IN FAULT TREE (REFER TO REMARK), NG #1 IDG FILTER BLOCKED INDICATION ON MFD. AMM 12-22-07-200-802 IDG OIL FILTER CONDITION	L087	OPEN	09/20/2023
	ENG					CHECK FC	LOWED. IDG PILTER BLOCKED INDICATION ON MFD. AMM 12-22-07-200-802 IDG OIL FILTER CONDITION LOWED. IDG DPI RED BUTTON INSPECTED FOUND NOT EXTENDED. FILTER REMOVED AND INSPECTED FILTER REPLACED IAW 24-11-01-000-801-001.(CONTINUE TO SWS ITEM 1)			0.0
						1C 1	FAULT STILL REMAINS DURING EGR IDLE. DEFECT DEFERRED. ADD RAISED AS PER AMM 12-22-07-200-802 FOR INSPECTION EVERY 7 DAYS 4 TIMES FOR DPI EXTENSION. ACTIONED IN ACCORDANCE WITH AMM 12-22-07-200-802 REV 05 MAY 2023. (PLS REF TO ATTACHED "CX DEFERRAL REPORT" FOR THE REQUIRED ACTION ITEMS)			0.0
						1C 2	PLS MAKE LOG BOOK ENTRY.			0.2
						.0 _			_	
										0.2
XJL0884	100	LOG	ΑE	53			PV A/C EXTERNAL DEFECT/REPAIR LIST ITEM FUS 3 : RH FX SKIN TOTAL 29EA HEAT DAMAGE AT	L088	OPEN	09/20/2023
	FUS					FASTENER	DUE LIGHTNING STRIKE LOC FROM STN 200 TO 2200 AND STR S36R TO S45R.			0.0
						1C 1	PLS MAKE LOG BOOK ENTRY			0.2
									-	0.2
XJL0892	200	NRR	CL	2524	777-53-920-00-01	CAB ALL (JRTAINS FOUND DIRTY	L089	WIP	09/22/2023
	CAB									0.0
						1C 1	REMOVE ALL CABIN CURTAIN			2.0
						1C 2	CLEAN THE CURTAIN			10.0
						1C 3	INSTALL CAB ALL CURTAIN			6.0
									-	
										18.0

0PPC DISTRIBUTION:

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE:

RUN TIME :

12 OF 83

0.2

RUN DATE: 9/28/2023 11:09

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE:

JSN RANGE SELECTED: ALL

515653

BMS571R1-2

STATUS: ALL

ORIG-STAGE: ALL

PERIOD: ALL

ZONE: ALL

ESTIMATED MHR: ALL DISPOSITION CODE: ALL

ORIGINATING CUST REF NO:

ALL

ATA NO: ALL TRADE: ALL CUST ENDORSE: ALL

AREA: ALL STAGE: ALL

2C

CTRL CODE:

DEFECT TYPE : ALL

TYPE CODE: ORIGINATOR: ALL

	ZONE	STG						STATUS	UPDATED DATE
JOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH NO DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
XJL0900	200	NRR	CL	2527	777-53-904-00-01	COCKPIT ALL CARPETS FOUND WORN	L090	WIP	09/22/2023
	CAB					1C 1 REMOVE COCKPIT FLOOR CARPET 1C 2 FABICATE COCKPIT FLOOR CARPET 1C 3 INSTALL COCKPIT FLOOR CARPET			0.0 2.0 10.0 6.0
									18.0
XJL0918	200	NRR	Al	25	777-53-904-00-01	#1 AND #2 DOOR GALLEY AREA FLOOR MAT THRESHOLD FOUND AGED	L091	OPEN	09/20/2023
	CAB								8.0
									8.0
XJL0926	200	NRR	Al	25	777-53-904-00-01	#4 AND #5 DOOR GALLEY AREA FLOOR MAT THRESHOLD FOUND AGED	L092	OPEN	09/20/2023
	CAB								8.0
									8.0
XJL0934	200	NRR	Al	25	777-53-920-00-01	M/D L AND M LAV WASTE COMPT DOOR INSIDE 2EA SCREWS MISSING.	L093	OPEN	09/20/2023
	CAB								1.0
									1.0
XJL0942	200	NRR	Al	25	777-53-912-00-01	M/D G LAV TOILET SHROUD AFT CLOURSE PANEL LOWER AREA CRACKED	L094	WIP	09/26/2023
	CAB								0.0
									0.0
XJL0959	200	NRR	Al	25	777-53-912-00-01	M/D G LAV UPPER CLOSE OUT SEAL FOUNS DETACHED	L095	OPEN	09/20/2023
	CAB								1.0
									1.0
XJL0967	200	LOG	SS	25		AS PER CX B-KPV DEFERRAL REPORT ITEM ADD A097: PBE EXPIRED. QTY 1 EXPIRED AT LOCATION FWD FACE OF	L096	WIP	09/27/2023
	CAB					AFT BULKHEAD ABOVE 2 ND OBSERVER SEAT. (PLS REF TO ATTACHED "CX DEFERRAL REPORT" FOR THE REQUIRED ACTION ITEMS)			0.0
						1C 1 PLS MAKE LOG BOOK ENTRY.			0.2
									0.2
XJL0975	200	LOG	AV	35		AS PER CX B-KPV DEFERRAL REPORT ITEM ADD A098: OFCR PORTABLE BREATHING EQUIPMENTS FOUND EXPIRED.	L097	WIP	09/27/2023
	CAB					DEFERRING REPLACEMENT OF TWO OFCR PBE. (PLS REF TO ATTACHED "CX DEFERRAL REPORT" FOR THE REQUIRED ACTION ITEMS)			0.0
						1C 1 PLS MAKE LOG BOOK ENTRY.			0.2
									0.2

ORIGINATING CUST REF NO:

515653

BMS571R1-2

ALL

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE: 13 OF 83

RUN DATE : 9/28/2023

RUN TIME: 11:09

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL STATUS: ALL ORIG-STAGE: ALL

STAGE: ALL PERIOD: ALL

ATA NO: ALL ZONE: ALL

DISPOSITION CODE: ALL

ESTIMATED MHR: ALL

DEFECT TYPE: ALL TRADE: ALL CUST ENDORSE: ALL AREA: ALL STAGE: ALL

CTRL CODE : TYPE CODE : ORIGINATOR :

CTRL CODE :					TYPE CODE:	ORIGINATOR: ALL			
	ZONE	STG						STATUS	UPDATED DATE
JOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH NO DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
XJL0983	200	LOG	AV	35		AS PER CX B-KPV DEFERRAL REPORT ITEM ADD A099: OFAR PORTABLE BREATHING EQUIPMENTS FOUND EXPIRED. REPLACEMENT DEFERRED FOR TWO PBE AT OFAR STATION. (PLS REF TO ATTACHED "CX DEFERRAL REPORT" FOR	L098	WIP	09/27/2023
	CAB					THE REQUIRED ACTION ITEMS)			0.0
						1C 1 PLS MAKE LOG BOOK ENTRY			0.2
									0.2
XJL0991	200	NRR	Al	2524	777-C252420-01-04- 02	CABIN FB2 SEAT RETRACTABLE ARMREST FOUND STIFF TO OPERATE FROM 11D TO 20D TTL 10EA	L099	OPEN	09/20/2023
	CAB				02				27.5
								-	27.5
XJL1007	200	NRR	SS	2527	777-53-912-00-01	M/D ALL AISLE AREA FLOOR CARPETS FOUND WORN	L100	WIP	09/22/2023
	CAB								0.0
						1C 1 REMOVE M/D ALL AISLE AREA FLOOR CARPETS FLOOR CARPETS.			44.0
						1C 2 REMOVE SEAT TRACK COVER 1C 3 FABRICATE M/D ALL AISLE AREA FLOOR CARPETS FLOOR CARPETS.			2.0 68.0
						1C 4 INSTALL M/D ALL AISLE AREA FLOOR CARPETS FLOOR CARPETS.			88.0
						2C 5 INSTALL SEAT TRACK COVER			2.0
								-	204.0
XJL1015	200	NRR	Al	25	777-53-912-00-01	G LAV FWD O/B SIDE CLOSE OUT SEAL FOUND MISSING	L101	COMP	09/26/2023
	CAB								2.0
								-	2.0
XJL1023	200	NRR	Al	2524	777-C252420-01-04-	CABIN FB2 SEAT RETRACTABLE ARMREST FOUND STIFF TO OPERATE FROM 21D TO 26D TTL 5EA	L102	OPEN	09/20/2023
	CAB				02		2102	OI LIV	27.5
								-	27.5
XJL1031	200	NRR	Al	2524	777-C252420-01-04-	CABIN FB2 SEAT RETRACTABLE ARMREST FOUND STIFF TO OPERATE FROM 11G TO 16G TTL 5EA	L103	OPEN	09/20/2023
	CAB			202 .	02		L103	OFLIN	16.5
								-	
XJL1049	200	NRR	Al	25	777-53-916-00-01	G4 GALLEY L/H FWD EMERGENCY EQUIPMENT RACK HANDLE CRACKED	L104	WIP	16.5 09/28/2023
70L1040	CAB	THICK	7 (1	20	777-00-010-00-01	04 OALLET LITT WE LINENGEROT EQUITIBLE TOWN THANKE GRACIES	L104	VVIP	1.0
								-	
XJL1056	200	NRR	Al	2524	777-C252420-01-04-	CADIN FD2 CEAT DETDACTABLE ADMORAT FOLIND STIFF TO ODEDATE FD0M 460 TO 200 TTL 4254		0051	1.0
AJL 1000	200 CAB	NKK	AI	2524	777-C252420-01-04- 02	CABIN FB2 SEAT RETRACTABLE ARMREST FOUND STIFF TO OPERATE FROM 16G TO 26G TTL 10EA	L105	OPEN	09/20/2023
	Ç, (D							_	44.0
								_	44.0

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE: 14 OF 83 RUN DATE: 9/28/2023

RUN TIME :

11:09

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL

515653

BMS571R1-2

STATUS: ALL

ORIG-STAGE: ALL

PERIOD: ALL

ESTIMATED MHR: ALL

ORIGINATING CUST REF NO: ALL

ATA NO: ALL

ZONE: ALL

DISPOSITION CODE: ALL

STAGE: ALL

DEFECT TYPE: ALL TRADE: ALL CUST ENDORSE: ALL AREA: ALL TYPE CODE: ORIGINATOR: ALL

CTRL CODE:

JIKL CODE .					TIPE CODE.	ORIGINATOR. ALI	-			
	ZONE	STG							STATUS	UPDATED DAT
JOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH NO	DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
JL1064	200	NRR	ΑI	25	777-53-916-00-01	G4 GALLEY L/H FWD VERTICAL BUMPER LO	WER AREA ATTACH SCREWS MISSING	L106	OPEN	09/20/2023
	CAB									1.0
									-	1.0
JL1072	200	LOG	AV	35			ADD A100: CABIN PORTABLE BREATHING EQUIPMENTS FOUND	L107	WIP	09/27/2023
	CAB					EXPIRED. SIX HAVE BEEN REPLACED TO SATISFY MEL REQUIREMENTS. REPLACEMENTS OF FIVE CABIN PBE DEFERRED TO HKG STATION. (PLS REF TO ATTACHED "CX DEFERRAL REPORT" FOR THE REQUIRED ACTION ITEMS)			0.0	
						1C 1 PLS MAKE LOG BOOK ENTR'	,			0.2
									-	0.2
IL1080	200	NRR	Al	25	777-53-920-00-01	M/D M LAV DOOR FRAME O/B EDGE SEAL FO	OUND DETACHED	L108	OPEN	09/20/2023
	CAB									1.0
									-	1.0
L1098	200	LOG	AV	23		AS PER CX B-KPV DEFERRAL REPORT ITEM	ADD A101: 23 COMMUNICATIONS,ON CHK FOUND VHF-R ANTENNA (LWR)	L109	OPEN	09/20/2023
CAB					VHF-L OPERATES NORMAL. ACTIONED IN AC	ERODEDTO ADD DUE TIME, VHF-R SYSTEM IS CONSIDERED INOP. CORDANCE WITH OTHER MEL 23-12-01 REV MAY23 (PLS REF TO			0.0	
					ATTACHED "CX DEFERRAL REPORT" FOR TH 1C 1 PLS MAKE LOG BOOK ENTR	,			0.2	
									-	0.2
JL1106	200	NRR	Al	25	777-53-920-00-01	M/D DOOR O/H PANEL ATTACH LANYARDS 1	OTAL 11EA BROKEN	L110	OPEN	09/20/2023
	CAB									1.0
									-	1.0
IL1114	200	NRR	Al	2524	777-C252420-01-04-	CABIN FB2 SEAT RETRACTABLE ARMREST I	FOUND STIFF TO OPERATE FROM 11A TO 22A TTL 12EA	L111	OPEN	09/20/2023
	CAB				01					44.0
									-	44.0
JL1122	200	NRR	Al	25	777-53-920-00-01	M/D M LAV FLOOR PAN I/B EDGE RETAINER	FOUND LOOSEN	L112	OPEN	09/20/2023
	CAB									1.0
									-	1.0
JL1130	200	NRR	Al	2524	777-C252420-01-04-	CABIN FB2 SEAT RETRACTABLE ARMREST I	OUND STIFF TO OPERATE FROM 22A TO 26A TTL 12EA	L113	OPEN	09/20/2023
	CAB				01	S. S DE GETT RETURN DEE / MWINEOTT	COLD CITE TO STATE THOM EDITION FOR THE LEET	LIIS	OFLIN	22.0
0/1									-	
										22.

ORIGINATING CUST REF NO:

515653

BMS571R1-2

ALL

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE: 15 OF 83 RUN DATE: 9/28/2023

3/20/2023

RUN TIME: 11:09

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL STATUS: ALL ORIG-STAGE: ALL PERIOD: ALL ESTIMATED MHR: ALL

ATA NO: ALL ZONE: ALL DISPOSITION CODE: ALL

DEFECT TYPE: ALL TRADE: ALL CUST ENDORSE: ALL AREA: ALL STAGE: ALL

CTRL CODE: TYPE CODE: ORIGINATOR: ALL

CIRL CODE.					TIPE CODE.	ORIGINATOR	A. ALL			
	ZONE	STG							STATUS	UPDATED DATE
JOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH NO	DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
(JL1148	200	NRR	Al	2524	777-C252420-01-04-	CABIN FB2 SEAT RETRACTABLE A	RMREST FOUND STIFF TO OPERATE FROM 11K TO 12K TTL 2EA	L114	OPEN	09/20/2023
	CAB				01					11.0
									-	11.0
JL1155	200	NRR	Al	25	777-53-920-00-01	M/D G6 GALLEY #7 COFFEE MAKE	R FOUND WATER LEAKING	L115	WIP	09/26/2023
	CAB									0.0
						1C 1 REPLACE COFFEE	MAKER			1.0
						1C 2 C/O COFFEE MAKI	ER FUNCTIONAL TEST			0.5
									-	1.5
JL1163	200	NRR	Al	2524	777-C252420-01-04-	CABIN FB2 SEAT RETRACTABLE A	RMREST FOUND STIFF TO OPERATE FROM 12K TO 26K TTL 14EA	L116	OPEN	09/20/2023
	CAB				01					38.5
									-	38.5
JL1171	200	NRR	Al	2524	777-C252420-01-05-	CABIN FB2 SEAT BACK SHELL NO	MEX TRIM FOUND DETACHED AT COLUMN D 15EA	L117	WIP	09/26/2023
	CAB				02					22.5
									-	22.5
(JL1189	200	NRR	Al	2524	777-C252420-01-05-	CABIN FB2 SEAT BACK SHELL NO	MEX TRIM FOUND DETACHED AT COLUMN G 13EA	L118	WIP	09/26/2023
	CAB				02					19.5
									-	19.5
JL1197	200	NRR	Al	2524	777-C252420-01-05-	CARIN FR2 SEAT BACK SHELL NO	MEX TRIM FOUND DETACHED AT COLUMN A 14EA	L119	WIP	09/26/2023
	CAB			202 .	01	ONDITT DE CENT BROKONELE NO	MEX. THIN GOLD DE PROTECT TO SOCIETY THE C	LII9	VVII	21.0
									-	
JL1205	200	NRR	Al	2524	777-C252420-01-05-	CADINI EDO CEAT DACIZ CUELL NO	MEX TRIM FOUND DETACHED AT COLUMN K 11EA		14/15	21.0
JL 1205	CAB	INICIA	AI	2524	01	CABIN FB2 SEAT BACK SHELL NO	MEX TRIM FOUND DETACHED AT COLUMN K TIEA	L120	WIP	09/26/2023
									_	16.5
										16.5
JL1213	200 CAB	NRR	Al	25	777-53-912-00-01	M/D #3 TO #4 DOOR L/H PARTITIO	N BABY BASSINET SCREWS FOUND LOOSEN	L121	OPEN	09/20/2023
	CAD									1.0
									-	1.0

REQUESTED BY:

REFERENCE NO:

DEFECT TYPE: ALL

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE: 16 OF 83

RUN TIME :

RUN DATE: 9/28/2023 11:09

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL

515653

BMS571R1-2

STATUS: ALL

ORIG-STAGE: ALL

ATA NO: ALL

PERIOD: ALL

ESTIMATED MHR: ALL

ORIGINATING CUST REF NO: ALL

ZONE: ALL CUST ENDORSE: ALL

AREA: ALL

DISPOSITION CODE: ALL STAGE: ALL

CTRL CODE:

TRADE: ALL TYPE CODE:

ORIGINATOR: ALL

ZONE STG JOB NO AREA TD ATA ORIG CUST REF NO. CTRL SH NO DEFECT DESCRIPTION XJL1221 200 NRR AI 25 777-53-912-00-01 M/D #3 TO #4 DOOR L/H PARTITION BABY BASSINET LOWER BUMPER FOUND MISSING CAB	JSN L122 L123	COMP	EST Mhr 09/25/2023 1.0 1.0 09/22/2023 0.0
			1.0 1.0 09/22/2023
CAB	L123	COMP	1.0
	L123	COMP	1.0 09/22/2023
	L123	COMP	09/22/2023
XJL1239 400 LOG AE 71 AS PER CX B-KPV DEFERRAL REPORT ITEM PADD P023: HTP T13 WORK ORDER (WO) / WORK CARD REF W/O			0.0
ENG 9571955/10 RAISE PADD TO PERFORM AN EDTO VERIFICATION FLT DUE TO FUEL & OIL SYSTEM DISTURBED ON BOTH ENGINES. PERFORM AN EDTO VERIFICATION FLIGHT DUE TO FUEL & OIL SYSTEM DISTURBED ON BOTH ENGINES.(CONTINUE TO SWS ITEM 1)			0.0
1C 1 ACTIONED IN ACCORDANCE WITH OTHER EEPM 3-1 REV AUG 2022. (PLS REF TO ATTACHED "CX DEFERRAL			0.0
REPORT" FOR THE REQUIRED ACTION ITEMS) 1C 2 PLS MAKE LOG BOOK ENTRY			0.2
			0.2
XJL1247 200 NRR AI 25 777-53-912-00-01 M/D #3 TO #4 DOOR R/H PARTITION 1EA MAGAZINE RACK FOUND BROKEN	L124	OPEN	09/20/2023
CAB			1.0
			1.0
XJL1254 200 NRR AI 25 777-53-912-00-01 M/D #3 TO #4 DOOR CTR PARTITION 1EA MAGAZINE RACK FOUND BROKEN	L125	OPEN	09/20/2023
CAB			1.0
			1.0
XJL1262 200 NRR AI 25 777-53-916-00-01 G4L GLY LOWER COMPT AFT TIE DOWN COVER FOUND DETACHED	L126	OPEN	09/20/2023
CAB			1.0
			1.0
XJL1270 200 NRR AI 25 777-53-916-00-01 G4L GLY L4-11.L4-12 COMPT CTR PARTITION 2EA TURN BUTTON FOUND STIFF	L127	OPEN	09/20/2023
CAB			1.0
			1.0
XJL1288 200 NRR AI 25 777-53-916-00-01 G4L GLY 421 COMPT LOWER EDGE TURN BUTTON FOUND STIFF	L128	OPEN	09/20/2023
CAB			1.0
			1.0
XJL1296 200 NRR AI 25 777-53-916-00-01 G4R GLY R4-12 ICE DRAWER TRAY FOUND LOOSEN	L129	OPEN	09/20/2023
CAB			2.0
			2.0

0PPC DISTRIBUTION:

ORIGINATING CUST REF NO:

515653

BMS571R1-2

ALL

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

17 OF 83 PAGE: RUN DATE: 9/28/2023

RUN TIME : 11:09

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL STATUS: ALL ORIG-STAGE: ALL PERIOD: ALL ESTIMATED MHR: ALL

> ATA NO: ALL ZONE: ALL DISPOSITION CODE: ALL

TRADE: ALL DEFECT TYPE : ALL CUST ENDORSE: ALL AREA: ALL STAGE: ALL

CTRL CODE: TYPE CODE: ORIGINATOR: ALL

CIRL CODE:					TYPE CODE:	ORIGINATOR: ALL			
	ZONE	STG						STATUS	UPDATED DATE
JOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH NO DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
XJL1304	200	NRR	Al	25	777-53-916-00-01	G4R GLY R4-31.R4-21 COMPT DOOR TURN BUTTON FOUND MALFUNCTION	L130	OPEN	09/20/2023
	CAB								2.0
								-	2.0
XJL1312	200	NRR	Al	25	777-53-916-00-01	G4R GLY FWD EQUIPMENT RACK HANDLE FOUND CRACKED	L131	OPEN	
AULIUIZ	CAB	MAX	711	20	777-30-310-00-01	OHN GETT WE EQUIT WEIGHT PAORETIANDEET GOING GRACKED	LIST	OPEN	09/20/2023
								_	1.0
									1.0
XJL1320	200	NRR	Al	25	777-53-916-00-01	G4R GLY AFT O/B EDGE SEAL LOOSEN	L132	OPEN	09/20/2023
	CAB								2.0
								-	2.0
XJL1338	400	LOG	AV	29		AS PER CX B-KPV DEFERRAL REPORT ITEM PADD P024: REFER_TL REFER TO TL ITEM REF TL3501, BOTH ENG	L133	OPEN	09/20/2023
	ENG					FADEC SOFTWARE VERSION A.0.8.6 INSTALLATION. PADD RAISED TO CALL OUT EDTO VERIFICATION FLIGHT AS PER			0.0
						CX EDTO POLICY. ACTIONED IN ACCORDANCE WITH OTHER AEO-29704 REV 00. (PLS REF TO ATTACHED "CX DEFERRAL REPORT" FOR THE REQUIRED ACTION ITEMS)			
						1C 1 PLS MAK LOG BOOK ENTRY.			0.2
								-	0.2
XJL1346	400	LOG	SS	72		AS PER CX B-KPV DEFERRAL REPORT ITEM SADD S087: ***THIS TASK TO C/OUT REPAIR AS TERMINATIVE	L134	WIP	09/23/2023
	ENG					ACTION***#2 ENGINE FAN BLADES #1, #14 AND #17 HAVE CONCAVE SURFACE COATING LOSS AND BLADES #14 AND #17 HAVE METAL TIP CAP EXPOSED. #2 ENGINE FAN BLADES #1 #14 AND #17 INSPECTED WITHIN AMM 72-21-02			0.0
						LIMITS.(CONTINUE TO SWS ITEM 1)			
						1C 1 NIL DISBOND ON METAL TIP CAPS OF BLADES #14 AND #17 TO SADD FOR COATING REPAIR OR REPEAT INSPECTION WITHIN 150 CYCLES IAW AMM 72-21-02 REV JAN 20. (PLS REF TO ATTACHED "CX DEFERRAL REPORT"			0.0
						FOR THE REQUIRED ACTION ITEMS)			
						1C 2 PLS MAKE LOG BOOK ENTRY			0.2 4.0
						2C 3 REMOVE THE FAN ROTOR SPINNER ASSY 2C 4 REMOVE THE SUBJECT FAN BLADES			4.0 6.0
						2C 5 DO AN INSPECTION TO THE REMOVAL FAN BLADES			2.0
						2C 6 INSTALL REMOVAL THE SUBJECT FAN BLADES			8.0
						3C 7 INSTALL REMOVAL FAN ROTOR SPINNER ASSY			6.0
						3C 8 PERFORM LPT VIBRATION SURVEY			2.0
						4C 9 PERFORM FAN BLADE TIP CLEARANCE INSPECTION			16.0
						TEN GRAIT/ARBEIDE III GEENWAGE INGI EGITON		-	
XJL1353	200	NRR	Al	2524	777-C252420-01-05-	CABIN FB2 SEAT SHELL RETRACTABLE TABLE FOUND STIFF TO OPERATE AT COLUMN A	1.405	ODEN	44.2
AULIUUU	CAB	INIXIX	ΑI	202 4	01	OADIN 1 DZ DEN I DILEE NETIVACIADEE TADEET OCIND STILL TO OPERATE AT COLUNINA	L135	OPEN	09/20/2023
								_	35.0
									35.0

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE: 18 OF 83

RUN DATE: 9/28/2023

0.2

RUN TIME : 11:09

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL

BMS571R1-2

515653

STATUS: ALL

ORIG-STAGE: ALL

CUST ENDORSE: ALL

PERIOD: ALL

ESTIMATED MHR: ALL

ORIGINATING CUST REF NO:

ALL

ATA NO: ALL

ZONE: ALL AREA: ALL

DISPOSITION CODE: ALL STAGE: ALL

DEFECT TYPE: ALL CTRL CODE:

TRADE: ALL

TYPE CODE: ORIGINATOR: ALL

TINE CODE .	ZONE	STG			THE CODE.				STATUS	UPDATED DATE
JOB NO	AREA	010	TD	ATA	ORIG CUST REF NO.	CTRL SH NO	DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
XJL1361	200 CAB	NRR	Al	2524	777-C252420-01-05-	CABIN FB2 SEAT SHELL RETRACTABLE TABLE	E FOUND STIFF TO OPERATE AT COLUMN K	L136	OPEN	09/20/2023
	CAB								-	32.5
(JL1379	200 CAB	NRR	Al	2524	777-C252420-01-05- 01	CABIN FB2 SEAT SHELL RETRACTABLE TABLE	E FOUND STIFF TO OPERATE AT COLUMN D	L137	OPEN	09/20/2023
	0.1.5								-	32.5
(JL1387	200	NRR	AI	2524	777-C252420-01-05-	CABIN FB2 SEAT SHELL RETRACTABLE TABLE	E FOUND STIFF TO OPERATE AT COLUMN G	L138	OPEN	09/20/2023
	CAB				01				-	32.5
(JL1395	200	LOG	SS	25		AS PER CX B-KPV DEFERRAL REPORT ITEM	SADD S110: HTP T13 WORK ORDER (WO) / WORK CARD REF W/O 9571960	L139	OPEN	32.5 09/20/2023
	CAB			6FC'S AFTER OCTOBER 7, 2022 UNTIL DECEM	ERFORM AEO-27666 PART-2 AND AEO-27669 PART 2 NO LATER THAN IBER 31, 2024. THE 6 FLIGHT CYCLES WILL BE FERRY FLIGHTS WITH NO			0.0		
	PASSENGERS ONBOARD. AFTER EMBODIMENT OF THE MODICATION AS PER (CONTINUE TO SWS ITEM 1) 1C 1 AEO-27666 PART 2 AND AEO-27669 PART 2. CLEAR SADD RAISED AGAINST THIS AEO PART 1. XFRD TO SADD AS PER INSTRUCTIONS IN AEO- 29541 REV 00 ACTIONED IN ACCORDANCE WITH AMM 25-11-01 REV 05 MAY 2023.(PLS REF TO ATTACHED "CX DEFERRAL REPORT" FOR THE REQUIRED ACTION ITEMS)			0.0						
						1C 2 PLS MAKE LOG BOOK ENTRY	,		-	0.2
(JL1403	200	NRR	AI	2524	777-C252420-01-05-	CABIN FB2 SEAT SHELL PTV ARM HARD TO (OPERATE AT 19D-26D 24A 22A 16A 12A 11A 12G 11K 18G 21G 22G 24G 25G	L140	WIP	0.2
021100	CAB	1414	, ,	2021	01	26G 17K 18K 19K 21K 22K 23K	7 EVVIETN 105 E05 E 11 EEU VON 12 V VIV 120 V IV 100 E 10 EEU E 10 E00	L140	VVIF	72.8
									-	72.8
JL1411	200	LOG	Al	25			SADD S112: HTP T13(WO)REPLACEMENT OF EMERGENCY ESCAPE /O: 9571786/1 P/N: 62771-128 S/N: 2039 ACTIONED IAW AMM 25-66-01 REV	L141	OPEN	09/20/2023
	CAB						RES. ACTIONED IAW AMM 25-66-01 REV 05 MAY 2023.(PLS REF TO			0.0
						1C 1 PLS MAKE LOG BOOK ENTRY			_	0.2
										0.2
JL1429	200 CAB	LOG	Al	25			SADD S113: HTP T13 WORK ORDER (WO) / WORK CARD REF W/O 9571787 SCAPE SLIDE ASSEMBLY. XFRD TO SADD DUE TO NIL SPARES.	L142	OPEN	09/20/2023
CAB					ACTIONED IAW AMM 25-65-01 REV 05 MAY 2023.(PLS REF TO ATTACHED "CX DEFERRAL REPORT" FOR THE REQUIRED ACTION ITEMS)				0.0	
						1C 1 PLS MAKE LOG BOOK ENTRY				0.2

ORIGINATING CUST REF NO:

515653

BMS571R1-2

ALL

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE: 19 OF 83

ESTIMATED MHR: ALL

RUN DATE: 9/28/2023

RUN TIME : 11:09

0.2

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

STATUS: ALL ORIG-STAGE: ALL PERIOD: ALL JSN RANGE SELECTED: ALL

> ATA NO: ALL DISPOSITION CODE: ALL ZONE: ALL

DEFECT TYPE: ALL TRADE: ALL CUST ENDORSE: ALL AREA: ALL STAGE: ALL

CTRL CODE : TYPE CODE: ORIGINATOR ·

7										
2	ONE S	STG							STATUS	UPDATED DATE
JOB NO A	REA		TD	ATA	ORIG CUST REF NO.	CTRL SH NO	DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
	00 I AB	LOG	Al	25		EMERGENCY ESCAPE SLIDE ASSEM	ORT ITEM SADD S114: HTP T13 REF W/O: 9571788/1 REPLACEMENT OF OFF-WING MBLY. XFRD TO SADD DUE TO NIL SPARES. ACTIONED IAW AMM 25-65-01 REV 05	L143	OPEN	09/20/2023
					MAY 2023. LH OFF WING SLIDE RAFT DETAILS: P/N: 5A3109-1 S/N: ST0958(PLS REF TO ATTACHED "CX DEFERRAL REPORT" FOR THE REQUIRED ACTION ITEMS) 1C 1 PLS MAKE LOG BOOK ENTRY.				0.2	
									-	0.2
XJL1445 20	00 I	LOG	Al	25			ORT ITEM SADD S115:HTP T13 (WO) REF W/O: 9571790 /1 REPLACEMENT OF	L144	OPEN	09/20/2023
С	AB						L4. XFRD TO SADD DUE TO NIL SPARES ACTIONED IAW AMM 25-66-01 REV 05 -339 S/N M8187 (PLS REF TO ATTACHED "CX DEFERRAL REPORT" FOR THE			0.0
						1C 1 PLS MAKE LOG BOO	OK ENTRY.			0.2
									-	0.2
		LOG	Al	25		AS PER CX B-KPV DEFERRAL REPO EMERGENCY ESCAPE SLIDE/RAFT	ORT ITEM SADD S116: HTP T13 (WO) REF W/O: 9571791 /1REPLACEMENT OF	L145	OPEN	09/20/2023
C	CAB				XFRD TO SADD DUE TO NIL SPARES	S. ACTIONED IAW AMM 25-66-01 REV 05 MAY 2023. L5 SLIDE RAFT DETAILS: P/N: TACHED "CX DEFERRAL REPORT" FOR THE REQUIRED ACTION ITEMS)			0.0	
						1C 1 PLS MAKE LOG BOX	,			0.2
									-	0.2
		LOG	Al	25			ORT ITEM SADD S117: REF W/O: 9571792 /1 REPLACEMENT OF EMERGENCY ID TO SADD DUETO NIL SPARE. ACTIONED IAW AMM	L146	OPEN	09/20/2023
С	AB						/RAFT DETAILS: P/N: 65344-428 S/N: 0274(PLS REF TO ATTACHED "CX DEFERRAL			0.0
						1C 1 PLS MAKE LOG BOO	OK ENTRY.			0.2
									-	0.2
	00 l AB	LOG	Al	25			ORT ITEM SADD S118: HTP T13 (WO) REF W/O: 9571794 /1 REPLACEMENT OF L2. XFRD TO SADD DUE TO NIL SPARE. ACTIONED IAW AMM 25-66-01 REV 05 MAY	L147	OPEN	09/20/2023
C	,AD						2771-127 S/N: M8984(PLS REF TO ATTACHED "CX DEFERRAL REPORT" FOR THE			0.0
						1C 1 PLS MAKE LOG BOO	OK ENTRY.			0.2
									•	0.2
	00 l SAB	LOG	Al	25)RT ITEM SADD S119: HTP T13 WORK ORDER (WO) / WORK CARD REF W/O: ENCY ESCAPE SLIDE/RAFT -R4. R4 SLIDE RAFT DETAILS: P/N: 63604-324 S/N: 0034	L148	OPEN	09/20/2023
C	,AD						5 MAY 2023.(PLS REF TO ATTACHED "CX DEFERRAL REPORT" FOR THE			0.0
						1C 1 PLS MAKE LOG BOO	DK ENTRY			0.2

515653

BMS571R1-2

REQUESTED BY:

REFERENCE NO:

DEFECT TYPE: ALL

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

AREA: ALL

PAGE:

RUN TIME :

STAGE: ALL

20 OF 83

RUN DATE: 9/28/2023 11:09

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL STATUS: ALL ORIG-STAGE: ALL PERIOD: ALL ESTIMATED MHR: ALL

ORIGINATING CUST REF NO: ATA NO: ALL ZONE: ALL DISPOSITION CODE: ALL ALL CUST ENDORSE: ALL

TYPE CODE: CTRL CODE : ORIGINATOR · ALL

TRADE: ALL

CTRL CODE:					TYPE CODE:	OF	riginator : All	-							
	ZONE	STG								STATUS	UPDATED DATE				
JOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH NO		DEFECT DESCRIPTION	JSN	STATUS	EST Mhr				
XJL1494	200	NRR	SS	25	777-53-904-00-01	CABIN F/C SEAT PAR	TIITON AISLE TEDLAR F	OUND SCEATCHED AT 1D 2D(TOTAL 2EA)	L149	WIP	09/23/2023				
	CAB										0.0				
							OVE F/C SEAT PARTITIO	N SIDE BUMPER 1D 2D			1.0				
								JMPER 1D 2D TEDLAR REPLACE			22.0				
						1C 3 REINS	STALL F/C SEAT PARTIT	TION SIDE BUMPER 1D 2D			1.0				
										-	24.0				
XJL1502	200	LOG	AV	33				SADD S120: OB2 9 ITEM NOT FOUND IN FAULT TREE (REFER TO	L150	OPEN	09/20/2023				
	CAB					OFAR BACK-UP LIGHT	TING POWER PACKS-TO 33-29-10 REV 05 MAY 20	OFAR) CAN'T BE USED. AMS 33-115-00 FUNCTIONALLY CHK OFCR & / OR DE PERFORMED NO LATER THAN NEXT REVENUE FLIGHT. TO SADD 23.(PLS REF TO ATTACHED "CX DEFERRAL REPORT" FOR THE			0.0				
							MAKE LOG BOOK ENTRY	<i>1</i> .			0.2				
										-	0.2				
XJL1510	200	NRR	Al	2524	777-C252420-01-05-	CABIN FB2 SEAT SHE	ELL O/B SIDE GAP COVE	R PANEL FOUND DISCOLOUR AT COLUMN A	L151	WIP	09/26/2023				
	CAB				01		2.0.	•••	14.0						
										-	14.0				
XJL1528	200	NRR	AI	2524	777-C252420-01-05-	CADIN FD2 CFAT CUF		ER PANEL FOUND DISCOLOUR AT COLUMN K	1.450						
AJL 1320	CAB		NIXI AI 2024	711 2024	711 2024	1 2024	2024	2324	01	CABIN FB2 SEAT SHE	ELL U/B SIDE GAP COVE	R PANEL FOUND DISCOLOUR AT COLUMN K	L152	WIP	09/26/2023
	0712										13.0				
										-	13.0				
XJL1536	200	LOG	AV	52				SADD S121: OB2 9 ITEM NOT FOUND IN FAULT TREE (REFER TO	L153	OPEN	09/20/2023				
	CAB					,		ER WING DOOR EPAS BATTERY NEED TO REPLACE.(PLS REF TO E REQUIRED ACTION ITEMS)			0.0				
							MAKE LOG BOOK ENTRY	,			0.2				
										-	0.2				
XJL1544	200	LOG	AV	52		AS PER CX B-KPV DE	FERRAL REPORT ITEM	SADD S122: OB2 9 ITEM NOT FOUND IN FAULT TREE (REFER TO	L154	OPEN	09/20/2023				
	CAB							3.3 OVER WING DOOR BACKUP BATTERY NEED TO REPLACE (PLS REF TO			0.0				
							RRAL REPORT" FOR TH MAKE LOG BOOK ENTRY	E REQUIRED ACTION ITEMS) (.			0.2				
								-	0.2						
XJL1551	200	LOG	AV	52		AC DED OV D I/DI/ DE	CEDDAL DEDORTITEM	SADD S123: OB2 9 ITEM NOT FOUND IN FAULT TREE (REFER TO							
AJL 100 I	CAB	LOG	AV	52				SADD S123. OB2 9 TIEM NOT FOUND IN FAULT TREE (REFER TO).3 RIGHT OVER WING EPAS BATTERY NEED TO REPLACE. (PLS REF TO	L155	OPEN	09/20/2023				
	OAD					ATTACHED "CX DEFE	RRAL REPORT" FOR TH	E REQUIRED ACTION ITEMS)			0.0				
						1C 1 PLS M	MAKE LOG BOOK ENTRY	1			0.2				
										-	0.2				

515653

BMS571R1-2

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE: 21 OF 83

RUN DATE: 9/28/2023

RUN TIME: 11:09

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL STATUS: ALL ORIG-STAGE: ALL PERIOD: ALL ESTIMATED MHR: ALL

ORIGINATING CUST REF NO: ALL ATA NO: ALL ZONE: ALL DISPOSITION CODE: ALL

DEFECT TYPE : ALL TRADE : ALL CUST ENDORSE : ALL AREA : ALL STAGE : ALL

CTRL CODE : TYPE CODE: ORIGINATOR : ALL

TRL CODE :					TYPE CODE:		ORIGINATOR: ALL			
	ZONE	STG							STATUS	UPDATED DA
JOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH N	NO DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
XJL1569	200	NRR	SS	25	777-53-904-00-01	CABIN F/C	SEAT BACK SHELL AISLE S/W FOUND SCEATCHED AT 1K 2K 1D 2D 1A 2A(TOTAL 6 EA)	L156	WIP	09/23/2023
	CAB									0.0
						1C 1	REMOVE F/C SEAT PARTITION AISLE BUMPER 1K 2K 1D 2D 2A 1A			2.0
						1C 2	REMOVE F/C SEAT PARTITION AISLE LIGHT 1K 2K 1D 2D 2A 1A			2.0
						1C 3	F/C SEAT PARTITION AISLE BUMPER 1K 2K 1D 2D 2A 1A TEDLAR REPLACE			60.0
						1C 4	REINSTALL F/C SEAT PARTITION AISLE BUMPER 1K 2K 1D 2D 2A 1A			2.0
						2C 5	REINSTALL F/C SEAT PARTITION AISLE LIGHT 1K 2K 1D 2D 2A 1A			2.0
									-	68.0
KJL1577	200	LOG	AV	52			B-KPV DEFERRAL REPORT ITEM SADD S124: OB2 9 ITEM NOT FOUND IN FAULT TREE (REFER TO	L157	OPEN	09/20/2023
	CAB					,	S PER CX WO/TASK 9571811/1 NO.3 RIGHT OVERWING DOOR BACKUP BATTERY NEED TO REPLACE.(PLS) TO REPLACE.(PLS		0.0
						1C 1	FACHED "CX DEFERRAL REPORT" FOR THE REQUIRED ACTION ITEMS) PLS MAKE LOG BOOK ENTRY.			0.2
									-	0.2
JL1585	100	LOG	Al	38		AS DED CY	B-KPV DEFERRAL REPORT ITEM SADD S126: HTP T13 (WO) REF W/O: 9571955/10 BOTTLE WATER UPLIFT	L158	OPEN	09/20/2023
JL 1303	LWR	LOG	Ai	30			POTABLE WATER SYSTEM-DISINFECTANT TO BE PERFORMED IN HKG. DON'T USE POTABLE WATER FOR	L158	OPEN	
	LVVIX						. TOILET FLUSH REMAINS SERVICEABLE. BOTTLE WATER UPLIFT REQUIRED. POTABLE WATER			0.0
							ECTANT TO BE PERFORMED IN HKG. (CONTINUE TO SWS ITEM 1)			
						1C 1	DON'T USE POTABLE WATER FOR BEVERAGE.			0.0
							TOILET FLUSH REMAIN SERVICEABLE. ACTIONED IAW AMM 38-10-00-600-801 REV 05 MAY 2023.(PLS REF TO ATTACHED "CX DEFERRAL REPORT" FOR THE REQUIRED ACTION			
							ITEMS)			
						1C 2	PLS MAKE LOG BOOK ENTRY			0.2
									-	0.2
JL1593	200	NRR	SS	25	777-53-904-00-01		SEAT MEAL SIDE DOOR TEDLAR FOUND SCRATCHED AT K1 .1D .(M3)AFT .(M1)AFT. 1A. (M2)AFT (TOTAL 6	L159	WIP	09/23/2023
	CAB					EA)				0.0
						1C 1	REMOVE F/C SEAT COMPT DOOR 1K 1D (M3)AFT (M1)AFT (M1)AFT 1A			2.0
						1C 2	REMOVE F/C SEAT COMPT DOOR LIGHT 1D			0.5
						1C 3	F/C SEAT COMPT DOOR 1K 1D (M3)AFT (M1)AFT (M2)AFT 1A TEDLAR REPLACE			60.0
						1C 4	REINSTALL F/C SEAT COMPT DOOR 1K 1D (M3)ADT (M1)AFR (M2)AFT 1A TOTAL 6 WA			2.0
						2C 5	REINSTALL F/C SEAT COMPT DOOR LIGHT 1D			0.5
									-	65.0

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE: 22 OF 83

RUN DATE: 9/28/2023 RUN TIME : 11:09

PROJECT: XJ

CUSTOMER: CX

A/C REGN: B-KPV

ATA NO: ALL

CHECK TYPE: 2C

ESTIMATED MHR: ALL

JSN RANGE SELECTED: ALL ORIGINATING CUST REF NO: ALL

STATUS: ALL

ORIG-STAGE: ALL PERIOD: ALL

DISPOSITION CODE: ALL

DEFECT TYPE: ALL

515653

BMS571R1-2

TRADE: ALL

A/C TYPE: 777

CUST ENDORSE: ALL

STAGE: ALL

ZONE: ALL

AREA: ALL

CTRL CODE :	TYPE CODE:		ΛII
		ORIGINATOR:	
			ALL

	ZONE	STG							STATUS	UPDATED DATE
JOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH NO	D DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
XJL1601	400 ENG	LOG	AE	71		PRESERVED	-KPV DEFERRAL REPORT ITEM SADD S127: HTP T13 (WO) , ENGINE 1 REF W/O 9571955 /16 ENG #1 IDG ON WING. REMOVE IDG FOR SHOP VISIT WITHIN MAXIMUM OF 25 FLIGHT HOURS. SADD RAISED. W AMM 24-11-01 REV 05 MAY 2023.(PLS REF TO ATTACHED "CX DEFERRAL REPORT" FOR THE	L160	WIP	09/23/2023
						1C 1	PLS MAKE LOG BOOK ENTRY.			0.2
						2C 2	DISCONNECT NO.1 ENG IDG ELECTRICAL CONNECTOR.			2.0
						2C 3	REPLACE NO.1 ENG IDG.			16.0
						2C 4	RECONNECT NO.1 ENG IDG ELECTRICAL CONNECTOR.			4.0
						2C 5	C/O IPI FOR IDG OIL SVC.			2.0
						3C 6	C/O OPERATIONAL TEST FOR RH IDG.			1.0
						3C 7	C/O OPERATIONAL TEST FOR RH IDG.			1.0
						3C 8 3C 9	CARRY OUT IPI PROCEDURE OF NO.1 ENG IDG FEEDER CABLE INSTALLATION C/O PART-POWER LEAK CHECK			0.5 1.0
									-	27.7
XJL1619	200	NRR	SS	25	777-53-904-00-01	CABIN F/C SI	EAT PARTITION POST TEDLAR FOUND TORN AT (M1)FWD/ AFT ,(M3)FWD/AFT TOTAL 4 EA	L161	WIP	09/26/2023
	CAB									0.0
									-	0.0
XJL1627	200	NRR	SS	25	777-53-904-00-01		EAT MEAL TABLE PNL TEDLAR FOUND SCRATCHED AT 2A 2D 1D 2K 1K(TOP SIDE)2A 1A 2D 2K SIDE) TOTAL 10 EA	L162	WIP	09/26/2023
	CAB					TI (BOTTOW)				40.0
									-	40.0
XJL1635	200	NRR	SS	2500	777-53-904-00-01	CABIN F/C S/	AET FWD LITERATURE SHROUD SURFACE TEDLAR FOUND SCRATCHED AT 2A 1D 2D 1K 2K TOTAL 5EA	L163	WIP	09/23/2023
	CAB									0.0
						1C 1	REMOVE F/C SEAT LITERATURE SHRPUD 1K 2K 1D 2D 2A			1.0
						1C 2	F/C SEAT MAGAZINE COVER 1K 2K 2A 1D 2D TEDLAR REPLACE			50.0
						1C 3	REINSTALL F/C SEAT LITERATURE SHROUD 1K 2K 2A 1D 2D			1.0
									-	52.0
XJL1643	200	NRR	SS	2500	777-53-920-00-01	CAB-G8 GLY	L/H AND R/H S8-01 COMPT DR TEDLAR FND DENT.	L164	WIP	09/25/2023
	CAB									0.0
						1C 1	REMOVE G8 GLY LOWER DOOR S8-01.			0.5
						1C 2	G8 GLY LOWER DOOR S8-01 TEDLAR REPLACE			16.0
						1C 3	REINSTALL G8 GLY LOWER DOOR S8-01.			0.5
									-	17.0

515653

BMS571R1-2

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE: 23 OF 83

RUN DATE: 9/28/2023

RUN TIME: 11:09

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL STATUS: ALL ORIG-STAGE: ALL PERIOD: ALL ESTIMATED MHR: ALL

ORIGINATING CUST REF NO: ALL ATA NO: ALL ZONE: ALL DISPOSITION CODE: ALL

DEFECT TYPE: ALL TRADE: ALL CUST ENDORSE: ALL AREA: ALL STAGE: ALL

CTRL CODE: TYPE CODE: ORIGINATOR: ALL

CTRL CODE:					TYPE CODE:		ORIGINATOR:	ALL			
	ZONE	STG								STATUS	UPDATED DATE
JOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH NO		DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
XJL1650	200	NRR	SS	2500	777-53-904-00-01	CAB #1 DOOR	S1 STOWAGE FWD B/HE	AD TEDLAR FOUND SCRATCHED	L165	WIP	09/23/2023
	CAB										0.0
						1C 1	REMOVE S1 STOWAGE	FWD B/HEAD BUMPER			0.5
						1C 2	REMOVE S1 STOWAGE	FWD B/HAED LIGHT			0.5
						1C 3	REINSTALL S1 STOWAG	GE FWD B/HAED BUMPER			0.5
						1C 4	REINSTALL S1 STOWAG	GE FWD B/HAED LIGHT			0.5
						2C 5	S1 STOWAGE FWD B/H	AED TEDLAR REPLACE			11.0
										-	13.0
KJL1668	400	LOG	AE	71				ITEM SADD S128: HTP T13 WORK ORDER (WO) / WORK CARD, ENGINE 2 REF	L166	WIP	09/25/2023
	ENG					HOURS. SADD		'ED ON WING. REMOVE IDG FOR SHOP VISIT WITHIN MAXIMUM OF 25. FLIGHT AMM 24-11-01 REV 05 MAY 23(PLS REF TO ATTACHED "CX DEFERRAL REPORT"			0.0
						1C 1	PLS MAKE LOG BOOK E	ENTRY.			0.2
								G IDG ELECTRICAL CONNECTOR.			2.0
						2C 3	REPLACE NO.2 ENG ID				16.0
						2C 4		GIDG ELECTRICAL CONNECTOR.			4.0
						2C 5	C/O IPI FOR IDG OIL SV				2.0
						3C 6	C/O OPERATIONAL TES	ST FOR RH IDG.			1.0
						3C 7	C/O OPERATIONAL TES	ST FOR RH IDG.			1.0
						3C 8	CARRY OUT IPI PROCE	DURE OF NO.2 ENG IDG FEEDER CABLE INSTALLATION			0.5
						3C 9	C/O PART-POWER LEA	K CHECK			1.0
										-	27.7
(JL1676	200	NRR	SS	2500	777-53-904-00-01	CAB-G1C GLY	C-102 C-103 COMPT DR	TEDLAR FND DENT	L167	WIP	09/23/2023
	CAB										0.0
						1C 1	REMOVE G1C GLY C-10	02 C103 COMPT DOOR			0.5
						1C 2	G1C GLY C-102 C-103 C	COMP DOOR TEDLAR REPLACE			12.0
						1C 3	REINSTALL G61C GLY	C-102 C-103 COMPT DOOR			1.0
										-	13.5

ORIGINATING CUST REF NO:

515653

BMS571R1-2

ALL

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE: 24 OF 83

RUN TIME :

ESTIMATED MHR: ALL

RUN DATE: 9/28/2023

11:09

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL STATUS: ALL ORIG-STAGE: ALL PERIOD: ALL

ATA NO: ALL ZONE: ALL DISPOSITION CODE: ALL

DEFECT TYPE: ALL TRADE: ALL CUST ENDORSE: ALL AREA: ALL STAGE: ALL

CTRL CODE: TYPE CODE: ORIGINATOR: ALL

CIRL CODE:					TYPE CODE:			ORIGINATOR: ALL			
	ZONE	STG								STATUS	UPDATED DATI
JOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTR	L SH NO	D DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
(JL1684	400	LOG	ΑE	71		AS I	PER CX E	-KPV DEFERRAL REPORT ITEM SADD S129:HTP T13 WORK ORDER (WO) / WORK CARD, ENGINE 1 REF	L168	WIP	09/23/2023
	ENG							/ 16 ENG# 1 BUG PRESERVED ON WING. REMOVE FOR SHOP VISIT WITHIN MAXIMUM 25 HRS. SADD			0.0
								ONED IAW AMM 24-25-01 REV 01 MAY 23. (PLS REF TO ATTACHED "CX DEFERRAL REPORT" FOR THE			0.0
						REQ 1C	UIRED A	CTION ITEMS) PLS MAKE LOG BOOK ENTRY.			0.2
						2C	2	DISCONNECT THE NO.1 ENG BUG ELECTRICAL CONNECTOR.			2.0
						2C	3	REPLACE NO.1 ENG BUG.			12.0
						2C	4	RECONNECT NO.1 ENG BUG THE ELECTRICAL CONNECTOR.			3.0
						2C	5	C/O IPI FOR NO.1 ENG BUG OIL SVC.			2.0
						3C	6	C/O NO.1 ENG PART-POWER LEAK CHECK.			1.0
						3C	7	DO THE NO.1 BUG INSTALLATION TEST.			1.0
						3C	8	TRANSFER TERMINAL BLOCK ADAPTER FROM OLD TO NEW BACKUP GENERATOR			2.0
						3C	9	C/O IPI PROCEDURE FOR NO.1 BACKUP GENERATOR PHASE LEADS			0.5
								0.0 1.1.1.00.2.501.2.1 0.1.101.1 0.1.12.1.1.101.1 1.1.1.1.1.1.1.1.1.1.1.1.1.1.1		-	
											23.7
JL1692	400	LOG	ΑE	71				-KPV DEFERRAL REPORT ITEM SADD S130: HTP T13 WORK ORDER (WO) / WORK CARD, ENGINE 2 REF	L169	WIP	09/25/2023
EN	ENG							/ 16 ENG# 2 BUG PRESERVED ON WING. REMOVE FOR SHOP VISIT WITHIN MAXIMUM 25 HRS. SADD			0.0
								ONED IAW AMM 24-25-01 REV 05 MAY 2023.(PLS REF TO ATTACHED "CX DEFERRAL REPORT" FOR THE CTION ITEMS)			
						1C	1	PLS MAKE LOG BOOK ENTRY.			0.2
						2C	2	DISCONNECT THE NO.2 ENG BUG ELECTRICAL CONNECTOR.			2.0
						2C	3	REPLACE NO.2 ENG BUG.			16.0
						2C	4	RECONNECT NO.2 ENG BUG THE ELECTRICAL CONNECTOR.			3.0
						2C	5	C/O IPI FOR NO.2 ENG BUG OIL SVC.			2.0
						3C	6	C/O NO.2 ENG PART-POWER LEAK CHECK.			1.0
						3C	7	DO THE NO.2 BUG INSTALLATION TEST.			1.0
						3C	8	TRANSFER TERMINAL BLOCK ADAPTER FROM OLD TO NEW BACKUP GENERATOR			2.0
						3C	9	C/O IPI PROCEDURE FOR NO.2 BACKUP GENERATOR PHASE LEADS			0.5
										-	27.7
(JL1700	200	NRR	SS	2500	777-53-904-00-01	CAE	#1 DOO	R G1L GALLEY AFT B/HEAD TEDLAR FOUN DENT	L170	WIP	09/23/2023
	CAB										0.0
						1C	1	REMOVE G1L GLY AFT B/HEAD PNL			0.5
						1C	2	REBOND G1L GLY AFT B/HEAD PNL TEDLAR REPLACE			11.0
						1C	3	REINSTALL G1L GLY AFT B/HEAD PNL			0.5
										-	
											12.0

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE: 25 OF 83 RUN DATE: 9/28/2023

STATUS

STATUS

WIP

RUN TIME : 11:09

UPDATED DATE

0.0 1.0

11.0 1.0

EST Mhr

09/23/2023

PROJECT: XJ

REQUESTED BY:

REFERENCE NO:

CUSTOMER: CX

A/C TYPE: 777

A/C REGN: B-KPV

PERIOD: ALL

ZONE: ALL

CHECK TYPE: 2C

ESTIMATED MHR: ALL

JSN

L171

JSN RANGE SELECTED: ALL ORIGINATING CUST REF NO: ALL

STATUS: ALL

ATA NO: ALL

DISPOSITION CODE: ALL

DEFECT TYPE: ALL

515653

BMS571R1-2

TRADE: ALL TYPE CODE:

CUST ENDORSE: ALL

ORIG-STAGE: ALL

ORIGINATOR: ALL

AREA: ALL STAGE: ALL

CTRL CODE:

JOB

XJL1

	ZONE	STG					
3 NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH NO	DEFECT DESCRIPTION
1718	200 CAB	NRR	SS	25	777-53-904-00-01	CABIN F/C SEAT CLOSET COMPT DOOR TEDLAR FOUND SCE	ATCHED AT M3

1C	1	REMOVE F/C SEAT CLOSET COMPT DOOR
1C	2	F/C SEAT CLOSET COMPT DOOR (M3)TEDLAR REPLACE

	_	.,,
1C	3	REINSTALL F/C SEAT CLOSET COMPT DOOR

1C	3	REINSTALL F/C SEAT CLOSET COMPT DOOR

XJL1726	200	LOG	SS	25	AS PER CX B-KPV DEFERRAL REPORT ITEM SADD S131: HTP T13(WO) REF W/O 9571960 TO PERFORM AE
	CAB				PART-1&AEO-27669 PART 1 NO LATER THAN 6 FC AFT OCTOBER 7 2022 UNTIL DECEMBER 31, 2024.6 FLIGH
					WILL BE FERRY FLIGHTS WITH NO PLOSENOFRS ON BOARD. AFT EMPORIMENT OF MODIFICATION AS DEF

								13.0
XJL1726	200 CAB	LOG	SS	25	PART-1&AEO-27669 PART 1 NO LATER THAN 6 FC AFT OCTOBER 7 2022 UNTIL DECEMBER 31, 2024.6 FLIGHT CYCLES WILL BE FERRY FLIGHTS WITH NO PASSENGERS ONBOARD. AFT EMBODIMENT OF MODIFICATION AS PER AEO-27666 PART Q,& AEO-27669 PART 1, CLEAR SADD RAISED AGAINST THIS AEO PART 1. (CONTINUE TO SWS ITEM 1)	L172	OPEN	09/20/2023
					1C 1 SADD RAISED AS PER INSTRUCTIONS IN AEO 29541 REV 00. ACTIONED IAW OTHER AEO-29541 REV REV 00.(PLS REF TO ATTACHED "CX DEFERRAL REPORT" FOR THE REQUIRED ACTION ITEMS)			0.0
					1C 2 PLS MAKE LOG BOOK ENTRY.			0.2
								0.2
XJL1734	100	LOG	ΑI	26	AS PER CX B-KPV DEFERRAL REPORT ITEM SADD S133: OB2 9 ITEM NOT FOUND IN FAULT TREE (REFER TO	L173	OPEN	09/20/2023
	LWR				REMARK) WO NO : 9571803/1 C/O REPLACEMENT OF CGO COMPARTMENT FIRE EXTINGUISHING BOTTLES SQUIB CARTRIDGES FOR BOTTLE 2A SERIAL NO: 1610BA PART NO : 473876-3 AS PER AMS LIST ACTIONED IAW AMM 26-23-01 REV 05 MAY 2023.(PLS REF TO ATTACHED "CX DEFERRAL REPORT" FOR THE REQUIRED ACTION ITEMS)			0.0
					1C 1 PLS MAKE LOG BOOK ENTRY.			0.2
					2C 2 REMOVE THE FIRE BOTTLE SQUIB			1.0
					2C 3 DISCONNECT THE ELECTRICAL CONNECTOR OF FIRE BOTTLE SQUIB			0.5
					2C 4 CONNECT THE ELECTRICAL CONNECTOR OF FIRE BOTTLE SQUIB			0.5
					2C 5 INSTALL THE FIRE BOTTLE SQUIB			1.0
					3C 6 CARRY OUT CARGO FIRE EXTINGUISHING SQUIBS OPERATIONAL TEST			1.0
								4.2
XJL1742	100	LOG	ΑI	26	AS PER CX B-KPV DEFERRAL REPORT ITEM SADD S134: OB2 9 ITEM NOT FOUND IN FAULT TREE (REFER TO	L174	OPEN	09/20/2023
	LWR				REMARK) WO NO : 9571801/1 C/O REPLACEMENT OF CARGO COMPARTMENT FIRE EXTINGUISHER BOTTLES SQUIB CARTRIDGE FOR 2D SERIAL NO : 1544BA PART NO: 473876-3 AS PER AMS LIST ACTIONED IAW AMM 26-23-01 REV 05			0.0

XJL1742	100	LOG	Al	26

MAY 2023.(PLS REF TO ATTACHED "CX DEFERRAL REPORT" FOR THE REQUIRED ACTION ITEMS) 1C PLS MAKE LOG BOOK ENTRY.

2C	2	REMOVE THE FIRE BOTTLE SQUIB
2C	3	DISCONNECT THE ELECTRICAL CONNECTOR OF FIRE BOTTLE SQUIB
2C	4	CONNECT THE ELECTRICAL CONNECTOR OF FIRE BOTTLE SQUIB

2C 5 INSTALL THE FIRE BOTTLE SQUIB 3C 6

CARRY OUT CARGO FIRE EXTINGUISHING SQUIBS OPERATIONAL TEST

1.0

0.2 1.0 0.5 0.5

515653

BMS571R1-2

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE: 26 OF 83 RUN DATE: 9/28/2023

RUN TIME :

11:09

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

STATUS: ALL PERIOD: ALL JSN RANGE SELECTED: ALL ORIG-STAGE: ALL ESTIMATED MHR: ALL

ATA NO: ALL DISPOSITION CODE: ALL ORIGINATING CUST REF NO: ALL ZONE: ALL

DEFECT TYPE: ALL TRADE: ALL CUST ENDORSE: ALL AREA: ALL STAGE: ALL

CTDL CODE TYPE CODE ODICINIATOD .

CTRL CODE:					TYPE CODE:	ORIGINATOR: ALL				
	ZONE	STG							STATUS	UPDATED DATE
JOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH NO	DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
XJL1759	500	NRM	AE	5708	AEO-28656-01	LHW FUEL TANK ACCESS DOORS 532AB GASKET FOUND W	ORN	L175	OPEN	09/20/2023
	F/T									1.0
									-	1.0
XJL1767	200	NRR	SS	2500	777-53-904-00-01	CABIN PARTITION R/H LOWER SURFACE FOUD SCRATHED		L176	OPEN	09/20/2023
AGETTOT	CAB	MINIX	00	2000	777-00-004-00-01	CADIN FARTHON WITEOWER SUNFACE FOOD SCHAFFIED		LI/O	OPEN	
									_	8.0
										8.0
XJL1775	600	NRM	ΑE	5700	AEO-28656-02	RHW FUEL TANK ACCESS DOORS632AB GASKET FOUND W	ORN	L177	OPEN	09/20/2023
	F/T									1.0
									-	1.0
XJL1783	200	NRR	SS	2500	777-53-908-00-01	CABIN #2 DOOR G3 GLY R/H AISLE S/W FOUND SCRATCHED		L178	WIP	09/24/2023
	CAB									0.0
						1C 1 REMOVE G3 GLY RHS AISLE LIGHT				0.5
						1C 2 REMOVE G3 GLY RHS AISLE PNL				1.0
						1C 3 G3 GLY RHS AISLE TEDLAR REPLACE				11.0
						1C 4 REINSTALL G3 GLY RHS AISLE PNL				1.0
						2C 5 REINSTALL G3 GLY RHS AISLE LIGHT				0.5
									-	14.0
XJL1791	200	NRR	Al	2531	777-53-908-00-01	CABIN G2 GALLERY COMPARTMENT 203 LOWER GUIDE BUI	MPER FOUND DAMAGE	L179	OPEN	09/20/2023
	CAB									5.0
									-	5.0
V II 4800	200	NRR	SS	2500	777-53-908-00-01	CARIN #2 DOOR C2D CLV L/LLAICLE CAM FOLIND CCDATCLE				
XJL1809	200 CAB	NKK	55	2500	777-53-908-00-01	CABIN #2 DOOR G2R GLY L/H AISLE S/W FOUND SCRATCHE	עו	L180	WIP	09/23/2023
	OAB					1C 1 REMOVE G2R GLY LHS AISLE PNL				0.0 0.5
						1C 1 REMOVE G2R GLY LHS AISLE PNL 1C 2 REMOVE G2RGLY LHS AISLE LIGHT				0.5
						1C 3 G2RGLY LHS AISLE TEDLAR REPLACE				11.0
						1C 4 REINSTALL G2R GLY LHS AISLE PNL				0.5
										0.5
						2C 5 REINSTALL G2R GLY LHS AISLE LIGHT				0.5
									-	13.0

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE: 27 OF 83 RUN DATE: 9/28/2023

16. 3/20/2020

RUN TIME : 11:09

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL STATUS: ALL

ORIG-STAGE: ALL

ESTIMATED MHR: ALL

ORIGINATING CUST REF NO: ALL

515653

BMS571R1-2

STATUS. ALL

ATA NO: ALL ZONE: ALL

PERIOD: ALL

AREA: ALL

DISPOSITION CODE: ALL

DEFECT TYPE : ALL

CTRL CODE:

TRADE : ALL TYPE CODE:

CUST ENDORSE: ALL ORIGINATOR: ALL

STAGE: ALL

STATUS	UPDATED DATE

	ZONE	STG							STATUS	UPDATED DATE
JOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH NO	DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
XJL1817	200 CAB	NRR	SS	2500	777-53-920-00-01	CAB-G7 GLY G702 COMPT DR TEDLAR FNE	DIDENT.	L181	WIP	09/25/2023
	0.12					1C 1 REMOVE G7 GLY 702 COM	PT DOOR			0.0 0.5
						1C 2 G7 GLY 702 COMPT DOOR				6.0
						1C 3 REINSTALL G7GLY 702 COI	MPT DOOR			0.5
									-	7.0
XJL1825	100	LOG	Al	26			M SADD S135: OB2 9 ITEM NOT FND IN FAULT TREE (REF REMARK)WO NO : INGUISHING FLOW VALVE FOR SQUIB CARTRIDGE REPLACE SERIAL:2186	L182	OPEN	09/20/2023
	LWR					PART :446347-1 FWD CGO LOCATION-FWD	PN-446347-1, SN-2186 MEL RAISED AS PER AMS LIST ACTIONED IAW AMM TACHED "CX DEFERRAL REPORT" FOR THE REQUIRED ACTION ITEMS)			0.0
						1C 1 PLS MAKE LOG BOOK ENTI	RY.			0.2
									-	0.2
XJL1833	200	NRR	Al	2531	777-53-908-00-01	CABIN G3 GALLERY 301 RH LOWER MATEL	TRIM FOUND MISSING	L183	OPEN	09/20/2023
	CAB									5.0
									-	5.0
XJL1841	100	NRR	AE	5300	777-53-800-00-09	FUSELAGE LOWER HALF TOTAL 15 EA DRA	AIN VALVE AGED	L184	OPEN	09/20/2023
	FUS									2.0
									-	2.0
XJL1858	100	LOG	Al	26			M SADD S136:OB2 9 ITEM NOT FND IN FAULT TREE WO NO: 9571799/1 C/O	L185	WIP	09/22/2023
	LWR					446347-1 FWD CGO LOCATION-AFT PN-4463	AFT FLOW VALVE FOR SQUIB CARTRIDGE REPLACE SERIAL: 2187 PART : 347-1 SN-2187 MEL RAISED AS PER AMS LIST. ACTIONED IAW AMM 26-23-02 "CX DEFERRAL REPORT" FOR THE REQUIRED ACTION ITEMS)			0.0
						1C 1 PLS MAKE LOG BOOK ENTI	,			0.2
									-	0.2
XJL1866	600	LOG	AE	27			M SADD S138:OB2 9 ITEM NOT FOUND IN FAULT TREE (REFER TO REMARK)	L186	COMP	09/23/2023
	WNG						R AUXILIARY RETRACT DEVICE (SARD) PYROTECHNIC CARTRIDGE NEED DEFERRAL REPORT" FOR THE REQUIRED ACTION ITEMS)			0.0
						1C 1 PLS MAKE LOG BOOK ENTI	RY.			0.2
									-	0.2
XJL1874	200	NRR	SS	2500	777-53-908-00-01	CAB #2 DOOR S1R UPPER B/HEAD TEDLAF	R FOUND SCRATCHED	L187	WIP	09/26/2023
	CAB									10.0
									-	10.0

515653

BMS571R1-2

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

AREA: ALL

PAGE: 28 OF 83

ESTIMATED MHR: ALL

STAGE: ALL

RUN DATE : 9/28/2023

RUN TIME: 11:09

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL STATUS: ALL ORIG-STAGE: ALL PERIOD: ALL

ORIGINATING CUST REF NO: ALL ATA NO: ALL ZONE: ALL DISPOSITION CODE: ALL

DEFECT TYPE: ALL TRADE: ALL CUST ENDORSE: ALL

CTRL CODE : TYPE CODE: ORIGINATOR : ALL

STILL CODE.	ZONE	STG			THE GODE.		ONOMATOR. ALL		STATUS	UPDATED DATI
JOB NO	AREA	0.0	TD	ATA	ORIG CUST REF NO.	CTRL SH N	D DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
(JL1882	500	LOG	AE	27			SE-KPV DEFERRAL REPORT ITEM SADD S139: 275 022 02 FLAP/SLAT CONTROL 2 (STATUS) EARLY IN	L188	WIP	09/22/2023
	WNG					LATCHED. N	EL APPLIED DUE TIME. MAINT PROCEDURE CARRIED OUT IAW AMM27-00-00 REV SEP23. (PLS REF TO CX DEFERRAL REPORT" FOR THE REQUIRED ACTION ITEMS)			0.0
						1C 1	PLS MAKE LOG BOOK ENTRY.			0.2
						2C 2	PERFORM T/S AS			2.0
						2C 3	C/O WIRING CHECK SLAT PRIMARY CONTROL VALVE V27003 RESISTANCE CHECK			2.0
						3C 4	DISCONNECT THE ELECTRICAL CONNECTORS			0.5
						3C 5	REMOVE THE LEFT WHEEL WELL SLAT PRIMARY CONTROL VALVE V27003			6.0
						3C 6	INSTALL THE LEFT WHEEL WELL SLAT PRIMARY CONTROL VALVE V27003			8.0
						3C 7	CONNECT THE ELECTRICAL CONNECTORS FOR THE SLAT PRIMARY CONTROL VALVE			1.0
						4C 8	CARRY OUT BONDING TEST BETWEEN THE VALVE ASSEMBLY AND STRUCTURE			1.0
						4C 9	CARRY OUT SLAT PRIMARY CONTROL VALVE TEST		_	2.0
										22.7
(JL1890 100 FUS	NRR	AV	3100	777-53-832-00-01	PLEASE DIS	CONNECT AND CONNECT THE LOWER BODY ANTI-COLLISION LIGHT CONNECTIONS FOR ACCESS	L189	WIP	09/25/2023	
					1C 1	DISCONNECT CONNECTOR OF LOWER ANTI-COLLISION LIGHT			0.0 1.0	
						1C 1	RECONNECT CONNECTOR OF LOWER ANTI-COLLISION LIGHT			1.0
						1C 2	PERFORM TEST OF LOWER ANTI-COLLISION LIGHT			0.5
						10 0	TEN ON TEN OF ESTERNITH OSCEDIONEIGH		-	2.5
										2.5
(JL1908	200	NRR	SS	25	777-53-912-00-01	CABIN FB2	EAT PARTITION SIDE CONSOLE AREA TEDLAR BUBBLE AT 11G 26K 26D 11K 18K TOTAL 5 EA	L190	WIP	09/23/2023
	CAB									0.0
						1C 1	REMOVE FB2 SEAT PARTITION SIDE CONSOLE AREA BUMPER 11G 26G 26D 11K 18K TOTAL 5 EA			2.0
						1C 2	FB2 SEAT PARTITION SIDE CONSOLE AREA BUMPER 11G 11K 26K 26D 11K 18K TEDLAR REPLACE			50.0
						1C 3	REINSTALL FB2 SEAT PARTITION SIDE CONSOLE AREA BUMPER 11G 26G 26D 11K 18K			2.0
									-	54.0
JL1916	200	LOG	AV	33			S-KPV DEFERRAL REPORT ITEM SADD S140:353 101 -1 PORTABLE OXYGEN DISPENSING UNITS	L191	OPEN	09/20/2023
	CAB					R3, L4, R4, L DATE TO 15	SKS) REF Z242 PORTABLE OXY CYLINDER 9EA AT LOCATIONS R1, L2, L3(2EA), &R5 FND EXPIRED. TO SADD DUE TO SPARE N/S, EXPIRED POB&MASK 9EA WERE REMOVED. ADD BACK EP23. ACTIONED IAW OTHER MEL 35-31-01 REV MAR23. (PLS REF TO ATT "CX DEFERRAL REPORT" FOR ED ACTION ITEMS)			0.0
						1C 1 PLS MAKE LOG BOOK ENTRY.				0.2
									-	0.2

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE: 29 OF 83 RUN DATE: 9/28/2023

RUN TIME :

11:09

PROJECT: XJ

515653

BMS571R1-2

CUSTOMER: CX

A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

ESTIMATED MHR: ALL

JSN RANGE SELECTED: ALL ORIGINATING CUST REF NO: ALL

STATUS: ALL

ORIG-STAGE: ALL PERIOD: ALL

ZONE: ALL

AREA: ALL

DISPOSITION CODE: ALL

DEFECT TYPE: ALL

CTRL CODE:

TRADE: ALL

CUST ENDORSE: ALL TYPE CODE: ORIGINATOR: ALL

ATA NO: ALL

STAGE: ALL

STATUS UPDATED DATE

	ZONE	STG								STATUS	UPDATED DATE
JOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTR	L SH N	O DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
XJL1924	200 CAB	NRR	SS	2500	777-53-904-00-01	CAE	B-CLOSE	T S2CR-01 COMPT DR TEDLAR FND DENT.	L192	WIP	09/23/2023
						1C	1	REMOVE CLOSET S2CR -01COMPT DOOR			0.5
						1C	2	CLOSET S2CR-01 COMPT DOOR TEDLAR REPLACE			6.0
						1C	3	REINSTALL CLOSET S2CR-01 COMPT DOOR			0.5
										-	7.0
XJL1932	100 FUS	NRP	AV	3831	777-53-545-01-01	PLE	EASE DIS	CONNECT AND CONNECT THE FUS LOWER FWD DRAIN MAST CONNECTIONS FOR ACCESS	L193	WIP	09/27/2023
	FU3					1C	4	DISCONNICAT THE ELECTRICAL ORLIGE CONNICATIONS TO THE DRAIN MACE			0.0
						1C	1 2	DISCONNECT THE ELECTRICAL SPLICE CONNECTIONS TO THE DRAIN MAST DISCONNECT THE DRAIN HOSE FROM THE DRAIN MAST			0.0 0.5
						1C	3	DISCONNECT THE DRAIN HOSE FROM THE DRAIN WAST DISCONNECT THE THE GROUND CONNECTION AND BONDING JUMPER TO STRUCTURE			0.5
						1C	4	CONNECT THE THE GROUND CONNECTION AND BONDING JUMPER TO STRUCTURE			0.5
						2C	5	CONNECT THE DRAIN HOSE FROM THE DRAIN MAST			0.5
						2C	6	CONNECT THE ELECTRICAL SPLICE CONNECTIONS TO THE DRAIN MAST			2.0
						2C	7	CHECK THAT THE RESISTANCE BETWEEN THE BONDING JUMPER TERMINAL AND THE STRUCTURE DOES NOT EXCEED 1. MILLIOHMS			0.5
						2C	8	APPLY THE SEALANT TO BONDING JUMPER TERMINAL			0.5
						3C	9	MAKE SURE THAT THE WATER FLOWS FROM THE FORWARD DRAIN MAST WITHOUT LEAKAGE			0.5
						3C	10	DO DRAIN MAST AND GRAY WATER DRAIN LINE HEATERS OPERATIONAL TEST			0.5
										-	6.0
XJL1940	100 LWR	NRR	Al	5234	777-52-190-00-01	FWI	D CGO D	OOR ROTARY ACTUATOR FOUND NOISY	L194	OPEN	09/20/2023
	LVVIX					40	4	DEMONE THE ANDRO DOTADY ANTHATODO			0.0
						1C 1C	1 2	REMOVE FWD CARGO ROTARY ACTUATORS			6.0
						1C	3	INSTALL FWD CARGO ROTARY ACTUATORS			6.0 10.0
						1C	4	DO THE LIFT MECHANISM ADJUSTMENT CARRY OUT FWD CARGO ROTARY ACTUATORS INSTALLATION TEST			2.0
						10	4	CARRY OUT FWD CARGO ROTART ACTUATORS INSTALLATION TEST		-	
V II 4057	000	100	A) /	00			DED 01/1	A VEN MATTER TO STUDY TAKE OF OUR AREST MATTER AT THE AREA TO MATTER AS INSTALLED MATTER AS INSTALLED MATTER AS			24.0
KJL1957	200	LOG	AV	26				3-KPV NOTICE TO FLIGHT AND GROUND CREW NTC001:THIS AIRCRAFT IS INSTALLED WITH 2 CREW LINDERS. (AEO-26231: OXYGEN - CREW OXYGEN SYSTEM - INSTALLATION OF ADDITIONAL CREW	L195	COMP	09/26/2023
	CAB							LINDER HAS BEEN EMBODIED.			0.2
										-	0.2
KJL1965	200	LOG	AV	11				3-KPV NOTICE TO FLIGHT AND GROUND CREW NTC002: AEO-27365 INCORPORATED THE GOGO 2KU	L196	COMP	09/26/2023
	CAB					CON	NECTIVI	TY RADOME STC HKCAD STC-2018-11 (FAA STC ST04240CH) ON THIS AIRCRAFT.			0.2
										-	0.2
											0.2

515653

BMS571R1-2

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE:

RUN TIME :

30 OF 83

RUN DATE: 9/28/2023 11:09

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL STATUS: ALL ORIG-STAGE: ALL PERIOD: ALL ESTIMATED MHR: ALL

ORIGINATING CUST REF NO: ATA NO: ALL ZONE: ALL DISPOSITION CODE: ALL ALL

DEFECT TYPE: ALL TRADE: ALL CUST ENDORSE: ALL AREA: ALL STAGE: ALL

TDI 0005					T) /DE 00DE	ODIONIATOD ALL									
TRL CODE :	ZONE	STC			TYPE CODE:	ORIGINATOR: ALL			STATUS	UPDATED DATE					
JOB NO	AREA	316	TD	ATA	ORIG CUST REF NO.	CTRL SH NO	DEFECT DESCRIPTION	JSN	STATUS	EST Mhr					
JL1973	200	NRR	PT	5121	777-53-908-00-01	M/D 1-5# DOOR FUSELAGE EDGE FND PAINT CH		L197	WIP	09/27/2023					
	CAB							2.0.		30.0					
									-	30.0					
JL1981	200	NRR	PT	2500	777-53-904-00-01	M/D B/C SEAT UPPER AROUND BUMPER SURFA	CE FND PAINT CHIPPED TTI 19FA	L198	OPEN	09/20/2023					
	CAB							L130	OI LIV	54.0					
									-						
JL1999	200	LOG	AV	12		AS DED CY B KDV NOTICE TO ELIGHT AND CDOL	IND CREW NTC003:AEO-27365 INCORPORATED THE GOGO 2KU	1.400	COMP	54.0					
JL 1999	CAB	200	AV	12		CONNECTIVITY CABIN STC HKCAD STC-2018-12 (L199	COMP	09/26/2023					
									-						
II 2005	200	NRR	PT	E404	777 52 000 00 04	M/D 4.5// DOOD EDAME EDOE END DAINT OURDE	TD TTL 40FA			0.2					
JL2005	200 CAB	NKK	ы	5121	777-53-908-00-01	M/D 1-5# DOOR FRAME EDGE FND PAINT CHIPPE	ED TIL:10EA	L200	WIP	09/27/2023					
									_	20.0					
										20.0					
JL2013	200 CAB	NRR	PT	2525	777-53-908-00-01	C/A SEAT SURFACE FND CHIPPED AT: 1#DOOR	5#DOOR TTL: 16EA	L201	OPEN	09/20/2023					
	CAB								_	8.0					
										8.0					
JL2021	200	NRR	PT	2500	777-53-904-00-01	M/D L/R 1 DOOR HINGE COVER FND PAINT CHIP	TTL:2EA	L202	WIP	09/27/2023					
	CAB									4.0					
									-	4.0					
IL2039	200	NRR	PT	5121	777-53-908-00-01	M/D ENTER DOORS FITTING FND FND PAINT CHI	P TTL:10EA	L203	OPEN	09/20/2023					
	CAB									10.0					
									-	10.0					
JL2047	200	LOG	Al	56			IND CREW NTC004: L1 WINDSHIELD HAS SCARTCH ON INNER PANE	L204	OPEN	09/20/2023					
	CAB					ABOUT 2/3 DOWN FROM THE TOP, ABOUT 2 INCE VISION IS NOT IMPAIRED.	ES IN LENGTH & LESS THAN 0.001 INCH IN DEPTH. WITHIN LIMITS /			0.2					
									-	0.2					
IL2054	200	LOG	AE	25			IND CREW NTC006: BOTH ENGINE OIL TYPE HAS BEEN CHANGED	L205	COMP	09/22/2023					
	CAB		AE	20		FROM MOBIL JET II TO ET02197 POST THE ACCOMPLISHMENT OF AEO-25935.		· · · · · · · · · · · · · · · · · · ·	0.2						
				O, 1D										-	0.2

515653

BMS571R1-2

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE: 31 OF 83

RUN DATE: 9/28/2023

RUN TIME : 11:09

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL STATUS: ALL ORIG-STAGE: ALL PERIOD: ALL ESTIMATED MHR: ALL

ORIGINATING CUST REF NO: ATA NO: ALL ZONE: ALL DISPOSITION CODE: ALL ALL

DEFECT TYPE: ALL TRADE: ALL CUST ENDORSE: ALL AREA: ALL STAGE: ALL

CTRL CODE :					TYPE CODE:	ORIGINATOR: ALL																			
	ZONE	STG							STATUS	UPDATED DATE															
JOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH NO	DEFECT DESCRIPTION	JSN	STATUS	EST Mhr															
XJL2062	500	LOG	AE	28			ND CREW NTC007: MAIN FUEL TANK WATER SCAVENGE SYSTI		COMP	09/22/2023															
	F/T					SB 777-28-0078 REV 02.	EM HAVE BEEN MODIFIED PER AEO-19540 ISSUED AGAINST BC	EING		0.2															
									-	0.2															
(JL2070	200	LOG	LOG AI 56	AI 56			ND CREW NTC008: R2 WINDOW DELAMINATED LWR FWD CORI	IER 3" L207	OPEN	09/20/2023															
	CAB					X 0.5" VISION NOT IMPAIRED.				0.2															
												0.2													
(JL2088	2088 200 LOG AI 5	56			ND CREW NTC009: L2 WINDOW DELAMINATED ALL FWD EDGE	L208	OPEN	09/20/2023																	
	CAB					APPROX 0.5" WIDE VISION NOT IMPAIRED.				0.2															
									-	0.2															
(JL2096	200	LOG AI 25	OG AI 25	G AI 25	Al 25		AS PER CX B-KPV NOTICE TO FLIGHT AND GROUND CREW NTC010: THIS AIRCRAFT IS FITTED WITH THE ETECH AS THE MASTER MAINTENANCE RECORD. THE IPAD EFB DEVICE IS STORED IN THE AML/CDML. THE PAPER	LOG L209	WIP	09/27/2023															
	CAB						AD EFB DEVICE IS STORED IN THE AME/COME. THE PAPER ONLY. COMPLY 365 IS INSTALLED IN BOTH FLIGHT DECK IPAD	AND		0.2															
									-	0.2															
(JL2104	200	LOG	Al	25			ND CREW NTC011: ACTIVE NTC/NTCC ENTRIES HAVE BEEN	L210	COMP	09/22/2023															
	CAB																			MIGRATED FROM PAPER TO E-TECHLOG WHICH IS NOW THE PRIMARY MEANS TO CONSULT NTC/NTCC ON THIS AIRCRAFT TAIL. PAPER COPIES IN AML/CDML SHALL BE USED DURING PAPER FALLBACK ONLY. (REF : AEO-28695)			0.2		
									-	0.2															
KJL2112	200	LOG	AV	25	25	25	25	25	25	25	25	25	25	25	25	25	25	25	25			ND CREW NTC012: SB777-22A0046/AEO-29595 AFCS S/W	L211	WIP	09/26/2023
	CAB						THIS SB CANCELS FCOM OMB CAT-136 ERRONEOUS AFDS CURS. THIS NTC IS VALID UNTIL 1 MONTH AFTER ALL AIRCRAF	TS		0.2															
									-	0.2															
KJL2120	200	LOG	AV	31			ND CREW NTC013: AEO-29174/SB 777-31A0342 EMBODIED ON T	LZ 1Z	COMP	09/26/2023															
	CAB					AIRCRAFT, REFER TO FON "AIMS-2 BLOCK POINT V17C INTRODUCTION". THIS NTC IS VALID UNTIL FLEET UPGRAD COMPLETED.		IDE		0.2															
									-	0.2															
(JL2138	200	LOG	AV	23			ND CREW NTC014: THE AIRCRAFT/ENGINES HAVE BEEN EQUIP	PED L213	OPEN	09/20/2023															
CAB					WITH NEW FADEC SOFTWARE P/N 730A-GECA08-	06 (A.U.8.6) REF SB 777-73-0037/AEO-29704.			0.2																
								-	0.2																

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE: RUN DATE: 9/28/2023

RUN TIME :

32 OF 83

11:09

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL

ZONE STG

515653

BMS571R1-2

STATUS: ALL

ORIG-STAGE: ALL

PERIOD: ALL

ESTIMATED MHR: ALL

ORIGINATING CUST REF NO:

ALL

ATA NO: ALL

ZONE: ALL

DISPOSITION CODE: ALL

DEFECT TYPE : ALL CTRL CODE:

TRADE: ALL TYPE CODE:

CUST ENDORSE: ALL ORIGINATOR: ALL

AREA: ALL STAGE: ALL

STATUS	UPDATED DATE

	ZONL	316								
JOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH NO	DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
XJL2146	200 CAB	LOG	Al	25		ETECHLOG AS THE MASTER MAIN	GHT AND GROUND CREW NTCC001: THIS AIRCRAFT IS FITTED WITH THE TENANCE RECORD. THE IPAD EFB DEVICE IS STORED IN THE AML/CDML. THE NBOARD AS A BACKUP ONLY. COMPLY 365 IS INSTALLED IN BOTH FLIGHT DECK ATIONAL MANUALS.	L214	WIP	09/27/2023
									-	0.2
XJL2153	200 CAB	LOG	Al	28		MIGRATED FROM PAPER TO E-TE	SHT AND GROUND CREW NTCC002:ACTIVE NTC/NTCC ENTRIES HAVE BEEN CHLOG WHICH IS NOW THE PRIMARY MEANS TO CONSULT NTC/NTCC ON THIS AML/CDML SHALL BE USED DURING PAPER FALLBACK ONLY. (REF : AEO-28695)	L215	WIP	09/27/2023 0.2
						AIRCRAFT TAIL. PAPER COPIES IN	AMILICUME SHALL BE USED DURING PAPER FALLBACK UNLT. (REF. AEC-20099)		-	0.2
XJL2161	200	LOG	AV	23		AS DED CY R-KDV NOTICE TO ELI	GHT AND GROUND CREW NTCC501: WHEN WI-FI CONNECTIVITY ISSUE REPOR TED	L216	COMP	0.2
XXLZTVT	CAB	200	Av	20		BY PAX, REFER TO GOGO SYSTEM CCM/SP TABLET. GREEN BAR INDI		L210		0.2
									-	0.2
XJL2179	200	NRR	ΑI	2500	777-53-908-00-01	CABIN G3 GALLERY COMPARTME	NT 311 BOTTOM BUMPERS FOUND CRACKED	L217	OPEN	09/21/2023
	CAB									3.0
									-	3.0
XJL2187	600	NRR	GW	5700	777-57-980-02-01	RHW #7 FIXED FAIRING 676BB SC	REW (2EA) FOUND SEIZED	L218	COMP	09/26/2023
	WNG									2.0
									-	2.0
XJL2195	600	NRR	GW	5700	777-57-984-02-01	RHW #8FIXED FAIRING 677DREW	(3EA) FOUND SEIZED	L219	COMP	09/26/2023
	WNG									3.0
									-	3.0
XJL2203	600	NRR	SM	5700	777-57-984-02-01	RHW #8FIXED FAIRING 677DR (3E	A) ANCHOR NUT FOUND WORN	L220	OPEN	09/21/2023
	WNG									1.5
									-	1.5
XJL2211	600	NRR	SM	5700	777-57-980-02-01	RHW #7 FIXED FAIRING 676BB AN	CHOR NUT (2EA) FOUND WORN	L221	OPEN	09/21/2023
	WNG									1.0
									-	1.0

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE: 33 OF 83

RUN TIME :

RUN DATE: 9/28/2023

11:09

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL

515653

BMS571R1-2

STATUS: ALL

ORIG-STAGE: ALL

ESTIMATED MHR: ALL

ORIGINATING CUST REF NO: ALL

ATA NO: ALL

PERIOD: ALL ZONE: ALL

DISPOSITION CODE: ALL

DEFECT TYPE: ALL

TRADE: ALL

CUST ENDORSE: ALL

AREA: ALL STAGE: ALL

CTRL CODE:

TYPE CODE:

ORIGINATOR: ALL

OTATLIO	LIDDATED DATE

IOP NO	ZONE AREA	STG	TD	ATA	ODIC CUST DEF NO	CTRL SH NO DEFECT DESCRIPTION	JSN	STATUS STATUS	UPDATED DATE EST Mhr
JOB NO XJL2229	500	NRR	AE	2780	ORIG CUST REF NO. 777-57-806-01-01	MANUAL RETRACT L/E SLAT FOR T/R MAINTENANCE(WITHOUT ELEC POWER)			
AJLZZZ9	WNG	INKK	AE	2/00	777-57-600-01-01	MANUAL RETRACT LIE SLAT FOR TIR MAINTENANCE (WITHOUT ELEC POWER)	L222	WIP	09/24/2023
	******					1C 1 REMOVE SLAT ELECTRICAL MOTOR			0.0 0.0
						1C 1 REMOVE SLAT ELECTRICAL MOTOR 1C 2 DISCONNECT L/E SLAT ELEC PLUG			0.0
						1C 3 MANUAL RETRACT L/E SLAT			0.0
						1C 4 EXTENDED L/E SLAT			0.0
						2C 5 REINSTALL L/E SLAT MOTOR			0.0
						2C 6 RECONNECT SLAT MOTOR ELEC PLUG			0.0
						2C 7 C/O L/E SLAT SYSTEM TEST			0.0
								-	0.1
XJL2237	600	NRR	CL	5711	777-57-984-02-01	RHW (#5~8)FLAP TRACK AND FAIRING INTERNAL FOUND DIRTY	L223	WIP	09/27/2023
	WNG								18.0
								-	18.0
XJL2245	200	NRR	PT	2500	777-53-904-00-01	COCKPIT OBSERVER SEAT HANDRAIL SURFACE AND SIDE STOWAGE FOUND PAINT PEEL OFF	L224	OPEN	09/21/2023
	CAB								4.0
								-	4.0
XJL2252	500	NRR	CL	57	777-57-892-01-01	LHW (#1~4)FLAP TRACK AND FAIRING INTERNAL FOUND DIRTY	L225	WIP	09/27/2023
	WNG								18.0
								-	18.0
XJL2260	200	NRR	Al	25	777-53-916-00-01	G4.G5 GALLEY PLACARD FOUND TORN	L226	OPEN	09/21/2023
AULLEUU	CAB		,	20	777 00 010 00 01	G.33 GILLETT BIOTHET ONE FORM	L220	OPEN	2.0
								_	
V II 0070	000	NDD		0.5	777 50 000 00 04	ON OT ONLIEVE AGADE FOUND TODA			2.0
XJL2278	200 CAB	NRR	Al	25	777-53-920-00-01	G6.G7 GALLEY PLACARD FOUND TORN	L227	OPEN	09/21/2023
	O/ LD							_	2.0
									2.0
XJL2286	500	NRR	CL	5700	777-57-868-01-01	LHW SPOILER LOWER SURFACE &T/E CAVITY FOUND DIRTY	L228	WIP	09/23/2023
	WNG								20.0
								-	20.0

515653

REQUESTED BY:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

PAGE :

34 OF 83

RUN DATE: 9/28/2023

REFERENCE NO: BMS571R1-2 (By JSN) RUN TIME: 11:09

PROJECT: XJ	CUSTOMER: CX	A/C TYPE: 777	A/C REGN: B-KPV	CHECK TYPE :	2C
-------------	--------------	---------------	-----------------	--------------	----

JSN RANGE SELECTED: ALL STATUS: ALL ORIG-STAGE: ALL PERIOD: ALL ESTIMATED MHR: ALL ORIGINATING CUST REF NO: ALL ZONE: ALL DISPOSITION CODE: ALL

DEFECT TYPE: ALL TRADE: ALL CUST ENDORSE: ALL AREA: ALL STAGE: ALL

CTRL CODE : TYPE CODE: ORIGINATOR : ALL

				TYPE CODE:	ORIGINATOR: AL	-			
ZONE	STG							STATUS	UPDATED DATE
AREA			ATA	ORIG CUST REF NO.	CTRL SH NO	DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
	NRR	AV	2331	777-23-010-00-01	PERFORMED ALL TEST FOUND L CTR LATTI	CE ABOVE ROW 64 SDM 5-2 DOES NOT RESPOND	L229	WIP	09/27/2023
CAB									2.0
								-	2.0
200	NRR	ΑI	25	777-53-916-00-01	G5 GALLEY OVEN2.OVEN4.OVEN5 LOWER A	REA BUMPER CRACKED	L230	OPEN	09/21/2023
CAB									6.0
								-	6.0
600	NRR	CL	5700	777-57-960-02-01	RHW SPOILER LOWER SURFACE & T/E CAV	TY FOUND DIRTY	L231	WIP	09/23/2023
WNG									20.0
								-	20.0
200	NRR	ΑI	25	777-53-916-00-01	G5 GLY 505 COMPT TURN RETAINER FOUNI	MALFUNCTION	L232	WIP	09/28/2023
CAB									1.0
								-	1.0
200	NRR	ΑI	25	777-53-916-00-01	G5 GALLEY AFT BABY BASSINET SCREWS L	OOSEN	L233	OPEN	09/21/2023
CAB									1.0
								-	1.0
500	NRR	CL	2781	777-57-504-01-01	LHW L/E SLAT T/E WEDGE & FRONT SPAR F	OUND DIRTY	L234	WIP	09/23/2023
WNG									20.0
								-	20.0
100	PNT	PT	51	777-11-000-09-CXNA	STRIP THE RESIDUAL COATING AFTER FUS	STRIPPING	L235	OPEN	09/21/2023
FUS				-01					160.0
								-	160.0
200	NRR	AV	3326	777-C330000-01-03-	PERFORM CSCP ALL TEST FOUND DOME LI	GHTS INOP AT LAV D,L,K,	L236	OPEN	09/21/2023
CAB				01					3.0
								-	3.0
200	NRR	Al	25	777-53-920-00-01	R5 FWD CLOSET S5R-11.S5R-12 INSIDE COM	MPT 2EA BUMPER MISSING	L237	WIP	09/28/2023
CAB									1.0
								-	1.0
	200 CAB 200 CAB 600 WNG 200 CAB 200 CAB 100 CAB 200 CAB 200 CAB 200 CAB 200 CAB	200 NRR CAB NRR CAB NRR 600 NRR WNG NRR CAB NRR WNG 100 NRR	AREA TD 200 NRR AV 200 NRR AI 200 NRR CL 200 NRR AI 200 NRR CL 200 NRR AV 200 NRR AV 200 NRR AV 200 NRR AI	AREA TD ATA 200 CAB NRR NRR AV 2331 200 CAB NRR NRR AI 25 600 WNG NRR AI 25 200 CAB NRR NRR AI 25 500 WNG NRR PNT CL 2781 100 FUS PNT PT 51 200 CAB NRR AV 3326 200 CAB NRR AI 25	AREA TD ATA ORIG CUST REF NO. 200 NRR AV 2331 777-23-010-00-01 200 NRR AI 25 777-53-916-00-01 600 NRR CL 5700 777-57-960-02-01 200 NRR AI 25 777-53-916-00-01 CAB NRR AI 25 777-53-916-00-01 500 NRR AI 25 777-53-916-00-01 WNG PNT PT 51 777-57-504-01-01 100 PNT FUS AV 3326 777-C330000-01-03-01 200 NRR AI 25 7777-53-920-00-01	AREA TD ATA ORIG CUST REF NO. CTRL SH NO 200 NRR AV 2331 777-23-010-00-01 PERFORMED ALL TEST FOUND L CTR LATTICE 200 NRR AI 25 777-53-916-00-01 G5 GALLEY OVEN2.0VEN4.0VEN5 LOWER AREA 600 NRR CL 5700 777-57-960-02-01 RHW SPOILER LOWER SURFACE & TIC CAVID WNG NRR AI 25 777-53-916-00-01 G5 GLY 505 COMPT TURN RETAINER FOUND CAB NRR AI 25 777-53-916-00-01 G5 GALLEY AFT BABY BASSINET SCREWS L 500 NRR CL 2781 777-57-504-01-01 LHW LIE SLAT TIE WEDGE & FRONT SPARF WNG PRIT PT 51 777-11-000-09-CXNA STRIP THE RESIDUAL COATING AFTER FUS 200 NRR AV 3326 777-C330000-01-03- PERFORM CSCP ALL TEST FOUND DOME LIE 200 NRR AI 25 777-53-920-00-01 R5 FWD CLOSET SSR-11.SSR-12 INSIDE COM	AREA TD ATA ORIG CUST REF NO. CTRL SH NO DEFECT DESCRIPTION 200 NRR AV 2331 777-23-010-00-01 PERFORMED ALL TEST FOUND L CTR LATTICE ABOVE ROW 64 SDM 5-2 DOES NOT RESPOND 200 NRR AI 25 777-53-916-00-01 G5 GALLEY OVEN2.0VEN4.0VENS LOWER AREA BUMPER CRACKED 600 NRR AI 25 777-53-916-00-01 RHW SPOILER LOWER SURFACE & THE CAVITY FOUND DIRTY 200 NRR AI 25 777-53-916-00-01 G5 GLY 505 COMPT TURN RETAINER FOUND MALFUNCTION 200 NRR AI 25 777-53-916-00-01 G5 GALLEY AFT BABY BASSINET SCREWS LOOSEN 500 NRR CL 2781 777-53-916-00-01 LHW LIE SLAT TIE WEDGE & FRONT SPAR FOUND DIRTY 100 PNT PT 51 777-57-504-01-01 LHW LIE SLAT TIE WEDGE & FRONT SPAR FOUND DIRTY 200 NRR AV 3326 777-C330000-01-03- PERFORM CSCP ALL TEST FOUND DOME LIGHTS INOP AT LAV D.L.X. 200 NRR AI 25 777-53-920-00-01 REFORM CSCP ALL TEST FOUND DOME LIGHTS INOP AT LAV D.L.X. <	AREA TD ATA ORIG CUST REF NO. CTRL SH NO DEFECT DESCRIPTION JSN 200 CAB NRR NRR AV 2331 777-23-010-00-01 PERFORMED ALL TEST FOUND L CTRL LATTICE ABOVE ROW 6I SOM 52 DDES NOT RESPOND L229 200 CAB NRR AV 25 777-53-916-00-01 GS GALLEY OVENZ OVENZ OVENZ OVENZ OVENZ HAVE AREA BUMPER CRACKED L230 600 WING NRR AV 25 777-53-916-00-01 GS GALLEY AFT BASY BASSINET SCREWS LOOSEN L231 200 CAB NRR AV 25 777-53-916-00-01 GS GALLEY AFT BASY BASSINET SCREWS LOOSEN L233 500 WING NRR AV 2781 777-57-504-01-01 LHWILE SLAT TIE WEDGE & FRONT SPAR FOUND DIRTY L234 100 FUS PNT 51 777-67-30-00-01-03- PERFORM CSCP ALL TEST FOUND DOME LIGHTS INOP AT LAY D.L.K. L235 200 CAB NRR AV 25 777-63-920-00-01 PERFORM CSCP ALL TEST FOUND DOME LIGHTS INOP AT LAY D.L.K. L236	AREA TD ATA ORIG CUST REF NO. CTRL SH NO DEFECT DESCRIPTION JSN STATUS 200 CAB NRR AV 2331 AV 777-23-010-00-01 AV PERFORMED AL TEST FOUND CITE LATTICE ABOVE ROW BS SDM S2 DOES NOT RESPOND 1229 AVE WIP 200 WND NRR AV 250 AV 777-53-916-00-01 GS GALLEY OVEN 2 OVEN 42 OVE

515653

REQUESTED BY:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

AREA: ALL

PAGE: RUN DATE: 9/28/2023

STAGE: ALL

35 OF 83

1.0

REFERENCE NO: BMS571R1-2 (By JSN) RUN TIME : 11:09

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL STATUS: ALL ORIG-STAGE: ALL PERIOD: ALL ESTIMATED MHR: ALL

ATA NO: ALL ORIGINATING CUST REF NO: ZONE: ALL DISPOSITION CODE: ALL ALL

DEFECT TYPE: ALL TRADE: ALL CUST ENDORSE: ALL CTRL CODE: TYPE CODE: ORIGINATOR: ALL

CIRL CODE:					TYPE CODE:	ORIGINATOR:	ALL			
	ZONE	STG							STATUS	UPDATED DATE
JOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH NO	DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
XJL2385	600	NRR	CL	2781	777-57-538-02-01	RHW L/E SLAT T/E WEDGE & FRONT S	SPAR FOUND DIRTY	L238	WIP	09/23/2023
	WNG									20.0
									-	20.0
XJL2393	200	NRR	Al	25	777-53-920-00-01	G6 GLY OVEN1.OVEN2.OVEN3 LOWER	R BUMPER FOUND CRACKED	L239	WIP	09/28/2023
	CAB									6.0
									-	6.0
XJL2401	200	NRR	AV	3326	777-C330000-01-03-	PERFORM CSCP ALL TEST FOUND RO	DW 46 LAVATORY SIGN INOP	L240	OPEN	09/21/2023
	CAB				01					1.0
									-	1.0
XJL2419	200	NRR	SS	25	777-C252000-01-07-	FB2 SEAT STRUCTURE VELCRO TAPE	FOUND LOOSEN AT:11G H 12G H 16G H -26G H TOTAL:26EA	L241	OPEN	09/21/2023
	CAB				R-01					10.5
									-	10.5
XJL2427	200	NRR	SS	25	777-C252000-01-07-	FB2 SEAT STRUCTURE VELCRO TAPE	FOUND LOOSEN AT:11A D 12A D 15A -26A 16D-26D TOTAL:27EA	L242	OPEN	09/21/2023
	CAB				R-01					10.5
									-	10.5
XJL2435	200	NRR	SS	25	777-C252430-01-06-	PEY PAX SEAT BACK REST FOUND DI	SALIGNMENT AT30DEFG 31DEFG 32DEFG 33DEFG 34DEFG TOTAL:20EA	L243	OPEN	09/21/2023
	CAB				01					10.0
									-	10.0
XJL2443	200	NRR	SS	25	777-C252430-01-01-	PEY PAX SEAT STRUCTURE VELCRO	TAPE FOUND LOOSEN AT:30DEFG-34DEFG 32HK-34HK 31AC -34AC TOTAL:34EA	L244	OPEN	09/21/2023
	CAB				01					17.0
									-	17.0
XJL2450	200	NRR	SS	25	777-C252430-01-04-		LE STOWAGE SHROUD VELCRO TAPE FOUND LOOSEN AT:30DEFG-34DEFG	L245	OPEN	09/21/2023
	CAB				01	31AC-34AC 32HK-34HK TOTAL34EA				13.5
									-	13.5
XJL2468	200	NRR	AV	3326	777-C330000-01-03-	PERFORM CSCP ALL TEST FOUND OF	FAR BUNK 4 AREA LIGHT INOP	L246	WIP	09/26/2023
	CAB				01					1.0

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PERIOD: ALL

ZONE: ALL

AREA: ALL

PAGE: 36 OF 83 RUN TIME :

RUN DATE: 9/28/2023

11:09

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL STATUS: ALL

ORIG-STAGE: ALL

ESTIMATED MHR: ALL DISPOSITION CODE: ALL

ORIGINATING CUST REF NO: ALL

515653

BMS571R1-2

ATA NO: ALL CUST ENDORSE: ALL

STAGE: ALL

CTRL CODE:

DEFECT TYPE: ALL

TYPE CODE:	ORIGINATOR:	ALL
------------	-------------	-----

TRADE: ALL

CTILL CODE.					TIFE CODE.	ONGINATOR. ALL				
	ZONE	STG							STATUS	UPDATED DATE
JOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH NO	DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
XJL2476	200	NRR	Al	25	777-53-920-00-01	G6.G7 GALLEY WORK DECK EDGE SEALANT F	DUND AGED	L247	OPEN	09/21/2023
	CAB									4.0
									-	4.0
XJL2484	200	NRR	SS	25	777-C252430-01-04-	PEY PAX SEAT CONSOLE IN ARM TABLE FOUN	D DISALIGNMENT AT:30DEFG-34DEFG 32HK-34HK 31AC -34AC	L248	OPEN	09/21/2023
	CAB				01	TOTAL34EA				13.5
									-	13.5
XJL2492	200	NRR	SS	25	777-C252430-01-04-	DEV DAY SEAT CONSOLE IN ARM TARLE OPER	ATION FOUND JAM AT:30D E F G-34D E F G 32H K -34H K 31A C -34A C	L249	OPEN	09/21/2023
AULZHUZ	CAB	Milit	00	20	01	TOTAL:34EA	ATION FOUND BANKAT. SUD ET G-04B ET G-02TTK-04TTK STA G-04A G	L249	OPEN	
									_	13.5
										13.5
XJL2500	200 CAB	NRR	Al	25	777-53-916-00-01	G4.G5 GALLEY WORK DECK EDGE SEALANT F	DUND AGED	L250	OPEN	09/21/2023
	CAD									4.0
									-	4.0
XJL2518	500	NRR	CL	57	777-57-856-01-01	LHW ALL REMOVED ACCESS PANEL INNER SU	RFACE FOUND DIRTY	L251	WIP	09/24/2023
	WNG									0.0
									-	0.0
XJL2526	200	NRR	Al	25	777-53-916-00-01	G4L.G4R GALLEY WORK DECK EDGE SEALAN	FOUND AGED.	L252	OPEN	09/21/2023
	CAB									4.0
									-	4.0
XJL2534	200	NRR	AV	3324	777-C330000-01-03-	PERFORM CSCP ALL TEST FOUND ROW 11&60	CTR NO SMOKING SIGN INOP	L253	OPEN	09/21/2023
	CAB				01					2.0
									-	2.0
XJL2542	600	NRR	CL	57	777-57-948-02-01	RHW ALL REMOVED ACCESS PANEL INNER SU	IRFACE FOUND DIRTY	L254	WIP	09/24/2023
	WNG							2201	****	0.0
									-	0.0
XJL2559	200	NRR	Al	25	777-53-920-00-01	G6 GALLEY 606.607 COMPT SHORT TURN BUT	TON FOLIND MALEUNICTION	1.055	COMP	
AULZUUU	CAB	MIXIX	Ai	20	777-33-920-00-01	GO CALLET GOO.GOT GOWN T SHORT TORK BOT	TON I SOND WALL GROTTON	L255	COMP	09/25/2023
									_	2.0
										2.0

0PPC DISTRIBUTION:

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE:

RUN TIME :

37 OF 83

RUN DATE: 9/28/2023 11:09

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL

515653

BMS571R1-2

STATUS: ALL

ORIG-STAGE: ALL

PERIOD: ALL

ESTIMATED MHR: ALL

ORIGINATING CUST REF NO: ALL

ATA NO: ALL

ZONE: ALL AREA: ALL

DISPOSITION CODE: ALL

DEFECT TYPE: ALL

TRADE: ALL

CUST ENDORSE: ALL

STAGE: ALL

	ZONE	STG						STATUS	UPDATED DATE
JOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH NO DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
XJL2567	200	NRR	Al	25	777-53-920-00-01	G6 GALLEY 603.605.607 LOWER COMPT UPPER T GUIDE 3EA BUMPER CRACKED	L256	OPEN	09/21/2023
	CAB								6.0
								-	6.0
XJL2575	200	NRR	AV	3321	777-C330000-01-01- 01	PERFORM CSCP ALL TEST FOUND CEILING LIGHTS INOP AT LAV 4F-1L(LAV H) ,ABOVE DR 2L STOWAGE S2L,ABOVE	L257	OPEN	09/21/2023
	CAB				01	DR 2 RIGHT , ROW 2 LEFT ABOVE BIN			4.0
								-	4.0
XJL2583	200	NRR	Al	25	777-53-920-00-01	G7 GALLEY 706.707 COMPT TURN RETAINER AFT INDICATOR BUMPER FOUND MISSING	L258	OPEN	09/21/2023
	CAB								1.0
								-	1.0
XJL2591	200	NRR	Al	25	777-53-920-00-01	G7 GALLEY 708 WASTE COMPT DOOR AFT SIDE UPPER AREA 1EA BUMPER CRACKED	L259	OPEN	09/21/2023
	CAB								2.0
								-	2.0
XJL2609	200	NRR	Al	25	777-53-920-00-01	G7 GALLEY 714.715.726 COMPT SMALL TURN BUTTON FOUND STIFF	L260	OPEN	09/21/2023
	CAB								1.0
								-	1.0
XJL2617	200	NRR	Al	25	777-53-920-00-01	G7 GALLEY 702 COMPT SHORT TURN BUTTON FOUND MALFUNCTION	L261	COMP	09/25/2023
	CAB								1.0
								-	1.0
XJL2625	200	NRR	Al	25	777-53-920-00-01	G7 GALLEY 701.705.707 LOWER COMPT UPPER T GUIDE 3EA BUMPER CRACKED	L262	OPEN	09/21/2023
	CAB								6.0
								-	6.0
XJL2633	200	NRR	AV	4420	777-24-001-00-01	PERFORM IFE TEST FOUND 66D,70E MONITORS TOUCHSCREEN DOES NOT RESPOND	L263	OPEN	09/21/2023
	CAB								4.0
								-	4.0
XJL2641	200	NRR	AV	4420	777-24-001-00-01	PERFORM IFE TEST FOUND 23A MONITOR TOUCHSCREEN DOES NOT RESPOND	L264	WIP	09/27/2023
	CAB								2.0
								-	2.0
								-	

ORIGINATING CUST REF NO:

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

38 OF 83 PAGE:

RUN DATE: 9/28/2023

RUN TIME : 11:09

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

TYPE CODE:

JSN RANGE SELECTED: ALL STATUS: ALL ORIG-STAGE: ALL PERIOD: ALL ESTIMATED MHR: ALL

> ATA NO: ALL ZONE: ALL DISPOSITION CODE: ALL

DEFECT TYPE: ALL TRADE: ALL CUST ENDORSE: ALL AREA: ALL STAGE: ALL

ORIGINATOR: ALL

CTRL CODE:

515653

BMS571R1-2

ALL

STILL CODE.					TIFE CODE.	ONGINATOR: ALL			CTATUC	LIDDATED DATE
100.110	ZONE	STG			ODIO GUOT DEE :::	OTPL CLING	PETER PEROPURION	10.1	STATUS	UPDATED DATE
JOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH NO	DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
(JL2658	200 CAB	NRR	AV	2525	777-24-001-00-01	PERFORM BC SEAT ELECTRICAL OPERATION	FEST FOUND 24A SEAT INOP	L265	OPEN	09/21/2023
	CAB									2.0
									-	2.0
JL2666	200	NRR	AV	2525	777-24-001-00-01	PERFORM BC SEAT OPERATION TEST FOUND	23G,20K,21G TTL LIGHT INOP	L266	OPEN	09/21/2023
	CAB									3.0
									-	3.0
JL2674	200	NRP	SS	25	777-25-060-01-CX-01	C/A SEAT STRUCTURE VELCRO TAPE FND LO	OSEN TTL:16EA	L267	OPEN	09/21/2023
	CAB									6.0
									-	6.0
JL2682	200	NRR	SS	25	777-C252410-01-01-	FIRST CLASS SEAT STRUCTURE VELCRO TAP	FND LOOSEN AT:1A D K-2A D K TTL:6EA	L268	OPEN	09/21/2023
	CAB				01					4.0
									-	4.0
JL2690	100	NRP	GW	5346	777-900002-01-1-01	FUS-LH BODY FAIRING 195AL 3EA SCREWS SE	IZED.	L269	COMP	09/27/2023
	FUS									3.0
									-	3.0
JL2708	200	NRR	SS	25	777-C252440-04-03-	E ZONE EY PAX SEAT BACKREST RECLINE OP	ERATION FND TIGHTEN AT:39AC-45ABC TTL:20EA	L270	WIP	09/25/2023
	CAB				01					4.0
									-	4.0
IL2716	200	NRR	SS	25	777-C252000-01-07-	CAB B ZONE B/C SEAT BACK COVER FOUND T	DRN TTL:13EA	L271	OPEN	09/22/2023
	CAB				R-01			LZII	OI LIV	6.5
									-	
JL2724	200	NRR	SS	25	777-C252000-01-07-	CAB B ZONE B/C SEAT LEGREST COVER FOUN	D NOT MATCH TTI -1EA	1.070	00511	6.5
JL2124	CAB	INIXIX	33	25	R-01	CAB B ZONE BIC SEAT LEGREST COVER FOUL	D NOT WATCH TIL.TEA	L272	OPEN	09/22/2023
									-	0.5
	000			0.5	777 0050655 5 / 55	0.10 0.70.05 0/0.05.15	- FOLIND ODLOVED TIL OF			0.5
IL2732	200 CAB	NRR	SS	25	777-C252000-01-07- R-01	CAB B ZONE B/C SEAT HEADREST STRUCTUR	E FOUND CRACKED TTL:6EA	L273	OPEN	09/22/2023
	CAB									3.0
									-	3.0

REQUESTED BY:

REFERENCE NO:

DEFECT TYPE: ALL

BMS571R1-2

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE: 39 OF 83

RUN DATE: 9/28/2023

RUN TIME : 11:09

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL

515653

STATUS: ALL

ORIG-STAGE: ALL

PERIOD: ALL

ZONE: ALL

ESTIMATED MHR: ALL DISPOSITION CODE: ALL

ORIGINATING CUST REF NO: ALL

TRADE: ALL

ATA NO: ALL CUST ENDORSE: ALL

ALL

CTRL CODE :

TYPE CODE:

ORIGINATOR · ALL

CTRL CODE :					TYPE CODE:	ORIGINATOR:	ALL			
	ZONE	STG							STATUS	UPDATED DATE
JOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH NO	DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
XJL2740	200	NRR	SS	25	777-C252000-01-08- R-01	CAB C ZONE PEY SEAT BOTTOM COVER	FOUND NOT MATCH TTL:4EA	L274	OPEN	09/22/2023
	CAB				K-01					2.0
									-	2.0
XJL2757	200	NRR	SS	25	777-C252440-04-03- 01	E ZONE EY PAX SEAT BACKREST RECLIN	E OPERATION FND TIGHTEN AT:39DEFG-46DEFG TTL:32EA	L275	WIP	09/25/2023
	CAB				O1					6.0
									-	6.0
XJL2765	200	NRR	SS	25	777-C252440-04-03- 01	E ZONE EY PAX SEAT BACKREST RECLIN	E OPERATION FND TIGHTEN AT:40HJK-46HJK TTL:21EA	L276	WIP	09/25/2023
	CAB				O1					6.0
									-	6.0
XJL2773	200	NRR	SS	25	777-C252000-01-08- R-01	CAB C ZONE PEY SEAT HEADREST STRU	CTURE SCREW FOUND LOOSE TTL:12EA	L277	OPEN	09/22/2023
	CAB				R-01					2.0
									-	2.0
XJL2781	200	NRR	SS	25	777-C252440-04-03- 01	D ZONE EY PAX SEAT BACKREST RECLIN	IE OPERATION FND TIGHTEN AT:59ABC-72AC TTL: 41	L278	WIP	09/25/2023
	CAB				O1					8.0
									-	8.0
XJL2799	200	NRR	SS	25	777-C252440-04-03- 01	D ZONE EY PAX SEAT BACKREST RECLIN	E OPERATION FND TIGHTEN AT:60DEFG-72DEG TTL:48EA	L279	WIP	09/25/2023
	CAB				01					9.0
									-	9.0
XJL2807	200	NRR	SS	25	777-C252440-04-03- 01	D ZONE EY PAX SEAT BACKREST RECLIN	E OPERATION FND TIGHTEN AT:59HJK-71HJK TTL:39EA	L280	WIP	09/25/2023
	CAB				O1					8.0
									-	8.0
XJL2815	200	NRR	SS	25	777-C252440-04-02- 01	EY F/R SEAT IN ARM TABLE FND TIGHTE	NAT:39A.C D.E.F.G H.J.K.59A.B.C.H.J.K.60D.E.F.G TTL:19EA	L281	WIP	09/25/2023
	CAB				O I					6.0
									-	6.0

515653

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

PAGE: 40 OF 83

RUN DATE: 9/28/2023

BMS571R1-2 (By JSN) RUN TIME : 11:09

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL STATUS: ALL ORIG-STAGE: ALL PERIOD: ALL ESTIMATED MHR: ALL

ORIGINATING CUST REF NO: ATA NO: ALL ZONE: ALL DISPOSITION CODE: ALL ALL

DEFECT TYPE: ALL TRADE: ALL CUST ENDORSE: ALL AREA: ALL STAGE: ALL

JINE CODE .	ZONE	STG			THE GODE.	ONOMATOR. ALL	STATUS	UPDATED DATE
JOB NO	AREA	010	TD	ATA	ORIG CUST REF NO.	CTRL SH NO DEFECT DESCRIPTION JSN	STATUS	EST Mhr
KJL2823	100 LWR	NRM	AV	2431	AEO-27438-01	DISCONNECT AND RECONNECT MAIN BATTERY AND APU BATTERY FOR POWER PANEL REWORK L282	WIP	09/22/2023
	2777					1C 1 RECONNECT CONNECTOR OF MAIN BATTERY		0.0
						1C 1 RECONNECT CONNECTOR OF MAIN BATTERY 1C 2 RECONNECT CONNECTOR OF APU BATTERY		1.0 1.0
						1C 3 PERFORM MAIN BATTERY RECONNECTION TEST		1.0
						1C 4 DISCONNECT CONNECTOR OF APU BATTERY		1.0
						2C 5 PERFORM APU BATTERY RECONNECTION TEST		1.0
						2C 6 DISCONNECT CONNECTOR OF MAIN BATTERY		1.0
							-	6.0
JL2831	200	NRR	SS	2500	777-53-908-00-01	CABIN #2 DOOR G2 GLY R/H AISLE S/W FOUND SCRATCHED L283	WIP	09/24/2023
	CAB							0.0
						1C 1 REMOVE G2 GLY RHS AISLE LIGHT		0.5
						1C 2 REMOVE G2 GLY RHS AISLE PNL		1.0
						1C 3 G2 GLY RHS AISLE TEDLAR REPLACE		11.0
						1C 4 REINSTALL G3 2 GLY RHS AISLE PNL		1.0
						2C 5 REINSTALL G2 GLY RHS AISLE LIGHT	-	0.5
								14.0
L2849	100	NRR	PT	2500	777-53-854-00-01	AFT CGO BILGE AREA RIVETS PAINT FOUND PEEL OFF L284	OPEN	09/22/2023
	LWR							4.0
							-	4.0
L2856	100	NRR	PT	5121	777-53-854-00-01	AFT CGO DOOR ARM SUPPORT FND PAINT CHIP L285	OPEN	09/22/2023
	LWR							2.0
							-	2.0
JL2864	100	NRR	PT	5121	777-53-818-00-01	FWD CGO DOOR ARM SUPPORT FND PAINT CHIP L286	OPEN	09/22/2023
	LWR							2.0
							-	2.0
L2872	100	NRR	PT	5121	777-53-818-00-01	FWD CGO DOOR DEPRESSOR SEAL FOUND PAINT CHIPPED.	WIP	09/27/2023
	LWR							6.0
							-	6.0

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE: 41 OF 83 RUN DATE: 9/28/2023

RUN TIME : 11:09

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL

515653

BMS571R1-2

STATUS: ALL

ORIG-STAGE: ALL

PERIOD: ALL ZONE: ALL

ESTIMATED MHR: ALL DISPOSITION CODE: ALL

ORIGINATING CUST REF NO:

ALL

ATA NO: ALL CUST ENDORSE: ALL

STAGE: ALL

CTRL CODE:

DEFECT TYPE: ALL

TRADE: ALL TYPE CODE:

ORIGINATOR: ALL

AREA:	ALL		

CIKL CODE.					TIPE CODE.	ORIGINATOR	N. ALL			
	ZONE	STG							STATUS	UPDATED DATE
JOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH NO	DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
XJL2880	100	NRR	PT	5121	777-53-854-00-01	AFT CGO COMP'T BALL MAT ARE	A RED LOCK FOUND PAINT PEELED.TTL30EA	L288	WIP	09/27/2023
	LWR									15.0
									-	15.0
XJL2898	100	NRR	PT	5121	777-53-870-00-01	BULK CGO DOOR SILL AND BLAC	K LINE FOUND PAINT PEELED.	L289	COMP	09/28/2023
	LWR									5.0
									-	5.0
XJL2906	100	NRR	PT	5121	777-53-870-00-01	BULK CGO CTR FLOOR PANEL FO	DUND PAINT PEELED.	L290	COMP	09/28/2023
	LWR									8.0
									-	8.0
XJL2914	100	NRR	PT	5121	777-53-854-00-01	FWD AND AFT CGO DOOR LOWE	R SILL FITTING BLACK MARKING FOUND PAINT PEELED	L291	OPEN	09/22/2023
	LWR									5.0
									-	5.0
XJL2922	100	NRR	PT	5121	777-53-818-00-01	FWD CGO COMP'T BALL MAT ARE	EA RED LOCK FOUND RED PAINT PEELED.TTL:30EA	L292	WIP	09/27/2023
	LWR									15.0
									-	15.0
XJL2930	100	NRR	PT	5121	777-53-818-00-01	FWD CGO COMP'T BALL MAT PAN	NEL FOUND PAINT PEELED.TTL5EA.	L293	COMP	09/28/2023
	LWR							2200	COM	15.0
									-	15.0
XJL2948	100	NRR	PT	5121	777-53-854-00-01	AFT CGO BALL MAT PNL FOUND	PAINT PEEL TTI :5FA	L294	COMP	09/28/2023
71022010	LWR	14141		0121	777 00 00 7 00 0 7	ALL OUR BALL MAN THE TOURS	7.1111 EEE. E.O.	L294	COMP	5.0
									-	
XJL2955	100	NRR	PT	5121	777-53-854-00-01	AFT CGO DOOR DEPRESSOR SE.	AL FOLIND DAINT CHIPDED	1.005	\\(\mathrea{\pi}\)	5.0
AJL2955	LWR	INIXIX	PI	3121	777-53-654-00-01	AFT CGO DOOR DEPRESSOR SE	AL POUND PAINT CHIPPED.	L295	WIP	09/27/2023
									-	6.0
										6.0

515653

BMS571R1-2

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE: 42 OF 83 RUN DATE: 9/28/2023

RUN TIME : 11:09

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

TYPE CODE:

JSN RANGE SELECTED: ALL STATUS: ALL ORIG-STAGE: ALL PERIOD: ALL ESTIMATED MHR: ALL

ORIGINATING CUST REF NO: ATA NO: ALL ZONE: ALL DISPOSITION CODE: ALL ALL

ORIGINATOR: ALL

DEFECT TYPE: ALL TRADE: ALL CUST ENDORSE: ALL AREA: ALL STAGE: ALL

CTRL CODE:

	ZONE	STG			2 0022.		STATUS	UPDATED DATE
JOB NO	AREA	0.0	TD	ATA	ORIG CUST REF NO.	CTRL SH NO DEFECT DESCRIPTION JSI	N STATUS	EST Mhr
XJL2963	200	NRR	SM	2520	777-53-907-00-01	FWD ZONE OFCR LH &RH CREW SEAT PAN FOUND DAMAGED L29	6 OPEN	09/22/2023
	CAB							0.0
						1C 1 PLS REMOVE L/R SEAT		2.0
						1C 2 REMOVE L/R SEAT L/R SIDE ARM		8.0
						1C 3 SEAT PAN& DOUBLER REPLACE		48.0
						1C 4 REINSTALL L/L SEAT L/R SIDE ARM		8.0
						2C 5 REINSTALL L/R SEAT		1.0
								67.0
JL2971	600	NRR	SS	5700	777-57-972-02-01	RHW #6 FIXED FAIRING FOUND EROSION L29	7 WIP	09/24/2023
	WNG							0.0
						1C 1 DO AN INSPECTION TO FIND THE DAMAGE DIMENSION		1.0
						1C 2 CONFIRM DAMAGE WITHIN SRM ADL		2.0
						1C 3 MAKE A PERMANENT SEAL TO PERMITTED DAMAGE		3.0
						1C 4 APPLY ONE LAYER OF BMS10-60 ENAMEL		0.0
								6.0
JL2989	600	NRR	SS	5700	777-57-982-02-01	RHW #7 FIXED FAIRING FWD CUTOUT FOUND EROSION L29	8 WIP	09/24/2023
	WNG							0.0
						1C 1 DO AN INSPECTION TO FIND THE DAMAGE DIMENSION		1.0
						1C 2 CONFIRM DAMAGE WITHIN SRM ADL		2.0
						1C 3 MAKE A PERMANENT SEAL TO PERMITTED DAMAGE		3.0
						1C 4 APPLY ONE LAYER OF BMS10-60 ENAMEL		0.0
								6.0
JL2997	600	NRR	SS	5700	777-57-982-02-01	RHW #8 FIXED FAIRING FWD CUTOUT FOUND EROSION L29	9 WIP	09/24/2023
	WNG							0.0
						1C 1 DO AN INSPECTION TO FIND THE DAMAGE DIMENSION		1.0
						1C 2 CONFIRM DAMAGE WITHIN SRM ADL		2.0
						1C 3 MAKE A PERMANENT SEAL TO PERMITTED DAMAGE		3.0
						1C 4 APPLY ONE LAYER OF BMS10-60 ENAMEL		0.0
								6.0
JL3003	600	NRR	ΑE	2708	777-57-954-02-01	RHW FLAPERON LIP DOORS I/B SEAL FOUND TORN	0 WIP	09/27/2023
	WNG							2.0
								2.0

ORIGINATING CUST REF NO:

515653

BMS571R1-2

ALL

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE: 43 OF 83

RUN DATE: 9/28/2023

RUN TIME : 11:09

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL STATUS: ALL ORIG-STAGE: ALL PERIOD: ALL ESTIMATED MHR: ALL

ATA NO: ALL ZONE: ALL DISPOSITION CODE: ALL

DEFECT TYPE: ALL TRADE: ALL CUST ENDORSE: ALL AREA: ALL STAGE: ALL

CTRL CODE:					TYPE CODE:	ORIGINATOR :	ALL			
	ZONE	STG							STATUS	UPDATED DATE
JOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH NO	DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
XJL3011	600	NRR	AE	2708	777-57-954-02-01	RHW FLAPERON O/B LOWERLOWER	SEAL FOUND TORN	L301	WIP	09/27/2023
	WNG									6.0
									-	6.0
XJL3029	600	NRR	AE	2750	777-57-952-02-01	RHW I/B MAIN FLAP I/B EDGE SEAL FO	OUND TORN	L302	OPEN	09/22/2023
	WNG									1.0
									-	1.0
XJL3037	600	NRR	ΑE	2750	777-57-860-01-01	LHW I/B MAIN FLAP I/B EDGE SEAL FO	DUND TORN	L303	OPEN	09/22/2023
	WNG									1.0
									-	1.0
XJL3045	600	NRR	AE	2708	777-57-862-01-01	LHW FLAPERON I/B UPPER LOWER S	SEAL FOUND TORN	L304	WIP	09/27/2023
	WNG							2001	****	6.0
									-	6.0
XJL3052	500	NRR	AE	2700	777-57-880-01-01	LHW FLAPERON I/B HINGE AFTER FA	DING SEAL FOLIND TORN	1.205	WIP	
AULUUZ	WNG	MIXIX	AL	2700	777-37-000-01-01	LIWITAFERON I/BIIINGE AFTERTA	INING SEALT OUND TORN	L305	WIP	09/27/2023
									-	
										2.0
XJL3060	500 WNG	NRR	SS	57	777-57-900-02-01	WING LE ACCESS PNLS 611 CB GB FO	OUND EXTERNAL SURFACE PAINT IRREGULARITY	L306	WIP	09/27/2023
	WINO					1C 1 APPLY THE RESIN CO	DATING TO IRREGULAR AREA			0.0 3.0
							ATING TO MAKE SURFACE SMOOTHER			3.0
						1C 3 APPLY THE SURFACE	PAINT			0.0
									-	6.0
XJL3078	100	NRR	ΑI	2500	777-53-862-00-01	AFT CGO R/H BALL MAT AREA PDU R	OLLER FOUND WORN.TOTAL 5 PAIRS	L307	OPEN	09/22/2023
	LWR									5.0
									-	5.0
XJL3086	100	NRR	ΑI	2500	777-53-862-00-01	AFT CGO R/H AFT BALL MAT AREA R/	/H AFT PDU SENSOR FOUND WORN. TOTAL 1EA.	L308	OPEN	09/22/2023
	LWR									2.0
									-	2.0

0PPC DISTRIBUTION:

ORIGINATING CUST REF NO:

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

44 OF 83 PAGE:

RUN TIME :

RUN DATE: 9/28/2023 11:09

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE:

JSN RANGE SELECTED: ALL STATUS: ALL ORIG-STAGE: ALL PERIOD: ALL

ESTIMATED MHR: ALL DISPOSITION CODE: ALL

2C

ATA NO: ALL ZONE: ALL

DEFECT TYPE : ALL TRADE: ALL CUST ENDORSE: ALL AREA: ALL STAGE: ALL

ALL

515653

BMS571R1-2

TRL CODE :					TYPE CODE:	ORIGINATOR: ALL			STATUS	UPDATED DAT
JOB NO	ZONE AREA	SIG	TD	ATA	ORIG CUST REF NO.	CTRL SH NO	DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
JL3094		NRR	Al	2500	777-53-862-00-01					
JL3094	100 LWR	NKK	AI	2500	777-53-862-00-01	AFT CGO R/H AFT BALL MAT AREA R/H FWD S	TOP AXLE PIN FOUND BROKEN. TOTAL TEA.	L309	OPEN	09/22/2023
	LVII								_	2.0
										2.0
JL3102	800	NRP	CL	52	777-52-531-01-01	M/D ALL DOOR STOP FITTING AREA FOUND D	IRTY.	L310	COMP	09/28/2023
	CAB									10.0
									-	10.0
JL3110	800	NRP	CL	52	777-52-531-01-01	M/D ALL DOOR CUTOUT STOP FITTING AREA	FOUND DIRTY.	L311	COMP	09/28/2023
	CAB									10.0
									-	10.0
JL3128	200	NRR	PT	2500	777-53-916-00-01	M/D R5 DOOR BUSTLE PNL FND PAINT CHIP		L312	WIP	09/28/2023
	CAB									4.0
									-	4.0
JL3136	200	NRR	PT	2500	777-53-908-00-01	CABIN S2CL S2CR CLOSET UPPER EDGE FND	PAINT CHIPPED	L313	OPEN	09/22/2023
	CAB							2010	01 211	10.0
									-	10.0
JL3144	200	NRR	PT	2500	777-53-916-00-01	M/D R4-01 R4-02 R4-03 R4-04 GALLEY DOOR IN	NITERIOR SURFACE FND PAINT CHIPPED	1044	ODEN	
JLJ 144	CAB	IVIXIX		2500	777-33-310-00-01	WID NEED INEED INEED IN	VIENON SON ACETNOT AINT OTHER ED	L314	OPEN	09/22/2023
									_	
	000	NDD	D T	0500	777 50 004 00 04	MD 0 400 D 400 D 400 O M EV DOOD WEEDIN				8.0
JL3151	200 CAB	NRR	PT	2500	777-53-904-00-01	M/D C-103 R-103 R-123 GALLEY DOOR INTERIO	DR SURFACE FND PAINT CHIPPED	L315	OPEN	09/22/2023
	O/ LD								_	6.0
										6.0
JL3169	200	NRR	PT	2500	777-53-908-00-01	M/D G201 G202 GALLEY DOOR INTERIOR SUR	FACE FND PAINT CHIPPED	L316	OPEN	09/22/2023
	CAB									4.0
									-	4.0
IL3177	200	NRR	PT	2500	777-53-908-00-01	M/D R2-01 R2-02 R2-03GALLEY DOOR INTERIO	R SURFACE FND PAINT CHIPPED	L317	OPEN	09/22/2023
	CAB									6.0
									-	6.0

ORIGINATING CUST REF NO:

515653

BMS571R1-2

ALL

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

PAGE: 45 OF 83 RUN DATE: 9/28/2023

(By JSN) RUN TIME : 11:09

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL STATUS: ALL ORIG-STAGE: ALL PERIOD: ALL ESTIMATED MHR: ALL

> ATA NO: ALL ZONE: ALL DISPOSITION CODE: ALL

DEFECT TYPE: ALL TRADE: ALL CUST ENDORSE: ALL AREA: ALL STAGE: ALL

TRL CODE .					TIPE CODE.	ORIGINATOR. ALL				
	ZONE	STG							STATUS	UPDATED DATE
JOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH NO	DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
JL3185	200	NRR	PT	2500	777-53-908-00-01	M/D G2 G4 GALLEY CEILING SURFACE FOUND PAIL	NT CHIP	L318	OPEN	09/22/2023
	CAB									16.0
									-	16.0
L3193	200	NRR	PT	2500	777-53-916-00-01	CABIN S1L S1R CLOSET UPPER EDGE FND PAINT	CHIPPED	L319	OPEN	09/22/2023
	CAB									10.0
									-	10.0
3201	100	NRR	PT	5121	777-53-920-00-01	M/D G702 703 706 707 606 607 GALLEY DOOR FOUR	ND PAINT PEEL TTL:6EA	L320	OPEN	09/22/2023
	CAB									12.0
									-	12.0
.3219	200	NRR	PT	2500	777-53-908-00-01	CABIN S2CL-11 S2CR-11CLOSET INTERIOR SURFA	CE FND PAINT CHIPPED	L321	OPEN	09/22/2023
	CAB									4.0
									-	4.0
3227	200	NRR	Al	2524	777-53-908-00-01	CAB-FB2 SEAT BACK SHELL BOTTLE CONSOLE HO	ORIZONTAL TRIM FOUND CRACKED AT 21K.	L322	OPEN	09/22/2023
	CAB							2022	01 2.1	1.0
									-	1.0
_3235	200	NRR	AI	2524	777-53-908-00-01	CABIN FB2 SEAT OTTOMAN FOOT REST PLASTIC (COVER GAP SEAL FOUND MISSING AT 11A 16A 21A 11C 16K	L323	OPEN	09/22/2023
-0200	CAB		<i>,</i>		00 000 00 0.	0.22.020		L323	OFLIN	15.0
									-	
_3243	200	NRR	SS	2524	777-53-908-00-01	CABIN FB2 SEAT SHELL BLACK FABRIC FOUND WO	DPN 4T 24D 20D 48D 26D	L324	WIP	15.0 09/27/2023
.0240	CAB	INIXIX	00	2024	777-33-900-00-01	OADIN 1 DZ SEAT STIELE BEAGKT ADMOT GOND WO	ONIT AT 210 200 100 200	L324	VVIP	0.0
						1C 1 REMOVAL SEAT BLACK FABRIC CO)VFR			3.0
						1C 2 REPLACE SEAT BLACK FABRIC	77 211			30.0
						1C 3 PLS INSTALL BLACK FABRIC COVE	R			3.0
									-	36.0
.3250	200	NRR	PT	2500	777-53-908-00-01	M/D D LAV WASTE BIN MARKING FND PAINT CHIP		L325	OPEN	09/22/2023
	CAB									1.0
									-	1.0
										1.

DISTRIBUTION:

REQUESTED BY:

REFERENCE NO:

DEFECT TYPE: ALL

0PPC TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE: RUN DATE: 9/28/2023 RUN TIME :

46 OF 83

11:09

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL

515653

BMS571R1-2

STATUS: ALL

ORIG-STAGE: ALL

ATA NO: ALL

PERIOD: ALL

ZONE: ALL

ESTIMATED MHR: ALL DISPOSITION CODE: ALL

ORIGINATING CUST REF NO:

ALL

TRADE: ALL

CUST ENDORSE: ALL

AREA: ALL STAGE: ALL

CTRL CODE:

TYPE CODE:

ORIGINATOR: ALL

SILTATS	EST Mbr

	ZONE	STG							STATUS	UPDATED DATE
JOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH NO	DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
XJL3268	200	NRR	Al	2524	777-53-908-00-01	CABIN FB2 SEAT OTTOMAN AROUND NOM	EX TRIM FOUND DAMAGE AT 26D 22G 19K	L326	WIP	09/27/2023
	CAB									10.0
									-	10.0
XJL3276	200	NRR	SS	2524	777-53-908-00-01		OLE RED FABRIC TRIM FOUND DAMAGE 19D 11K 17K 12K 25A 18A 16K 22K	L327	WIP	09/27/2023
	CAB					24K 18D 17G 12G 18G 21G 26G				0.0
						1C 1 REMOVAL SEAT RED NOME				7.5
						1C 2 REPLACE SEAT RED NOME				45.0
						2C 3 PLS INSTALL RED NOMEX (COVER		_	7.5
										60.0
XJL3284	200	NRR	Al	2524	777-53-908-00-01	CABIN FB2 SEAT OTTOMAN FOOT REST CL	ISHION LEATHER FOUND WORN AT 12G	L328	OPEN	09/22/2023
	CAB									3.0
									-	3.0
XJL3292	200	NRR	Al	2524	777-53-908-00-01	CAB-FB2 SEAT BACK SHELL BOTTLE CONS	OLE PLASTIC TRIM FOUND DETACHED AT 26K.	L329	OPEN	09/22/2023
	CAB									0.5
									-	0.5
XJL3300	200	NRR	Al	2541	777-53-904-00-01	CABIN ZONE A LAV A FLOOR PAN EDGE TR	IM FOUND DAMAGE	L330	OPEN	09/22/2023
	CAB									2.0
									-	2.0
XJL3318	200	NRR	PT	2500	777-53-870-00-01	BULK CGO S/W PNLS SURFACE FND PAINT	CHIPPED TTL:6EA	L331	WIP	09/28/2023
	LWR									18.0
									-	18.0
XJL3326	200	NRR	SS	2525	777-C252000-01-09-	EY PAX SEAT POCKET COVER FND DIRTY	AT: 40H 65K 69H 67C 59C TTL: 5EA	L332	OPEN	09/22/2023
	CAB				R-04					4.0
									-	4.0
XJL3334	200	NRR	SS	2525	777-C252000-01-09-	EY PAX SEAT POCKET COVER BUTTON FN	D LOOSEN AT: 41F 45E 59H 63K 71D 71A TTL: 6EA	L333	OPEN	09/22/2023
	CAB				R-04			2000	J. 2	1.0
									-	
										1.0

0PPC DISTRIBUTION:

REQUESTED BY:

REFERENCE NO:

PROJECT: XJ

CTRL CODE:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

47 OF 83 PAGE:

RUN TIME :

RUN DATE: 9/28/2023 11:09

515653

BMS571R1-2

CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV

CHECK TYPE: 2C

ESTIMATED MHR: ALL

JSN RANGE SELECTED: ALL ORIGINATING CUST REF NO: ALL STATUS: ALL

PERIOD: ALL ZONE: ALL

DISPOSITION CODE: ALL

DEFECT TYPE: ALL

TRADE: ALL TYPE CODE:

CUST ENDORSE: ALL

ORIG-STAGE: ALL

ORIGINATOR: ALL

ATA NO: ALL

AREA: ALL

STAGE: ALL

	ZONE	STG							STATUS	UPDATED DATE
JOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH NO	DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
XJL3342	200	NRR	SS	25	777-C252000-01-06-	CAB A ZONE SEAT OTTOMANS CUSHION FOUND TORN T	TL:6EA	L334	OPEN	09/22/2023
	CAB				R-02					3.0
									-	3.0
XJL3359	200	NRR	SS	25	777-C252000-01-09-	CAB F ZONE EY SEAT ALL HEADREST TTL 128EA FOUND	DIRTY	L335	OPEN	09/22/2023
	CAB				R-04					8.0
									-	8.0
XJL3367	200	NRR	SS	25	777-C252000-01-09-	CAB E ZONE EY SEAT ALL HEADREST TTL73EA FOUND D	IRTY	L336	OPEN	09/22/2023
	CAB				R-04					4.0
									-	4.0
XJL3375	200	NRR	SS	25	777-C252000-01-09-	CAB F ZONE EY SEAT BOTTOM DRESS COVER FOUND NO	OT MATCH TTL:28EA	L337	OPEN	09/22/2023
	CAB				R-04					14.0
									-	14.0
XJL3383	200	NRR	SS	25	777-C252000-01-09-	CAB E ZONE EY SEAT BOTTOM DRESS COVER FOUND NO	OT MATCH TTL:13EA	L338	OPEN	09/22/2023
	CAB				R-04					6.5
									-	6.5
XJL3391	200	NRR	SS	2525	777-C252440-04-02-	EY PAX SEAT BACKREST TABLE FND DIRTY AT:40H 41K 4	5H 62D 69D 60B 71B TTL:7EA	L339	WIP	09/27/2023
	CAB				01					4.0
									-	4.0
XJL3409	600	NRR	GW	5700	777-57-948-02-01	RHW T/E ACCESS PANEL 652LB (3EA) SCREW FOUND SE	IZED	L340	COMP	09/26/2023
	WNG									3.0
									-	3.0
XJL3417	600	NRR	SM	5700	777-57-948-02-01	RHW T/E ACCESS PANEL 652LB (3EA) ANCHOR NUT		L341	OPEN	09/22/2023
	WNG									1.5
									-	1.5
XJL3425	500	NRR	GW	5700	777-12-008-00-01	LHW L/E ACCESS PANEL 511FB (1EEA 511GB(1EA) 511KB	(2EA) 511PB(10EA) SCREW FOUND SEIZED	L342	COMP	09/26/2023
	WNG									14.0
									-	14.0

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE: 48 OF 83

RUN DATE: 9/28/2023

RUN TIME : 11:09

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL

BMS571R1-2

515653

STATUS: ALL ORIG-STAGE: ALL PERIOD: ALL

ESTIMATED MHR: ALL

ORIGINATING CUST REF NO: ALL

ATA NO: ALL ZONE: ALL DISPOSITION CODE: ALL

DEFECT TYPE: ALL CTRL CODE:

TRADE: ALL

AREA: ALL STAGE: ALL

CUST ENDORSE: ALL TYPE CODE: ORIGINATOR: ALL

CIRL CODE :					TYPE CODE:	ORIGINATOR:	ALL			
	ZONE	STG							STATUS	UPDATED DATE
JOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH NO	DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
XJL3433	500	NRR	SM	5700	777-12-008-00-01	LHW L/E ACCESS PANEL 511FB (1EEA	511GB(1EA) 511KB(2EA) 511PB(10EA) ANCHOR NUT FOUND WORN	L343	OPEN	09/22/2023
	WNG									7.0
									-	7.0
XJL3441	500	NRR	ΑE	5700	777-12-008-00-01	LHW L/E ACCESS PANEL 511FB GB CI	3 SCREW FOUND WORN	L344	OPEN	09/22/2023
	WNG									1.0
									-	1.0
XJL3458	200	NRR	AV	2525	777-24-001-00-01	PERFORM BC SEAT ELECTRICAL OPE	ERATION TEST FOLIND 23D SEAT INOP	L345	OPEN	09/22/2023
7020400	CAB	Milit	7.00	2020	777-24-001-00-01	TENTONIN DO SEAT ELECTRICAL OF E	TATION TEST FOUND 200 SEAT INCI	L345	OPEN	3.0
									_	
V II 0 400	000	NDD		5700	777 40 000 00 04					3.0
XJL3466	600 WNG	NRR	AE	5700	777-12-008-00-04	RHW L/E ACCESS PANEL 621 ACB BB	GB MB WB ZB QB RB AFB SCREWS FOUND WORN	L346	OPEN	09/22/2023
	WING								_	1.0
										1.0
XJL3474	500	NRR	AE	5700	777-57-856-01-01	LHW T/E ACCESS PANEL 552HB CB LE	3 SCREWS FOUND WORN	L347	OPEN	09/22/2023
	WNG									1.0
									-	1.0
XJL3482	500	NRR	AE	5700	777-57-856-01-01	PERFORM LHW T/E REAR SPAR CIC A	FTER CLEANING	L348	OPEN	09/22/2023
	WNG									4.0
									-	4.0
XJL3490	500	NRR	ΑE	5700	777-57-948-02-01	PERFORM RHW T/E REAR SPAR CIC	AFTER CLEANING	L349	OPEN	09/22/2023
	WNG									4.0
									-	4.0
										7.0

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

49 OF 83 PAGE:

RUN DATE: 9/28/2023 RUN TIME :

11:09

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL

515653

BMS571R1-2

STATUS: ALL

ORIG-STAGE: ALL PERIOD: ALL ESTIMATED MHR: ALL

STAGE: ALL

ORIGINATING CUST REF NO: ALL ATA NO: ALL

ZONE: ALL

AREA: ALL

DISPOSITION CODE: ALL

DEFECT TYPE: ALL

CTRL CODE:

REQUESTED BY:

REFERENCE NO:

TRADE: ALL

CUST ENDORSE: ALL TYPE CODE: ORIGINATOR: ALL

	ZONE	STG						STATUS	UPDATED DATE
JOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH NO DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
XJL3508	200	NRP	AV	3351	777-33-115-00-02	DISCONNECT ALL EMERGENCY LIGHT POWER SUPPLY ELECTRICAL CONNECTORS DURING AIRCRAFT POWER OFF	L350	WIP	09/23/2023
	CAB					PERIOD TO PREVENT BATTERY FAILURE.			0.0
						1C 1 LOWER DOWN ALL OVERDOOR PANELS.			2.0
						1C 2 REMOVE OFAR LH AFT MIRROR PANEL ASSY AND A PANEL IN THE RIGHT WALL OF THE AFT CLOSET.			1.0
						1C 3 REMOVE OFCR ENTRY MODULE A SUPPORT PANEL UNDER THE SECOND STEP AND ANOTHER SUPPORT PANEL ABOVE SEAT 2D			1.0
						1C 4 DISCONNECT ALL OVERDOOR EMERGENCY LIGHT POWER SUPPLY UNIT ELECTRICAL CONNECTORS.			5.0
						2C 5 RECONNECT ALL EMERGENCY LIGHT POWER SUPPLY UNIT ELECTRICAL CONNECTORS			5.0
						2C 6 DISCONNECT OFAR EMERGENCY LIGHT POWER SUPPLY ELECTRICAL CONNECTORS			1.0
						2C 7 DISCONNECT OFCR EMERGENCY LIGHT POWER SUPPLY ELECTRICAL CONNECTORS			1.0
						2C 8 RECONNECT OFAR EMERGENCY LIGHT POWER SUPPLY ELECTRICAL CONNECTORS			1.0
						3C 9 REINSTALL OFAR LH AFT MIRROR PANEL ASSY AND A PANEL IN THE RIGHT WALL OF THE AFT CLOSET			1.0
						3C 10 RECONNECT OFCR EMERGENCY LIGHT POWER SUPPLY ELECTRICAL CONNECTORS			1.0
						3C 11 REINSTALL OFCR ENTRY MODULE A SUPPORT PANEL UNDER THE SECOND STEP AND ANOTHER SUPPORT PANEL ABOVE SEAT 2D			1.0
						3C 12 REINSTALL ALL OVERDOOR PANELS.			2.0
						4C 13 CARRY OUT EMERGENCY LIGHT POWER SUPPLY UNIT INSTALLATION TEST			3.0
								-	25.0
XJL3516	200	NRR	Al	25	777-53-920-00-01	OFAR FWD CLOET LOWER DRAWER UPPER EDGE TRIM FOUND DISBOND	L351	OPEN	09/23/2023
	CAB								3.0
								-	3.0
XJL3524	200	NRP	SS	25	777-25-060-01-CX-01	C/A SEAT PAN VELCRO TAPE COVER FOUND BROKEN AT L1AFT	L352	OPEN	09/23/2023
	CAB								2.0
								-	
									2.0
XJL3532	200	NRP	SS	25	777-25-060-01-CX-01	C/A SEAT COVER FOUND DIRTY AT R1 R2FWD L2AFT L4 R5I/B L5I/B O/B TTL7EA	L353	OPEN	09/23/2023
	CAB								3.0
								-	3.0
XJL3540	200	NRP	SS	25	777-25-060-01-CX-01	C/A SEAT LOWER BACKRES SCREW NUT SPRING FOUND MISSING L1FWD	L354	OPEN	09/23/2023
	CAB						2001	0. 2.1	1.0
								-	
V II 2557	100	NDD	Δ.	0500	777 52 000 00 04	END GOOTH STACKS SIDE OF DAIL ISSUED BY THE END DROVEN THESE			1.0
XJL3557	100 LWR	NRR	Al	2500	777-53-822-00-01	FWD CGO LH STA540 SIDE GUIDE RAIL JOINT PLATE FND BROKEN. TTL2EA	L355	OPEN	09/23/2023
	LVVK								2.0
								-	2.0

REQUESTED BY:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE: 50 OF 83 RUN DATE: 9/28/2023

5.0

RUN TIME : 11:09

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL

515653

STATUS: ALL

ORIG-STAGE: ALL

PERIOD: ALL

ESTIMATED MHR: ALL

ORIGINATING CUST REF NO:

REFERENCE NO: BMS571R1-2

ALL

ATA NO: ALL CUST ENDORSE: ALL ZONE: ALL AREA: ALL

DISPOSITION CODE: ALL

DEFECT TYPE: ALL

TRADE: ALL

STAGE: ALL

CTRL CODE:					TYPE CODE:	ORIGINATOR: ALL			
	ZONE	STG						STATUS	UPDATED DATE
JOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH NO DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
XJL3565	100	NRR	Al	2500	777-53-822-00-01	FWD CGO HANDLING SYSTEM PDU ROLLER FND WORN AT 6R 7R 17R & 20R.	L356	OPEN	09/23/2023
	LWR								4.0
								-	4.0
XJL3573	100	NRR	ΑI	2500	777-53-822-00-01	FWD CGO THE LAST CENTER GUIDE RED LEAF FND STIFF.	L357	OPEN	09/23/2023
	LWR								0.5
								-	0.5
XJL3581	100	NRR	ΑI	2500	777-53-812-00-01	MEC INSULATION BLANKET FOUND BROKEN	L358	OPEN	09/23/2023
	LWR								6.0
								-	6.0
XJL3599	300 EMP	NRP	AE	5535	777-55-806-00-01	EMPREMOVE VERTICAL FIN L/E PANEL 321E FOR ACCESS.	L359	WIP	09/23/2023
	EIVIP								0.0
						1C 1 REMOVE VERTICAL FIN 321E ACCESS FAIRING FOR ACCESS. 1C 2 REMOVE VERTICAL V/FIN HF COMMUNICATION ANTENNA FEEDLINE CONNECTION ATTACH BOLT			2.0 0.5
						1C 3 REINSTALL THE L/E FRG 321E			4.0
						1C 4 RECONNECT HF COMMUNICATION ANTENNA FEED LINES CONNECTOR			1.0
						2C 5 CARRY OUT BONDING TEST BETWEEN HF ANTENNA AND THE STRUCTURE			0.5
						2C 6 CARRY OUT HF SYSTEM TEST			0.5
								-	8.5
XJL3607	200 CAB	NRR	Al	25	777-53-920-00-01	L5.L4.R4 DOOR BUSTLE EDGE TRIM FOUND TORN.	L360	WIP	09/24/2023
	CAB								6.0
								-	6.0
XJL3615	100	NRR	SM	5300	777-53-874-00-01	BULK CGO FLOOR PANEL ANCHOR NUT FOUND DAMAGED.TOTAL 4EA	L361	OPEN	09/23/2023
	LWR								4.0
								-	4.0
XJL3623	100	NRR	Al	2500	777-53-854-00-01	AFT CGO SIDEWALL FOUND WORN	L362	OPEN	09/23/2023
	LWR								4.0
								-	4.0
XJL3631	200	NRR	Al	56	777-53-904-00-01	M/D R1 DOOR WINDOW INSIDE FOUND DIRTY	L363	COMP	09/25/2023
	CAB								5.0
								-	5.0

ORIGINATING CUST REF NO:

515653

BMS571R1-2

ALL

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE: RUN DATE: 9/28/2023

RUN TIME :

51 OF 83

11:09

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

TYPE CODE:

JSN RANGE SELECTED: ALL STATUS: ALL ORIG-STAGE: ALL PERIOD: ALL ESTIMATED MHR: ALL

> ATA NO: ALL ZONE: ALL DISPOSITION CODE: ALL

DEFECT TYPE: ALL TRADE: ALL CUST ENDORSE: ALL AREA: ALL STAGE: ALL

ORIGINATOR: ALL

CTRL CODE:

TRL CODE :					TYPE CODE:	ORIGINATOR: ALL			CTATUC	LIDDATED DATE
	ZONE	STG							STATUS	UPDATED DATE
JOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH NO	DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
JL3649	200	NRR	Al	56	777-53-904-00-01	M/D L1 DOOR WINDOW INSIDE FOUND DIRTY		L364	COMP	09/25/2023
	CAB									5.0
									-	5.0
JL3656	200	NRR	Al	56	777-53-908-00-01	M/D L2 DOOR WINDOW INSIDE FOUND DIRTY		L365	COMP	09/25/2023
	CAB									5.0
									-	5.0
JL3664	200	NRR	Al	56	777-53-908-00-01	M/D R2 DOOR WINDOW INSIDE FOUND DIRTY		L366	COMP	09/25/2023
	CAB							2000	001111	5.0
									-	
JL3672	700	NRP	CL	32	777-900002-01-1-01	NOSE LANDING GEAR W/W AREA FND DIRTY.		1.007	MID	5.0
JL3072	LDG	INIXE	OL	32	777-900002-01-1-01	NOSE LANDING GEAR W/W AREA FIND DIRTT.		L367	WIP	09/24/2023
						1C 1 CLEAN THE AREA .				0.0 12.0
						1C 2 APPLY CIC.				6.0
									-	18.0
JL3680	700	NRP	CL	32	777-900002-01-1-01	RH MLG W/W AREA FND DIRTY		L368	WIP	09/24/2023
	LDG			-				2300	VVII	0.0
						1C 1 CLEAN THE AREA .				24.0
						1C 2 APPLY CIC.				10.0
									-	34.0
JL3698	700	NRP	CL	32	777-900002-01-1-01	LH MLG W/W AREA FND DIRTY.		L369	WIP	09/24/2023
	LDG			-				2309	VVII	0.0
						1C 1 CLEAN THE AREA .				24.0
						1C 2 APPLY CIC.				10.0
						7.0. 2. 7.0. 2. 0.0.			-	
JL3706	200	NRR	SS	25	777-25-040-03-CX-01	ED2 SEAT AIDDAS INEI ATADI E END EVDIDV DATE	AT:15A 26D 25D 24D 23D 22D 21D 20D 19D 18D 17D 16D 12D 11D		0.0511	34.0
11.3706	CAB	NKK	33	23	-01	TTL:14EA	. AT. 19A 26D 29D 24D 23D 22D 21D 20D 19D 16D 17D 16D 12D 11D	L370	OPEN	09/23/2023
	0								_	21.0
										21.0
IL3714	200	NRR	SS	25	777-C252440-04-02- 01	EY PAX SEAT COAT HOOK FND LOOSEN AT:63E		L371	OPEN	09/23/2023
	CAB									1.0
									-	1.0

ORIGINATING CUST REF NO:

515653

BMS571R1-2

ALL

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

PAGE: 52 OF 83

RUN DATE: 9/28/2023

(By JSN) RUN TIME : 11:09

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL STATUS: ALL ORIG-STAGE: ALL PERIOD: ALL ESTIMATED MHR: ALL

> ATA NO: ALL ZONE: ALL DISPOSITION CODE: ALL

DEFECT TYPE: ALL TRADE: ALL CUST ENDORSE: ALL AREA: ALL STAGE: ALL

TINE CODE.	ZONE	STC.			TIFE CODE.	ONGINATOR: ALI	-		STATUS	UPDATED DATE
JOB NO	AREA	316	TD	ATA	ORIG CUST REF NO.	CTRL SH NO	DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
XJL3722	200	NRR	SS	25	777-C252440-04-02-	EY PAX SEAT COAT HOOK FND MISSING AT:		L372	OPEN	09/23/2023
	CAB				01					1.0
									-	1.0
XJL3730	200	NRR	SS	25	777-C252440-04-02-	F ZONE EY PAX SEAT LITERATURE POCKET	SPRING FND LOOSEN AT:61A 62A 64A.B 66A 67A 68A 69A 71A 65J 62F 63D	L373	OPEN	09/23/2023
	CAB				01	64G 65E 65F 66F 67G 69E.G 71E.G 59A 60A.B		2010	01 211	8.0
									-	8.0
JL3748	200	NRR	SS	25	777-C252440-04-02-	F ZONE FY PAX SEAT LITERATURE POCKET	SPRING FND LOOSEN AT:42K 44J 45H 39F 40D 41D 41G 42D.E.F 43F 44D	L374	OPEN	09/23/2023
.0207 10	CAB				01	42B 43A TTL:14EA	GTANGETHE ESCALATION IN THE TEST TO THE TEST.	L374	OFLIN	4.0
									-	4.0
(JL3755	200	NRR	SS	25	777-C252410-01-01-	F/C SEAT RECLINE CABLE FOUND LOOSEN	AT 1D	1.075	ODEN	
OLO7 00	CAB	IVIXIX	00	20	01	THE SEAT RECEIVE CABLE FOUND ECOSEN	טווה	L375	OPEN	09/23/2023
									-	
JL3763	200	NRP	SS	25	777-25-060-01-CX-01	C/A CEAT DAN CODING FOUND LOCEN AT L	FOID	1.070	ODEN	1.0
JL3703	CAB	INIXE	33	25	777-23-000-01-CA-01	C/A SEAT PAN SPRING FOUND LOOSEN AT I	.3O/B	L376	OPEN	09/23/2023
									-	1.0
0774	200	NRR	00	0.5	777 OF 040 02 OV 04		ATE AT:11G 12G 16G 17G 18G 19G 20G 21G 22G 23G 24G 26G TTL:12EA			1.0
(JL3771	200 CAB	NKK	SS	25	777-25-040-03-CX-01 -01	FBZ SEAT AIRBAG INFLATOR FND EXPIRY D	ATE AT:TIG 12G 16G 17G 18G 19G 20G 21G 22G 23G 24G 26G TTL:TZEA	L377	OPEN	09/23/2023
									_	18.0
										18.0
JL3789	200 CAB	NRR	SS	25	777-25-040-03-CX-01 -01	FB2 SEAT AIRBAG INFLATOR FND EXPIRY D	ATE AT:11K 12K 16K 17K 18K 19K 20K 21K 22K 23K 24K 25K TTL:12EA	L378	OPEN	09/23/2023
	OAD								_	18.0
										18.0
(JL3797	500 WNG	NRR	GW	5700	777-57-856-01-01	LHW T/E ACCESS PANEL 552BB(3EA) CB(3EA	N) LB(3EA) SCREW FOUND SEIZED	L379	COMP	09/26/2023
	WING								_	9.0
									-	9.0
JL3805	500	NRR	SM	5700	777-57-856-01-01	LHW T/E ACCESS PANEL 552BB(3EA) CB(3EA	N) LB(3EA) ANCHOR NUT FOUND WORN	L380	OPEN	09/24/2023
	WNG									6.0
									-	6.0

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE: RUN TIME :

53 OF 83

RUN DATE: 9/28/2023 11:09

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL STATUS: ALL

515653

BMS571R1-2

ORIG-STAGE: ALL

ESTIMATED MHR: ALL

ORIGINATING CUST REF NO:

ALL

ATA NO: ALL

PERIOD: ALL ZONE: ALL

DISPOSITION CODE: ALL

DEFECT TYPE: ALL

REQUESTED BY:

REFERENCE NO:

TRADE: ALL

CUST ENDORSE: ALL

AREA: ALL STAGE: ALL

TRL CODE :					TYPE CODE:	ORIGINATOR :	ALL		0747110	
	ZONE	STG							STATUS	UPDATED DATE
JOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH NO	DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
(JL3813	200	NRR	SS	25	777-C252410-01-01- 01	F/C SEAT RECLINE CABLE FOUND LOO	SEN AT 1D	L381	OPEN	09/24/2023
	CAB				O I					2.0
									-	2.0
KJL3821	200	NRR	Al	2531	777-53-904-00-01	CABIN ZONE A G1 GALLERY OVEN1&3	NATER HOSE FOUND LEAK	L382	OPEN	09/24/2023
	CAB									3.0
									-	3.0
(JL3839	200	NRR	Al	2533	777-C250009-01-01-	GALLEY 1L CHILLER TEMPERATURE O	IT OF LIMIT	1202	ODEN	
(313039	CAB	INIXIX	AI	2333	R-01	GALLET IL CHILLER TEWPERATURE O	OF LIMIT	L383	OPEN	09/24/2023
									_	0.0
										0.0
(JL3847	200	NRR	Al	2531	777-53-904-00-01	CABIN ZONE A G5 GALLERY OVEN 2 W.	ATER HOSE FOUND LEAK	L384	OPEN	09/24/2023
	CAB									3.0
									-	3.0
(JL3854	200	NRR	Al	2533	777-C250009-01-01-	GALLEY 4R CHILLER MALFUNCTION		L385	OPEN	09/24/2023
	CAB				R-01					0.0
									-	0.0
(JL3862	200	NRR	Al	2531	777-53-904-00-01	CARIN ZONE A GZ GALLERY OVEN 2&3	GALLERY G6 OVEN 1&4 WATER HOSE FOUND LEAK	L386	OPEN	09/24/2023
.02002	CAB			200.	66 66 . 66 6 .	5.5 25.12 5. 5.12 6.12 6.12 6.12 6.12 6.12 6.12 6.12 6.12 6.12 6.12 6.1	0.111.000.11.000.11.001.001.001.001.001	L300	OFLIN	3.0
									-	
										3.0
JL3870	200 CAB	NRR	Al	2531	777-53-908-00-01	CABIN G3 GALLERY OVEN LOWER BUN	PER FOUND DAMAGE	L387	OPEN	09/24/2023
	CAB									5.0
									-	5.0
JL3888	200	NRR	Al	2500	777-53-900-00-01	COCKPIT LH RAIN COAT CLOSET INSID	E CATCH FOUND DAMAGE	L388	OPEN	09/24/2023
	CAB									1.0
									-	1.0
(JL3896	200	NRR	AV	3327	777-C330000-01-02-	GALLEY 2&3 LOWER CEILING PANEL L/	H AFT AREA LIGHT MALFUNCTION	L389	OPEN	09/24/2023
	CAB				01			2000	O. LIV	2.0
									_	
										2.0

ORIGINATING CUST REF NO:

515653

BMS571R1-2

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE: 54 OF 83

2C

RUN DATE : 9/28/2023 RUN TIME : 11:09

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE:

JSN RANGE SELECTED: ALL STATUS: ALL ORIG-STAGE: ALL PERIOD: ALL ESTIMATED MHR: ALL

ALL ATA NO : ALL ZONE : ALL DISPOSITION CODE : ALL

DEFECT TYPE: ALL TRADE: ALL CUST ENDORSE: ALL AREA: ALL STAGE: ALL

IRL CODE :	ZONE	STG			TYPE CODE:	ORIGINATOR:		1011	STATUS	UPDATED DAT
OB NO	AREA	NDD	TD	ATA	ORIG CUST REF NO.	CTRL SH NO	DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
L3904	200 CAB	NRR	AV	3327	777-C330000-01-02- 01	GALLEY 4&5 LOWER CEILING PANEL	. R/H FWD AREA LIGHT MALFUNCTION	L390	OPEN	09/24/2023
	OND								_	2.0
										2.0
_3912	500 WNG	NRR	GW	5700	777-12-008-00-03	LHW L/E ACCESS PANEL 521ZB(2EA) UB(2EA) TB(2EA) QB(3EA) MB(1EA) FB(1EA) SCREWS FOUND SEIZED	L391	WIP	09/27/2023
	WING								_	11.0
										11.0
_3920	500 WNG	NRR	SM	5700	777-12-008-00-03	LHW L/E ACCESS PANEL 521ZB(2EA)) UB(2EA) TB(2EA) QB(3EA) MB(1EA) FB(1EA) ANCHOR NUT FOUND WORN	L392	OPEN	09/24/2023
	WNG									6.0
									-	6.0
L3938	200	NRP	AV	2532	777-C250008-01-01- 01	G6 OVEN 2 CONTROL PANEL ON/OF	F BUTTOM MALFUNCITON	L393	OPEN	09/24/2023
	CAB				· ·					1.5
									-	1.5
L3946	500	NRR	GW	5708	777-57-864-01-01	LHW T/E ACCESS PANEL561LB(2EEA	A SCREWS FOUND SEIZED	L394	COMP	09/26/2023
	WNG									2.0
									-	2.0
L3953	500	NRR	SM	5708	777-57-864-01-01	LHW T/E ACCESS PANEL561LB(2EA)	ANCHOR NUT FOUND WORN	L395	OPEN	09/24/2023
	WNG									1.0
									-	1.0
L3961	100	NRR	CL	2500	777-53-818-00-01	FWD CARGO CEILING PANEL SURFA	ACE FND DIRTY	L396	OPEN	09/24/2023
	LWR									7.0
									-	7.0
L3979	100	NRR	CL	2500	777-53-818-00-01	FWD CARGO SIDEWALL PANEL SUR	FACE FND DIRTY	L397	OPEN	09/24/2023
	LWR									7.0
									-	7.0
_3987	100	NRR	CL	2500	777-53-854-00-01	AFT CARGO CEILING PANEL SURFA	CE FND DIRTY	L398	OPEN	09/24/2023
	LWR									7.0
									-	7.0

515653

REQUESTED BY:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE:

55 OF 83

RUN DATE: 9/28/2023 11:09

REFERENCE NO: BMS571R1-2 RUN TIME :

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL STATUS: ALL ORIG-STAGE: ALL PERIOD: ALL ESTIMATED MHR: ALL ORIGINATING CUST REF NO: ATA NO: ALL ZONE: ALL DISPOSITION CODE: ALL ALL

DEFECT TYPE: ALL TRADE: ALL CUST ENDORSE: ALL AREA: ALL STAGE: ALL

TYPE CODE: CTRL CODE : ORIGINATOR · ALL

CTRL CODE :					TYPE CODE:	ORIGINATOR	: ALL			
	ZONE	STG							STATUS	UPDATED DATE
JOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH NO	DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
XJL3995	100	NRR	CL	2500	777-53-854-00-01	AFT CARGO SIDEWALL PANEL SUF	RFACE FND DIRTY	L399	OPEN	09/24/2023
	LWR									7.0
									-	7.0
XJL4001	100	NRR	CL	2500	777-53-870-00-01	BULK CARGO COMP CEILING AND	SIDEWALL PANEL FND DIRTY	L400	OPEN	09/24/2023
	LWR									5.0
									-	5.0
XJL4019	100	NRR	CL	2500	777-53-862-00-01	AFT CARGO AND BULK CGO FLOO	R PANEL FND DIRTY	L401	OPEN	09/24/2023
	LWR									10.0
									-	10.0
XJL4027	100	NRR	CL	2500	777-53-862-00-01	AFT CARGO ROLLER TRAY FND DI	RTY	L402	OPEN	09/24/2023
	LWR									16.0
									-	16.0
XJL4035	100	NRR	CL	2500	777-53-822-00-01	FWD CARGO FLOOR PANEL SURFA	ACE FND DIRTY	L403	OPEN	09/24/2023
	LWR									7.0
									-	7.0
XJL4043	100	NRR	CL	2500	777-53-822-00-01	FWD CARGO ROLLER TRAY FND D	DIRTY	L404	OPEN	09/24/2023
	LWR									16.0
									-	16.0
XJL4050	200	NRR	Al	2541	777-53-908-00-01	CABIN LAV A C D F TOILET SHROU	ID ANTICOLLISION PLATE FOUND MISSING	L405	OPEN	09/24/2023
	CAB									4.0
									-	4.0
XJL4068	200	NRR	Al	2541	777-53-908-00-01	CABIN LAV M L H TOILET SHROUD	ANTICOLLISION PLATE FOUND MISSING	L406	OPEN	09/24/2023
	CAB							L400	OI LIV	3.0
									-	3.0
XJL4076	200	NRR	Al	2541	777-53-908-00-01	CARIN LAV M TOILET SHROLID SEA	AT COVER DAMPER COVER FOUND CRACKED	L407	OPEN	09/24/2023
X0L+070	CAB	MAC	7.0	2041	777-00-000-00-01	ONDING ENVINTOILE FOR INCODE OF	TOOVER DAWN EN GOVERN GOND GIVIONED	L407	OPEN	3.0
									-	
										3.0

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE: 56 OF 83 RUN DATE: 9/28/2023

RUN TIME : 11:09

PROJECT: XJ

REQUESTED BY:

REFERENCE NO:

CUSTOMER: CX

A/C TYPE: 777

A/C REGN: B-KPV

CHECK TYPE: 2C

ESTIMATED MHR: ALL

JSN RANGE SELECTED: ALL ORIGINATING CUST REF NO: ALL STATUS: ALL

PERIOD: ALL ZONE: ALL

DISPOSITION CODE: ALL

DEFECT TYPE: ALL

CTRL CODE:

515653

BMS571R1-2

TRADE: ALL

CUST ENDORSE: ALL

ORIG-STAGE: ALL

ATA NO: ALL

AREA: ALL STAGE: ALL

TYPE CODE: ORIGINATOR: ALL

TINE CODE .	70115	0.70			THEOODE			ONIONATON. ALL		STATUS	UPDATED DAT
	ZONE	SIG									
OB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTR	L SH N	DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
L4084	500 WNG	NRR	SS	5700	777-20-251-10-01	LHV	V L/E ACC	ESS PANEL511AB EXTERNAL SURFACE FOUND DELAMINATION	L408	WIP	09/25/2023
						1C	1	DO AN INSPECTION TO FIND THE DAMAGE DIMENSION			1.0
						1C	2	DO THE REPAIR TO DAMAGED AREA			20.0
						1C	3	DO THE POST REPAIR INSPECTION			1.0
						1C	4	APPLY RESIN AND SMOOTH OUT			2.0
						2C	5	APPLY CONDUCTIVE COATING			0.5
						2C	6	MEASURE THE RESISTIVITY OF CONDUCTIVE COATING			0.5
						2C	7	RESTORE SURFACE FINISH			0.5
						2C	8	FILL IN THE SDR FORM			0.0
										-	25.5
_4092	500 WNG	NRR	SS	5700	777-20-251-10-01	RHV	W L/E AC	CESS PANEL611GB EXTERNAL SURFACE FOUND DELAMINATION	L409	WIP	09/25/2023
	WING										0.0
						1C	1	DO AN INSPECTION TO FIND THE DAMAGE DIMENSION			1.0
						1C	2	DO THE REPAIR TO DAMAGED AREA			20.0
						1C	3	DO THE POST REPAIR INSPECTION			1.0
						1C	4	APPLY RESIN AND SMOOTH OUT			2.0
						2C	5	APPLY CONDUCTIVE COATING			0.5
						2C	6	MEASURE THE RESISTIVITY OF CONDUCTIVE COATING			0.5
						2C	7	RESTORE SURFACE FINISH			0.5
						2C	8	FILL IN THE SDR FORM			0.0
										-	25.5
4100	500	NRR	SS	5700	777-20-251-10-01	RHV	W L/E AC	CESS PANEL611KB EXTERNAL SURFACE FOUND DELAMINATION	L410	WIP	09/25/2023
	WNG										0.0
						1C	1	DO AN INSPECTION TO FIND THE DAMAGE DIMENSION			1.0
						1C	2	DO THE REPAIR TO DAMAGED AREA			20.0
						1C	3	DO THE POST REPAIR INSPECTION			1.0
						1C	4	APPLY RESIN AND SMOOTH OUT			2.0
						2C	5	APPLY CONDUCTIVE COATING			0.5
						2C	6	MEASURE THE RESISTIVITY OF CONDUCTIVE COATING			0.5
						2C	7	RESTORE SURFACE FINISH			0.5
						2C	8	FILL IN THE SDR FORM			0.0
										-	25.5

0PPC DISTRIBUTION:

ORIGINATING CUST REF NO:

515653

BMS571R1-2

ALL

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE: 57 OF 83

RUN DATE: 9/28/2023

RUN TIME : 11:09

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL STATUS: ALL ORIG-STAGE: ALL PERIOD: ALL ESTIMATED MHR: ALL

> ATA NO: ALL ZONE: ALL DISPOSITION CODE: ALL

TRADE: ALL DEFECT TYPE: ALL CUST ENDORSE: ALL AREA: ALL STAGE: ALL

ZONE AREA	STG			TYPE CODE:	ORIGINATOR: ALL			0747110	
	STG								UPDATED DAT
AKEA		TD	ATA	ODIC CUCT DEF NO	CTRL CLINO	DEFECT DESCRIPTION	ION	STATUS	
	NRR	TD AV	ATA 2525	ORIG CUST REF NO.	CTRL SH NO	DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
200 CAB	NKK	AV	2525	777-24-001-00-01	PC POWER TEST FOUND 31E PC OULET RED LI	GHI	L411	OPEN	09/24/2023
OND									2.0
								-	2.0
300	NRP	AV	2361	777-55-806-00-01	VERTICAL FIN FWD #1 STATIC DISCHARGER BF	ROKEN.	L412	OPEN	09/24/2023
EMP									2.0
								-	2.0
200	NRM	Al	2560	AEO-29097-01	CABIN PASSENGER LIFE VEST FOUND EXPIRED	D DAY LESS THAN 4.5 MONTHS 154EA	L413	WIP	09/28/2023
CAB									7.5
								-	7.5
200	NRM	Al	2560	AEO-29097-01	CABIN SPARE LIFE VEST FOUND EXPIRED DAY	LESS THAN 4.5 MONTHS 3EA IN 70AC	L414	WIP	09/26/2023
CAB									1.0
								-	1.0
200	NRM	ΔI	2560	AFO-29097-01	CARIN SPARE LIFE VEST FOLIND EXPIRED DAY	LESS THAN 4.5 MONTHS 1EA IN 70HK	1.415	WID	09/28/2023
CAB	14140	,	2000	7120 20001 01	OVER OF THE ENE VEGT TO GOOD EXTENSES BY	ELOO TIMA 4.5 MONTHO IEANN TOTAL	L413	VVIP	1.0
								-	
000	NDM		0500	AEO 00007.04	0.400.00.405.005.005.005.005.005.005.005				1.0
	NRM	Al	2560	AEO-29097-01	CABIN SPARE INFANT LIFE VEST FOUND EXPIR	ED DAY LESS THAN 4.5 MONTHS 11EA IN 70AC	L416	WIP	09/28/2023
0/10								_	1.0
									1.0
600	NRR	AV	2361	777-57-958-02-01	RH WING TIP 1 EA STATIC DISCHARGER BROKE	EN.	L417	OPEN	09/24/2023
WNG									2.0
								-	2.0
300	NRR	AV	2361	777-55-830-01-01	LEFT STAB TIP 1EA STATIC DISCHARGER BROK	KEN.	L418	OPEN	09/24/2023
EMP									2.0
								-	2.0
300	NRR	AV	2361	777-55-850-02-01	RIGHT STAB. TIP 1EA STATIC DISCHARGER BRI	OKEN.	L419	OPEN	09/24/2023
EMP									2.0
								-	2.0
3 E 2 C 2 C 2 C 3 E 3	200 CAB 200 CAB 200 CAB 200 CAB 300 WNG	200 NRM CAB 300 NRR WNG 300 NRR	ROO NRP AVEMP ROO NRM ALCAB ROO NRR AVEMP ROO NRR AVEMP	NRP AV 2361 EMP NRM AI 2560 CAB NRR AV 2361 EMP	NRP AV 2361 777-55-806-00-01 NRM AI 2560 AEO-29097-01 NRR AV 2361 777-57-958-02-01 NRR AV 2361 777-55-830-01-01	300 NRP AV 2361 777-55-806-00-01 VERTICAL FIN FWD #1 STATIC DISCHARGER BEAMP 200 NRM AI 2560 AEO-29097-01 CABIN PASSENGER LIFE VEST FOUND EXPIRED DAY CABIN SPARE LIFE VEST FOUND EXPIRED DAY CAB 200 NRM AI 2560 AEO-29097-01 CABIN SPARE LIFE VEST FOUND EXPIRED DAY CABIN SPARE LIFE VEST FOUND EXPIRED DAY CABIN SPARE INFANT LIFE VEST FOUND EXPIRED DAY CABIN SPARE LIFE VES	NRP AV 2361 777-55-806-00-01 VERTICAL FIN FWD #1 STATIC DISCHARGER BROKEN. NRM AI 2560 AEO-29097-01 CABIN PASSENGER LIFE VEST FOUND EXPIRED DAY LESS THAN 4.5 MONTHS 154EA NRM AI 2560 AEO-29097-01 CABIN SPARE LIFE VEST FOUND EXPIRED DAY LESS THAN 4.5 MONTHS 3EA IN 70AC NRM AI 2560 AEO-29097-01 CABIN SPARE LIFE VEST FOUND EXPIRED DAY LESS THAN 4.5 MONTHS 1EA IN 70HK NRM AI 2560 AEO-29097-01 CABIN SPARE LIFE VEST FOUND EXPIRED DAY LESS THAN 4.5 MONTHS 1EA IN 70HK NRM AI 2560 AEO-29097-01 CABIN SPARE INFANT LIFE VEST FOUND EXPIRED DAY LESS THAN 4.5 MONTHS 11EA IN 70AC NRM AV 2361 777-57-958-02-01 RH WING TIP 1 EA STATIC DISCHARGER BROKEN.	NRM AI 2560 AEO-29097-01 CABIN PARSENGER LIFE VEST FOUND EXPIRED DAY LESS THAN 4.5 MONTHS 154EA L413	100 NRP AV 2361 777-55-806-00-01 VERTICAL FIN PWD #1 STATIC DISCHARGER BROKEN. L412 OPEN 100 NRM AI 2560 AEO-29097-01 CABIN PASSENGER LIFE VEST FOUND EXPIRED DAY LESS THAN 4.5 MONTHS 154EA 100 AEO AEO AEO-29097-01 CABIN SPARE LIFE VEST FOUND EXPIRED DAY LESS THAN 4.5 MONTHS 3EA IN 70AC 100 NRM AI 2560 AEO-29097-01 CABIN SPARE LIFE VEST FOUND EXPIRED DAY LESS THAN 4.5 MONTHS 1EA IN 70HK 100 NRM AI 2560 AEO-29097-01 CABIN SPARE LIFE VEST FOUND EXPIRED DAY LESS THAN 4.5 MONTHS 1EA IN 70HK 100 NRM AI 2560 AEO-29097-01 CABIN SPARE INFANT LIFE VEST FOUND EXPIRED DAY LESS THAN 4.5 MONTHS 11EA IN 70HK 100 NRM AI 2560 AEO-29097-01 CABIN SPARE INFANT LIFE VEST FOUND EXPIRED DAY LESS THAN 4.5 MONTHS 11EA IN 70HK 100 NRR AV 2361 777-57-958-02-01 RH WING TIP 1 EA STATIC DISCHARGER BROKEN. 100 NRR AV 2361 777-55-830-01-01 LEFT STAB TIP 1EA STATIC DISCHARGER BROKEN. 100 NRR AV 2361 777-55-830-01-01 RIGHT STAB. TIP 1EA STATIC DISCHARGER BROKEN. 100 NRR AV 2361 777-55-850-02-01 RIGHT STAB. TIP 1EA STATIC DISCHARGER BROKEN. 100 OPEN

515653

BMS571R1-2

ALL

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE: 58 OF 83

RUN DATE: 9/28/2023 RUN TIME : 11:09

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

STATUS: ALL ORIG-STAGE: ALL PERIOD: ALL JSN RANGE SELECTED: ALL ESTIMATED MHR: ALL

> ATA NO: ALL ZONE: ALL DISPOSITION CODE: ALL

DEFECT TYPE: ALL TRADE: ALL CUST ENDORSE: ALL AREA: ALL STAGE: ALL

ORIGINATING CUST REF NO:

						***************************************	AUCH TILL	On tol: The		
TRL CODE :					TYPE CODE:	ORIGINATOR: ALL			STATUS	UPDATED DAT
JOB NO	ZONE AREA	SIG	TD	ATA	ORIG CUST REF NO.	CTRL SH NO	DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
JL4209	100	NRP	AE	0711	777-900002-01-1-01	FUS-PERFORM THE A/C SPECIAL JACKING.	BEI EUT BEGOMI TION	L420	OPEN	09/24/2023
	FUS			• • • • • • • • • • • • • • • • • • • •		REF TO XMN TASK CARD: TA07000101-BOE		L420	OI LIV	0.0
									-	0.0
JL4217	200	NRR	AV	2525	777-25-040-03-CX-01	FB2 BC SEAT COMPLIANCE CHECK OF EMA FOUN	ID 56EA EMA EXPIRY DATE OUT OF LIMIT	L421	OPEN	0.0
,_ ,_ ,,	CAB	14141	7.0	2020	-01	T BZ BO OLYT GOWN ENWOL GITEOR OF ENWYT GOV	AD SOLIT LIMIT DATE SO FOT LIMIT	L42 I	OPEN	112.0
									-	
JL4225	500	NRR	ΑE	5700	777-57-848-01-01	LHW WING TIP L/E FAIRING SEALANT FOUND MIS	SING	1.400	MID	112.0
JL4223	WNG	IVIXIX	AL	3700	777-040-01-01	LIW WING HE LET AIRING SEALANT FOUND WIS	Siro	L422	WIP	09/27/2023
									-	
JL4233	200	NRM	Al	2560	AEO-29573-01	CARIN DRE INCIDE GEAR AT DOOR 5 ON LOWER S	SIDE WALL PANEL ACROSS FROM STAIRCASE FOUND EXPIRE	D 1400	OPEN	1.0
JL4233	CAB	INIXIVI	Al	2300	ALO-29373-01	CABIN FBE INSIDE OFAR AT DOOR 3 ON LOWER 3	SIDE WALL PANEL ACKOSS FROM STAIRCASE FOUND EXFIRE	D L423	OPEN	09/24/2023
									-	
JL4241	200	NRR	Al	2521	777-53-908-00-01	CABIN G2R GALLERY COMPARTMENT R2-12 ICE D	DRAWER TRACK FOLING DAMACE		0.0511	1.0
JL424 I	CAB	INIXIX	AI	2001	777-33-906-00-01	CABIN GZR GALLERY COMPARTMENT RZ-12 ICE L	DRAVVER TRACK FOUND DAINIAGE	L424	OPEN	09/24/2023
									_	5.0
II 4050	000	NDD	۸.	20	777 00 004 40 05	DUM FUEL TANK ACCESS DAILS FOUND DIDTY				5.0
JL4258	600 WNG	NRR	AE	28	777-28-021-10-05	RHW FUEL TANK ACCESS PNLS FOUND DIRTY		L425	COMP	09/26/2023
									_	8.0
	500	NDD		00	777 00 004 40 04					8.0
JL4266	500 WNG	NRR	AE	28	777-28-021-10-04	LHW FUEL TANK ACCESS PNLS FOUND DIRTY		L426	COMP	09/26/2023
									_	8.0
										8.0
JL4274	100 FUS	NRR	AE	2152	777-53-830-00-02	FUS-RH PACK HEAT EXCHANGER FOUND CRACK	ED.	L427	OPEN	09/24/2023
	100								_	0.0
			. –							0.0
JL4282	100 FUS	NRR	AE	2152	777-53-830-00-02	FUS-RH PACK DIFFUSER HOUSING FOUND DE LA	MINATION.	L428	OPEN	09/24/2023
	1 00									0.0
									-	0.0

REQUESTED BY:

REFERENCE NO:

DEFECT TYPE: ALL

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE: 59 OF 83 RUN DATE: 9/28/2023

RUN TIME : 11:09

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL

515653

BMS571R1-2

STATUS: ALL ORIG-STAGE: ALL

ESTIMATED MHR: ALL

ORIGINATING CUST REF NO:

ALL

ATA NO: ALL

PERIOD: ALL ZONE: ALL AREA: ALL

DISPOSITION CODE: ALL

STAGE: ALL

CTRL CODE:

TRADE: ALL TYF

CUST ENDORSE: ALL

PE CODE:	ORIGINATOR :	ALL

	ZONE	STG				STA	TUS	UPDATED DATE
JOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH NO DEFECT DESCRIPTION JSN STA	TUS	EST Mhr
KJL4290	100	NRR	AE	2152	777-53-830-00-02	FUS-RH PACK RAM AIR INLET DUCT AFT SLEEVE CONNECTOR FOUND TORN. L429 OP	ΞN	09/24/2023
	FUS							2.0
							-	2.0
XJL4308	100	NRR	AE	2152	777-53-830-00-02	FUS-RH PACK LWR FCV BONDING BROKEN. 1430 OP		
NJL4300	FUS	INIXIX	AL	2102	777-33-030-00-02	FUS-RH PACK LWR FCV BONDING BROKEN. L430 OP	ΞN	09/24/2023
	. 00					1C 1 REPLACE THE BONDING.		0.0 1.0
						1C 2 DO THE BONDING TEST.		0.5
							-	1.5
KJL4316	300	NRR	SM	5500	777-55-861-00-01	RIGHT SIDE HORIZONTAL STABILIZER T/E ACCESS PANEL 345GXB 3 EA ANCHOR NUT BROKEN 1.431 OP		
NJL43 10	EMP	INIXIX	SIVI	5500	777-55-661-00-01	RIGHT SIDE HORIZONTAL STABILIZER T/E ACCESS PANEL 345GXB 3 EA ANCHOR NUT BROKEN L431 OP	ΞN	09/24/2023
	LIVII							3.0
							-	3.0
(JL4324	100	NRR	ΑE	2152	777-53-830-00-02	FUS-RH PACK THE CONDITIONING LOW LIMIT VALVES 2EA BONDINGS BROKEN. L432 OP	ΞN	09/24/2023
	FUS							0.0
						1C 1 REPLACE THE BONDING.		1.0
						1C 2 DO THE BONDING TEST.		0.5
							-	1.5
(JL4332	100	NRR	ΑE	2152	777-53-830-00-02	FUS-RH PACK THE CONDITIONING ECONOMY VALVE BONDING BROKEN. L433 OP	ΞN	09/24/2023
	FUS							0.0
						1C 1 REPLACE THE BONDING.		1.0
						1C 2 DO THE BONDING TEST.		0.5
							-	1.5
(JL4340	100	NRR	ΑE	2152	777-53-830-00-02	FUS-RH PACK RAM AIR INLET DUCT MIDDLE BONDING BROKEN. L434 OP	ΞN	09/24/2023
	FUS							0.0
						1C 1 REPLACE THE BONDING.		1.0
						1C 2 DO THE BONDING TEST.		0.5
							-	1.5

515653

BMS571R1-2

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

AREA: ALL

PAGE: 60 OF 83

RUN TIME :

STAGE: ALL

RUN DATE: 9/28/2023

11:09

5.0

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL STATUS: ALL ORIG-STAGE: ALL PERIOD: ALL ESTIMATED MHR: ALL

ORIGINATING CUST REF NO: ALL ATA NO: ALL ZONE: ALL DISPOSITION CODE: ALL

DEFECT TYPE: ALL TRADE: ALL CUST ENDORSE: ALL

CTRL CODE :					TYPE CODE:	ORIGINATOR: ALL			
	ZONE	STG						STATUS	UPDATED DATE
JOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH NO DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
XJL4357	500	NRR	SS	5700	777-12-008-00-02	RHW L/E ACCESS PANEL611CB EXTERNAL SURFACE FOUND DELAMINATION	L435	WIP	09/25/2023
	WNG								0.0
						1C 1 DO AN INSPECTION TO FIND THE DAMAGE DIMENSION			1.0
						1C 2 DO THE REPAIR TO DAMAGED AREA			12.0
						1C 3 DO THE POST REPAIR INSPECTION			1.0
						1C 4 APPLY RESIN AND SMOOTH OUT			2.0
						2C 5 FILL IN THE SDR FORM			0.0
						2C 6 APPLY CONDUCTIVE COATING			1.0
						2C 7 MEASURE THE RESISTIVITY OF CONDUCTIVE COATING			0.5
						2C 8 RESTORE SURFACE FINISH			0.0
								-	17.5
XJL4365	200	NRP	AV	3351	777-33-060-01-CX-01	EMERGENCY LIGHT TEST FOUND 1D.2D AISLE EMERGENCY LIGHT COVER MISSING	L436	OPEN	09/24/2023
	CAB								2.0
								-	2.0
XJL4373	200	NRP	AV	3351	777-33-060-01-CX-01	REMOVE THE CEILING PANEL FOUND 67HK. 65HK CONNECTOR CRACK	L437	OPEN	09/24/2023
	CAB								2.0
								-	2.0
XJL4381	100	NRR	AE	2100	777-53-830-00-01	LEFT AIR CONDITIONING SYSTEM RAM AIR INLET DUCT OUTBOARD SUPPORT ROD FOUND ROD END BEARING	L438	OPEN	09/24/2023
7024001	FUS	IVIXIX	/\L	2100	777-00-000-00-01	WORN	L430	OPEN	
								_	2.0
									2.0
XJL4399	300	NRR	AE	5500	777-55-824-00-01	VERTICAL STABILIZER FORWARD TIP FAIRING 327 1 EA BONDING JUMPER FOUND WIRE BROKEN	L439	WIP	09/26/2023
	EMP								0.0
						1C 1 REPLACE THE BONDING.			1.0
						1C 2 DO THE BONDING TEST.			0.5
								-	1.5
XJL4407	300	NRR	ΑE	5500	777-55-824-00-01	VERTICAL STABILIZER TIP FAIRING 327 FOUND BULB SEAL TORN	L440	COMP	09/27/2023
	EMP								2.0
								-	2.0
XJL4415	200	NRM	CL	2500	AEO-29097-01	CABIN FLASH LIGHT BASE FOUND DIRTY	L441	OPEN	09/24/2023
	CAB						L 14 I	OI LIN	5.0
								_	5.0
									5.0

REQUESTED BY:

REFERENCE NO:

DEFECT TYPE: ALL

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE: 61 OF 83

RUN TIME :

RUN DATE: 9/28/2023

11:09

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL

515653

BMS571R1-2

STATUS: ALL

ORIG-STAGE: ALL

PERIOD: ALL

ESTIMATED MHR: ALL DISPOSITION CODE: ALL

ORIGINATING CUST REF NO:

ALL

ATA NO: ALL ZONE: ALL CUST ENDORSE: ALL AREA: ALL

CTRL CODE:

TRADE: ALL TYPE CODE:

ORIGINATOR: ALL

STAGE:	ALL	

CIRL CODE :					TYPE CODE:	ORIGINATOR: ALL	•			
	ZONE	STG							STATUS	UPDATED DATE
JOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH NO	DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
XJL4423	200	NRM	Al	2560	AEO-29097-01	CABIN EMERGENCY EQUIPMENT SECURITY	SEAL FOUND DAMAGE	L442	WIP	09/28/2023
	CAB									1.0
									-	1.0
XJL4431	200	NRR	SS	25	777-C252430-01-03-		T SCREW FOUND LOOSEN AT:32A 30E F 31E 32D 33F G 34D EF G 34K 33H	L443	WIP	09/26/2023
	CAB				01	K 32H 31D 30D 31A 34C 33C TOTAL:20EA				10.0
									-	10.0
XJL4449	200	NRR	SS	25	777-C252430-01-06-	PEY PAX SEAT BACK REST HYD FWD COVER	R &SCREW FOUND MISSING AT:33A 34A TOTAL:2EA	L444	OPEN	09/25/2023
	CAB				01					1.0
									-	1.0
XJL4456	200	NRR	SS	25	777-C252430-01-04-	PEY PAX SEAT CONSOLE FWD COVER FOUN	ID CRACKED AT:34AC 31FG TOTAL:2EA	L445	OPEN	09/25/2023
	CAB				01					2.0
									-	2.0
XJL4464	200	NRR	SS	25	777-C252430-01-03-	PEY PAX SEAT LEGREST HYD SCREW FOUN	D LOOSEN AT:33A C 34A C 30E 32H 32E 33D TOTAL:8EA	L446	WIP	09/26/2023
	CAB				01					4.0
									-	4.0
XJL4472	200	NRR	SS	25	777-C252430-01-03-	PEY PAX SEAT LEGREST BUTTON CABLE OF	PERATION FOUND TIGHTEN AT:33A H TOTAL:2EA	L447	WIP	09/26/2023
	CAB				01					1.0
									-	1.0
XJL4480	200	NRR	SS	25	777-C252430-01-06-	PEY PAX SEAT BACK REST HYD FWD COVER	R SCREW FOUND MISSING AT:33C	L448	OPEN	09/25/2023
	CAB				01					0.5
									-	0.5
XJL4498	200	NRR	SS	25	777-C252430-01-03-	PEY PAX SEAT BOTTOM PAN STRUCTURE FO	OUND CRACKED AT:33A 30D E F 32G TOTAL:5EA	L449	OPEN	09/25/2023
	CAB				01					5.0
									-	5.0
XJL4506	200	NRR	SS	25	777-C252430-01-05-	PEY PAX SEAT ARM REST LOWER PLUG FOL	JND MISSING AT:33A 33F 34G (2EA) 33H TOTAL:5EA	L450	OPEN	09/25/2023
	CAB				01				-	2.5
									-	2.5
										2.0

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE: 62 OF 83

RUN DATE: 9/28/2023 RUN TIME : 11:09

0.5

PROJECT: XJ

CTRL CODE:

REQUESTED BY:

REFERENCE NO:

CUSTOMER: CX

ALL

A/C TYPE: 777

A/C REGN: B-KPV

CHECK TYPE: 2C

ESTIMATED MHR: ALL

JSN RANGE SELECTED: ALL ORIGINATING CUST REF NO:

STATUS: ALL

ORIG-STAGE: ALL ATA NO: ALL

DISPOSITION CODE: ALL

DEFECT TYPE: ALL

515653

BMS571R1-2

TRADE: ALL

CUST ENDORSE: ALL

AREA: ALL STAGE: ALL

PERIOD: ALL

ZONE: ALL

TYPE CODE: ORIGINATOR: ALL

CIRL CODE.					TIPE CODE.	ORIGINATOR. A	LL			
	ZONE	STG							STATUS	UPDATED DATE
JOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH NO	DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
XJL4514	200	NRR	SS	25	777-C252430-01-05-	PEY PAX SEAT ARM REST AFT PLUG FOU	ND MISSING AT:33A 34A 32K 34K 32A K TOTAL:6EA	L451	OPEN	09/25/2023
	CAB				01					3.0
									-	3.0
XJL4522	200	NRR	SS	25	777-C252430-01-03-	PEY PAX SEAT AFT FOOTREST WASHER I	OUND MISSING AT:32A C 30E(2EA) 31D F G 32D 33E(3EA) TOTAL:11EA	L452	OPEN	09/25/2023
	CAB				01					11.0
									-	11.0
XJL4530	200	NRR	SS	25	777-C252430-01-03-	PEY PAX SEAT LEGREST OPERATION FOL	IND NOISE AT:34A 31E 34D TOTAL:3EA	L453	WIP	09/26/2023
	CAB				01					1.5
									-	1.5
XJL4548	200	NRR	SS	25	777-C252430-01-05-	PEY PAX SEAT ARM REST TIRM CAP FOU	ND LOOSEN AT:32A 32G 34H TOTAL:3EA	L454	WIP	09/26/2023
	CAB				01					1.5
									-	1.5
XJL4555	200	NRR	SS	25	777-C252430-01-03-	PEY PAX SEAT BOTTOM PAN FWD PLUG S	CREW FOUND LOOSEN AT:32C 33C	L455	WIP	09/26/2023
	CAB				01					1.0
									-	1.0
XJL4563	200	NRR	SS	25	777-C252430-01-06-	PEY PAX SEAT BACK REST HYD SIDE BAY	SCREW FOUND LOOSEN AT:32C 34C	L456	WIP	09/26/2023
	CAB				01			2100	**	1.0
									-	1.0
XJL4571	200	NRR	SS	25	777-C252430-01-03-	PEY PAX SEAT AFT FOOTREST BUSHING	FOUND MISSING AT:31A 33E 33F G TOTAL:3EA	L457	OPEN	09/25/2023
	CAB				01			L431	OI LIV	3.0
									-	3.0
XJL4589	200	NRR	SS	25	777-C252430-01-03-	PEY PAX SEAT I EGREST SUPPORT BRAC	KET PIN AND WASHER&CLIP AND BUSHING FOUND MISSING AT:34A	L458	OPEN	09/25/2023
702 1000	CAB	14141	00	20	01	TETTINGEN ELONEOT GOTT ON BINNO	ALTERNATION OF THE POST WAS A STREET AND THE STREET	L436	OPEN	1.0
									-	
XJL4597	200	NRR	SS	25	777-C252430-01-06-	PEY PAX SEAT BACK REST ATT HEADRES	T SLIDE TRACK EQUIND LOQSEN AT 21C		\A/IE	1.0
AJL409/	CAB	INIXIX	33	۷۵	01	FLI FAN SEAT DAON KEST ATT HEADKES	I SLIDE TIMON FOUND LOOSEN AT.STO	L459	WIP	09/26/2023
									_	0.5

DISTRIBUTION:

REQUESTED BY:

REFERENCE NO:

DEFECT TYPE: ALL

0PPC TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

63 OF 83 PAGE: RUN DATE: 9/28/2023

0747110

RUN TIME :

LIDDATED DATE

11:09

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL

515653

BMS571R1-2

STATUS: ALL ORIG-STAGE: ALL PERIOD: ALL

ESTIMATED MHR: ALL DISPOSITION CODE: ALL

ORIGINATING CUST REF NO: ALL

TRADE: ALL

ATA NO: ALL ZONE: ALL CUST ENDORSE: ALL AREA: ALL

STAGE: ALL

CTRL CODE:

TYI

YPE CODE:	ORIGINATOR :	ALL	

	ZONE	STG							STATUS	UPDATED DATE
JOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH NO DEFECT DESCRIPTION	N	JSN	STATUS	EST Mhr
XJL4605	200	NRR	SS	25	777-C252430-01-04- 01	PEY PAX SEAT CONSOLE TOP CAP FOUND CRACKED AT:34AC		L460	OPEN	09/25/2023
	CAB				U I					1.0
									-	1.0
XJL4613	200	NRR	SS	25	777-C252430-01-06-	PEY PAX SEAT BACK REST SCREW FOUND LOOSEN AT31C 33A C 31E 30F G D 32E F G 33E	E 34D E G 32H K 33H K 34H K	L461	OPEN	09/25/2023
	CAB				01	TOTAL:20EA				10.0
									-	10.0
XJL4621	200	NRR	SS	25	777-C252430-01-03-	PEY PAX SEAT FOOTREST ATT SCREW FOUND LOOSEN AT:31A C 30D E F G 32H K TOTAL:	.8EA	L462	WIP	09/26/2023
	CAB				01					4.0
									-	4.0
XJL4639	200	NRR	SS	25	777-C252430-01-06-	PEY PAX SEAT CONSOLE FWD TOP CAP SCREW FOUND MISSING AT:31C 33F 34K TOTAL:3	3EA	L463	OPEN	09/25/2023
	CAB				01					1.5
									-	1.5
XJL4647	200	NRR	SS	25	777-C252440-04-04-	EY FIRST SEAT INNER SHOUD FOUND LOOSEN AT 40HJK 39DEFG 39AC40C 59ABC 60DEFG	G 59HJK TTL 20EA	L464	OPEN	09/25/2023
	CAB				01					5.0
									-	5.0
XJL4654	200	NRR	SS	25	777-C252430-01-05-	PEY PAX SEAT CONSOLE ARM CAP SCREW FOUND MISSING AT:31C 30G TOTAL:2EA		L465	OPEN	09/25/2023
	CAB				01					1.0
									-	1.0
XJL4662	200	NRR	SS	25	777-C252430-01-05-	PEY PAX SEAT ARM REST SHROUD FOUND CRACKED AT:30D		L466	OPEN	09/25/2023
	CAB				01					1.0
									-	1.0
XJL4670	200	NRP	SS	25	777-25-050-08-CX-R-	PEY PAX SEAT CONSOLE TV ARM GAS SPRING OPERATION FOUND MALFUNCTION AT:30D	D E F G 31A C 32H K	L467	OPEN	09/25/2023
	CAB				01	TOTAL:8EA				8.0
									-	8.0
XJL4688	200	NRR	SS	25	777-C252440-04-04-	EY FIRST SEATSIDE BUMPER PANL FOUND BROKEN AT 60G		L468	OPEN	09/25/2023
	CAB	*			01			L 4 00	OI LIV	1.0
									-	
										1.0

0PPC DISTRIBUTION:

REQUESTED BY:

REFERENCE NO:

DEFECT TYPE: ALL

CTRL CODE:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

64 OF 83 PAGE:

RUN DATE: 9/28/2023

RUN TIME : 11:09

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL

515653

BMS571R1-2

STATUS: ALL

TYPE CODE:

ORIG-STAGE: ALL

ORIGINATOR: ALL

ATA NO: ALL

PERIOD: ALL

ESTIMATED MHR: ALL DISPOSITION CODE: ALL

ORIGINATING CUST REF NO:

ALL

TRADE: ALL

CUST ENDORSE: ALL

ZONE: ALL AREA: ALL

STAGE: ALL

CIRL CODE :					TYPE CODE:	URIGINATUR: A	ALL			
	ZONE	STG							STATUS	UPDATED DATE
JOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH NO	DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
XJL4696	200	NRR	SS	25	777-C252430-01-01- 01	PEY PAX SEAT BELT FOUND FRAY AT:31A	33A 30G TOTAL:3EA	L469	OPEN	09/25/2023
	CAB				O I					1.5
									-	1.5
XJL4704	200	NRR	SS	25	777-C252430-01-05-	PEY PAX SEAT ARM REST OPERATION FO	OUND NOISE AT:31C	L470	WIP	09/26/2023
	CAB				01					0.5
									-	0.5
XJL4712	200	NRR	SS	25	777-C252430-01-05-	PEY PAX SEAT ARM REST STRUCTURE F	OUND LOOSEN AT:30D 31D G 34G 33H TOTAL: 5EA	L471	OPEN	09/25/2023
	CAB				01					5.0
									-	5.0
XJL4720	200	NRR	SS	25	777-C252440-04-04-	EY FIRST SEAT SIDE FAIRING SCREW FO	UND LOOSEN AT 39G	L472	OPEN	09/25/2023
	CAB				01					0.5
									-	0.5
XJL4738	200	NRP	SS	25	777-25-050-08-CX-R-	PEY PAX SEAT CONSOLE PTV ARM PLUG	FOUND MISSING AT:30D	L473	OPEN	09/25/2023
	CAB				01					0.5
									-	0.5
XJL4746	200	NRR	SS	25	777-C252430-01-03-	PEY PAX SEAT LEGREST BUTTON CABLE	FOUND BROKEN AT:30E	L474	OPEN	09/25/2023
	CAB				01					1.0
									-	1.0
XJL4753	200	NRR	Al	2502	777-C252420-01-05-	CAB-FB2 SEAT BACKSHELL ROLLER BLIN	D BLACK FASTENER FOUND MISSING	L475	OPEN	09/25/2023
	CAB				01					5.0
									-	5.0
XJL4761	200	NRR	AV	3326	777-C330000-01-03-	TOILET LIGHT INSPECTION FOUND CEILIN	NG LIGHT COVER CRACK AT LAV D	L476	OPEN	09/25/2023
	CAB				01					1.0
									-	1.0
XJL4779	200	NRR	AV	3326	777-C330000-01-03-	TOILET LIGHT INSPECTION FOUND LAV C	ALL LIGHT LENS CRACK AT LAV C,E,H,K,L	L477	WIP	09/27/2023
	CAB				01					2.5
									-	2.5

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE: 65 OF 83 RUN DATE: 9/28/2023

STATUS

UPDATED DATE

RUN TIME : 11:09

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL

ZONE STG

515653

BMS571R1-2

STATUS: ALL

ORIG-STAGE: ALL

ATA NO: ALL

PERIOD: ALL

ESTIMATED MHR: ALL DISPOSITION CODE: ALL

ORIGINATING CUST REF NO:

DEFECT TYPE: ALL

ALL

TRADE: ALL

CUST ENDORSE: ALL

ZONE: ALL AREA: ALL

STAGE: ALL

CTRL CODE:

TYPE CODE: ORIGINATOR: ALL

CTRL SH NO	DEFECT DESCRIPT

JOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH N	O DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
XJL4787	200	NRR	Al	2502	777-C252420-01-05-	CAB-FB2 SE	AT BACKSHELL ROLLER BLIND FOUND DAMAGE AT 19K 20K 21A 18A 15A	L478	WIP	09/25/2023
	CAB				01					5.0
									-	5.0
XJL4795	200	NRR	SS	2511	777-25-020-02-01	PILOT SEAT	VELCRO TAPE FND LOOSE	L479	OPEN	09/25/2023
	CAB							20	0. 2	1.0
										1.0
XJL4803	200 CAB	NRR	SS	2511	777-25-020-02-01	PILOT SEAT	HEADREST FND NOISE	L480	OPEN	09/25/2023
	CAB									1.0
									-	1.0
XJL4811	200	NRR	SS	2511	777-25-020-02-01	PILOT SEAT	BOTTOM COVER FND WORN	L481	WIP	09/26/2023
	CAB									1.0
									-	1.0
XJL4829	200	NRR	SS	2511	777-25-020-02-01	DII OT SEAT	BOTTOM CUSHION	L482	OPEN	09/25/2023
70L4020	CAB	IVIXIX	00	2011	777-20-020-02-01	I ILOT OLAT	BOTTOW GOSTILON	L402	OPEN	
									_	1.0
										1.0
XJL4837	200	NRR	SS	2511	777-25-020-02-01	1ST OBS SE	AT RECLINE SIDE SCREW FND LOOSE	L483	OPEN	09/25/2023
	CAB									1.0
									-	1.0
XJL4845	600	NRR	AE	2800	777-28-015-00-01	RHW F/T VE	NT SCOOP DOOR 644BB FOUND ONE PUNCH HOLE	L484	OPEN	09/25/2023
	F/T									0.0
						1C 1	REMOVE VENT SCOOP ASSEMBLY TO THE ACCESS DOOR			3.0
						1C 2	REINSTALL VENT SCOOP ASSEMBLY TO THE NEW ACCESS DOOR			3.0
						1C 3	CARRY OUT BONDING RESISTANCE TEST BETWEEN THE UPPER DUCT ON THE VENT SCOOP ASSEMBLY AND THE ACCESS DOOR			0.5
						1C 4	APPLY THE SEALANT ALONG THE TOP OF THE SCREWS			1.0
						2C 5	REINSTALL VENT SCOOP ACCESS DOOR			0.0
						2C 6	CARRY OUT BONDING RESISTANCE TEST BETWEEN THE ACCESS DOOR AND THE LOWER WING SKIN			0.5
						2C 7	DO A VISUAL CHECK TO MAKE SURE THAT ACCESS DOOR INSTALLATION IS FLUID TIGHT			0.5
									-	8.5

ORIGINATING CUST REF NO:

515653

REQUESTED BY:

PROJECT: XJ

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE: 66 OF 83

RUN DATE: 9/28/2023 RUN TIME : 11:09

REFERENCE NO: BMS571R1-2

CUSTOMER: CX

ALL

A/C REGN: B-KPV

CHECK TYPE: 2C

JSN RANGE SELECTED: ALL STATUS: ALL ORIG-STAGE: ALL PERIOD: ALL ESTIMATED MHR: ALL

A/C TYPE: 777

ATA NO: ALL ZONE: ALL DISPOSITION CODE: ALL

DEFECT TYPE: ALL TRADE: ALL CUST ENDORSE: ALL AREA: ALL STAGE: ALL

CIRL CODE:					TYPE CODE:			ORIGINATOR: ALL			
	ZONE	STG								STATUS	UPDATED DAT
JOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTR	LSHNO	DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
(JL4852	100	NRP	SM	5000	777-53-545-01-01	LEF	T FORWA	RD BSTA1035+20 INCH LOWER WING TO BODY FAIRING SUPPORT ANGLE CRACKED	L485	OPEN	09/25/2023
	FUS										0.0
						1C	1	REMOVE SUPPORT FTG ATT SCREW			4.0
						1C	2	REMOVE CRACK SUPPORT FTG			4.0
						1C	3	TRANSFER HOLES TO NEW FTG			4.0
						1C	4	INSTALL NEW FTG			4.0
						2C	5	INSTALL SUPPORT FTG ATT SCREW			4.0
						2C	6	CARRY OUT FASTENERS SEAL APPLICATION			2.0
						2C	7	PERFORM THE FUEL TANK LEAKAGE CHECK			2.0
						2C	8	TOUCH UP PAINT			1.0
										-	25.0
L4860	100	NRR	ΑE	2152	777-53-830-00-01	FUS	-LH PAC	HEAT EXCHANGER FOUND CRACKED.	L486	OPEN	09/25/2023
	FUS										0.0
										-	0.0
JL4878	100	NRR	AE	2152	777-53-830-00-01	FUS	-RH PACI	UPR FCV BONDING BROKEN.	L487	OPEN	09/25/2023
	FUS										0.0
						1C	1	REPLACE THE BONDING.			1.0
						1C	2	DO THE BONDING TEST.			0.5
										-	1.5
IL4886	100	NRR	AE	2152	777-53-830-00-01	FUS	-LH PAC	RAM AIR INLET DUCT AFT BONDING BROKEN.	L488	OPEN	09/25/2023
	FUS								2.00	01 211	
						10	4	REPLACE THE BONDING.			0.0
						1C 1C	1 2	DO THE BONDING TEST.			1.0 0.5
						10	2	DO THE DONDING FEST.		_	0.5
											1.5

515653

BMS571R1-2

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE: 67 OF 83

RUN DATE: 9/28/2023 RUN TIME :

11:09

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL STATUS: ALL ORIG-STAGE: ALL PERIOD: ALL ESTIMATED MHR: ALL

ATA NO: ALL ORIGINATING CUST REF NO: ZONE: ALL DISPOSITION CODE: ALL ALL

DEFECT TYPE: ALL TRADE: ALL CUST ENDORSE: ALL AREA: ALL STAGE: ALL

TYPE CODE CTDL CODE ODICINIATOD .

CTRL CODE:					TYPE CODE:	ORIGINATOR: ALL			
	ZONE	STG						STATUS	UPDATED DATE
JOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH NO DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
XJL4894	300	NRR	PT	5500	777-55-000-06-CX-01	VERTICAL STABILIZER LEADING EDGE 321E FOUND COATING DETERIORATION	L489	WIP	09/27/2023
	EMP								0.0
						1C 1 DISCONNECT HF ANTENNA FEEDLINE			2.0
						1C 2 REMOVE PNL 321E			0.0
						1C 3 APPLY ANTI-STATIC COATING TO SURFACE			30.0
						1C 4 C/O RESISTANCE CHECK			2.0
						2C 5 RESTORE THE ORIGINAL FINISH COATING			10.0
						2C 6 RECONNECT THE HF ANTENNA FEEDLINE CONNECTOR			2.0
						2C 7 RE-INSTALL THE 321E			0.0
						2C 8 C/O HF SYSTEM TEST			1.0
						3C 9 DISCONNECT HF ANTENNA FEEDLINE			0.0
								-	47.0
XJL4902	100	NRR	ΑE	2152	777-53-830-00-01	FUS-LH PACK TRIM AIR VALVE BONDING BROKEN.	L490	OPEN	09/25/2023
	FUS								0.0
						1C 1 REPLACE THE BONDING.			1.0
						1C 2 DO THE BONDING TEST.			0.5
								-	1.5
XJL4910	100	NRR	ΑE	2152	777-53-830-00-01	FUS-LH PACK THE CONDITIONING O/B LOW LIMIT VALVES BONDINGS BROKEN.	L491	OPEN	09/25/2023
	FUS								0.0
						1C 1 REPLACE THE BONDING.			1.0
						1C 2 DO THE BONDING TEST.			0.5
								-	1.5
XJL4928	200	NRR	SS	25	777-C252420-01-02-	FB2 SEAT BACK REST SIDE BAY GEAR INNER STOP SCREW&BUSHING FOUND MISSING AT:17G		0.0511	
AJL4920	CAB	INICIA	33	25	02	FBZ SEAT BACK REST SIDE BAT GEAR INNER STOP SCREWABUSHING FOUND MISSING ATTI	L492	OPEN	09/25/2023
	CAB				02				1.0
								-	1.0
XJL4936	200	NRR	SS	25	777-C252420-01-02-	FB2 SEAT BOTTOM PAN FWD BUTTON CAP FOUND BROKEN AT:17K	L493	OPEN	09/25/2023
	CAB				01				2.0
								-	2.0
XJL4944	200	NRR	SS	25	777-C252440-04-04-	EY F/R SEAT CENTER CONSOLE CONNECT STRUCTURE ATT CLAMP FND BROKEN AT:40HJ 39G 39D 39C 59A 60E	L494	OPEN	09/25/2023
	CAB			-	01	TTL:6EA	L 104	OI LIV	24.0
								=	24.0
								-	24.0

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE: 68 OF 83

RUN DATE: 9/28/2023

5.0

RUN TIME : 11:09

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL

515653

BMS571R1-2

STATUS: ALL

TRADE: ALL

ORIG-STAGE: ALL

PERIOD: ALL ZONE: ALL

AREA: ALL

ESTIMATED MHR: ALL DISPOSITION CODE: ALL

ORIGINATING CUST REF NO:

ALL

ATA NO: ALL CUST ENDORSE: ALL

STAGE: ALL

CT	DI.	\sim		
U	ΚL	$\mathcal{C}_{\mathcal{C}}$	ルヒ	

DEFECT TYPE : ALL

TVDE CODE.	ODICINIATOD .	A I I
TYPE CODE:	ORIGINATOR:	ALL

CIRL CODE :					TYPE CODE:	ORIGINATOR: A	LL			
	ZONE	STG							STATUS	UPDATED DATE
JOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH NO	DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
XJL4951	200	NRR	SS	25	777-C252420-01-02- 01	FB2 SEAT BOTTOM PAN LOWER BRACKET	FWD SCREW FOUND LOOSEN AT:12D 16D 19A 11K TOTAL:4EA	L495	OPEN	09/25/2023
	CAB				01					2.0
									-	2.0
XJL4969	200	NRR	SS	25	777-C252420-01-02-	FB2 SEAT BOTTOM PAN SIDE BAY BRACK	ET SCREW FOUND LOOSEN AT:21K	L496	OPEN	09/25/2023
	CAB				01					0.5
									-	0.5
XJL4977	200	NRR	SS	25	777-C252420-01-02-	FB2SEAT TRACKING BUTTON SCREW FOL	JND LOOSEN AT:25K 22K 20G 19G TOTAL:4EA	L497	OPEN	09/25/2023
	CAB				01					2.0
									-	2.0
XJL4985	200	NRR	SS	25	777-C252420-01-02-	FB2 SEAT BACK REST ATT SCREW FOUNI) LOOSEN AT:17K 26K 16G 23A 21A 17A 16A 25K 21G TOTAL:9EA	L498	OPEN	09/25/2023
	CAB				01					4.5
									-	4.5
XJL4993	200	NRR	SS	25	777-C252420-01-02-	FB2 SEAT BACK REST SCREW FOUND MIS	SING AT:20D	L499	OPEN	09/25/2023
	CAB				02					0.5
									-	0.5
XJL5008	200	NRR	SS	25	777-C252420-01-02-	FB2SEAT BELT AIR BAG FOUND TORN AT	19D 22D 21K 19G 17G TOTAL:5EA	L500	OPEN	09/25/2023
	CAB				02					7.5
									-	7.5
XJL5016	200	NRR	SS	25	777-C252420-01-02-	FB2 SEAT BACK REST SIDE BAY GEAR AT	T SCREW FOUND LOOSEN AT:17A 22D 25D A 25K 23G 22K 20K 17G 16K G	L501	OPEN	09/25/2023
	CAB				01	12K G 11G TOTAL:14EA				7.0
									-	7.0
XJL5024	200	NRR	SS	25	777-C252420-01-02-	FB2 SEAT BACK REST HEADREST STRUC	FURE SCREW FOUND LOOSEN AT:17A 18A D 19D 22A 23A 25G 24K G 23G	L502	OPEN	09/25/2023
	CAB				02	18G 16K TOTAL:12EA				6.0
									-	6.0
XJL5032	200	NRR	SS	25	777-C252420-01-02-	FB2 SEAT RECLINE MOTOR GEAR ATT PIN	FOUND BROKEN AT:17D 19A 20A 24A 16G TOTAL:5EA	L503	OPEN	09/25/2023
	CAB				01			2003	OI LIV	5.0
										0.0

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD. 515653

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE: 69 OF 83 RUN DATE: 9/28/2023

1.0

RUN TIME : 11:09

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL

STATUS: ALL

ORIG-STAGE: ALL

PERIOD: ALL

ESTIMATED MHR: ALL

ORIGINATING CUST REF NO:

ALL

BMS571R1-2

ATA NO: ALL

CUST ENDORSE: ALL

ZONE: ALL AREA: ALL

DISPOSITION CODE: ALL

STAGE: ALL

DEFECT TYPE: ALL

CTRL CODE:

TRADE: ALL

TYPE CODE:

ORIGINATOR: ALL

OTTL CODE.	ZONE	STG			THE GODE.	ONGIVATOR. A			STATUS	UPDATED DATE
JOB NO	AREA	010	TD	ATA	ORIG CUST REF NO.	CTRL SH NO	DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
XJL5040	200 CAB	NRR	SS	25	777-C252420-01-02- 01	FB2 SEAT LEGREST BUTTON SCREW FOU	ND LOOSEN AT:17A 16A 17D 18D 23D 24A 26K 24K 23K 20K 16K TOTAL:11EA	L504	OPEN	09/25/2023 5.5
									-	5.5
XJL5057	200 CAB	NRR	SS	25	777-C252420-01-02- 02	FB2 SEAT BACK REST HEADREST SLIDE TO	RACK FOUND BROKEN AT:15A 17D 19D 20D 21G TOTAL:5EA	L505	OPEN	09/25/2023 2.5
									-	2.5
XJL5065	200 CAB	NRR	SS	25	777-C252420-01-02- 02	FB2 SEAT BOTTOM PAN LOWER BRACKET	FWD SCREW&NUT FOUND MISSING AT:11D	L506	OPEN	09/25/2023 1.0
									-	1.0
XJL5073	200 CAB	NRR	SS	25	777-C252420-01-02- 02	FB2 SEAT LEGREST MOTOR ATT SCREW F	OUND LOOSEN AT:11D 16D 23D 23A 20K 12G TOTAL:6EA	L507	OPEN	09/25/2023 3.0
									-	3.0
XJL5081	200 CAB	NRR	SS	25	777-C252420-01-02- 02	FB2SEAT RECLINE BUTTON SCREW FOUN	D LOOSEN AT:11D 23D 26D TOTAL3EA	L508	OPEN	09/25/2023 1.5
									-	1.5
XJL5099	200 CAB	NRR	SS	25	777-C252420-01-02- 02	FB2SEAT BELT BUCKLE FOUND FRAY AT:1	1D 20D 22A 23A 25D 25G 23G 22G 16G TOTAL:9EA	L509	OPEN	09/25/2023 4.5
									-	4.5
XJL5107	200 CAB	NRR	SS	25	777-C252420-01-02- 01	FB2 SEAT BELT BUCKLE FOUND FRAY AT:	18A 19A 26K 25K 18K 16K TOTAL:6EA	L510	OPEN	09/25/2023 9.0
									-	9.0
XJL5115	200 CAB	NRR	SS	25	777-C252430-01-06- 01	PEY PAX SEAT BACK REST TV SHROUD LC	OWER COVER FOUND LOOSEN AT:33F	L511	OPEN	09/25/2023 0.5
									-	0.5
XJL5123	200 CAB	NRR	SS	25	777-C252430-01-03- 01	PEY PAX SEAT BACK REST TV SHROUD PL	ACARD FOUND TORN AT:33D 32A 33K TOTAL:3EA	L512	OPEN	09/25/2023
	-								_	1.0

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE: 70 OF 83 RUN DATE: 9/28/2023

RUN TIME :

0747110

LIDDATED DATE

0.5

11:09

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL

515653

BMS571R1-2

STATUS: ALL

ORIG-STAGE: ALL PERIOD: ALL ESTIMATED MHR: ALL

ORIGINATING CUST REF NO: DEFECT TYPE: ALL

ALL

ATA NO: ALL TRADE: ALL CUST ENDORSE: ALL ZONE: ALL AREA: ALL

DISPOSITION CODE: ALL

STAGE: ALL

CTRL CODE:

TYPE CODE:

ORIGINATOR:	ALL
ONIGINATOR.	ALL

	ZONE	STG							STATUS	UPDATED DATE
JOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH NO DEFECT	T DESCRIPTION	JSN	STATUS	EST Mhr
XJL5131	200	NRR	SS	25	777-C252430-01-06-	PEY PAX SEAT BACK REST TV SHROUD LOWER COVER SCREW FOUND	LOOSEN AT:33D	L513	OPEN	09/25/2023
	CAB				01					0.5
									-	0.5
XJL5149	200	NRR	SS	25	777-C252430-01-04-	PEY PAX SEAT CONSOLE ARM CAP SCREW FOUND LOOSEN AT:33G		L514	OPEN	09/25/2023
	CAB				01					0.5
									-	0.5
XJL5156	200	NRR	SS	25	777-C252430-01-01-	PEY PAX SEAT LEGREST DRESS COVER FOUND NO MATCH AT:33G		L515	OPEN	09/25/2023
	CAB				01					0.5
									-	0.5
XJL5164	200	NRR	SS	25	777-C252430-01-06-	PEY PAX SEAT BACK REST BRACKET SCREW FOUND LOOSEN AT:33G 34	4F E G D TOTAL:5EA	L516	OPEN	09/25/2023
	CAB				01					2.5
									-	2.5
XJL5172	200	NRR	SS	25	777-C252430-01-02-	PEY PAX SEAT SIDE FAIRING FOUND LOOSEN AT:32D		L517	OPEN	09/25/2023
	CAB				01					0.5
									-	0.5
XJL5180	200	NRR	SS	25	777-C252430-01-03-	PEY PAX SEAT LEGREST LIFE JACKET BOX VELCRO TAPE FOUND LOOS	ENAT:32D F G 31E F 33F E G 34D G 32H 34K	L518	OPEN	09/25/2023
	CAB				01	33H 32C 33A TOTAL:15EA				7.5
									-	7.5
XJL5198	200	NRR	SS	25	777-C252430-01-03-	PEY PAX SEAT LEGREST LIFE JACKET BOX FOUND BROKEN AT:32E 34C	33E 31D TOTAL:4EA	L519	OPEN	09/25/2023
	CAB				01					4.0
									-	4.0
XJL5206	200	NRR	SS	25	777-C252430-01-02-	PEY PAX SEAT SIDE BAY REAR COVER SCREW FOUND LOOSEN AT:31E		L520	OPEN	09/25/2023
	CAB				01					0.5
									-	0.5
XJL5214	200	NRR	SS	25	777-C252430-01-03-	PEY PAX SEAT LEGREST SUPPORT ATT SCREW&NUT INSTALL FOUND W	VRONG AT:32E	L521	OPEN	09/25/2023
	CAB				01					0.5
									-	

ORIGINATING CUST REF NO:

515653

BMS571R1-2

ALL

REQUESTED BY:

REFERENCE NO:

0PPC TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE: 71 OF 83

RUN DATE: 9/28/2023

RUN TIME: 11:09

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL STATUS: ALL ORIG-STAGE: ALL PERIOD: ALL ESTIMATED MHR: ALL

ATA NO: ALL ZONE: ALL DISPOSITION CODE: ALL

DEFECT TYPE: ALL TRADE: ALL CUST ENDORSE: ALL AREA: ALL STAGE: ALL

CIRL CODE :					TYPE CODE:	ORIGINATOR: ALL				
	ZONE	STG							STATUS	UPDATED DATE
JOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH NO	DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
XJL5222	200	NRR	SS	25	777-C252430-01-04- 01	PEY PAX SEAT CONSOLE IN ARM TABLE SLIDI	E TRACK SCREW FOUND MISSING AT:32F	L522	OPEN	09/25/2023
	CAB				01					0.5
									-	0.5
XJL5230	200	NRR	SS	25	777-C252430-01-03- 01	PEY PAX SEAT AFT FOOTREST BUSHING FOU	ND MISSING AT:31E F G TOTAL3EA	L523	OPEN	09/25/2023
	CAB				O1					1.5
									-	1.5
(JL5248	200	NRR	SS	25	777-C252430-01-03-	PEY PAX SEAT LEGREST SUPPORT BRACKET	AND SCREW&NUT AND WASHER FOUND MISSING AT:31D	L524	OPEN	09/25/2023
	CAB				01					1.0
									-	1.0
KJL5255	200	NRR	SS	25	777-C252430-01-05-	PEY PAX SEAT ARM REST CAP FOUND TORN	AT:31D 33D TOTAL:2EA	L525	OPEN	09/25/2023
	CAB				01					1.0
									-	1.0
KJL5263	200	NRR	SS	25	777-C252430-01-03-	PEY PAX SEAT AFT FOOTREST SCREW FOUN	D LOOSEN AT:30G	L526	OPEN	09/25/2023
	CAB				01					0.5
									-	0.5
(JL5271	200	NRR	SS	25	777-C252430-01-03-	PEY PAX SEAT BOTTOM PAN PLUG SCREW FO	DUND MISSING AT:30G	L527	OPEN	09/25/2023
	CAB				01					0.5
									-	0.5
(JL5289	200	NRR	SS	25	777-C252430-01-03-	PEY PAX SEAT CONSOLE SIDE BAY FAIRING F	OUND CRACKED AT:30F 32G TOTAL:2EA	L528	OPEN	09/25/2023
	CAB				01					2.0
									-	2.0
(JL5297	200	NRR	SS	25	777-C252430-01-04-	PEY PAX SEAT CONSOLE IN ARM TABLE STO	VAGE SHROUD FOUND BROKEN AT:30F G 31G 32G E 33D H 34H	L529	OPEN	09/25/2023
	CAB				01	TOTAL:8EA				8.0
									-	8.0
JL5305	200	NRR	SS	25	777-C252430-01-05-	PEY PAX SEAT ARM REST OPERATION FOUND) LOOSEN AT:30E	L530	OPEN	09/25/2023
	CAB				01				-	0.5
									-	0.5
										0.5

ORIGINATING CUST REF NO:

515653

BMS571R1-2

ALL

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE: 72 OF 83 RUN DATE: 9/28/2023

RUN TIME : 11:09

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL STATUS: ALL ORIG-STAGE: ALL PERIOD: ALL ESTIMATED MHR: ALL

> ATA NO: ALL ZONE: ALL DISPOSITION CODE: ALL

DEFECT TYPE: ALL TRADE: ALL CUST ENDORSE: ALL AREA: ALL STAGE: ALL

CTRL CODE :	L. ALL	•			TYPE CODE:	ORIGINATOR: ALL	L ANLA. ALL	STAGE. ALL		
THE GODE .	ZONE	STG			111 2 0052.	orden with order.			STATUS	UPDATED DAT
IOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH NO	DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
IL5313	300	NRR	AE	2700	777-55-822-00-01	RUDDER TAB LOWER LEFT AND RIGHT SIDE B	ULB SEALS TORN	L531	OPEN	09/25/2023
	EMP									3.0
									-	3.0
IL5321	100	NRR	Al	5600	777-53-904-00-01	CABIN A ZONE LH SIDEWALL WINDOW DUST O	COVER INSIDE FOUND DUSTY	L532	OPEN	09/25/2023
	CAB									8.0
									-	8.0
IL5339	100	NRR	Al	5600	777-53-904-00-01	CABIN A ZONE RH SIDEWALL WINDOW DUST (COVER INSIDE FOUND DUSTY	L533	OPEN	09/25/2023
	CAB									8.0
									-	8.0
L5347	100	NRR	Al	5600	777-53-908-00-01	CABIN B ZONE RH SIDEWALL WINDOW DUST (COVER INSIDE FOUND DUSTY	L534	OPEN	09/25/2023
	CAB									16.0
									-	16.0
JL5354	100	NRR	Al	5600	777-53-908-00-01	CABIN B ZONE LH SIDEWALL WINDOW DUST O	OVER INSIDE FOUND DUSTY	L535	OPEN	09/25/2023
	CAB									16.0
									-	16.0
IL5362	100	NRR	Al	2500	777-53-904-00-01	CABIN A RH WINDOW SHADE FOUND STIFF TO) OPERATE	L536	OPEN	09/25/2023
	CAB									5.0
									-	5.0
L5370	100	NRR	Al	2500	777-53-904-00-01	CABIN A LH WINDOW SHADE FOUND STIFF TO	OPERATE	L537	OPEN	09/25/2023
	CAB									5.0
									-	5.0
IL5388	100	NRR	Al	2500	777-53-908-00-01	CABIN B ZONE LH WINDOW SHADE FOUND ST	IFF TO OPERATE	L538	OPEN	09/25/2023
	CAB									8.0
									-	8.0
L5396	100	NRR	Al	2500	777-53-908-00-01	CABIN B ZONE RH WINDOW SHADE FOUND ST	IFF TO OPERATE	L539	OPEN	09/25/2023
	CAB									8.0
									-	8.0

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE:

RUN TIME :

73 OF 83

RUN DATE: 9/28/2023 11:09

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL

515653

BMS571R1-2

STATUS: ALL

ORIG-STAGE: ALL

PERIOD: ALL

ESTIMATED MHR: ALL

ORIGINATING CUST REF NO:

ALL

ATA NO: ALL

ZONE: ALL

DISPOSITION CODE: ALL

DEFECT TYPE: ALL

TRADE: ALL

CUST ENDORSE: ALL

AREA: ALL STAGE: ALL

CTRL CODE :					TYPE CODE:	ORIGINATOR:	ALL			
	ZONE	STG							STATUS	UPDATED DATE
JOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH NO	DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
XJL5404	200	NRR	SS	25	777-C252440-04-04- 01	CAB E ZONE EY SEAT TRIMCAP FOL	JND CRACKED AT:46FG	L540	OPEN	09/25/2023
	CAB				01					0.5
									-	0.5
XJL5412	200	NRR	SS	25	777-C252440-04-04-	CAB E ZONE EY SEAT ARMREST OP	PERATION FOUND LOOSE AT:43FG 42H 44H 45HJ 72C 72D 63HJ TTL:7EA	L541	OPEN	09/25/2023
	CAB				01					2.5
									-	2.5
XJL5420	200	NRR	SS	25	777-C252440-04-04-	CAB E ZONE EY SEAT ARMREST OP	PERATION FOUND TIGHTEN AT:41JK 42JK 63BC 69BC 66FG 61HJ 61JK TTL:7EA	L542	OPEN	09/25/2023
	CAB				01					2.5
									-	2.5
XJL5438	200	NRR	AV	3326	777-C330000-01-03-	LAV D CEILING LIGHT MALFUNCTION	N	L543	OPEN	09/25/2023
7,020100	CAB	14141	, .,	0020	01	DAV D CEIEIRO EIGITI WINEI GROTIOI	•	L343	OPEN	2.0
									-	
V II 5440	000	NDD	00	05	777 0050440 04 04	0.10 5 70.15 57.05.17 1.01.05.07 50	AND AN ENDOTON AT THE CONTRACT OF A			2.0
XJL5446	200 CAB	NRR	SS	25	777-C252440-04-04- 01	CAB E ZONE EY SEAT ARMREST FO	OUND MULFUNCTION AT:71D 66H 67H TTL:3EA	L544	OPEN	09/25/2023
	O/ LD								_	6.0
										6.0
XJL5453	200	NRR	ΑI	25	777-53-904-00-01	CABIN G1 GALLERY TABLE SEALAN	T CHIPPED	L545	OPEN	09/25/2023
	CAB									2.0
									-	2.0
XJL5461	200	NRR	SS	25	777-C252440-04-04-	CAB E ZONE FIRST ROW SEAT ARM	REST FOUND LOOSEN AT:59JK 59C 4H TTL:3EA	L546	OPEN	09/25/2023
	CAB				01					1.5
									-	1.5
XJL5479	200	NRR	ΑI	25	777-53-908-00-01	CABIN G2&G3 GALLERY TABLE SEA	LANT CHIPPED	L547	OPEN	09/25/2023
	CAB									3.0
									-	3.0
XJL5487	200	NRR	Al	5600	777-56-000-01-CX-01	COCKPIT L1&R1 WINDSHIELD MOIST	TURE SEAL FOLIND WORN	L548	WIP	09/28/2023
	CAB					The state of the s		LJ40	VVII	10.0
									-	
										10.0

515653

BMS571R1-2

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE: 74 OF 83

RUN DATE: 9/28/2023

RUN TIME: 11:09

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL STATUS: ALL ORIG-STAGE: ALL PERIOD: ALL ESTIMATED MHR: ALL

TYPE CODE:

ORIGINATING CUST REF NO: ALL ATA NO: ALL ZONE: ALL DISPOSITION CODE: ALL

ORIGINATOR: ALL

DEFECT TYPE: ALL TRADE: ALL CUST ENDORSE: ALL AREA: ALL STAGE: ALL

CTRL CODE:

TINE CODE .					TIFE CODE.	ONGINATOR. A	<u>-L</u>		CTATUC	LIDDATED DATE
	ZONE	STG							STATUS	UPDATED DATE
OB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH NO	DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
IL5495	200	NRR	SS	25	777-C252000-01-07- R-01	CAB B ZONE B/C SEAT BOTTOM COVER FO	DUND TORN TTL:1EA	L549	OPEN	09/25/2023
	CAB				14-01					0.5
									-	0.5
L5503	100	NRW	ΑE	5336	SWC-28028-01-01	FUS-RAM AIR INLET ACTUATOR DOOR PA	NEL 191LL 5EA STUDS HEAD WORN.	L550	OPEN	09/25/2023
	FUS									3.0
									-	3.0
L5511	100	NRW	AE	5336	SWC-28028-01-01	FUS-RAM AIR INLET ACTUATOR DOOR PA	NEL 191LR 4EA STUDS HEAD WORN.	L551	OPEN	09/25/2023
	FUS									3.0
									-	3.0
L5529	200	NRR	Al	25	777-53-920-00-01	M/D M LAV FAUCET FOUND WATER LEAKI	IG .	L552	OPEN	09/25/2023
	CAB									0.0
						1C 1 REPLACE LAV FAUCET				4.0
						1C 2 C/O LAV FAUCET WATER L	EAK CHECK			0.5
									-	4.5
L5537	200	NRP	AV	3351	777-33-115-00-02	FOUND L1,L4,R1,R2 DOOR EMERGENCY L	GHT LENS LOOSEN	L553	WIP	09/27/2023
	CAB									6.0
									-	6.0
L5545	100	NRW	AE	5336	SWC-28028-01-01	FUS-RAM AIR INLET ACTUATOR DOOR PA	NEL 191LR 2EA HINGE BONDINGS BROKEN.	L554	OPEN	09/25/2023
	FUS									0.0
						1C 1 REPLACE THE BONDING.				1.0
						1C 2 DO THE BONDING TEST.			_	0.5
										1.5
_5552	200 CAB	NRP	AV	3351	777-33-115-00-02	FOUND L3 DOOR NO 2 EMERGENCY LIGHT	DIM	L555	WIP	09/27/2023
	OAD								_	6.0
										6.0
-5560	100	NRR	Al	5200	777-12-102-00-01	AFT CGO DOOR LINING SCREWS AND SPA	CERS FOUND WORN	L556	OPEN	09/25/2023
	LWR									0.5
									-	0.5

0PPC DISTRIBUTION:

ORIGINATING CUST REF NO:

515653

BMS571R1-2

ALL

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE:

RUN TIME :

75 OF 83

RUN DATE: 9/28/2023 11:09

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL STATUS: ALL ORIG-STAGE: ALL PERIOD: ALL ESTIMATED MHR: ALL

> ATA NO: ALL ZONE: ALL DISPOSITION CODE: ALL

DEFECT TYPE: ALL TRADE: ALL CUST ENDORSE: ALL AREA: ALL STAGE: ALL

CINE CODE.					TIFE CODE.	ONGINATOR. ALL			CTATUC	LIDDATED DATE
	ZONE	STG							STATUS	UPDATED DATE
JOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH NO	DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
XJL5578	100	NRR	Al	3800	777-38-000-09-CX-01	BULK CGO AFT WASTE TANK RINSE LINE WATER FI	LTER HOUSING FOUND BROKEN	L557	OPEN	09/25/2023
	LWR									3.0
									-	3.0
XJL5586	200	NRR	Al	2500	777-53-912-00-01	CABIN DR3- DR4 LH PAX WINDOW DUST COVER INT	TERIOR FND DIRTY	L558	WIP	09/26/2023
	CAB									34.0
									-	34.0
XJL5594	200	NRR	Al	2500	777-53-912-00-01	CABIN DR3- DR4 RH PAX WINDOW DUST COVER IN	TERIOR FND DIRTY	L559	WIP	09/26/2023
	CAB									34.0
									-	34.0
XJL5602	200	NRR	Al	2500	777-53-916-00-01	CABIN DR4- DR5 LH PAX WINDOW DUST COVER INT	TERIOR FND DIRTY	L560	OPEN	09/25/2023
	CAB									40.0
									-	40.0
XJL5610	200	NRR	Al	2500	777-53-916-00-01	CABIN DR4- DR5 RH PAX WINDOW DUST COVER IN	TERIOR END DIRTY	L561	OPEN	09/25/2023
	CAB							2001	OI LIV	40.0
									-	
XJL5628	200	NRR	Al	2500	777-53-916-00-01	CARIN DR4- DR5 L12 L17 L20 R0 R11 AND DR3-DR	4 R17 PAX WINDOW DUST COVER FND SCRATCHED	1.500	WID	40.0
AJLJ020	CAB	MIXIX	Ai	2300	777-33-910-00-01	CABIN DIA4- DIA3 E12, E17, E20, IA9, ICTT AND DIA3-DIA	A KIT FAX WINDOW DOST COVER FIND SCRATCHED	L562	WIP	09/26/2023
									_	12.0
										12.0
XJL5636	100 LWR	NRR	SM	5200	777-52-190-00-01	FWD CGO DOOR OPERATIONAL SWITCH ACCESS D	OOR SPRING FOUND BROKEN	L563	OPEN	09/25/2023
	LVVIX					1C 1 REMOVE BROKEN HINGE ATT FAST	ENIEDS			2.0 4.0
						1C 2 REMOVE BROKEN HINGE ATT SCRE				1.0
						1C 3 INSTALL NEW HINGE				8.0
						1C 4 TOUCH UP PAINT				0.5
						2C 5 REINSTALL NEW HINGE ATT SCREW	1			1.0
									-	16.5
XJL5644	200	NRR	Al	2500	777-53-916-00-01	CABIN SIDE BIN DR INTERIOR SURFACE AT 67A, 68I	H AND EXTERIOR SURFACE AT 67D, 68D FND DENT	L564	OPEN	09/25/2023
	CAB									8.0
									-	8.0
										3.0

ORIGINATING CUST REF NO:

515653

BMS571R1-2

ALL

REQUESTED BY:

REFERENCE NO:

0PPC TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE: 76 OF 83 RUN DATE: 9/28/2023

3/20/2020

RUN TIME: 11:09

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL STATUS: ALL ORIG-STAGE: ALL PERIOD: ALL ESTIMATED MHR: ALL

ATA NO: ALL ZONE: ALL DISPOSITION CODE: ALL

DEFECT TYPE: ALL TRADE: ALL CUST ENDORSE: ALL AREA: ALL STAGE: ALL

	ZONE	STG							STATUS	UPDATED DATE
JOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH NO	DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
XJL5651	100 LWR	NRR	SM	5200	777-52-195-00-01	AFT CGO DOOR OPERAT	TIONAL SWITCH ACCESS DOOR SPRING FOUND BROKEN	L565	OPEN	09/25/2023
	Livit					40 4 PENOVE	PROVENUINAE ATT FAOTENERO			2.0
							: BROKEN HINGE ATT FASTENERS : BROKEN HINGE ATT SCREW			4.0 1.0
							NEW HINGE			8.0
						1C 4 TOUCH U	JP PAINT			0.5
						2C 5 REINSTA	ILL NEW HINGE ATT SCREW			1.0
									-	16.5
XJL5669	200	NRR	Al	2500	777-53-912-00-01	CABIN AFT ZONE O/H BIN	N SIDE TRIM FND CRACKED AT 40G FWD, 41G AFT, 41A FWD, 42D AFT AND 43D FWD & AFT.	L566	WIP	09/28/2023
	CAB									12.0
									-	12.0
XJL5677	200	NRR	SS	25	777-C252430-01-02-	D ZONE PEY SEAT PAN L	LOWER WIRE COVER FND MISSING AT:30F 33E	L567	OPEN	09/25/2023
	CAB				01					2.0
									-	2.0
XJL5685	300	NRR	AV	5500	777-55-828-01-01		NECT THE ELECTRICAL CONNECTOR FROM LEFT AND RIGHT SIDE H/STABILIZER L/E TAXI	L568	WIP	09/26/2023
	EMP					CAMERA				2.0
						1C 1 DISCONN	NECT THE CONNECTOR FROM THE LEFT AND RIGHT SIDE CAMERA			0.0
						1C 2 CONNEC	T THE CONNECTOR FROM THE LEFT AND RIGHT SIDE CAMERA			0.0
									-	2.0
XJL5693	100	NRR	ΑE	5346	777-53-844-00-01	FUS-KEEL BEAM PANEL1	149C 2EA BLOCKS MISSING.	L569	OPEN	09/25/2023
	FUS									1.0
									-	1.0
XJL5701	100	NRR	SM	5300	777-53-818-00-01	FWD CGO R/H STA825 CE	EILING SUPPORT ANCHOR NUT FOUND DAMAGED	L570	OPEN	09/25/2023
	LWR									1.0
									-	1.0
XJL5719	300	NRR	ΑE	5300	777-53-880-00-01	FORWARD WIN TO BODY	Y FAIRING 191GL 191JL 191KL 191PL 191RL TOTAL 200EA SCREWS HEAD WORN	L571	OPEN	09/26/2023
	EMP									0.5
									-	0.5

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE: 77 OF 83 RUN DATE: 9/28/2023

RUN TIME :

0.747110

LIDDATED DATE

1.5

11:09

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL STATUS: ALL ORIG-STAGE: ALL

PERIOD: ALL

ESTIMATED MHR: ALL

ORIGINATING CUST REF NO: ALL

515653

BMS571R1-2

ATA NO: ALL

ZONE: ALL AREA: ALL

DISPOSITION CODE: ALL

DEFECT TYPE: ALL

TRADE: ALL

CUST ENDORSE: ALL

STAGE: ALL

	ZONE	STG						STATUS	UPDATED DATE
JOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH NO DEFECT DESC	CRIPTION JSN	STATUS	EST Mhr
XJL5727	300	NRP	AV	2361	777-55-806-00-01	VERTICAL FIN TOP #2 STATIC DISCHARGER BROKEN.	L572	OPEN	09/26/2023
	EMP								1.0
								-	1.0
XJL5735	300	NRP	AV	2361	777-55-806-00-01	VERTICAL FIN AFT ALL 6 EA STATIC DISCHARGER BROKEN.	L573	OPEN	09/26/2023
	EMP								6.0
								-	6.0
XJL5743	200	NRR	SS	25	777-C252430-01-07-	PEY PAX SEAT BACK REST RECLINE CABLE OPERATION FOUND TIGHTEN AT:33F	F 32G 31G 34H TOTAL:4EA L574	OPEN	09/26/2023
	CAB				01				2.0
								-	2.0
XJL5750	200	NRM	AV	3531	AEO-29573-01	FOUND PORTABLE OXYGEN BOTTLE NEAR EXPIRY DATE AT LAV B, STOWAGE E	E3R LOWER, G4 DOGHOUSE UPPER, L575	OPEN	09/26/2023
	CAB					G4 DOGHOUSE LOWER, 72G DOGHOUS MIDDLE, TOTAL 5EA			9.0
								-	9.0
XJL5768	200	NRR	Al	2560	777-53-904-00-01	CABIN R2 DOOR AREA BESIDE THE ATTENDANT SEAT FOUND FLASHLIGHT(UTILI	LITY) FOUND DAMAGE L576	WIP	09/28/2023
	CAB								1.0
								-	1.0
XJL5776	200	NRR	Al	2560	777-53-904-00-01	CABIN R5 DOOR AREA INSIDE THE ATTENDANT SEAT FOUND FLASHLIGHT(DME)) FOUND LOW POWER L577	WIP	09/27/2023
	CAB								1.0
								-	1.0
XJL5784	100	NRR	AE	5200	777-53-800-00-07	EXTERNAL ELECTRICAL POWER RECEPTACLE ACCESS DOOR MISS ALIGNMENT	T WITH FUSELAGE SKIN L578	OPEN	09/26/2023
	FUS								0.0
								-	0.0
XJL5792	100	NRR	AE	5200	777-53-800-00-07	EXTERNAL ELECTRICAL POWER RECEPTACLE ACCESS DOOR 1EA BONDING JUN	IMPER WIRES FOUND BROKEN L579	OPEN	09/26/2023
	FUS								0.0
						1C 1 REPLACE THE BONDING.			1.0
						1C 2 DO THE BONDING TEST.			0.5
								-	

515653

BMS571R1-2

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE: 78 OF 83 RUN DATE: 9/28/2023

RUN TIME :

11:09

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL STATUS: ALL ORIG-STAGE: ALL PERIOD: ALL ESTIMATED MHR: ALL

ORIGINATING CUST REF NO: ATA NO: ALL ZONE: ALL DISPOSITION CODE: ALL ALL

DEFECT TYPE: ALL TRADE: ALL CUST ENDORSE: ALL AREA: ALL STAGE: ALL

TRECODE.	ZONE	STG			TIPE CODE.	ORIGINATOR	ALL		STATUS	UPDATED DATE
JOB NO	AREA	316	TD	ATA	ORIG CUST REF NO.	CTRL SH NO	DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
JL5800	100	NRR	AE	2900	777-53-844-00-01	AFT KEEL BEAM ACCESS PANEL	149CL INNER CAVITY FOUND CENTER HYD RESERVOIR DRAIN HOSE TORN	L580	OPEN	09/26/2023
	FUS									1.0
									-	1.0
JL5818	200	NRR	CL	5300	777-53-546-01-01	BOTH LEFT AND RIGHT SIDE OVE	RWING TO BODY FAIRING INNER CAVITY DIRTY	L581	OPEN	09/26/2023
2200.0	FUS		0_	0000	65 6 16 6 1 6 1	BOTTLET TAND THOM OIDE OVE	ANNIO TO BODI TAIMINO INNELLOSANTI BILLI	L301	OFLIN	6.0
									-	
U 5000	000	NDD	01	0504	777 50 000 00 04	040 500 0547 0407 0454 007				6.0
JL5826	200 CAB	NRR	CL	2501	777-53-908-00-01		ILE CONSOLE RED FABRIC TRIM FOUND DIRTY 11A 12A 16A 17A 19A 20A 21A 23A 22D 24D 25D 26D 11G 16G 20G 23G 24G 25G 18K 20K 23K 25K 17K	L582	OPEN	09/26/2023
	O/ LD								_	0.0
										0.0
JL5834	200	NRR	AE	5300	777-53-546-01-01	APPLY CIC TO BOTH LEFT AND RI	IGHT SIDE OVERWING TO BODY FAIRING INNER CAVITY AFTER CLEANING	L583	OPEN	09/26/2023
	FUS									3.0
									-	3.0
JL5842	100	NRR	SM	5300	777-53-800-00-10	FWD CARGO BILGE AREA BSTA10	000 LEFT SIDE FRAME FOUND ELECTRICAL WIRE 1EA STANDOFF BROKEN	L584	OPEN	09/26/2023
	LWR									1.0
									-	1.0
JL5859	200	NRR	ΑI	25	777-53-920-00-01	M/D M LAV TOILET SHROUD COVE	ER FOUND CRACKED	L585	OPEN	09/26/2023
	CAB									1.0
									-	1.0
JL5867	400	NRP	SM	5400	777-900001-01-1-01	#2 PYLON AFT FAIRING I/B FWD &	AFT ACC DOOR LOWER 2EA LATCHES SPRING BROKEN.	L586	OPEN	09/26/2023
	ENG							2000	OI LIV	0.0
						1C 1 REMOVE BROKEN	ILATCH			4.0
						1C 2 INSTALL NEW LAT	CH			4.0
						1C 3 TOUCH UP PAINT				1.0
									-	9.0
IL5875	400	NRP	AE	7100	777-900001-01-1-01	#1 ENG FAN COWL 3EA HOIST PL	UGS FND BROKEN.	L587	OPEN	09/26/2023
	ENG									2.0
									-	2.0

0PPC DISTRIBUTION:

ORIGINATING CUST REF NO:

515653

BMS571R1-2

ALL

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE: 79 OF 83

RUN TIME :

RUN DATE: 9/28/2023

11:09

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL STATUS: ALL ORIG-STAGE: ALL PERIOD: ALL ESTIMATED MHR: ALL

> ATA NO: ALL ZONE: ALL DISPOSITION CODE: ALL

TRADE: ALL DEFECT TYPE: ALL CUST ENDORSE: ALL AREA: ALL STAGE: ALL

JIKL CODE :					TYPE CODE:	URIGINATUR: AL	L			
	ZONE	STG							STATUS	UPDATED DATE
JOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH NO	DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
XJL5883	400	NRP	AE	7100	777-900001-01-1-01	#2 ENG FAN COWL 2EA HOIST PLUGS FND	BROKEN.	L588	OPEN	09/26/2023
	ENG									1.0
									-	1.0
XJL5891	200	NRR	Al	2500	777-53-912-00-01	CABIN DOOR 3 FWD CENTER PARTITION A	TER SIDE KICK STRIP FOUND DETACHED	L589	OPEN	09/26/2023
	CAB									2.0
									-	2.0
XJL5909	400	NRP	AE	7500	777-900001-01-1-01	#2 ENG TURBINE COOLING DUCT 5EA CLAI	IP RETAININGS FND WORN.	L590	OPEN	09/26/2023
	ENG									8.0
									-	8.0
XJL5917	400	NRP	AE	8000	777-900001-01-1-01	#1 ENG STARTER DUCT 6 O'CLOCK 1EA SU	PPORT ROD FND WORN	L591	OPEN	09/26/2023
	ENG									2.0
									-	2.0
XJL5925	300	NRR	CL	5300	777-55-800-00-01	HORIZONTAL STABILIZER JACKSCREW CO	MPARTMENT BSTA2174 TO BSTA2412 BILGE AREA DIRTY	L592	OPEN	09/26/2023
	EMP									6.0
									-	6.0
XJL5933	300	NRR	ΑE	5300	777-55-800-00-01	APPLY CIC TO HORIZONTAL STABILIZER JA	CKSCREW COMPARTMENT BSTA2174 TO BSTA2412 BILGE AREA	L593	OPEN	09/26/2023
	EMP									3.0
									-	3.0
XJL5941	400	NRP	AE	7100	777-900001-01-1-01	#1 ENG RH FAN COWL ACTUATOR NIPPLE	ND LEAKAGE.	L594	OPEN	09/26/2023
	ENG							2001	0. 2.1	3.0
									-	3.0
XJL5958	200	NRR	AV	2502	777-25-040-03-CX-01	EMA TEST FOUND 19D EMA INTERFACE CA	BLE ASSEMBLY INOP	L595	OPEN	09/26/2023
.02000	CAB			2002	-01		3-2-7-00-11-10-1	E393	OFLIN	3.0
									-	
XJL5966	200	NRR	Al	2500	777-53-916-00-01	CABIN SIDE BIN DR INTERIOR SURFACE AT	A3H AND AAH END DENT	1.500	ODEN	3.0
VOE0300	CAB	ININI	Δi	2500	111-00-016-00-01	OADIN SIDE DIN DIN INTENION SURFACE AT	דאון חוע דדון וועט ט <i>ב</i> וזון וואס טבוזון וואס טבוזין וואס טבוזין וואס טבוזין וואס טבוזין וואס טבוזין וואס טבוזין	L596	OPEN	09/26/2023
									_	4.0
										4.0

515653

BMS571R1-2

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE: 80 OF 83

ESTIMATED MHR: ALL

RUN DATE: 9/28/2023

RUN TIME: 11:09

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL STATUS: ALL ORIG-STAGE: ALL PERIOD: ALL

ORIGINATING CUST REF NO: ALL ATA NO: ALL ZONE: ALL DISPOSITION CODE: ALL

DEFECT TYPE: ALL TRADE: ALL CUST ENDORSE: ALL AREA: ALL STAGE: ALL

TRL CODE :					TYPE CODE:	ORIGINATOR: ALL			
	ZONE	STG						STATUS	UPDATED DATE
JOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH NO DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
(JL5974	200	NRR	AV	2502	777-25-040-03-CX-01 -01	INSPECTION EMA FOUND 11G.25G TEST BLANK PLUG MISSING	L597	OPEN	09/26/2023
	CAB				-01				1.0
								-	1.0
JL5982	200	NRP	AV	3531	777-35-160-01-CX-01	LAV B 2EA SPARE PORTABLE OXYGEN MASK NEAR EXPIRY DATE	L598	OPEN	09/26/2023
	CAB								2.0
								-	
(JL5990	200	NRR	CL	2527		NID HADOOD TO HODOOD DENOVED AND E CARDETO ADEA ELOOD DIN LIDDED CUREACE FAID DIDTY			2.0
JE5990	CAB	INKK	CL	2321		M/D #1DOOR TO #3DOOR REMOVED AISLE CARPETS AREA FLOOR PNL UPPER SURFACE FND DIRTY	L599	WIP	09/28/2023
	O/ LD							_	32.0
									32.0
JL6006	300	NRR	SM	5300	777-53-924-00-01	TAIL CONE FUSELAGE EXTERNAL SKIN BSTA2390 TO BSTA2412 STR1L TO STR2L FOUND 1EA DENT MARK	L600	OPEN	09/26/2023
	EMP								0.0
						1C 1 CARRY OUT CRACK FREE CHECK			1.0
								-	1.0
JL6014	700	NRR	AE	3222	777-32-802-00-01	L/G-NLG RH AFT DOOR OPERATIONAL ROD GEAR SIDE ATTACHED BOLT 1EA GREASE NIPPLE MISSING.	L601	OPEN	09/26/2023
	LDG								1.0
								-	1.0
(JL6022	300	NRR	SM	5300	777-53-924-00-01	TAIL CONE FUSELAGE EXTERNAL SKIN BSTA2390 TO BSTA2412 STR2L TO STR3L FOUND 1EA SCRATCH MARK	L602	WIP	09/28/2023
	EMP								0.0
						1C 1 REMOVE THE SCRATCH DAMAGE			2.0
						1C 2 APPLY A CHEMICAL CONVERSION COATING			0.5
						1C 3 ASSESS THE REWORK AREA			1.0
						1C 4 APPLY 1 LAY OF BMS 10-79, TYPE III PRIMER TO THE SURFACE			1.0
						2C 5 CARRY OUT THICKNESS CHECK			1.0
						2C 6 CARRY OUT CRACK FREE CHECK			1.0
								-	6.5
JL6030	700	NRR	AE	3245	777-53-810-00-01	L/G-NLG LH SPIN BRAKE METAL PLATE CRACKED.	L603	OPEN	09/26/2023
	LDG								4.0
								-	4.0

ORIGINATING CUST REF NO:

515653

BMS571R1-2

ALL

REQUESTED BY:

REFERENCE NO:

PPC TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

PAGE: 81 OF 83

RUN DATE: 9/28/2023

RUN TIME: 11:09

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL STATUS: ALL ORIG-STAGE: ALL PERIOD: ALL ESTIMATED MHR: ALL

ATA NO: ALL ZONE: ALL DISPOSITION CODE: ALL

DEFECT TYPE: ALL TRADE: ALL CUST ENDORSE: ALL AREA: ALL STAGE: ALL

CTRL CODE :					TYPE CODE:	ORIGINATOR	R: ALL			
	ZONE	STG							STATUS	UPDATED DATE
JOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH NO	DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
XJL6048	300	NRR	SM	5500	777-55-820-00-01	VERTICAL STABILIZER T/E ACCES	SS PANEL 324DXL FOUND 5EA ANCHOR NUTS BROKEN	L604	OPEN	09/26/2023
	EMP									2.0
									-	2.0
XJL6055	300	NRR	AE	5500	777-55-820-00-01	VERTICAL STABILIZER T/E ACCES	SS PANEL 324DXL 324AL AND 324GK TOTAL 200EA SCREW HEAD WORN	L605	OPEN	09/26/2023
	EMP									0.0
									-	0.0
XJL6063	200	NRR	Al	1100	777-11-000-01-CX-R-	CABIN LAV WATER HEATER ACC F	PNL INSIDE FND PLACARDS MISSING AT LAV A(1EA) AND LAV B(2EA)	L606	OPEN	09/26/2023
	CAB				01					3.0
									-	3.0
XJL6071	300	NRR	CL	5300	777-53-880-00-01	PLEASE CLEAN BODY FAIRING BA	ACK SIDE SURFACE	L607	OPEN	09/26/2023
	EMP									4.0
									-	4.0
XJL6089	100	NRR	SS	2500	777-53-862-00-01	AFT CARGO BILGE AREA INSULAT	TION BLANKET FOUND BROKEN AT STA 1434+21 TO STA 1434+42 R/H	L608	OPEN	09/26/2023
	LWR									0.0
									-	0.0
XJL6097	100	NRR	SS	2500	777-53-862-00-01	AFT CARGO BILGE AREA INSULAT	TION BLANKET FOUND BROKEN AT STA 1434+42 TO STA 1434+63 R/H	L609	OPEN	09/26/2023
	LWR							2003	OI LIV	0.0
									-	0.0
XJL6105	100	NRR	SS	2500	777-53-862-00-01	AFT CARGO BII GE AREA INSUI AT	TION BLANKET FOUND BROKEN AT STA 1434+84 TO STA 1434+105 R/H	L610	OPEN	09/26/2023
7.020.00	LWR			2000	66 662 66 6.	7.1.1.07.11.00 B.12.02.7.11.12.11.11.00.21.1		2010	OFLIN	0.0
									-	
XJL6113	100	NRR	SS	2500	777-53-862-00-01	AET CADCO DII CE ADEA INCLII AT	TION BLANKET FOUND BROKEN AT STA 1434+168 TO STA 14+189 R/H	1.044	0051	0.0
AJLOTIS	LWR	INIXIX	33	2500	777-33-802-00-01	AFT CARGO BILGE AREA INSULAT	TION BLANKET FOUND BROKEN AT STA 1454+100 TO STA 14+109 R/IT	L611	OPEN	09/26/2023
									-	0.0
V II 0404	400	NDD		0500	777 50 000 00 04	457 04 DOO DU OF 4 DE4 551 1551				0.0
XJL6121	100 LWR	NRR	SS	2500	777-53-862-00-01	AFT CARGO BILGE AREA CENTER 2EA	R AND L/H INSULATION BLANKET FOUND BROKEN AT STA 1643 TO STA 1664.TOTAL	L612	OPEN	09/26/2023
	LVVIX								_	0.0
									-	0.0

515653

BMS571R1-2

REQUESTED BY:

REFERENCE NO:

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD.

NRC TALLY LIST WITH ESTIMATE MANHOUR

(By JSN)

AREA: ALL

PAGE: RUN DATE: 9/28/2023 RUN TIME :

STAGE: ALL

82 OF 83

11:09

PROJECT: XJ CUSTOMER: CX A/C TYPE: 777 A/C REGN: B-KPV CHECK TYPE: 2C

JSN RANGE SELECTED: ALL STATUS: ALL ORIG-STAGE: ALL PERIOD: ALL ESTIMATED MHR: ALL

ORIGINATING CUST REF NO: ATA NO: ALL ZONE: ALL DISPOSITION CODE: ALL ALL

DEFECT TYPE: ALL TRADE: ALL CUST ENDORSE: ALL CTRL CODE: TYPE CODE: ORIGINATOR: ALL

OTTLE GODE :	ZONE	STG			111 2 0002.	ONGINATION. ALL			STATUS	UPDATED DATE
JOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH NO	DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
XJL6139	100	NRR	SS	2500	777-53-862-00-01	AFT CARGO BILGE AREA R/H AND L/H INSULA	TION BLANKET FOUND BROKEN AT STA 1685 TO STA 1706.TOTAL 2EA	L613	OPEN	09/26/2023
	LWR									0.0
									-	0.0
XJL6147	100	NRR	SS	2500	777-53-862-00-01	AFT CARGO BILGE AREA INSULATION BLANKE	T FOUND BROKEN AT STA 1748 TO STA 1769 R/H	L614	OPEN	09/26/2023
	LWR									0.0
									-	0.0
XJL6154	100	NRR	SS	2500	777-53-862-00-01	AFT CARGO BILGE AREA INSULATION BLANKE	T FOUND BROKEN AT STA 1853 TO STA 1874 R/H	L615	OPEN	09/26/2023
	LWR									0.0
									-	0.0
XJL6162	700	NRR	ΑE	3245	777-32-810-02-01	L/G-RH MLG NO.8 FOUND DEEP CUT.		L616	OPEN	09/27/2023
	LDG									0.0
									-	0.0
XJL6170	400	NRP	AE	2911	777-29-000-02-CX-01	LH HYD COMPARTMENT 5EA DIFFERENT PRE	SSURE INDICATOR COVERS AGED.	L617	OPEN	09/27/2023
	FUS									3.0
									-	3.0
XJL6188	400	NRP	AE	2911	777-29-000-02-CX-01	RH HYD COMPARTMENT 5EA DIFFERENT PRE	SSURE INDICATOR COVERS AGED.	L618	OPEN	09/27/2023
	FUS									3.0
									-	3.0
XJL6196	400	NRP	AE	2911	777-29-000-02-CX-01	CTR HYD SYS 10EA DIFFERENT PRESSURE IN	DICATOR COVERS AGED.	L619	OPEN	09/27/2023
	FUS									4.0
									-	4.0
XJL6204	700	NRR	AE	3211	777-32-300-00-01	L/G-LH MLG DRAG BRACE LOCK LINK ASSY TO	GGLE 3EA GREASE NIPPLES MISSING.	L620	OPEN	09/27/2023
	LDG									3.0
									-	3.0
XJL6212	500	NRP	AE	5700	777-900001-01-1-01	L & R WING UPPER PANEL (#6~9 SPOILER FWI) SEALANT FOUND MISSING & POOR CONDITION	L621	WIP	09/27/2023
	WNG									3.0
									-	3.0

TAIKOO (XIAMEN) AIRCRAFT ENGINEERING CO.,LTD. NRC TALLY LIST WITH ESTIMATE MANHOUR

PAGE: 83 OF 83

RUN TIME :

REFERENCE NO: BMS571R1-2

(By JSN)

RUN DATE: 9/28/2023

11:09

A/C TYPE: 777 CHECK TYPE: PROJECT: XJ CUSTOMER: CX A/C REGN: B-KPV 2C

JSN RANGE SELECTED: ALL STATUS: ALL ORIG-STAGE: ALL PERIOD: ALL ESTIMATED MHR: ALL

> ATA NO: ALL ZONE: ALL DISPOSITION CODE: ALL

DEFECT TYPE: ALL TRADE: ALL CUST ENDORSE: ALL AREA: ALL STAGE: ALL

CTRL CODE : TYPE CODE: ORIGINATOR ·

CIRLCODE	:				TYPE CODE:	ORIGINATOR: ALL				
	ZONE	STG							STATUS	UPDATED DATE
JOB NO	AREA		TD	ATA	ORIG CUST REF NO.	CTRL SH NO	DEFECT DESCRIPTION	JSN	STATUS	EST Mhr
XJL6220	100	NRR	AE	5300	777-53-804-00-01	NOSE RADOME PRESSURE BULKHEAD LEFT SIDE BULB SI	EAL TORN	L622	OPEN	09/27/2023
	FUS									2.0
									-	2.0
XJL6238	400	NRP	AE	7800	777-24-030-00-01	#2 ENG LH TR COWL 9 O'CLOCK FWD SEAL ASSY FND CRA	CKED.	L623	OPEN	09/27/2023
	ENG									4.0
									-	4.0
XJL6246	400	NRP	AE	5400	777-24-030-00-01	#1 PYLON AFT CAVITY WATER LEVELING COMPOUND FND	LOOSEN.	L624	OPEN	09/27/2023
	ENG									4.0
									-	4.0
XJL6253	400	NRP	AE	5400	777-24-030-00-01	#2 PYLON AFT CAVITY WATER LEVELING COMPOUND FND	LOOSEN.	L625	OPEN	09/27/2023
	ENG									4.0
									-	4.0
TOTAL NO O	F NRC PRI	INTED :		6	25			Total Mhr		4,929.2

Jobs OPEN: 422 Jobs READY: 0 Jobs WIP: 166 Jobs HOLD: 0 Jobs CANC: 0 Jobs DEFER: 0 Jobs COMP: 37

REQUESTED BY:

ORIGINATING CUST REF NO:

515653

ALL

I CERTIFY THAT I HAVE CHECKED THAT ALL THE ABOVE REFERENCED CARDS HAVE BEEN CERTIFIED AS HAVING BEEN COMPLETED.

PLANNING ENGINEER _____ DATE ____ CERTIFYING STAFF _____ DATE _____ STAMP AND SIGNATURE