


Short-window anchors and process controls

Reduction (%)



Process controls

Hexose anchors

Pentose branch

55 C, 2 h

55 C, 3 h

55 C, 4 h

60 C, 2 h

60 C, 4 h