Recorded Steps

This file contains all the steps and information that was recorded to help you describe the recorded steps to others. Before sharing this file, you should verify the following:

- The steps below accurately describe the recording.
- There is no information below or on any screenshots that you do not want others to see.

Passwords or any other text you typed were not recorded, except for function and shortcut keys that you used.
You can do the following:

- Review the recorded steps
- Review the recorded steps as a slide show
- Review the additional details

Steps

Next

Step 1: (9/12/2022 12:25:39) User left click on "Ethernet (tree item)" in "Advantech ADAM/APAX Utility (Win32) Version 2.6.00 (B15)"



Previous Next

Step 2: (9/12/2022 12:25:41) User left click on "toolStripButton3 (button)" in "Advantech ADAM/APAX Utility (Win32) Version 2.6.00 (B15)"



Previous Next

Step 3: (9/12/2022 12:25:51) User left click on "192.168.0.42-[] (tree item)" in "Advantech ADAM/APAX Utility (Win32) Version 2.6.00 (B15)"



Previous Next

Step 4: (9/12/2022 12:26:05) User left click on "Network (tab item)" in "Advantech ADAM/APAX Utility (Win32) Version 2.6.00 (B15)"



Previous Next

Step 5: (9/12/2022 12:26:09) User left click on "second(s) (edit)" in "Advantech ADAM/APAX Utility (Win32) Version 2.6.00 (B15)"



Previous

Step 6: (9/12/2022 12:26:11) User keyboard input on "second(s) (edit)" in "Advantech ADAM/APAX Utility (Win32) Version 2.6.00 (B15)" [Backspace Backspace ...]

Comment: Type your prefered IP addess here, and press apply changes.



Additional Details

The following section contains the additional details that were recorded.
These details help accurately identify the programs and UI you used in this recording.
This section may contain text that is internal to programs that only very advanced users or programmers may understand.
Please review these details to ensure that they do not contain any information that you would not like others to see.

Recording Session: 9/12/2022 12:25:35 - 12:26:23

Recorded Steps: 6, Missed Steps: 0, Other Errors: 0

Operating System: 22621.1.amd64fre.ni_release.220506-1250 10.0.0.0.2.164

Step 1: User left click on "Ethernet (tree item)" in "Advantech ADAM/APAX Utility (Win32) Version 2.6.00 (B15)"
Program: ADAM/APAX Utility, 2.6.0010.0, Advantech, ADAMNET.EXE, ADAMNET.EXE
UI Elements: Ethernet, Advantech ADAM/APAX Utility (Win32) Version 2.6.00 (B15), WindowsForms10.SysTreeView32.app.0.141b42a_r7_ad1, Advantech ADAM/APAX Utility (Win32) Version 2.6.00 (B15), WindowsForms10.Window.20008.app.0.141b42a_r7_ad1

Step 2: User left click on "toolStripButton3 (button)" in "Advantech ADAM/APAX Utility (Win32) Version 2.6.00 (B15)"
Program: ADAM/APAX Utility, 2.6.0010.0, Advantech, ADAMNET.EXE, ADAMNET.EXE
UI Elements: toolStripButton3, mainToolStrip, WindowsForms10.Window.8.app.0.141b42a_r7_ad1, Advantech ADAM/APAX Utility (Win32) Version 2.6.00 (B15), WindowsForms10.Window.20008.app.0.141b42a_r7_ad1

Step 3: User left click on "192.168.0.42-[] (tree item)" in "Advantech ADAM/APAX Utility (Win32) Version 2.6.00 (B15)"
Program: ADAM/APAX Utility, 2.6.0010.0, Advantech, ADAMNET.EXE, ADAMNET.EXE
UI Elements: 192.168.0.42-[], 192.168.0.150, Ethernet, Advantech ADAM/APAX Utility (Win32) Version 2.6.00 (B15), WindowsForms10.SysTreeView32.app.0.141b42a_r7_ad1, Advantech ADAM/APAX Utility

(Win32) Version 2.6.00 (B15), WindowsForms10.Window.20008.app.0.141b42a_r7_ad1

Step 4: User left click on "Network (tab item)" in "Advantech ADAM/APAX Utility (Win32) Version 2.6.00 (B15)"
Program: ADAM/APAX Utility, 2.6.0010.0, Advantech, ADAMNET.EXE, ADAMNET.EXE
UI Elements: Network, WindowsForms10.SysTabControl32.app.0.141b42a_r7_ad1, FormAdamTCPLocal, WindowsForms10.Window.8.app.0.141b42a_r7_ad1,
WindowsForms10.Window.8.app.0.141b42a_r7_ad1, Advantech ADAM/APAX Utility (Win32) Version 2.6.00 (B15), WindowsForms10.Window.20008.app.0.141b42a_r7_ad1

Step 5: User left click on "second(s) (edit)" in "Advantech ADAM/APAX Utility (Win32) Version 2.6.00 (B15)"
Program: ADAM/APAX Utility, 2.6.0010.0, Advantech, ADAMNET.EXE, ADAMNET.EXE
UI Elements: second(s), WindowsForms10.EDIT.app.0.141b42a_r7_ad1, Network Setting, WindowsForms10.Window.8.app.0.141b42a_r7_ad1, Network,
WindowsForms10.Window.8.app.0.141b42a_r7_ad1,
WindowsForms10.SysTabControl32.app.0.141b42a_r7_ad1, FormAdamTCPLocal,
WindowsForms10.Window.8.app.0.141b42a_r7_ad1,
WindowsForms10.Window.8.app.0.141b42a_r7_ad1, Advantech ADAM/APAX Utility (Win32) Version 2.6.00 (B15), WindowsForms10.Window.20008.app.0.141b42a_r7_ad1

Step 6: User keyboard input on "second(s) (edit)" in "Advantech ADAM/APAX Utility (Win32) Version 2.6.00 (B15)" [Backspace Backspace ...]
Program: ADAM/APAX Utility, 2.6.0010.0, Advantech, ADAMNET.EXE, ADAMNET.EXE
UI Elements: second(s), WindowsForms10.EDIT.app.0.141b42a_r7_ad1, Network Setting, WindowsForms10.Window.8.app.0.141b42a_r7_ad1, Network,
WindowsForms10.Window.8.app.0.141b42a_r7_ad1,
WindowsForms10.SysTabControl32.app.0.141b42a_r7_ad1, FormAdamTCPLocal,
WindowsForms10.Window.8.app.0.141b42a_r7_ad1,
WindowsForms10.Window.8.app.0.141b42a_r7_ad1, Advantech ADAM/APAX Utility (Win32) Version 2.6.00 (B15), WindowsForms10.Window.20008.app.0.141b42a_r7_ad1

Return to top of page...