

Individual pressure steps, P3 then P2 then P1: 32 runtime tip-MISSING reports
Raw sensor positions, no interpolation
P3
P2
P1
X
Y
Z
data1
data2
Tip raw XYZ (mm)
200
100
0
-100
-200
-300
-400
-500
0
20
40
60
80
100
120
Intervals between reported frame counters; not GUI-refresh timestamps
Frame-counter-derived interval
Nominal update period
data1
data2
Reply frame interval (s)
0.16
0.14
0.12
0.1
0.08
0.06
0.04
0.02
Runtime MISSING reports: base 0, tip 32
Transform valid
1
0.8
0.6
0.4
0.2
0
0A base
0B tip
Runtime tip missing
data1
data2
Seconds from first final-session BX reply