



SineWave4: missing tip transforms during channel-3 motion
Orientation-derived phi (rad)
P3 command (bar)
Simulation time (s)
Measured phi
Last valid phi before loss
P3 command


First loss: tip status2, base stays valid
Status / Boolean flag
Simulation time (s)
Tip NDI status
Orientation valid
Base valid


Actual last-valid poses before losses; missing poses unknown
Relative sensor Z (mm)
Relative sensor X (mm)
Every tenth valid sample
Before missing transform