

3310 Kitty Hawk Road, Suite 100 Wilmington, NC 28405 Tel: (888) 610-7664 Fax: (910) 401-1114

www.GlobalTestSupply.com - sales@GlobalTestSupply.com

Calibration Certificate

Customer: UNIVERSITY OF ARKANSAS

Certificate: 32343-00-1

UNIT IDENTIFICATION

Manufacture: FLUKE

Model: 51-2

Description: THERMOMETER

CALIBRATION DATE

Calibration Date: 11-Sep-2015

Due Date: 11-Sep-2016

CALIBRATION CONDITIONS

Serial: 32170100WS

ID: N/A

Temperature: 76.68 °F

Humidity: 47 %

Barometric Pressure: N/A

GENERAL INFORMATION

Procedure: FLUKE 51-II: (SPEC:1Y) /5500 Rev: 1

As Received: Within Specifications

As Returned: As Received

Data Type: As Found-As Left Adjusted: No

Remark: N/A

STANDARDS USED

ID GTS001 Manufacturer

FLUKE

Model 5500A

Cal Date 26-May-2015

lust Coffee

Due Date

26-May-2017

The calibration was performed using measurement standards traceable to the National Measurement Institute Standards (NMIS) part of the National Research Council of Canada (NRC) or the National Institute of Standards and Technology (NIST), or to accepted instrinsic standards or measurement, or is derived by ratio type self-calibration techniques. Measurement uncertainties given in this report are based on a coverage factor of k=2 corresponding to a confidence level of approximately 95%. ALEX H. COFFEY

Calibrated by: N. Bal.

Certificate: 32343-00-1 Asset: 32170100WS.51-2

Calibration Certificate Data Type: As Found-As Left Page 1 of 2

Test Results							
Test Description	True Value	Reading	Lower limit	Upper limit	<u>Units</u>	Test Status	Exp Uncert
BACKLIGHT TEST							
Result of Operator Evaluation						Pass	
INPU	JT T1						
THERMOCOUPLE T	ГҮРЕ Ј						
1000 °C		1000	999	1001	°C	Pass	6.0e-001°C
600.0 °C		600.2	599.4	600.6	°C	Pass	1.4e-001°C
300.0 °C		300.2	299.6	300.4	°C	Pass	1.4e-001°C
100.0 °C		100.2	99.7	100.3	°C	Pass	1.2e-001°C
0.0 °C		0.1	-0.3	0.3	°C	Pass	1.2e-001°C
-150.0 °C		-149.8	-150.6	-149.4	°C	Pass	2.2e-001°C
THERMOCOUPLE T	ГҮРЕ К						
1300 °C		1300	1299	1301	°C	Pass	6.6e-001°C
1000 °C		1000	999	1001	°C	Pass	6.1e-001°C
600.0 °C		600.2	599.4	600.6	°C	Pass	2.1e-001°C
200.0 °C		200.2	199.6	200.4	°C	Pass	2.1e-001°C
0.0 °C		0.1	-0.3	0.3	°C	Pass	1.4e-001°C
-150.0 °C		-149.9	-150.6	-149.4	°C	Pass	2.6e-001°C
HOLD TEST							
Result of Operator Ev	aluation					Pass	