

PX-100 Service Log - Production Line 3

Equipment: PX-100 Industrial Circulation Pump, asset tag PX100-L3-007. Site: Plant B (fictional).

This is a fictional document created for AI testing training. All people, employee IDs and phone numbers are invented. It intentionally contains personal details so learners can test data minimisation.

Date	Technician	Employee ID	Mobile (personal)	Shift	Work carried out	Result
2026-03-04	Anil Varghese	EMP-40217	+91 99999 00101	Early	6-month preventive maintenance: seals inspected, bearing temperature checked	OK
2026-05-19	Meera Pillai	EMP-40388	+91 99999 00102	Late	Overheating alarm investigated. Ventilation clearance restored (boxes stored too close to motor)	OK after fix
2026-06-02	Tobias Krüger	EMP-51120	+49 1500 0000103	Early	Unusual vibration reported. Shaft alignment checked and corrected	OK
2026-09-03	Meera Pillai	EMP-40388	+91 99999 00102	Late	6-month preventive maintenance: seals inspected, lubricant level checked, bearings normal	OK
2026-09-21	Rahul Menon	EMP-40755	+91 99999 00104	Night	Overheating alarm at 46 °C. Pump stopped, lubricant replaced, restarted after cool-down	OK; monitor
2026-09-29	Sara Thomas	EMP-40912	+91 99999 00105	Early	Follow-up check after overheating. Temperature 38 °C under normal load	OK

Supervisor note: in case of repeated overheating, contact the line supervisor on the internal maintenance channel. Do not call technicians on personal mobile numbers outside their shift.