


ABAS Feature demo


Defect analytics

ABAS is designed for defects at scale — it's nice to know there's a defect, it's better to know there's a cluster of defects and be able to provide a picture-report around that information.

ABAS customers (you) can provide your customers with online portals, allowing them to access defect reports and analytics. This provides huge value add, cements your relationship with larger customers, and often means customers bring over wider portfolios just to have all their data in one place.


Here's a client summary dashboard:








Monitor portfolio compliance over time:




Understand your defects across multiple tracking categories:






See common problems and provide reactive maintenance solutions to your customers before a competitor does.



Provide portfolio reports with photos, history, and geographical information:





Per visit reports can be customised to include relevant photos, defect listings, service history:

Section 3. Personal Injury Risk

3.1. Garden & Vegetation

This report is a visual inspection only carried out under the conditions of the day. This report is not an arborist report and is not an expert report on the condition or toxicity of the garden.

3.1.1. Location - Front of property

No.	Issue	Recommendation	Severity
3.1.1.1	Vegetation/Powerlines. There are tree branches in close proximity to overhead wiring.	Have a suitable contractor cut back the vegetation in accordance with power authority requirements.	Medium



3.2. Hazardous Goods

This report is a visual inspection only carried out under the conditions of the day. For a definitive report AESG recommend that you refer to the Dangerous Goods Act; this report is not an assessment under the dangerous goods act.

There were no issues identified for this section.

3.3. Lighting Hazards

This report is a visual inspection only carried out under the conditions of the day. Note this section of the report was carried out in daylight. Verification of the report must occur at night. Note this report makes no comment on personal security issues.

There were no issues identified for this section.