

Raspberry Pi + Sensors Guide



Grove hat

If your Raspberry Pi is in a case, please remove it. Mount the grove hat on your raspberry pi. Make sure the pins are properly aligned. Push the hat down as far as it will go but be careful not to apply too much force.



Then insert the spacers between the hat and the Pi, and screw them in. Be careful not to overtighten the screws, as to not damage the boards.

Grove sensors

There are 4 sensors to attach.

- Moisture sensor
- GPS
- Accelerometer
- Sonar

The moisture, GPS and Accelerometer are attached via the Grove connector. These are easily plugged in.

The Sonar is attached by four DuPont cables.

