AVIATION **SAFETY** NETWORK

AN EXCLUSIVE SERVICE OF FLIGHT SAFETY FOUNDATION

- Home
- <u>Database</u>
- Investigation
- Statistics
- Contact us
- About



Home » ASN Aviation Safety WikiBase

This information is added by users of ASN. Neither ASN nor the Flight Safety Foundation are responsible for the completeness or correctness of this information. If you feel this information is incomplete or incorrect, you can <u>submit</u> <u>corrected information</u>.

Share 0

Date: Friday 21 November 1997

Time:



Type: Airbus A320-232
Owner/operator: United Airlines

Registration: N413UA MSN: 470 Year of manufacture: 1994

Engine model: IAE V2527-A5

Fatalities: Fatalities: 0 / Occupants:

Other fatalities: 0
Aircraft damage: Minor
Category: Accident

Location: Washington-Dulles International Airport, DC (IAD/KIAD) - <u>United States of America</u>

Phase: Initial climb

Nature: Passenger - Scheduled

Departure airport: Washington-Dulles International Airport, DC (IAD/KIAD)

Destination airport:

Confidence Rating: O Information is only available from news, social media or unofficial sources

Narrative:

The aircraft returned to land at Washington-Dulles International Airport, USA after the no.1 engine fan cowls separated after takeoff.

It appeared that fan cowls were not correctly latched following engine maintanance.

Sources:

FAA

History of this aircraft

Other occurrences involving this aircraft

7 April 1997 N413UA United Airlines 0 Newark, NJ ■ non Turbulence

Revision history:

Date/time Contributor Updates 30-Nov-2018 19:36 harro Added

Corrections or additions? ... Edit this accident description

The Aviation Safety Network is an exclusive service provided by:

Quick Links:

ASN Home Send Correction / Feedback

FSF Home Disclaimer

Copyright

Contact Us Privacy Policy

Press / Media





©2024 Flight Safety Foundation