AVIATION **Safety** Network

AN EXCLUSIVE SERVICE OF FLIGHT SAFETY FOUNDATION

- Home
- <u>Database</u>
- Investigation
- Statistics
- Contact us
- About



Home » ASN Aviation Safety WikiBase

This information is added by users of ASN. Neither ASN nor the Flight Safety Foundation are responsible for the completeness or correctness of this information. If you feel this information is incomplete or incorrect, you can <u>submit</u> <u>corrected information</u>.

Date: Thursday 11 January 2018

Time:



Type: <u>Airbus A320-232 (WL)</u>

Owner/operator: Thai Smile Registration: HS-TXH MSN: 5828
Year of manufacture: 2013

Engine model: IAE V2527-A5

Fatalities: Fatalities: 0 / Occupants:

Other fatalities: 0
Aircraft damage: None

Category: Serious incident

Location: near Bangkok Airport - Thailand

Phase: Approach

Nature: Passenger - Scheduled

Departure airport: Hat Yai Airport (HDY/VTSS)

Destination airport: Bangkok-Suvarnabhumi International Airport (BKK/VTBS)

Confidence Rating:

Information verified through data from accident investigation authorities

Narrative:

A pilot declared emergency due to low fuel quantity level before landing at Suvarnabhumi International Airport.

Sources:

 $\frac{https://bea.aero/en/investigation-reports/notified-events/detail/serious-incident-to-the-airbus-a320-registered-hs-txh-and-operated-by-thai-smile-airways-on-11-01-2018-near-bangkok-investigation-led-by-aib---thailand/$

History of this aircraft

Other occurrences involving this aircraft

Revision history:

Date/time **Contributor Updates** Added 13-Apr-2023 16:47 harro

Corrections or additions? ... Edit this accident description

The Aviation Safety Network is an exclusive service provided by:

Quick Links:

ASN Home Send Correction / Feedback

Disclaimer FSF Home

Copyright

Contact Us **Privacy Policy**

Press / Media



CONNECT WITH US:









©2025 Flight Safety Foundation