

The stop request is a software path, not an independent disconnection of motor power.

Calibration establishes the coordinate reference in software; missed steps can invalidate it without the controller knowing.