



TODO:

- Change R 0402 to 0605
- Add the jumper resistor for RD+/- pin and LED to make it 2nd source with HanRun Mag jack
- >RD_CONN_P Würth use pin 3
- >RD_CONN_P HanRun use pin 7
- >LED Yellow polarity on HanRun is opposite of Würth



Note:
50 Ohm impedance



iRob_ETH_Sch v26

2026-06-27 5:39 PM

Sheet: Ethernet



