

TODO:

- Change R 0402 to 0605
- Add the jumper resistor for RD+/- pin and LED to make it 2nd source with HanRun Mag jack
- >RD_CONN_P Wurth use pin 3
- >RD_CONN_P HanRun use pin 7
- >Green and Yellow of HanRun and Wurth are opposite, and pin 12/11 polarity is also opposite



