

Función	Opcode	Funct3	Funct7	Tipo Instruccion
lb (load byte)	0000011	000	-	I
lh	0000011	001	-	I
lw	0000011	010	-	I
lbu	0000011	100	-	I
lhu	0000011	101	-	I
addi	0010011	000	-	I
slli	0010011	001	0000000	I
slti	0010011	010	-	I
sltiu	0010011	011	-	I
xori	0010011	100	-	I
srli	0010011	101	0000000	I
srai	0010011	101	0100000	I
ori	0010011	110	-	I
andi	0010011	111	-	I
sb (store byte)	0100011	000	-	S
sh	0100011	001	-	S
sw	0100011	010	-	S
add	0110011	000	0000000	R
sub	0110011	000	0100000	R
sll	0110011	001	0000000	R
slt	0110011	010	0000000	R
sltu	0110011	011	0000000	R
xor	0110011	100	0000000	R
srl	0110011	101	0000000	R
sra	0110011	101	0100000	R
or	0110011	110	0000000	R
and	0110011	111	0000000	R
lui	0110111	-	-	U
beq	1100011	000	-	B
bne	1100011	001	-	B
blt	1100011	100	-	B
bge	1100011	101	-	B
jal	1101111	-	-	J