

ID	0	Task Mode	Task Name	Duration	Start	Finish	Predecess	ors	т	Dec 27		W	Jan 10,	, '21 S	Jan T	24, '21 T S	Feb 7, '21
15			Research CO2/O2 sensors	4 days	Jan 18 '21	Jan 21 '21				<u> </u>			IVI			ndon	1 70
16		-5	Research Temp&Light sensors	4 days	Jan 18 '21	Jan 21 '21									Yiku	ın	
17		- 5	Research Smartmesh IP Mote module	4 days	Jan 18 '21	Jan 21 '21									Yud		
18		-3	Research Smartmesh IP Manager	4 days	Jan 18 '21	Jan 21 '21									Calv	vin	
19		*	Week 4	6 days?	Jan 25 '21	Feb 1 '21											+
20		-5	Research Smartmesh amstermode starter kit	4 days	Jan 25 '21	Jan 28 '21										Yous	sef
		- -3	Sensor spreadsheet	4 days	Jan 28 '21	Feb 2 '21											Brandon
22		-5	Research vibration&water sensors	4 days	Jan 28 '21	Feb 2 '21											Yikun
23			Research Vmware&Emana	4 days	Jan 28 '21	Feb 2 '21											Yudi
24		- 5	Research GUI&Smartmesh intergration	4 days	Jan 28 '21	Feb 2 '21											Calvin
			Task			Inactive Sum	mary			¶ Ex	ternal T	asks					1
			Split			Manual Task				Ex	ternal N	√iles	tone	\Diamond			
Projec	rt. San	sor Suita	e - Team 20 Milestone		♦	Duration-onl	y			De	eadline			•			
Date:			Summary			Manual Sum	mary Rollup			■ Pr	ogress			-			•
			Project Sum	mary		Manual Sum	mary			1 M	anual P	rogre	ess	_			•
			Inactive Tasl	k		Start-only	[_									
			Inactive Mile	estone	\Diamond	Finish-only	·]									
						Page 2											

ID	0	Task Mode	Task Name	Duration	Start	Finish	Predecess	sors	Т	Dec 2	7, '20 F	w	Jan 10, M	'21 S	24, '21 T S	Feb 7, '21
25		-5	Finish Initial Bo	N2 days	Jan 25 '21	Jan 26 '21										
26	00	-5	Submit Project schedule	0.5 days?	Feb 5 '21	Feb 5 '21										Brandor
27	00	-	Submit PDS	1 day?	Feb 5 '21	Feb 5 '21										
28		*	Week 5	6 days?	Feb 8 '21	Feb 14 '21										
29		-5	Order sensors	4 days	Feb 8 '21	Feb 11 '21										Bi
30		-5	Order Smartmesh module	4 days	Feb 8 '21	Feb 11 '21										Y
31		5	Research Emanager interface	4 days	Feb 8 '21	Feb 11 '21										Y
32		-5	Review&revise project design specifications	4 days	Feb 8 '21	Feb 11 '21										Ca
33		*	Week 6	6 days?	Feb 15 '21	Feb 21 '21										
34		-5	Research PCB schematic	4 days	Feb 15 '21	Feb 18 '21										
35	*	-5	Test&Program huminity	4 days	Feb 15 '21	Feb 18 '21										
36	*	-5	Test&Program Water contact sensors	4 days	Feb 15 '21	Feb 18 '21										
37		-5	Research Smartmesh programming	4 days	Feb 15 '21	Feb 18 '21										
			Task			Inactive Sumr	mary			1 Ex	xternal	Tasks				
			Split				-			E)	xternal	Miles	tone	\Diamond		
	_		Milestone		♦	Duration-only	,			D	eadline	e		+		
Project Date:			e - Team 20 Summary			Manual Sumr					rogress			_		
Date:	reb 5)	Project Sun	nmary		Manual Sumr					1anual I		ess	_		
			Inactive Tas			Start-only	•	Е				,				
			Inactive Mil		\Diamond	Finish-only		3								
			I			Page 3										

)	•	Task Mode	Task Name	Duration	Start	Finish	Predecessor	rs T	ec 27, '2		Jan 10, M	'21 S	Jan T	1 24, '2' T	l s	Feb 7, '2 F W
38		-5	Present PDS	0.1 days	Feb 19 '21	Feb 19 '21					'					
39		*	Week 7	6 days?	Feb 22 '21	Feb 28 '21										
40		-5	Begin testing smartmesh	4 days	Feb 22 '21	Feb 25 '21										
41	&	-5)	Test&Program temp&light sensors	4 days	Feb 22 '21	Feb 25 '21										
42	.	-5	Test&Program CO2/O2 sensors		Feb 22 '21	Feb 25 '21										
43		*	Week 8	6 days?	Mar 1 '21	Mar 7 '21										
44	*	5	Enable communication between LTP5902 and	1.33 days	Mar 1 '21	Mar 2 '21										
45	*	-5	Learn how to operate Emanager	2 days	Mar 1 '21	Mar 2 '21										
46	*	-5	Test mote connection	2 days	Mar 1 '21	Mar 2 '21										
47	.	-5	Discuss Sensor and smartmesh Integration	4 days	Mar 1 '21	Mar 4 '21										
48	&	-5	Test&Program Wind speed and direction		Mar 1 '21	Mar 1 '21										
			Task			Inactive Sumi	mary [Exter	nal Tasl	:S					
			Split				· •			nal Mile		\Diamond				
			Milestone		♦	Duration-only	,		Dead			•				
-			e - Team 20 Summary			l Manual Sumr			Prog			_				
vate:	Feb 5)	Project Sum	mary		Manual Sumr	•		_	ual Prog	ress	_				
			Inactive Tasl			Start-only				3						
			Inactive Mile			Finish-only	3									
						Page 4										

)	0	Task Mode	Task Name	Duration	Start	Finish	Predecessor	S		ec 27, ' S			10, '21 И .		24, '21 T S	Feb 7, '
49	*	-5	Test&Program Vibration	4 days	Mar 1 '21	Mar 4 '21			·	·					·	
50		*	Week 9	6 days?	Mar 8 '21	Mar 14 '21										
51	*	- 5	Put together basic breadboard	4 days	Mar 8 '21	Mar 11 '21										
52		-5	Begin hand-sketch	4 days	Mar 8 '21	Mar 11 '21										
53	&	-5	Integrate senor programming w/ SmartMesh	4 days	Mar 8 '21	Mar 11 '21										
54		-5	Configure Smartmesh E-manager	4 days	Mar 8 '21	Mar 11 '21										
55		*	Week 10	6 days?	Mar 15 '21	Mar 21 '21										
56	•	-	Test extra coding capabilities on functioning breadboard prototype(switc master and	4 days	Mar 15 '21	Mar 18 '21										
57	*	-53	Test power consumption on a scope	1.33 days	Mar 15 '21	Mar 16 '21										
			Task			Inactive Sumr	mary			Exte	rnal Ta	sks				
			Split			Manual Task				Exte	rnal Mi	lestone	9	\Diamond		
roie	rt. Sar	nsor Suita	e - Team 20 Milestone		♦	Duration-only				Dea	dline			•		
-	Feb 5		Summary			Manual Sumr	nary Rollup 📥			Prog	gress					-
			Project Sum	mary		Manual Sumr	nary I			Mar	nual Pro	gress				-
			Inactive Tas	<		Start-only	Е									
			Inactive Mile	estone		Finish-only	3									
			l			Page 5										

D	0	Task Mode	Task Name		Duration	Start	Finish	Predecess	sors	Т	Dec 2	27, '20 F) W	Jan 10 M	, '21 S	J T	lan 24,	'21 S	Feb 7, '21
58		-5)	powe	e detailed r imption	4 days	Mar 15 '21	Mar 18 '21												
59	.	-5		arch PCB ection	4 days	Mar 15 '21	Mar 18 '21												
60	*	4	testir	ng OTAP	4 days	Mar 15 '21	Mar 18 '21												
61		*	Week 1	1	6 days?	Mar 22 '21	Mar 28 '21												
62	*	- 5	powe consu	type n,(with	4 days	Mar 22 '21	Mar 25 '21												
63	.	-5	Resea	rch layout	4 days	Mar 22 '21	Mar 25 '21												
64		-5		ze Test or sensors	1 day?	Mar 22 '21	Mar 22 '21												
65	*	-5	Finaliz plan f	ze test or	1 day?	Mar 22 '21	Mar 22 '21												
66		*	Week 12	2	6 days?	Mar 29 '21	Apr 4 '21												
67	00	-5	Begin	PCB desig	r 4 days	Mar 29 '21	Apr 1 '21												
68		-5		arch Power rmance	3 days	Mar 29 '21	Mar 31 '21												
69		-5		extra ion of ager	4 days	Mar 29 '21	Apr 1 '21												
70		*	Week 13	3	6 days?	Apr 5 '21	Apr 11 '21												
				Task			Inactive Sumr	mary			1 E	xtern	al Task	s					
				Split			Manual Task				I E	xtern	al Mile	stone	\Diamond				
D	C	· · · · · · · ·	T 20	Milestone		♦	Duration-only	/				Deadli	ine		+				
Project Date:			e - Team 20	Summary			Manual Sumr	nary Rollup			_ F	rogre	ess		_				
Dutc.		, <u>_</u> 1		Project Sum	mary		Manual Sumr	mary			1 1	Manua	al Prog	ress	_				
				Inactive Tas	k		Start-only		Е										
				Inactive Mile	estone		Finish-only		3										
							Page 6												

ID	0	Task Mode	Task Name	Duration	Start	Finish	Predecess	sors	Т	Dec S	27, '2		Jan 10 M	, '21 S	Ja	an 24, '	21 S	Feb 7, '2'
71	*	-5	Begin Housing Design, finish Protoboard	4 days	Apr 5 '21	Apr 8 '21							,					
72	*	-5	Begin layout design	3 days	Apr 5 '21	Apr 7 '21												
73	*	-5	Finish physical Protoboard	4 days	Apr 5 '21	Apr 8 '21												
74	*		Finish software protoboard	3 days	Apr 5 '21	Apr 7 '21												
75		*	Week 14	6 days?	Apr 12 '21	Apr 18 '21												
76				4 days	Apr 12 '21	Apr 15 '21												
77		-5	Configure data-organizatio system	4 days	Apr 12 '21	Apr 15 '21												
78			Finish coding on protoboard	4 days	Apr 12 '21	Apr 15 '21												
79			Discuss PCB progress	4 days	Apr 12 '21	Apr 15 '21												
80		*	Week 15	6 days?	Apr 19 '21	Apr 25 '21												
81			Finalize PCB design and send files for	4 days	Apr 19 '21	Apr 22 '21												
82			FInalize Housing Design	4 days	Apr 19 '21	Apr 22 '21												
			Task			Inactive Sum	mary				Exterr	nal Task	S					
			Split			Manual Task					Exterr	al Mile	stone	\Diamond				
Duc!s	at. C - :	naan Cuits	Milestone		♦	Duration-only	y				Deadl	ine		•				
Project Date:			e - Team 20 Summary			Manual Sumr	mary Rollup				Progr	ess		_				
Date.		, <u>-</u> 1	Project Sum	mary		Manual Sumr	mary			_	Manu	al Prog	ress	_				
			Inactive Tasl	<		Start-only		С										
			Inactive Mile	estone		Finish-only		3										
						Page 7												

)	0	Task Mode	Task Name	Duration	Start	Finish	Predecess	ors		ec 27, '2		Jan 10, M	'21 S	Jar	1 24, '21 T	I S	Feb 7, '2
83		-5	Finalize Power Source	4 days	Apr 19 '21	Apr 22 '21			·								
84		- 5	Discuss Documentation progress	1 day?	Apr 19 '21	Apr 19 '21											
85		-5)	Finish final BoM	4 days	Apr 19 '21	Apr 22 '21											
86		*	Week 16	6 days?	Apr 26 '21	May 2 '21											
87	*	-5	Allow for shipping time for PCB	4 days	Apr 26 '21	Apr 29 '21											
88			Calculate theorical power consumption of 2nd propotype system	4 days	Apr 26 '21	Apr 29 '21											
89	&	-5	Build 2nd prototype in real	4 days	Apr 26 '21	Apr 29 '21											
90		*	Week 17	6 days?	May 3 '21	May 9 '21											
91		-5	begin Final Documentation	4 days	May 3 '21	May 6 '21											
92		-9	Test power consumption of 2nd propotype	4 days	May 3 '21	May 6 '21											
			consumption of 2nd propotype														
			Task			Inactive Sumi	mary			Exter	nal Task	.s					
			Split			Manual Task				Exter	nal Mile	stone	\Diamond				
roio	-+· Cor	ocor Suita	e - Team 20 Milestone		♦	Duration-only	,			Dead	lline		•				
	r. sei Feb 5		Summary			Manual Sumr	mary Rollup			Prog	ress		_				
J.C.		<u> </u>	Project Sum	mary		Manual Sumr	mary			Manı	ual Prog	ress	_				
			Inactive Tasl	(Start-only	1	Ε									
			Inactive Mile	estone		Finish-only		3									
						Page 8											-

D	0	Task Mode	Task Name	Duration	Start	Finish	Predecesso			ec 27, '2 S F		Jan 10, '2		Jan 24		Feb 7, '	
93		-5	Analysis difference between theory	4 days	May 3 '21	May 6 '21				·			·	·	·		
94		*	Week 18	6 days?	May 10 '21	May 16 '21											
95			PCB received, began soldering	4 days	May 10 '21	May 13 '21											
96		-5	Documentation work	4 days	May 10 '21	May 13 '21											
97		5	Configure software to max	4 days	May 10 '21	May 13 '21											
98		*	Week 19	6 days?	May 17 '21	May 23 '21											
99	.		final testing and	4 days	May 17 '21	May 20 '21											
100		-5	Begin Final Presentation	4 days	May 17 '21	May 20 '21											
101		*	Week 20	6 days?	May 24 '21	May 30 '21											
102	*	-5	final bug fix and polishing,	4 days	May 24 '21	May 27 '21											
103	*	-3	Create Operations	4 days	May 24 '21	May 27 '21											
104	*	-3	Begin Final Project Report	4 days	May 24 '21	May 27 '21											
105		*	Week 21	6 days?	May 31 '21	Jun 6 '21											
			Task Split			Inactive Summ	ary				nal Tasks		• • • • • • • • • • • • • • • • • • •		_		
			Milestone		♦	Duration-only				Dead			•				
-			e - Team 20 Summary		<u> </u>	Manual Summ				Progr			_				
Date:	reb 5	21	Project Sum	mary		Manual Summ				_	ıal Progr	ess					
			Inactive Tasl	•	_	Start-only		- -	-		9.						
			Inactive Mile			Finish-only	:]									
			l			Page 9											\neg

ID	0	Task Mode	Task Name	Duration	Start	Finish	Predecessors	Т.	ec 2	7, '20		\	an 10, M	'21 S	т	1 24, ' T	21 S	Fe	b 7, '21 W
106	*	-5	Finished with presentation(slice presentations	1 day?	May 31 '21	May 31 '21					•	•				•			
107	.	4)	Practice presentations	1 day?	May 31 '21	May 31 '21													
108	*	4)	Discuss Final Documentation	1 day?	May 31 '21	May 31 '21													
109		*	Week 22	6 days?	Jun 7 '21	Jun 13 '21													
110			Presentations (Completed with project, presentation), Final Project	1 day?	Jun 13 '21	Jun 13 '21													
111		-3	Second Team evaluation	1 day?	Jun 13 '21	Jun 13 '21													





















