Description	Quantity	Cost Per Unit	Total Cost	Link	Note		SUM
Stepper Motor Driver	1	\$6.95	\$6.95	https://www.adafruit.d			\$52.59
Adafruit APDS9960 Sensor	1	\$7.50	\$7.50	https://www.adafruit.c			
Wireless Remote	1	\$6.95	\$6.95	https://www.adafruit.d			
RF Reciever	1	\$4.95	\$4.95	https://www.adafruit.d			
Lazy Susan	1					LAB supply	
Stepper Motor	1	\$24.95	\$24.95	https://www.adafruit.d		Covered	
3D Prints	1					RPL Print	
Laser Cuts						RPL Scrap	
Gesture Sensor Bolts	4				M2.5	LAB supply	
Gesture Sensor Nuts	4				M2.5	M2.5	
Lazy Susan to Carousel	4	\$0.10	\$0.39	https://www.mcmaste	M4X16		
Carousel to Gear	3	\$0.10	\$0.29	https://www.mcmaste	M4X16		
Motor Mount to Plate	3	\$0.10	\$0.29	https://www.mcmaste	M4X16		
Lazy Susan to Plate Bolts	4				1/4-20	Found	
Lazy Susan to Plate Nuts	4				1/4-20	Found	
M4 Nuts	10	\$0.03	\$0.31	https://www.mcmaste	M4		