Everlight Chemical

臺灣永光化學工業股份有限公司
EVERLIGHT CHEMICAL INDUSTRIAL CORPORATION

Tel: +886-2-27066006 Fax: +886-2-27081254

E-mail: sales-CCBU@ecic.com.tw

Everlight (Shanghai) Ltd.
上海德樺貿易有限公司
Tel: +86-21-62196954 Fax: +86-21-62191276

Everlight (Suzhou) Advanced Chemicals Ltd.
永光（蘇州）光電材料有限公司
Tel: +86-512-62871980 Fax: +86-512-62871217

Everlight (HongKong) Ltd.
香港永光有限公司
Tel: +852-26191095 Fax: +852-26191031

Ethical (Guangzhou) Ltd.
廣州明廣貿易有限公司
Tel: +86-20-38497030 Fax: +86-20-38497031

Qingdao Office
青島分公司
Tel: +86-532-85016051 Fax: +86-532-85016063

Tianjin Office
天津分公司
Tel: +86-22-23202016 Fax: +86-22-23202015

Everlight USA, Inc.
美國永光公司
Tel: +1-704-5881004 Fax: +1-704-5880051

Everlight Europe B.V. (Netherlands)
荷蘭永光公司
Tel: +31-10-2380099 Fax: +31-10-2380090

Elite Foreign Trading Inc. (Turkey)
土耳其 Elite 公司
Tel: +90-324-2377789 Fax: +90-324-2370246

Everlight Chemicals (Vietnam) Co., Ltd.
越南永光公司
Tel: +84-28-3520-2761 Fax: +84-28-3636-8375

Technical Marketing & Service Division
技術行銷處
Tel: +886-3-4838088 E-mail: ccbu-tms@ecic.com.tw

警語：*本資料所提供的資訊與建議是以我們最大的用心完成，但不能涵括所有可能的狀況。使用相關產品或搭配其他產品時，請先自行測試。本資料並不具保證及法律效用，僅供參考使用。使用者必須自行承擔所有的風險與法律責任。*

Warnings: *The information and recommendations presented here were completed with the utmost care, but can't be extended to cover every possible case. They are intended to serve as non-binding guidelines and must be adapted to the prevailing condition. The product whether used singly or in combination with other substances, should be carried out in lab test prior to bulk production. The user needs to assume all risk and liability no matter whatsoever results are.*

bluesign SYSTEM PARTNER

July 2025

Everzol®

耐氣體變褪色之解決方案

Best Solution for Gas Fading



Everlight Chemical

Everzol® 耐氣體變褪色之解決方案

Best Solution for Gas Fading

許多棉質染色物於後整理流程產生不明原因色變，主要來自 NOx 氣體所造成。

現有市售的高反應性紅色及藍色染料不耐 NOx 氣體的破壞，甚至很難找到同時兼具 NOx 氣體變褪色及日光牢度之三原色組合。

Everzol Yellow CS、Red LF-4B、Blue NXF 優異三原色組合可用於浸染及連續染色，符合染整廠的需求及提供最佳方案。

Why Gas Fading? Trouble-Shooting by Everzol Dyes

One of the most important causes of unknown color change of cellulosic dyed fabric is gas fading produced in final finishing process. NOx is the main component of the air pollutants.

The modern reactive dyes from existing red and blue ones are more sensitive to withstand the attack of NOx during finishing process. It's rare to find unique resistance of NOx and outstanding compatibility, lightfastness as well, on red and blue dyes.

Everzol Yellow CS, Red LF-4B, and Blue NXF are performing trichromatic compatibility in exhaust and continuous dyeing providing the trouble-shooting of best of the best for gas fading.

	0.1%	1%			
Everzol Yellow CS			Rugby Tan		Y: 0.18% R: 0.06% B: 0.06%
Everzol Red LF-4B			Lavender Herb		Y: 0.06% R: 0.18% B: 0.06%
Everzol Blue NXF			Aleutian Pain		Y: 0.06% R: 0.06% B: 0.18%

染程適用性 / Versatile Application

浸染（60C） Exhaustion	吉革染色（60C） Jigger	連續染色 Continuous	冷壓染色 CPB	成衣染色 Garment
◎	◎	◎	◎	◎


Note：Very Good ○：Good △：Moderate

染料特點 / Specialty

適合於淺中色系 & 日光牢度特性	Suitable for pale/medium shade
優異耐氣體變褪色牢度	Excellent resistance of gas fading and lightfastness
優異均染性及組合性及染色再現性	Unique levelness and compatibility and RFT operation

染色特點 / Outstanding Reproducibility and Fastness

Everzol Yellow CS 0.3% + Red LF-4B 0.3% + Blue NXF 0.3%



Standard:

1. Temp. -5
2. Temp. +5
3. Temp. -15
4. Temp. +15
5. G/S -20%
6. G/S +20%
7. S/A -20%
8. S/A +20%
9. L/R -3
10. L/R +3

Lightfastness (AATCC 16-3, 20AFU)

original / tested



Color change: 4

Colorfastness to Nitrogen Oxides (ISO 105 G01)

dry 1 cycle / original / dry 3 cycle

4-5 color change 4-5

牢度與特性 / Fastness & Property

Fastness / Everzol Dyes	Solubility (g/l)	Light Fastness 1%, o.w.f.		Nitrogen Oxides Fastness ISO 105-G01 1%, o.w.f.	
		ISO 105-B02 Grade	AATCC 16-3 Color Change	dry x 1cycle	dry x 3cycle
Yellow CS	75	6	4–5	4–5	4–5
Red LF-4B	100	5–6	4	4–5	4
Blue NXF	100	5–6	4	4–5	4