

Reliability capabilities: original vs OptiComp2

Original

OptiComp2

Motion command verified / resent on swallow		
Final-position check + corrective move		
Saturation detected and masked (NaN)		
Dark matched to the spectrum integration time		
Single-thread, serialised DLL access		
Auto integration-time calibration (enabled)		
Reference calibrated in both S and P		
Spectrometer USB recovery ladder		
Motor-state record + anomaly gate		
Protected home for the fibre arm		
Shutter fail-safe on error / abort		
GS02 mechanical-timeout policy		
Atomic, corruption-safe manifest		
Lamp-stability gate before reference		
Unit tests + offline demo mode		

open ring = absent filled = present