

Result



no hardware required - fake serial port + fake DLL - passes on the workstation and the instrument PC (Python 3.9)