PREFACE, ix

1. INTRODUCTION,

- Introduction, 2 1.1
- 1.2 A History of Control Systems, 4
- System Configurations, 7
- Analysis and Design Objectives, 10 Case Study, 12
- The Design Process, 15
- Computer-Aided Design, 20
- 1.7 The Control Systems Engineer, 21 Summary, 23 Review Questions, 23 Problems, 24 Cyber Exploration Laboratory, 30 Bibliography, 31

2. MODELING IN THE FREQUENCY DOMAIN, 33

- 2.1 Introduction, 34
- Laplace Transform Review, 35
- The Transfer Function, 44
- 2.4 Electrical Network Transfer Functions, 47
- Translational Mechanical System Transfer Functions, 61
- Rotational Mechanical System Transfer Functions, 69
- 2.7 Transfer Functions for Systems with Gears, 74
- 2.8 Electromechanical System Transfer Functions, 79
- Electric Circuit Analogs, 84
- 2.10 Nonlinearities, 88
- 2.11 Linearization, Case Studies, 94 Summary, 97 Review Questions,

Problems, 98 Cyber Exploration Laboratory, 112 Bibliography, 115

3. MODELING IN THE TIME DOMAIN, 117

- Introduction, 118 3.1
- Some Observations, 119
- The General State-Space Representation, 123
- 3.4 Applying the State-Space Representation, 124
- 3.5 Converting a Transfer Function to State Space, 132
- 3.6 Converting from State Space to a Transfer Function, 139
- 3.7 Linearization, 141 Case Studies, 144 Summary, 148 Review Questions, 149 Problems, 149 Cyber Exploration Laboratory, 157 Bibliography, 159

4. TIME RESPONSE, 161

- Introduction, 162 4.1
- Poles, Zeros, and System Response, 162
- 4.3 First-Order Systems, 166
- Second-Order Systems: Introduction, 168
- 4.5 The General Second-Order System, 173
- 4.6 Underdamped Second-Order Systems, 177
- System Response with Additional Poles, 186
- System Response With Zeros,
- Effects of Nonlinearities Upon Time Response, 196

- 4.10 Laplace Transform Solution of State Equations, 199
- 4.11 Time Domain Solution of State Equations, 203 Case Studies, 207 Summary, 213 Review Questions, 214 Problems, 215 Cyber Exploration Laboratory, 228 Bibliography, 232

5. REDUCTION OF **MULTIPLE SUBSYSTEMS**, 235

- 5.1 Introduction, 236
- Block Diagrams, 236
- Analysis and Design of Feedback Systems, 245
- Signal-Flow Graphs, 248
- Mason's Rule, 251
- Signal-Flow Graphs of State Equations, 254
- 5.7 Alternative Representations in State Space, 256
- Similarity Transformations, 266 Case Studies, 272 Summary, 278 Review Questions, 279 Problems, 280 Cyber Exploration Laboratory, 297 Bibliography, 299

6. STABILITY, 301

- 6.1 Introduction, 302
- 6.2 Routh-Hurwitz Criterion, 305
- Routh-Hurwitz Criterion: Special Cases, 308
- 6.4 Routh-Hurwitz Criterion: Additional Examples, 314
- Stability in State Space, 320 Case Studies, 323 Summary, 325 Review Questions, 325 Problems, 326

Cyber Exploration Laboratory, 335 Bibliography, 336

7. STEADY-STATE ERRORS, 339

- 7.1 Introduction, 340
- 7.2 Steady-State Error for Unity Feedback Systems, 343
- 7.3 Static Error Constants and System Type, 349
- 7.4 Steady-State Error Specifications, 353
- Steady-State Error for Disturbances, 356
- 7.6 Steady-State Error for Nonunity Feedback Systems, 358
- 7.7 Sensitivity, 362
- 7.8 Steady-State Error for Systems in State Space, 364 Case Studies, 368 Summary, 371 Review Questions, 372 Problems, 373 Cyber Exploration Laboratory, 384

8. ROOT LOCUS TECHNIQUES, 387

8.1 Introduction, 388

Bibliography, 386

- Defining the Root Locus, 392
- Properties of the Root Locus, 394
- Sketching the Root Locus, 397
- Refining the Sketch, 402
- An Example, 411
- Transient Response Design via Gain Adjustment, 415
- Generalized Root Locus, 419
- Root Locus for Positive-Feedback Systems, 421
- 8.10 Pole Sensitivity, 424 Case Studies, 426 Summary, 431 Review Questions, 432 Problems, 432 Cyber Exploration Laboratory, 450 Bibliography, 452

Chapter 8. Root Locus Techniques

Objectives


- The *definition* of a root locus
- How to *sketch* a root locus
- How to *refine* your sketch of a root locus
- How to use the root locus to *find the poles* of a closed-loop system
- How to use the root locus to *design a parameter value* to meet a transient response specification

```
s=tf('s');
sys=1/(s+1)
controlSystemDesigner(sys)

s=tf('s');
sys=1/(s+1)^3
pidtool(sys)
```

8.1 Introduction

• Root locus (Evans, 1948:1950): a powerful method of analysis and design for stability and transient response




$$G(s) = \frac{(s+1)}{s(s+2)}, \quad H(s) = \frac{(s+3)}{(s+4)} \implies T(s) = \frac{K(s+1)(s+4)}{s^3 + (6+K)s^2 + (8+4K)s + 3K}$$

• The root locus will be used to trace the poles of T(s) as K varies.

Example 8.1: Evaluation of a complex function via vectors

Find F(s) at the point s = -3 + j4.

$$F(s) = \frac{(s+1)}{s(s+2)}$$



Use magnitude and phase angle


$$F(s) = \frac{[s - (-1)]}{[s - 0][s - (-2)]}$$

$$= \frac{\sqrt{20} \angle 116.6^{\circ}}{(5 \angle 126.9^{\circ})(\sqrt{17} \angle 104.0^{\circ})}$$

$$= \frac{\sqrt{20}}{5\sqrt{17}} \angle 116.6^{\circ} - 126.9^{\circ} - 104.0^{\circ}$$

$$= 0.217 \angle -114.3^{\circ} = M \angle \theta$$

Vector Representation of Complex Numbers




(a)
$$s = \sigma + j\omega$$
;

- (b) (s + a);
- (c) Alternate representation of (s + a);
- (d) $(s + 7)|_{s \to 5 + j2}$

8.2 Defining the Root Locus



CameraMan: Courtesy of ParkerVision




• Pole location as a function of gain for the system

K	Pole 1	Pole 2
0 5 10 15	-10 -9.47 -8.87 -8.16	$ \begin{array}{r} 0 \\ -0.53 \\ -1.13 \\ -1.84 \end{array} $
20 25 30 35 40 45 50	$ \begin{array}{r} -7.24 \\ -5 \\ -5 + j2.24 \\ -5 + j3.16 \\ -5 + j3.87 \\ -5 + j4.47 \\ -5 + j5 \end{array} $	$ \begin{array}{r} -2.76 \\ -5 \\ -5 - j2.24 \\ -5 - j3.16 \\ -5 - j3.87 \\ -5 - j4.47 \\ -5 - j5 \end{array} $


G(s)

```
% ch8_2.m
clc, clear all
numg=[1];
deng=[1 10 0];
  % deng=poly([0 -10]);
G=tf(numg, deng);
rlocus(G)
```



 $overdamped (0 \le K < 25), critically \ damped (K = 25), \ and \ underdamped (K > 25)$

8.3 Properties of the Root Locus




Closed-loop pole:
$$1 + KG(s)H(s) = 0$$

$$KG(s)H(s) = -1$$

= $1\angle (2k+1)180^{\circ}, \quad k = 0, \pm 1, \pm 2$

$$|KG(s)H(s)|=1$$
 and


$$\angle G(s)H(s) = (2k+1)180^{\circ}, K > 0$$



• Plot the poles of the closed—loop system T(s), as a function of K.

$$T(s) = \frac{KG_P(s)}{1 + KG_P(s)}$$

Poles:
$$1 + KG_P(s) = 0$$



Example:

$$G_P(s) = \frac{1}{(s+2)^2}$$


$$1 + KG_P(s) = 0$$
, $1 + \frac{K}{(s+2)^2} = 0$

$$s^{2} + 4s + (K + 4) = 0$$


$$s = -2 \pm \sqrt{4 - (K + 4)} = -2 \pm \sqrt{-K}$$

$$s = -2 \pm j\sqrt{K}$$

System is stable for all *K*



```
clc, clear all
numg = [1];
deng = poly([-2 -2]);
G=tf(numg, deng)
rlocus(G)
```



Example:
$$G_P(s) = \frac{s-1}{(s+1)^2}$$


$$1 + KG_P(s) = 0$$
, $(s+1)^2 + K(s-1) = 0$

$$s^{2} + (2+K)s + (1-K) = 0$$

$$s = \frac{-(2+K) \pm \sqrt{(2+K)^{2} - 4(1-K)}}{2}$$

$$= \frac{-(2+K) \pm \sqrt{K^{2} + 4K + 4 - 4 + 4K}}{2}$$

$$s = \frac{-2 - K \pm \sqrt{K^2 + 8K}}{2}$$



```
clc, clear all
numg = poly([1]);
deng = poly([-1 -1]);
G=tf(numg, deng)
rlocus(G)
```

Example (continued):

$$s = \frac{-2 - K \pm \sqrt{K^2 + 8K}}{2} = \frac{-2 + (-K \pm \sqrt{K^2 + 8K})}{2}$$

$$+:-K+\sqrt{K^2+8K} = \frac{(-K+\sqrt{)}(K+\sqrt{)}}{K+\sqrt{}} = \frac{-K^2+K^2+8K}{K+\sqrt{K^2+8K}} = \frac{8K}{K\left(1+\sqrt{1+\frac{8}{K}}\right)}$$

$$\rightarrow \lim_{K \to \infty} \frac{8K}{K \left(1 + \sqrt{1 + \frac{8}{K}}\right)} = \lim_{K \to \infty} \frac{8K}{K \left(1 + \sqrt{1 + 0}\right)} = \frac{8}{2} \rightarrow 4 \implies K \to \infty , s \to \frac{-2 + 4}{2} = 1$$

$$-: -K - \sqrt{K^2 + 8K} = \frac{(-K - \sqrt{)}(-K + \sqrt{)}}{-K + \sqrt{}} = \frac{(K^2 - K^2 - 8K)}{-K + \sqrt{K^2 + 8K}} = \frac{-8K}{K\left(-1 + \sqrt{1 + \frac{8}{K}}\right)}$$

$$\rightarrow \lim_{K \to \infty} \frac{-8K}{K\left(-1 + \sqrt{1 + \frac{8}{K}}\right)} = \lim_{K \to \infty} \frac{-8K}{K\left(-1 + \sqrt{1 + 0}\right)} = \frac{-8}{0} \to -\infty$$

$$\Rightarrow K \to \infty, \ s \to \frac{-2 - \infty}{2} = -\infty$$

$$s^{2} + (2 + \overline{K})s + (1 - \overline{K})\Big|_{s=0} = 0 \Longrightarrow \overline{K} = 1$$


Stability: K < 1

If you have higher order polynomials, it can be impossible to plot the roots in this way.


 \Rightarrow You need systematic plotting methods.

Let
$$G_P(s) = A \frac{(s - z_1) \cdots (s - z_m)}{(s - p_1) \cdots (s - p_n)}, m \le n$$

Rules for Root Locus



Rule 1. Symmetry about the real axis




Rule 2. Each branch starts at a pole of $G_P(s)$ and terminates at a zero of $G_P(s)$, including zeros at ∞ .

Explanation Let
$$G_P(s) = \frac{s-1}{s^3 + 4s + 2}$$

 $G_P(s)$ has one zero and three poles.

At ∞ , namely as $s \to \infty$, $G_P(s)$ behaves like i.e. it has two zeros at ∞ .

 \Rightarrow How do the *branches* approach to ∞ ?



Chapter 8. Root Locus Techniques -14-

Rule 3. *n-m branches* approach ∞ like asymptotes


with angles
$$\Psi_K = \frac{180 + 360K}{n - m}$$
, $K = 0, 1, \dots, n - m - 1$.


The asymptotes intersect at the real axis at


$$\sigma = \frac{\sum Poles - \sum Zeros}{n - m}$$

Example:

$$G_P(s) = \frac{1}{(s+2)^2}$$
, $n = 2$, $m = 0$
 $\sigma = (-4)/2 = -2$,
 $\Psi_0 = 180/2 = 90$,
 $\Psi_1 = (180 + 360)/2 = -90$







Chapter 8. Root Locus Techniques -15-


Rule 4. If a branch is on the <u>real axis</u>, then the number of real poles + zeros of $G_P(s)$ to the right of it must be <u>odd</u>.


Example:

$$G_P(s) = \frac{s-1}{(s+1)(s+1)}$$

$$n - m = 1$$

 $\Psi_0 = 180 \rightarrow \text{you have a branch at } -\infty$





Chapter 8. Root Locus Techniques -16-

Example:
$$G_P(s) = \frac{s-2}{(s+1)(s+5)}$$

$$n-m=1$$

$$\Psi_0 = 180$$
 Stability: $K < \overline{K}$

$$1 + \overline{K} \frac{s-2}{(s+1)(s+5)} \Big|_{s=0} = 0, \quad \overline{K} = 2.5, \quad \text{Stability: } K < 2.5$$

Stability:
$$K < 2.5$$

Example:
$$G_p(s) = \frac{1}{(s+2)(s-1)(s+1)}$$

$$1 + KG_p(s) = 0$$

$$s^3 + 2s^2 - s - 2 + K = 0$$

$$1 + KG_p(s) = 0$$

$$-2 - 1$$

$$-2 + 1$$
never stable


Cross
$$j\omega$$
 axis: $\Rightarrow 1 + KG_p(s)|_{s=j\omega} = 0$

$$-j\omega^3 - 2\omega^2 - j\omega - 2 + K = 0$$

$$(K - 2\omega^2 - 2) - j\omega(1 + \omega^2) = 0$$

$$\downarrow \qquad \qquad \neq 0$$

$$K=2 \qquad \omega^{2+1=0} \text{ or } \omega=0 \text{ is the only solution}$$




numg = poly([]);
deng = poly([-2 1 -1]);
G=tf(numg, deng)
rlocus(G)

Rule 5. Angle rule

Let $p_1, ..., p_n$ be the poles of G_p Let $z_1, ..., z_m$ be the zeros of G_p


Simple pole: Let p_i be a simple pole.


Let ϕ_j =angle at which the branch starts from p_j



$$\phi_j = \sum_{k=1}^m \angle (p_j - z_k) - \sum_{\substack{i=1 \ i \neq j}}^n \angle (p_j - p_i) + r \cdot 180 \quad (r : odd)$$

Example:
$$G_p(s) = \frac{(s-1)(s+2)}{s^2+2}$$





numg = poly([1 -2]);
deng = [1 0 2];
G=tf(numg, deng)
rlocus(G)

$$\angle(p_1 - z_2) \approx 125^{\circ}$$
 $\angle(p_1 - z_1) \approx 35^{\circ}$
 z_2


>> atan(sqrt(2)/2)*180/pi
ans = 35.2644

$$\phi_1 = \angle (p_1 - z_1) + \angle (p_1 - z_2) - \angle (p_1 - p_2) + (1) \cdot 180$$

$$\phi_1 \approx 35^{\circ} + 125^{\circ} - 90^{\circ} + 180^{\circ} = 250^{\circ} = -110^{\circ}$$

• Crossing of '0':
$$1+K\frac{(s-1)(s+2)}{s^2+2}=0$$

 $s=0, 1+K\frac{-2}{2}=0, K=1$



• Explanation of rule 5: For every s on a branch,

stability: K < 1

$$T(s) = \frac{KG_P(s)}{1 + KG_P(s)}$$

$$1 + K \frac{(s - z_1) \cdots (s - z_m)}{(s - p_1) \cdots (s - p_n)} = 0$$


$$K \frac{(s - z_1) \cdots (s - z_m)}{(s - p_1) \cdots (s - p_n)} = -1$$

$$\sum_{k=1}^{m} \angle (s - z_k) - \sum_{k=1}^{n} \angle (s - p_i) = r \cdot 180 \quad (r : odd)$$

$$\sum_{k=1}^{n} \angle (s - z_k) - \sum_{k=1}^{n} \angle (s - p_i) = r \cdot 180 \quad (r : odd)$$

• Explanation of rule 5(continue):

now:
$$\theta_j = \lim_{s \to p_j} \angle (s - p_j)$$



Then,
$$\theta_{j} = \lim_{s \to p_{j}} \angle(s - p_{j})$$

$$= \lim_{s \to p_{j}} \sum_{k=1}^{m} \angle(s - z_{k}) - \lim_{s \to p_{j}} \sum_{\substack{i=1 \ i \neq j}}^{n} \angle(s - p_{i}) + r \cdot 180 \qquad (r : odd)$$

$$= \sum_{k=1}^{m} \angle(p_{j} - z_{k}) - \sum_{\substack{i=1 \ i \neq j}}^{n} \angle(p_{j} - p_{i}) + r \cdot 180$$

$$\sum_{k=1}^{m} \angle (s - z_k) - \sum_{i=1}^{n} \angle (s - p_i) = r \cdot 180 \quad (r : odd)$$

$$\sum_{k=1}^{m} \angle (s - z_k) - \sum_{i=1}^{n} \angle (s - p_i) = r \cdot 180 \quad (r : odd)$$

• Angle rule for double pole

Let $p_1 = p_2$, for all s on a branch

$$\sum_{k=1}^{m} \angle(s - z_k) - \sum_{i=1}^{n} \angle(s - p_i) + r \cdot 180$$

$$\angle(s - p_1) + \angle(s - p_2) = \sum_{k=1}^{m} \angle(s - z_k) - \sum_{i=3}^{n} \angle(s - p_i) + r \cdot 180$$
but $p_1 = p_2 \rightarrow \angle(s - p_1) = \angle(s - p_2)$


$$\Rightarrow 2\angle(s - p_1) = \sum_{k=1}^{m} \angle(s - z_k) - \sum_{i=3}^{n} \angle(s - p_i) + r \cdot 180$$

$$\Rightarrow \varphi_1, \varphi_2 = \left[\sum_{k=1}^{m} \angle(s - z_k) - \sum_{i=3}^{n} \angle(s - p_i) + r \cdot 180\right] / 2$$

$$\Rightarrow p_i$$

Example:
$$G_p(s) = \frac{(s+1)(s-3)}{(s+2)^2}$$

$$\begin{cases} z_1 = -1, & z_2 = 3 \\ p_1 = p_2 = -2 \end{cases}$$




$$\angle (p_1 - z_1) = \angle (p_1 - z_2) = 180$$

 $\rightarrow \varphi_1, \varphi_2 = [+180 + 180 - 0 + 180r]/2 = 90r$

$$r = 1 : \varphi_1 = 90^{\circ}$$


$$r = 3 : \varphi_2 = 270^{\circ} = -90^{\circ}$$

numg = poly([-1 3]);
deng = poly([-2 -2]);
G=tf(numg, deng)
rlocus(G)



Chapter 8. Root Locus Techniques -24-

Example (continue):



$$G_p(s) = \frac{s^2 - 2s - 3}{s^2 + 4s + 4}, \quad 1 + KG_p(s) = 0$$

$$s^{2} + 4s + 4 + K(s^{2} - 2s - 3) = 0$$

Example (continue):


$$(1+K)s^2 + (4-2K)s + (4-3K) = 0$$
 at $j\omega$ -axis $\rightarrow s = j\omega$

$$-\omega^{2}(1+K)+j\omega(4-2K)+(4-3K)=0$$

$$K=2$$
,

$$-\omega^2(3)+(4-6)=0$$


$$3\omega^2 + 2 \neq 0$$
: impossible $\therefore \Rightarrow$



At
$$s = 0 \to 1 + KG_p(s) = 0 \to 1 + K\left(-\frac{3}{4}\right) = 0 \to K = \frac{4}{3} = 1.333$$

$$(1+K)s^2 + (4-2K)s + (4-3K) = 0$$

$$\therefore$$
 stability $K < \frac{4}{3}$




Pole Sensitivity

Case 1: Very small changes in gain
High Sensitivity.

Very large changes

- in pole location
- in performance


- Case 2: Low Sensitivity.
- ⇒ We prefer systems with *low sensitivity* to changes in gain
- Root sensitivity
 Sensitivity of a closed-loop pole:



$$S_{s:K} = \frac{K}{s} \cdot \frac{\Delta s}{\Delta K} \implies$$

$$\Delta s = s(S_{S:K}) \frac{\Delta K}{K}$$

Change in the pole location



(ref: chapter 7.7)

$$S_{F:P} = \lim_{\Delta P \to 0} \frac{\Delta F/F}{\Delta P/P}$$
$$= \lim_{\Delta P \to 0} \frac{P}{F} \frac{\Delta F}{\Delta P}$$

Example:

$$\begin{array}{c|c}
R(s) & K & C(s) \\
\hline
 & s^2 + 10s + K & \end{array}$$

- 1 Find the root sensitivity of the system at s = -9.47 and s = -5 + j5
- ② Calculate the change in the pole location for a 10% change in *K*.

$$s^2 + 10s + K = 0$$

Example (continued):

$$\Rightarrow \text{Characteristic equation}$$

$$s^2 + 10s + K = 0$$

$$\frac{\delta s}{\delta K} = 2s \frac{\delta s}{\delta K} + 10 \frac{\delta s}{\delta K} + 1 = 0$$

$$\frac{\delta s}{\delta K} = \frac{-1}{2s + 10}$$

$$S_{s:K} = \frac{K}{s} \cdot \frac{\delta s}{\delta K} = \frac{K}{s} \cdot \frac{-1}{2s + 10} \cdot \dots (1)$$

K	Pole 1	Pole 2
0	- 10	0
5	-9.47	-0.53
:	:	:
50	-5+j5	-5-j5

i)
$$s = -9.47 \rightarrow K = 5 \rightarrow (1)$$

 $S_{s:K} = -0.059$

$$\Delta s = s(S_{s:K}) \frac{\Delta K}{K}$$

$$= 0.056$$

The pole will move to the right by 0.056 units for a 10% change in K at K=5 or s=-9.47

Example (continue):

ii) For
$$s = -5 + j5 \rightarrow K = 50 \rightarrow (1)$$
;

$$S_{s:k} = \frac{K}{s} \cdot \frac{-1}{2s+10} = \frac{1}{2} - j\frac{1}{2} = \sqrt{\frac{1}{2}} \angle -45^{\circ}$$


Find the change in the pole location at $\Delta K / K = 10\%$

$$\Delta s = s \left(S_{s:K} \right) \frac{\Delta K}{K}$$
$$= (-5 + j5) \left(\frac{1}{2} - j \frac{1}{2} \right) (0.1)$$



The pole will move vertically by 0.5 unit for a 10% change in *K*

8.3 Properties of the Root Locus



$$1 + KG(s)H(s) = 0$$

$$KG(s)H(s) = -1 = 1\angle(2k+1)180^{\circ}, k = 0, \pm 1, \pm 2,...$$

$$|KG(s)H(s)|=1 \implies K = \frac{1}{|G(s)H(s)|}$$


$$\angle G(s)H(s) = (2k+1)180^{\circ} (K > 0)$$



A point s on the root locus should be satisfied these conditions.

$$\frac{K(s+3)(s+4)}{(s+1)(s+2)}$$

$$(a)$$



$$KG(s)H(s) = \frac{K(s+3)(s+4)}{(s+1)(s+2)}$$

(1) In the case of s = -2 + j3

$$\angle G(s)H(s) = \angle G(s) = \theta_1 + \theta_2 - \theta_3 - \theta_4$$


= 56.31° + 71.57° - 90° - 108.43°

$$=-70.55^{\circ} \neq \pm 180^{\circ}$$

Therefore, s = -2 + j3 is not a point on the root locus.

(2) In the case of
$$s = -2 + j\frac{1}{\sqrt{2}}$$

 $\angle G(s)H(s) = \theta_1 + \theta_2 - \theta_3 - \theta_4$
 $= 19.47^{\circ} + 35.26^{\circ} - 90^{\circ} - 144.74^{\circ}$
 $= -180^{\circ} = +180^{\circ}$



Therefore, $s = -2 + j \frac{1}{\sqrt{2}}$ is a point on the root locus for some value of K.

 $\frac{GH \to \frac{1}{GH}}{GH} \to \frac{1}{GH}$

s-plane

Let's find the *K*!

Ĺ

$$K = \frac{1}{|G(s)||H(s)|} = \frac{1}{M} = \frac{\Pi \text{ pole lengths}}{\Pi \text{ zero lengths}}$$

$$K = \frac{l_3 l_4}{l_1 l_2} = \frac{\frac{1}{\sqrt{2}} (1.22)}{(2.12)(1.22)} = 0.33$$
 and $M = 3$

A point *s* on the root locus should be satisfied the following conditions.

$$\hat{\Box}$$

$$|KG(s)H(s)|=1 \Rightarrow K = \frac{1}{|G(s)H(s)|}$$

 $\angle G(s)H(s) = (2k+1)180^{\circ} (K>0)$

```
G=(s^2+7*s+12)/(s^2+3*s+2);
                                                         deng = poly([-1 -2]);
                                                                                                                                  Theta=(180/pi)*angle(G)
                                                         G=tf(numg, deng)
                                                                                                                                  M=abs(G)
                                                        rlocus(G)
                                                                                                                                  Theta = 180
                                                                                                                                 M = 3
                                                                                   Root Loc System: T1
                                                                                           Gain: 0.333
                                                                                           Pole: -2 + 0.707i
                                                                                           Damping: 0.943
                                                                                           Overshoot (%): 0.0138
   8.0
                                                                                           Frequency (rad/s): 2.12
   0.6
   0.4
   0.2
Imaginary Axis (seconds
                                                                                           System: T1
   -0.4
                                                                                           Gain: 0.333
                                                                                           Pole: -2 - 0.707i
                                                                                           Damping: 0.943
                                                                                           Overshoot (%): 0.0138
   -0.6
                                                                                           Frequency (rad/s): 2.12
   -0.8
     -1
                                      -3.5
                                                       -3
                                                                       -2.5
                                                                                                       -1.5
                                                                                                                                         -0.5
                                                                                                                                                                          0.5
     -4.5
                                                                              Real Axis (seconds
```

numg = poly([-3 -4]);

Chapter 8. Root Locus Techniques -33-

>> a=1/sqrt(2); s=-2+a*j;


8.4 Sketching the Root Locus

- (1) Number of branches :# of branches = # of closed-loop poles
- (2) Symmetry
- (3) Real-axis segments
- (4) Starting and ending points: (K=0, poles), ($K=\infty$, zeros)
- (5) Behavior at infinity: asymptote

Real-axis intercept:
$$\sigma_a = \frac{\Sigma \text{ finite poles } - \Sigma \text{ finite zeros}}{\# \text{ of finite poles } - \# \text{ of finite zeros}}$$


Angle:
$$\theta_a = \frac{(2k+1)\pi}{\# \text{ of finite poles } - \# \text{ of finite zeros}}$$

Example 8.2 Sketching a root locus with asymptotes



8.5 Refining the Sketch


(1) Root locus example showing real- axis breakaway (σ_1) and break-in points (σ_2)



$$1 + KG(s)H(s) = 0$$


$$K = -\frac{1}{G(s)H(s)}$$


$$K(\sigma) = -\frac{1}{G(\sigma)H(\sigma)}$$



Chapter 8. Root Locus Techniques -36-

Example 8.3 Breakaway and break-in points via differentiation





$$KG(s)H(s) = \frac{K(s-3)(s-5)}{(s+1)(s+2)} = \frac{K(s^2-8s+15)}{s^2+3s+2}$$

$$\frac{K(\sigma^2 - 8\sigma + 15)}{\sigma^2 + 3\sigma + 2} = -1$$

$$K = \frac{-(\sigma^2 + 3\sigma + 2)}{(\sigma^2 - 8\sigma + 15)}$$


$$\frac{dK}{d\sigma} = \frac{11\sigma^2 - 26\sigma - 61}{\sigma^2 - 8\sigma + 15} = 0$$

$$\Rightarrow \sigma = -1.453$$
, 3.817

Example 8.4 Breakaway and break-in points without differentiation

• Breakaway and break-in points satisfy the relationship: $\sum_{i=1}^{m} \frac{1}{\sigma + z_i} = \sum_{i=1}^{n} \frac{1}{\sigma + p_i}$

where z_i and p_i are the zero and pole values, respectively, of G(s)H(s)



$$\frac{1}{\sigma - 3} + \frac{1}{\sigma - 5} = \boxed{\frac{1}{\sigma + 1} + \frac{1}{\sigma + 2}}$$

$$11\sigma^2 - 26\sigma - 61 = 0$$

$$\Rightarrow \sigma = -1.453, \quad 3.817$$

- The *jw* -Axis Crossings
- Angle of Departure and Arrival
- Plotting and Calibrating the Root Locus

8.7 Transient Response design via Gain Adjustment (Find K for t_s , t_p , e_{ss} , overshoot)

8.8 Generalized Root Locus

How can we obtain a root locus for variations of the value of p_1 ?

- 8.9 Root Locus for Positive-Feedback Systems
- 8.10 Pole Sensitivity