

Maintenance feature screening diagnostics							
Candidate maintenance feature	CIM1	pass	pass	pass	pass	pass	
	CIM2	pass	pass	pass	pass	pass	
	CIM3	pass	pass	pass	pass	pass	
	FIM1	pass	pass	pass	pass	flag	
	FIM2	pass	pass	pass	pass	pass	
	MP1	pass	pass	pass	pass	flag	
	MP2	pass	pass	pass	pass	flag	
	MP3	pass	pass	pass	pass	pass	
	MP4	pass	pass	pass	pass	pass	
	MP5	pass	pass	pass	pass	flag	
	MP6	pass	pass	pass	pass	flag	
	MP7	pass	pass	pass	pass	pass	
	MP8	pass	pass	pass	pass	pass	
	MP9	pass	pass	pass	pass	pass	
	MP10	pass	pass	pass	pass	pass	
	MP11	pass	pass	pass	pass	pass	
	MP12	pass	pass	pass	flag	pass	
	MP13	pass	pass	pass	pass	pass	
	MP14	pass	pass	pass	pass	pass	
	MP15	pass	pass	pass	pass	pass	
MP16	pass	pass	pass	pass	flag		
MP17	pass	pass	pass	pass	flag		
MP18	pass	flag	pass	pass	pass		
MP19	pass	pass	pass	pass	flag		
		std ok	not sparse	scale ok	target signal	vif ok	vif safe
Diagnostic							