meeting minutes (10/11/23)
oreview Find Scare factor!
· Specifications Discussion:
o weight of cerch ocode dimensions
o Dimension of couch a Error Steady state
Micro Centroller Specs (# of Inputs and outputs)
Safety feature time to Stop
o Take Servo Inventory o Deliverable S (due monday)
O complete statics problem/Scale Factor - Devin
I uploud con necessary Documents
I create bones of Presentation/Document
Important Note  Four couner legs Middle Legs
Four corner legs By one Middle Legs
Ax 17 A Ax 12 A
MX 28 AT SENVO