Road Capacity Obstruction Report

Date of analysis: **24 Oct 2026** · Site: site.jpg · Indo-HCM 2017 (urban roads) basis · Report generated 24 Oct 2026, 02:15 PM

Date of data collection	24 Oct 2026
Date of analysis	24 Oct 2026
Road type	4-lane divided — one carriageway (2 lanes, one direction) — capacity basis: one direction
Functional class	Arterial
Carriageway width (measured)	7.0 m
Operating speed	50.0 km/h (default for functional class (draft Table 3))
Base capacity C0	3400.0 PCU/h — Table 5 base capacity for 4-lane divided — one carriageway (2 lanes, one direction)
Adjustment factors	F_W = 0.693, F_P = 0.917, F_OP = 0.7, F_BS = 0.8, F_AC = 1.0, F_PD = 1.0
Reduced capacity C	1210.1 PCU/h
Capacity loss	64.4%
Service volume at LOS-C (0.70 C)	2380.0 → 847.0 PCU/h
Level of service	V = 2000.0 PCU/h: LOS C (ideal) → LOS F (current)
Overall guidance	Severe — Over half the capacity lost. Escalate to traffic/municipal authority.

Municipal Corporation - Encroachment Removal Cell

Vending encroaching on carriageway width, relevant to the Street Vendors (Protection of Livelihood and Regulation of Street Vending) Act, 2014.

Defect	Count	Width / mechanism	Capacity loss	Severity	IRC code ref / action
Street Vendor	1	1.25 m F_W (usable width)	17.9%	Urgent	**Street Vendors (Protection of Livelihood and Regulation of Street Vending) Act, 2014** Relocation drive coordinated with the Town Vending Committee.

Municipal Corporation - Solid Waste Management Department

Garbage accumulation obstructing carriageway / roadside drainage.

Defect	Count	Width / mechanism	Capacity loss	Severity	IRC code ref / action
Garbage	1	0.9 m F_W (usable width)	12.9%	Routine	**Solid Waste Management Rules, 2016** Request priority clearance from the SWM department.

Public Works Department (PWD) - Roads Division

Carriageway surface defect requiring pothole repair / resurfacing.

Defect	Count	Width / mechanism	Capacity loss	Severity	IRC code ref / action
Pothole	1	0.0 m F_P (speed reduction)	8.3%	Urgent	**IRC:82-2015 cl. 7.5.3 (potholes), cl. 5.3 (prompt rectification)** Cut to regular shape, clean, tack coat and fill with premix per IRC:82 cl. 7.5.3.5. Distress affecting riding quality should be rectified straightaway (cl. 5.3).

Traffic Police Department

Vehicle parked in violation of Motor Vehicles Act, obstructing traffic flow.

Defect	Count	Width / mechanism	Capacity loss	Severity	IRC code ref / action
Illegal Parking	1	1.2 m F_OP (Indo-HCM on-street parking factor)	30.0%	Urgent	**Motor Vehicles Act 1988 s.122; IRC:67 (signs), IRC:35 (markings)** Towing enforcement under MV Act s.122; consider bollards on the stretch.

Generated automatically from an Indo-HCM 2017 (urban roads) capacity analysis of a single cross-section photo. Obstruction widths are image-based estimates and pothole size is a width-only proxy; verify on site before dispatching crews.