Road Capacity Obstruction Report

Date of analysis: **25 Oct 2026** · Site: road.jpg · Indo-HCM 2017 (urban roads) basis · Report generated 25 Oct 2026, 08:56 AM

Date of data collection	25 Oct 2026
Date of analysis	25 Oct 2026
Road type	Intermediate-lane (Ch. 2) — capacity basis: both directions
Carriageway width (measured)	5.8 m
Operating speed	75.0 km/h (speed at which Indo-HCM Section 2.10.1 states the base capacity (not measured))
Base capacity C0	2343.5 PCU/h — Section 2.10.1 (2150 PCU/h at 75 km/h) x f_w 1.09 (Table 2.6, 5.8 m)
Indo-HCM factors (Eq. 5.5)	F_OP = 0.7, F_BS = 1.0, F_AC = 1.0
Indo-HCM capacity	1640.4 PCU/h
Project extension factors	F_W = 0.679, F_R = 1.0
Capacity incl. extensions	1113.8 PCU/h
Capacity loss	52.5%
Service volume at LOS-C (0.70 C)	1406.0 → 668.0 PCU/h
Level of service	V = 300.0 PCU/h (Table 2.9): base LOS A, Indo-HCM LOS A, with extensions LOS B
Overall guidance	Severe — Over half the capacity lost. Escalate to traffic/municipal authority.

Municipal Corporation - Encroachment Removal Cell

Vending encroaching on carriageway width, relevant to the Street Vendors (Protection of Livelihood and Regulation of Street Vending) Act, 2014.

Defect	Count	Width / mechanism	Capacity loss	Severity	IRC code ref / action
Street Vendor	1	0.87 m F_W usable width (project extension)	16.4%	Urgent	**Street Vendors (Protection of Livelihood and Regulation of Street Vending) Act, 2014** Relocation drive coordinated with the Town Vending Committee.

Public Works Department (PWD) - Roads Division

Carriageway surface defect requiring pothole repair / resurfacing.

Defect	Count	Width / mechanism	Capacity loss	Severity	IRC code ref / action
Pothole	1	0.83 m F_W usable width (project extension)	15.7%	Urgent	**IRC:82-2015 cl. 7.5.3 (potholes), cl. 5.3 (prompt rectification)** Cut to regular shape, clean, tack coat and fill with premix per IRC:82 cl. 7.5.3.5. Distress affecting riding quality should be rectified straightaway (cl. 5.3).

Traffic Police Department

Vehicle parked in violation of Motor Vehicles Act, obstructing traffic flow.

Defect	Count	Width / mechanism	Capacity loss	Severity	IRC code ref / action
Illegal Parking	1	0.99 m F_OP Indo-HCM Table 5.9 Low	30.0%	Urgent	**Motor Vehicles Act 1988 s.122; IRC:67 (signs), IRC:35 (markings)** Towing enforcement under MV Act s.122; consider bollards on the stretch.

Generated automatically from an Indo-HCM 2017 (urban roads) capacity analysis of a single cross-section photo. Obstruction widths are image-based estimates and pothole size is a width-only proxy; verify on site before dispatching crews.