File Ed	it View :	Search Run Wa	tch Options Calls	Help
	it view	loca		
_ .		-source1 CS:I		
052A:0090	8D169600	LEA	DX, Word Ptr [0096]	$\mathbf{BX} = 0002$
052A:0094	B409	MOV	AH,09	$\mathbf{CX} = 0002$
052A:0096	CD21	INT	21	DX = 0096
052A:0098	B44C	MOV	AH,4C	SP = 0000
052A:009A		INT	21	BP = 0000
052A:009C	Company of the Compan	OR	AX,450A	SI = 00B4
052A:009F		DEC	SI	DI = 0134
052A:00A0		PUSH	SP	DS = 0533
052A:00A1		INC	BP	ES = 051A
052A:00A2		PUSH	DX	SS = 0529 CS = 052A
052A:00A3 052A:00A6		AND	Byte Ptr [BP+49],AL DX	CS = 052A IP = 009C
052A:00AB		PUSH PUSH	BX	FL = 0202
052A:00A8		PUSH	SP	FL - 0202
052A:00A9		AND	Byte Ptr [BP+DI+54],DL	NV UP EI PL
052A:00AC		PUSH	DX	NZ NA PO NC
		comma		
0533:0000	8D 16 96	00 B4 09 CD 21		
0533:0010				TER F
>				ii l
	000000000000000000000000000000000000000	000000000000000000000000000000000000000		00000000

Copyright (C) Microsoft Corp 1981-1985, 1987. All rights reserved.

51618 + 464926 Bytes symbol space free

O Warning Errors

O Severe Errors

C:\MASM>link strcomp;;

Microsoft (R) Overlay Linker Version 3.60
Copyright (C) Microsoft Corp 1983-1987. All rights reserved.

LINK: warning L4021: no stack segment

C:\MASM>cv strcomp

ENTER FIRST STRING : 45

ENTER SECOND STRING : 35

LENGTH OF FIRST STRING: 02 LENGTH OF SECOND STRING: 02 ---STRINGS ARE NOT EQUAL---