

	Liaison	Illustration	Schéma 3D	Schéma plan $(\vec{x}, \vec{y})$	Schéma plan $(\vec{y}, \vec{z})$	DDL	Torseur ciném. $V_{2/1}$	lieu	Torseur stat. $\tau_{1 \rightarrow 2}$
Liaisons d'axe	Pivot d'axe $(O, \vec{x})$					Rotation autour de $(O, \vec{x})$: R_x	$O \begin{Bmatrix} \omega_x & 0 \\ 0 & 0 \\ 0 & 0 \end{Bmatrix}_{(\vec{x}, \dots)}$	Forme identique $\forall P \in (O, \vec{x})$	$O \begin{Bmatrix} X_{12} & 0 \\ Y_{12} & M_{O,12} \\ Z_{12} & N_{O,12} \end{Bmatrix}_{(\vec{x}, \dots)}$
	Pivot glissant d'axe $(O, \vec{x})$					R_x T_x	$O \begin{Bmatrix} \omega_x & v_x \\ 0 & 0 \\ 0 & 0 \end{Bmatrix}_{(\vec{x}, \dots)}$		$O \begin{Bmatrix} 0 & 0 \\ Y_{12} & M_{O,12} \\ Z_{12} & N_{O,12} \end{Bmatrix}_{(\vec{x}, \dots)}$
	Hélicoïdale d'axe $(O, \vec{x})$					R_x et $liées$	$O \begin{Bmatrix} \omega_x & v_x \\ 0 & 0 \\ 0 & 0 \end{Bmatrix}_{(\vec{x}, \dots)}$ $ v_x = \omega_x \cdot \frac{p}{2\pi}$		$O \begin{Bmatrix} X_{12} & L_{O,12} \\ Y_{12} & M_{O,12} \\ Z_{12} & N_{O,12} \end{Bmatrix}_{(\vec{x}, \dots)}$ $ L_x = X \cdot \frac{p}{2\pi}$
Direction	Glissière de direction $\vec{x}$					T_x	$\forall P \begin{Bmatrix} 0 & v_x \\ 0 & 0 \\ 0 & 0 \end{Bmatrix}_{(\vec{x}, \dots)}$	$\forall P$	$O \begin{Bmatrix} 0 & L_{O,12} \\ Y_{12} & M_{O,12} \\ Z_{12} & N_{O,12} \end{Bmatrix}_{(\vec{x}, \dots)}$
Centre	Sphérique ou Rotule de centre O					R_x R_y R_z	$O \begin{Bmatrix} \omega_x & 0 \\ \omega_y & 0 \\ \omega_z & 0 \end{Bmatrix}_{(\dots)}$	En O	$O \begin{Bmatrix} X_{12} & 0 \\ Y_{12} & 0 \\ Z_{12} & 0 \end{Bmatrix}_{(\dots)}$

	Liaison	Illustration	Schéma 3D	Schéma plan $(\vec{x}, \vec{y})$	Schéma plan $(\vec{y}, \vec{z})$	DDL	Torseur ciném. $V_{2/1}$	lieu	Torseur stat. $\tau_{1 \rightarrow 2}$
Centre	Sphérique ou Rotule à doigt centre O direction y					R_x R_z	$O \begin{Bmatrix} \omega_x & 0 \\ 0 & 0 \\ \omega_z & 0 \end{Bmatrix}_{(\dots, \vec{y}, \dots)}$	En O	$O \begin{Bmatrix} X_{12} & 0 \\ Y_{12} & M_{O,12} \\ Z_{12} & 0 \end{Bmatrix}_{(\dots, \vec{y}, \dots)}$
	Linéaire annulaire centre O Direction x					R_x R_y R_z T_x	$O \begin{Bmatrix} \omega_x & v_x \\ \omega_y & 0 \\ \omega_z & 0 \end{Bmatrix}_{(\vec{x}, \dots, \dots)}$		$O \begin{Bmatrix} 0 & 0 \\ Y_{12} & 0 \\ Z_{12} & 0 \end{Bmatrix}_{(\vec{x}, \dots, \dots)}$
De normale	Linéaire rectiligne de normale $(O, \vec{y})$ Direction x					R_x R_y T_x T_z	$O \begin{Bmatrix} \omega_x & v_x \\ \omega_y & 0 \\ 0 & v_z \end{Bmatrix}_{(\vec{x}, \vec{y}, \vec{z})}$	$\forall P \in (O, \vec{x})$	$O \begin{Bmatrix} 0 & 0 \\ Y_{12} & 0 \\ 0 & N_{O,12} \end{Bmatrix}_{(\vec{x}, \vec{y}, \vec{z})}$
	Ponctuelle de normale $(O, \vec{y})$					R_x R_y R_z T_x T_z	$O \begin{Bmatrix} \omega_x & v_x \\ \omega_y & 0 \\ \omega_z & v_z \end{Bmatrix}_{(\vec{x}, \vec{y}, \vec{z})}$	$\forall P \in (O, \vec{y})$	$O \begin{Bmatrix} 0 & 0 \\ Y_{12} & 0 \\ 0 & 0 \end{Bmatrix}_{(\dots, \vec{y}, \dots)}$
	Appui plan de normale $(O, \vec{y})$					R_y T_x T_z	$O \begin{Bmatrix} 0 & v_x \\ \omega_y & 0 \\ 0 & v_z \end{Bmatrix}_{(\vec{x}, \vec{y}, \vec{z})}$	$\forall P$	$O \begin{Bmatrix} 0 & L_{O,12} \\ Y_{12} & 0 \\ 0 & N_{O,12} \end{Bmatrix}_{(\dots, \vec{y}, \dots)}$