

Contractor Pre-Qualification Package

Redline Mechanical LLC | Phoenix, Arizona | Submitted: February 2026

1. Company Information

Legal Name	Redline Mechanical LLC
DBA	Redline Mechanical
Federal Tax ID	47-8812334
Year Established	2011
Headquarters	Phoenix, Arizona
Field Employees	78
Office Staff	9
Union / Non-Union	Non-Union
Primary Services	HVAC, pipefitting, mechanical systems maintenance, industrial retrofits
Annual Revenue	\$11,200,000
Annual Manhours	192,000
ISNetworld ID	ISN-AZ-54219
Avetta ID	Not enrolled

2. Primary Contacts

Role	Name	Email	Phone
Owner / President	Gary Stubbs	gstubbs@redlinemech.com	(602) 555-7741
Safety Coordinator	Pam Hewitt	phewitt@redlinemech.com	(602) 555-7790
Training Contact	Gary Stubbs	gstubbs@redlinemech.com	(602) 555-7741

Note: Safety coordinator role was vacated in October 2025. Pam Hewitt assumed duties in addition to HR responsibilities.

3. EMR Documentation

EMR history certified by Southwest Casualty Insurance, NAIC #67210, Policy #WC-AZ-119843. EMR has exceeded the 1.0 threshold in two of three policy years.

Policy Year	EMR	Status
2026	1.18	Above threshold — REVIEW REQUIRED
2025	1.22	Above threshold — REVIEW REQUIRED
2024	1.15	Above threshold — REVIEW REQUIRED

Issuing Carrier: Southwest Casualty Insurance | Signed: R. Alderman, Underwriter | Date: January 28, 2026

4. OSHA Incident Statistics (3-Year Summary)

Year	Hours Worked	Recordables	TRIR	DART	Lost Time Cases	Fatalities
2025	192,000	4	4.17	2.08	2	0
2024	178,000	3	3.37	1.12	1	0
2023	165,000	4	4.85	2.42	2	0

TRIR significantly above industry average (industry benchmark ~1.5 for mechanical contractors). No narrative explanation or corrective action documentation provided.

5. OSHA Citation History (5 Years)

Year	Type	Standard	Description	Status
2025	Serious	1910.147	Inadequate LOTO procedure — energy control gaps	OPEN
2024	Serious	1926.502	Fall protection anchor point failure	CLOSED
2022	Other-than-Serious	1910.132	Incomplete PPE hazard assessment	CLOSED

WARNING: One serious citation currently open (1910.147 LOTO). Corrective action plan submitted but not yet verified by OSHA.

6. Employee Training Matrix

Employee	OSHA	H2S	Confined Space	LOTO	Respirator	TWIC	Expiry Status
Dale Hooker	OSHA 10	Current	EXPIRED 08/2025	Current	Current	Active	EXPIRED — CS
Tina Morales	OSHA 10	Current	Current	EXPIRED 06/2025	Current	Active	EXPIRED — LOTO
Ed Brannigan	OSHA 10	EXPIRED	N/A	Current	N/A	Active	EXPIRED — H2S
Frank Osei	OSHA 10	Current	Current	Current	Current	Active	All current
Liz Harmon	None	Current	N/A	Current	N/A	N/A	No OSHA card

WARNING: Multiple expired certifications. One employee with no OSHA card on file.

7. Insurance Coverage

Coverage	Limit	Status
General Liability	\$1,000,000	At minimum
Auto Liability	\$1,000,000	Current
Workers Compensation	Statutory	Current
Umbrella Liability	\$2,000,000	Below typical refinery requirement

General Liability and Umbrella coverage below typical refinery thresholds (\$5M GL / \$5-10M Umbrella).

8. Evaluation Summary

Category	Max Points	Score	Notes
OSHA Statistics	20	8	TRIR 3x industry avg; no corrective action narrative
EMR	15	4	1.18 — above threshold all 3 years
Safety Manual Quality	15	9	Basic manual; high-risk programs incomplete
Training Systems	15	6	Multiple expired certifications; one employee no OSHA

Category	Max Points	Score	Notes
Citation History	10	4	Open serious citation; LOTO gap
Drug & Alcohol	10	8	Policy in place; no consortium documentation
Supervisor Experience	10	6	Limited refinery-specific experience
Environmental	5	4	No documented violations

OVERALL RESULT: CONDITIONAL — Significant remediation required before site access approved.