

BRANCH DOCUMENT — IRIS-3

Branch: branch_20260512_135257 | Base: main-v1.0

Generated: 2026-05-12 13:52

Decision: NO_GO | Confidence: 28%

CHANGE REQUEST

eliminare il pannello solare di destra

CASCADE ISSUES IDENTIFIED

No cascade issues identified.

MISSING ECSS TESTS — NOW REQUIRED

No additional tests required.

SUBSYSTEM STATUS — UPDATED

Subsystem	Score	Status	Detail	Changed
optical	92%	OK	MTF 0.42 > threshold 0.40	—
thermal	61%	WARN	ΔT 14.8°C — margin < 5%	—
mechanical	88%	OK	1st mode 112 Hz > 80 Hz req	—
structure	91%	OK	Mass 33.8 kg / budget 35 kg	—
solar	89%	OK	Power margin +18%	—
startracker	67%	WARN	Stray light analysis pending	—
dataproc	71%	WARN	Compression ratio TBC	—

AFFECTED REQUIREMENTS

No requirements directly invalidated.