


## **Chapter 1: Gain Linearity Graphs**






- (a) 0 pF input load capacitance.
- (b) 33 pF input load capacitance.


Figure 1.1: Gain linearity measurements for default settings.






- (a) 0 pF input load capacitance.
- (b) 33 pF input load capacitance.


Figure 1.2: Gain linearity measurements for 500 ns shaping time.






- (a) 0 pF input load capacitance.
- (b) 33 pF input load capacitance.

Figure 1.3: Gain linearity measurements for 1  $\mu$ s shaping time.





- (a) 0 pF input load capacitance.
- (b) 33 pF input load capacitance.

Figure 1.4: Gain linearity measurements for 2  $\mu$ s shaping time.