


Height_Adjusment For Ortur LaserMaster 20W


1. Print this 2 Parts:



4. Insert the screw into the hole from above and fix it with two screw nuts underneath



2. Depending on the quality of the



But only so much that it can slide smoothly.

3. Attach the plain bearing where ever you like it:





