Automated MetClo Assembly Plan

3 Assemblies

Assembly Name: 2frag Assembly Size: 21,949 (Recommend: Electroporation)

3 Parts

| MpMXBP_pFa | ра | aq |
|------------|----|----|
|------------|----|----|

Reagents

| ligase_buffer.1 | ligase_buffer.2 | ligase_buffer.3 | ligase | bsai |
|-----------------|-----------------|-----------------|--------|------|
| 2.0 | 0.5 | 0.5 | 0 | |

Assembly Name: 3frag Assembly Size: 29,494 (Recommend: Electroporation)

4 Parts

| MpMXBP pFa | pa | ab | bq |
|------------|----------|----|----------|
| ' =' | ! | | <u> </u> |

Reagents

| ligase_buffer.1 | ligase_buffer.2 | ligase_buffer.3 | ligase | bsai |
|-----------------|-----------------|-----------------|--------|------|
| 2.0 | 0.5 | 0.5 | 0 | |

Assembly Name: 4frag Assembly Size: 37,286 (Recommend: Electroporation)

5 Parts

| MpMXBP_pFa | ра | ab | bc |
|------------|----|----|----|
| cq | | | |

Reagents

| ligase_buffer.1 | ligase_buffer.2 | ligase_buffer.3 | ligase | bsai |
|-----------------|-----------------|-----------------|--------|------|
| 2.0 | 0.5 | 1.0 | 0 | |

Automated MetClo Assembly Plan

9 Parts

| Part Name Size | Conc. | Times Used | Volume(30fmol) | Total Volume*1.2 | |
|----------------|-------|------------|----------------|------------------|--|
|----------------|-------|------------|----------------|------------------|--|

Reagents Total * 1.25

| ligase_buffer.1 | ligase_buffer.2 | ligase_buffer.3 | ligase | bsai |
|-----------------|-----------------|-----------------|--------|-------|
| [200] | [200] | [50] | [1.5] | [2.0] |

Automated MetClo Assembly Plan

OT2 Set-Up Instructions

Materials