## **Packing List**



HP Inc. c/o Service Mgmt Solutions 4051 N HIGHWAY 121 SUITE 200 Grapevine TX US 760512300

Wentworth Institute of Technology 550 Huntington Ave Boston MA US 021155901 ramirezf@wit.edu

2024/05/01 11:28:54

**FDEI** 

738095818783



3006790258



0604875001



OD00872617

PO#:INC0238322;

INC0238322

		a dipon		81010	ON
000010	M87577-601	SPS-MB i7-11800H Fury 15 G8 WIN	11-3PL-CT-NREQ		1

**Total Quantity Shipped:** 

Total Box/PalletShipped:

**Total Weight:** 

Special Text:

Attention Recieving Personnel: In case of conceal or visual damage. 1. Save all packaging material. 2. Contact HP Customer Support.

DEFECTIVE

740133234994

PN: M87577-601

RMA Defective: 0604875001010200B

HP Order #: 0604875001 REF #: INC0238322

RETURN PART TO HP WITHIN 2 DAYS

OF RECEIPT

\*\*\*\*\*\*\* REMOVE OLD LABELS

APPLY RETURN LABEL FOR DEFECTIVE RETURN PART IN ORIGINAL PACKAGING

USE ONLY HP SUPPLIED LABEL AND RETURN TO

DEFECTIVE LABEL ADDRESS KEEP COPY OF RETURN INFORMATION DISCARD ANY LEFTOVER RETURN LABELS

740201639218 RMA Good:06048750010102006 REF #: INC0238322

UNUSED

PN: M87577-601

RMA Good:060487

PN: M87577-601

REF #: INCOX

RETURN UNUSED PART TO HP MITHIN

2 DAYS OF RECEIPT

2 DAYS OF RECEIPT

PACKAGING: REMOVE OLD LABEL AND USE HP
PACKAGING: REMOVE OLD LABEL AND USE HP
CABEL ADDRESS:
LABEL ADDRESS:
\*\*\*NEED ADDITIONAL HELP\*\*\*\*

KEEP COPY OF RETURN INFORMATION. DISCARD ANY LEFTOVER RETURN LABELS

REF #: INC0238322 HP DN: 3006790258

HP CSO: 0D00872617 

> RMA Good:0604875001010200G PN: M87577-601

From: 1–999–999–9999 Wentworth Institute of Technology

550 Huntington Ave Boston, MA 02115 US

TO: UNUSED/WPIB/DOA HP Inc. c/o Service Mgmt S 4051 N HICHWAY 121 SUITE 2 Grapevine, TX 76051 US (972)906-7800 REF: 0000872617 PO: 3006790258 Solutions 200

Ship Date: 01MAY2024 Actual Wgt: 1.00LB BILL SHIPPER System#: 436117/FXRS18x



76051